

Proposed Rules

Federal Register

Vol. 84, No. 199

Tuesday, October 15, 2019

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0665; Product Identifier 2019-NE-25-AD]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, and CF34-3B1 model turbofan engines. This proposed AD was prompted by an in-flight failure of a fan blade that led to an in-flight shutdown. This proposed AD would require removal and replacement of the affected fan blades. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 29, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215;

phone: 513-552-3272; email: aviation.fleetsupport@ge.com. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0665; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Christopher McGuire, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0665; Product Identifier 2019-NE-25-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

The FAA was notified of an in-flight failure of a fan blade installed on a GE CF34-3B1 engine. As a result of this failure, the crew shut down the engine and performed an air turnback and a

safe landing. A review by GE determined that a lancepeen was not performed on certain fan blades after a repair done at a repair station between 2007 and 2009. Fan blades can lose their compressive residual stress during certain electron beam weld repairs and hot form repairs. The loss of mechanical properties is restored with the lance peening process called out in these repairs. During an audit, GE identified the fan blades referenced in paragraph (c) of this AD as suspected of missing lance peening. This condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

Related Service Information Under 14 CFR Part 51

The FAA reviewed GE Service Bulletin (SB) CF34-BJ S/B 72-0306, dated September 27, 2017, and GE SB CF34-AL S/B 72-0314, dated September 27, 2017. GE SB CF34-BJ S/B 72-0306 describes procedures for removal and replacement of affected fan blades installed on CF34-1A, -3A, -3A1, -3A2, and -3B model turbofan engines. GE SB CF34-AL S/B 72-0314 describes procedures for removal and replacement of affected fan blades installed on CF34-3A1 and -3B1 model turbofan engines.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA also reviewed GE SB CF34-AL S/B 72-0148, Revision 05, dated July 23, 2015; and GE SB CF34-BJ S/B 72-0123, Revision 04, dated October 21, 2015. GE SB CF34-AL S/B 72-0148 describes procedures for repair of fan blades installed on GE CF34-3A1 and -3B1 model turbofan engines. GE SB CF34-BJ S/B 72-0123 describes procedures for repair of fan blades installed on GE CF34-1A, -3A, -3A1, -3A2, and -3B model turbofan engines.

FAA's Determination

The FAA is proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require removal and replacement of the affected fan blades.

Costs of Compliance

The FAA estimates that this proposed AD affects 121 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace fan blade	2 work-hours × \$85 per hour = \$170	\$11,000	\$11,170	\$1,351,570

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA-2019-0665; Product Identifier 2019-NE-25-AD.

(a) Comments Due Date

The FAA must receive comments by November 29, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, and CF34-3B1 model turbofan engines having a fan blade with a part number listed in Planning Information, paragraph 1.A., of GE Service Bulletin (SB) CF34-AL S/B 72-0314, dated September 27, 2017 or of GE SB CF34-BJ S/B 72-0306, dated September 27, 2017, and with any serial number listed in paragraph 4., Appendix A, of GE SB CF34-AL S/B 72-0314 or of GE SB CF34-BJ S/B 72-0306.

(d) Subject

Joint Aircraft System Component (JASC) Code 7220, Turbine Engine Inlet Section.

(e) Unsafe Condition

This AD was prompted by an in-flight failure of a fan blade that led to an in-flight

shutdown. The FAA is issuing this AD to prevent failure of the fan blade. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Remove the affected fan blades from service within 90 days after the effective date of this AD and replace with a part eligible for installation.

(h) Definition

A part that is eligible for installation is any fan blade other than those identified by paragraph (c) of this AD or a fan blade that has been repaired per GE SB CF34-AL S/B 72-0148, Revision 05, dated July 23, 2015; or GE SB CF34-BJ S/B 72-0123, Revision 04, dated October 21, 2015.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Christopher McGuire, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: aviation.fleet-support@ge.com. You may view this referenced service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the

availability of this material at the FAA, call 781–238–7759.

Issued in Burlington, Massachusetts, on October 7, 2019.

Robert J. Ganley,

Manager, Engine & Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2019–22393 Filed 10–11–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG–121508–18]

RIN 1545–BO97

Multiple Employer Plans; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Proposed rule; notice of hearing.

SUMMARY: This document provides a notice of public hearing on proposed regulations relating to the tax qualification of plans maintained by more than one employer. These plans, maintained pursuant to section 413(c) of the Internal Revenue Code (Code), are often referred to as multiple employer plans or MEPs.

DATES: The public hearing is being held on Wednesday, December 11, 2019, at 10:00 a.m. The IRS must receive speakers' outlines of the topics to be discussed at the public hearing by Monday, November 25, 2019. If no outlines are received by November 25, 2019, the public hearing will be cancelled.

ADDRESSES: The public hearing is being held in the IRS Auditorium, Internal Revenue Service Building, 1111 Constitution Avenue NW, Washington, DC 20224. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present a valid photo identification to enter the building.

Send Submissions to CC:PA:LPD:PR (REG–121508–18), Room 5205, Internal Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday to CC:PA:LPD:PR (REG–121508–18), Couriers Desk, Internal Revenue Service, 1111 Constitution Avenue NW, Washington, DC 20224 or sent electronically via the Federal eRulemaking Portal at www.regulations.gov (IRS REG–121508–18).

FOR FURTHER INFORMATION CONTACT:

Concerning the regulations, Pamela Kinard at (202) 317–6000 or Jamie Dvoretzky at (202) 317–4102; concerning submissions of comments, the hearing and/or to be placed on the building access list to attend the hearing, Regina Johnson at (202) 317–6901 (not toll-free numbers), fdms.database@irs.counsel.treas.gov.

SUPPLEMENTARY INFORMATION: The subject of the public hearing is the notice of proposed rulemaking (REG–121508–18) that was published in the **Federal Register** on Wednesday, July 3, 2019 (84 FR 31777).

The rules of 26 CFR 601.601(a)(3) apply to the hearing. Persons who wish to present oral comments at the hearing that submitted written comments by October 1, 2019, must submit an outline of the topics to be addressed and the amount of time to be devoted to each topic by Monday, November 25, 2019.

A period of 10 minutes is allotted to each person for presenting oral comments. After the deadline for receiving outlines has passed, the IRS will prepare an agenda containing the schedule of speakers. Copies of the agenda will be made available, free of charge, at the hearing or by contacting the Publications and Regulations Branch at (202) 317–6901 (not a toll-free number).

Because of access restrictions, the IRS will not admit visitors beyond the immediate entrance area more than 30 minutes before the hearing starts. For information about having your name placed on the building access list to attend the hearing, see the **FOR FURTHER INFORMATION CONTACT** section of this document.

Martin V. Franks,

Branch Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedure and Administration).

[FR Doc. 2019–22369 Filed 10–11–19; 8:45 am]

BILLING CODE 4830–01–P

DEPARTMENT OF THE TREASURY

Alcohol and Tobacco Tax and Trade Bureau

27 CFR Part 9

[Docket No. TTB–2019–0008; Notice No. 186]

RIN 1513–AC53

Proposed Establishment of the Royal Slope Viticultural Area

AGENCY: Alcohol and Tobacco Tax and Trade Bureau, Treasury.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Alcohol and Tobacco Tax and Trade Bureau (TTB) proposes to establish the 156,389-acre “Royal Slope” viticultural area in Adams and Grant Counties, in Washington. The proposed viticultural area lies entirely within the existing Columbia Valley viticultural area. TTB designates viticultural areas to allow vintners to better describe the origin of their wines and to allow consumers to better identify wines they may purchase. TTB invites comments on this proposed addition to its regulations.

DATES: Comments must be received December 16, 2019.

ADDRESSES: You may electronically submit comments to TTB on this proposal, and view copies of this document, its supporting materials, and any comments TTB receives on it within Docket No. TTB–2019–0008 as posted on Regulations.gov (<https://www.regulations.gov>), the Federal e-rulemaking portal. Please see the “Public Participation” section of this document below for full details on how to comment on this proposal via Regulations.gov, U.S. mail, or hand delivery, and for full details on how to view or obtain copies of this document, its supporting materials, and any comments related to this proposal.

FOR FURTHER INFORMATION CONTACT: Karen A. Thornton, Regulations and Rulings Division, Alcohol and Tobacco Tax and Trade Bureau, 1310 G Street NW, Box 12, Washington, DC 20005; phone 202–453–1039, ext. 175.

SUPPLEMENTARY INFORMATION:

Background on Viticultural Areas

TTB Authority

Section 105(e) of the Federal Alcohol Administration Act (FAA Act), 27 U.S.C. 205(e), authorizes the Secretary of the Treasury to prescribe regulations for the labeling of wine, distilled spirits, and malt beverages. The FAA Act provides that these regulations should, among other things, prohibit consumer deception and the use of misleading statements on labels and ensure that labels provide the consumer with adequate information as to the identity and quality of the product. The Alcohol and Tobacco Tax and Trade Bureau (TTB) administers the FAA Act pursuant to section 1111(d) of the Homeland Security Act of 2002, codified at 6 U.S.C. 531(d). The Secretary has delegated various authorities through Treasury Order 120–01, dated December 10, 2013, (superseding Treasury Order 120–01, dated January 24, 2003), to the TTB