

(e) Unsafe Condition

This AD was prompted by a report of a loss of tail rotor controls due to a broken control rod of the yaw actuator. The root cause of this damage is unknown, and investigation is ongoing. The FAA is issuing this AD to detect and address damage to the ball bearing control system. The unsafe condition, if not addressed, could result in loss of tail rotor controls and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2025–0108, dated May 8, 2025 (EASA AD 2025–0108).

(h) Exceptions to EASA AD 2025–0108

(1) Where EASA AD 2025–0108 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2025–0108 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (2) of EASA AD 2025–0108 specifies “any discrepancy, as defined in the ASB”, this AD requires replacing that text with “any wear or damage.”

(4) Where the material referenced in EASA AD 2025–0108 specifies to examine the close-tolerance bolt, the input lever, the rod end, the adapter, and the connector cover for wear and damage, for the purposes of this AD damage is defined as specified in paragraphs (h)(4)(i) through (iv) of this AD, as applicable.

(i) Damage for the close-tolerance bolt is defined as deformed or stripped, rounded head; bent, stripped, or missing threads; bent shank; grooves in the shank, corrosion or rust; and gouges.

(ii) Damage for the input lever is defined as deformation or elongated attachment hole; bent flange; gouges; corrosion; and cracks.

(iii) Damage for the rod end is defined as corrosion, gouges, bending, and seizing.

(iv) Damage for the adapter or connector is defined as deformation, elongated attachment holes, gouges, cracks, corrosion, and missing surface coating on the adapter or connector.

(5) Where the material referenced in EASA AD 2025–0108 specifies if the ball pivot shows rough stiffness, hard stops, corrosion, or damage, for the purposes of this AD damage is defined as deformation (bent flanges), gouges, areas of bare metal, or missing finish.

(6) Where paragraph (4) of EASA AD 2025–0108 specifies to report inspection results to Airbus Helicopters Deutschland within certain compliance times, for this AD, report inspection results at the applicable times specified in paragraphs (h)(6)(i) or (ii) of this AD.

(i) For an inspection done on or after the effective date of this AD: Submit the report within 15 days after the inspection.

(ii) For an inspection done before the effective date of this AD: Submit the report

within 15 days after the effective date of this AD.

(7) Where the material referenced in EASA AD 2025–0108 specifies actions for non-installed equipment or parts, this AD does not require those actions.

(8) Where the material referenced in EASA AD 2025–0108 specifies to replace an affected part, this AD requires removing an affected part from service and replacing it with a serviceable part.

(9) This AD does not adopt the Remarks section of EASA AD 2025–0108.

(i) No Returning Parts Requirement

Although the material referenced in EASA AD 2025–0108 specifies to return parts to the manufacturer, this AD does not require that action.

(j) Special Flight Permits

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(l) Additional information

For more information about this AD, contact Steven Warwick, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY; phone: (817) 222–5225; email: steven.r.warwick@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2025–0108, dated May 8, 2025.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on

the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on June 18, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–12388 Filed 6–30–25; 4:15 pm]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2025–0209; Project Identifier MCAI–2024–00636–E; Amendment 39–23073; AD 2025–13–07]

RIN 2120–AA64

Airworthiness Directives; Safran Helicopter Engines, S.A. (Type Certificate Previously Held by Turbomeca, S.A.) Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A. (Safran) Model ARRIUS 2B2 engines. This AD was prompted by a manufacturer review of collected data from in-service engines that indicated the preference injector may clog over time caused by fuel coking, which decreases the permeability of the preference injector. This AD requires initial and repetitive non-extinguishing tests for engine flameout and replacement of the preference injector if necessary, a one-time modification (software upgrade) of the electronic engine control unit (EECU) and, for certain engines, repetitive replacements of the preference injector. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 6, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 6, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2025–0209; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and

other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-0209.

FOR FURTHER INFORMATION CONTACT:

David Bergeron, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (860) 386-1805; email: david.j.bergeron@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Safran Helicopter Engines, S.A. (Safran) Model ARRIUS 2B2 engines. The NPRM was published in the **Federal Register** on February 25, 2025 (90 FR 10617). The NPRM was prompted by EASA AD 2024-0195R1, dated October 22, 2024 (EASA AD 2024-0195R1) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union, which revised EASA AD 2024-0195, dated October 18, 2024 (EASA AD 2024-0195). EASA AD 2024-0195 states that a manufacturer review of collected data from in-service engines indicated that the preference injector may clog over time caused by fuel coking, which could decrease the

permeability of the preference injector. EASA AD 2024-0195 also specifies non-extinguishing tests and replacements of the preference injector at reduced intervals, and upgrade of the EECU software based on two manufacturer design changes which, in combination, reduce the clogging rate, but do not mitigate the potential of the unsafe condition. The manufacturer also issued service material that provided instructions for a non-extinguishing test and replacement of the preference injector at shorter intervals than specified in the Engine Maintenance Manual. The manufacturer then developed an EECU software upgrade (modification TU 173) for certain engines installed on certain helicopters, which allows automatic accomplishment of the non-extinguishing test, and published service material providing instructions to embody the software upgrade on in-service engines.

EASA AD 2024-0195R1 states that EASA revised EASA AD 2024-0195 and issued EASA AD 2024-0195R1 to retain all actions from EASA AD 2024-0195 and amend the applicable groups, because modification TU 173 is applicable only to engines installed on Airbus Helicopters Deutschland EC135T2, EC135T2+, EC635T2, or EC635T2+ helicopters.

In the NPRM, the FAA proposed to require initial and repetitive non-extinguishing tests for engine flameout and replacement of the preference injector if necessary, a one-time modification (software upgrade) of the EECU and, for certain engines, repetitive replacements of the preference injector.

Clogging of the preference injector, if not detected and corrected, and if combined with a sharp reduction in the fuel flow during the flight after a pilot command, could lead to a flameout in the combustion chamber, which could result in an uncommanded in-flight shutdown of the engine and reduced control of the helicopter. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2025-0209.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from 1 individual commenter. The commenter supported the NPRM without change.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024-0195R1, which specifies procedures for initial and repetitive non-extinguishing tests, a one-time modification (software upgrade) of the EECU, and repetitive replacements of the preference injector. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 186 engines installed on helicopters of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Initial non-extinguishing test (186 engines)	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$15,810
Repetitive non-extinguishing test (54 engines)	1 work-hour × \$85 per hour = \$85	0	85	4,590
Injector replacement (186 engines)	1 work-hour × \$85 per hour = \$85	1,819	1,904	354,144
EECU software upgrade (132 engines)	7 work-hours × \$85 per hour = \$595	0	595	78,540

The FAA estimates the following costs to do any necessary on-condition replacement that would be required

based on the results of any required tests. The agency has no way of determining the number of engines that

might need this on-condition replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Injector replacement	1 work-hour x \$85 per hour = \$85	\$1,819	\$1,904

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–13–07 Safran Helicopter Engines, S.A. (Type Certificate previously held by Turbomeca, S.A.): Amendment 39–23073; Docket No. FAA–2025–0209; Project Identifier MCAI–2024–00636–E.

(a) Effective Date

This airworthiness directive (AD) is effective August 6, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Safran Helicopter Engines, S.A. (type certificate previously held by Turbomeca, S.A.) Model ARRIUS 2B2 engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7300, Engine Fuel and Control.

(e) Unsafe Condition

This AD was prompted by a manufacturer review of collected data from in-service engines that indicated the preference injector may clog over time caused by fuel coking, which could decrease the permeability of the preference injector. The FAA is issuing this AD to detect and correct clogging and decreased permeability of the preference injector due to fuel coking. The unsafe condition, if not addressed, when combined with a sharp reduction in fuel flow, could result in a flameout in the combustion chamber, which could result in an uncommanded in-flight shutdown of the engine and reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0195R1, dated October 22, 2024 (EASA AD 2024–0195R1).

(h) Exceptions to EASA AD 2024–0195R1

(1) Where EASA AD 2024–0195R1 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the “Remarks” section of EASA AD 2024–0195R1.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0195R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(k) Additional Information

For more information about this AD, contact David Bergeron, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (860) 386–1805; email: david.j.bergeron@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0195R1, dated October 22, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on June 18, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–12332 Filed 7–1–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–1116; Project Identifier MCAI–2024–00708–R; Amendment 39–23071; AD 2025–13–05]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model H160–B helicopters. This AD was prompted by occurrences of premature in-service degradation of the main rotor swashplate assembly (swashplate) bearing. This AD requires repetitively inspecting the swashplate bearing for the presence of grease, and depending on the inspection results, performing corrective actions. This AD requires performing certain operational checks, downloading and analyzing certain data, and, depending on the results of the operational checks, further corrective actions. This AD also requires repetitively performing one flight under specific conditions. Additionally, this AD requires inspecting grease on the swashplate bearing and, depending on the inspection results, applying a certain grease or replacing the grease. This AD allows installing certain part-numbered swashplate bearings provided certain requirements are met. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 17, 2025.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 17, 2025.

The FAA must receive comments on this AD by August 18, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- **Fax:** (202) 493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–1116; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–1116.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

FOR FURTHER INFORMATION CONTACT:

Aryanna Sanchez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (817) 222–4058; email: aryanna.t.sanchez@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2025–1116; Project Identifier MCAI–2024–00708–R” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the

following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Aryanna Sanchez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024–0229, dated December 2, 2024 (EASA AD 2024–0229) (also referred to as the MCAI) to correct an unsafe condition on Airbus Helicopters Model H160–B helicopters. The MCAI states multiple occurrences were reported of premature in-service degradation of the swashplate bearing, which could have been due to the use of the wrong grease or a mixture of incompatible greases. The MCAI also states the health usage monitoring system (HUMS) has been effective to detect early degradation of the swashplate bearings; however, data shows that additional inspections and repetitive flights are needed to ensure HUMS data is analyzed on a regular basis to detect the degradation.

The FAA is issuing this AD to prevent premature swashplate bearing degradation. The unsafe condition, if not addressed, could result in failure of the swashplate bearing and consequent reduced control of the helicopter.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–1116.