

Parts Installation

(d) As of the effective date of this AD: No person may install an Arkwin Industries RAT actuator having P/N 764711 on any Airbus Model A319, A320, or A321 airplane, unless it is in compliance with this AD.

Note 1: The subject of this AD is addressed in French airworthiness directive 2001-236(B) R1, dated December 24, 2002.

Issued in Renton, Washington, on December 5, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-31065 Filed 12-16-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2002-NM-18-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, and A321 series airplanes. This proposal would require replacing the upper guide rod fittings at the rear passenger doors with improved fittings. This action is necessary to prevent failure of an upper guide rod fitting, which could cause a rear passenger door to jam during opening, delaying an emergency evacuation and resulting in injury to passengers or crew members. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 16, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-18-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain

“Docket No. 2002-NM-18-AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to

Docket Number 2002-NM-18-AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-18-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A319, A320, and A321 series airplanes. The DGAC advises that there have been several reports of cracking and rupture of the upper guide rod fittings for the rear passenger doors on in-service airplanes. This condition, if not corrected, could cause a rear passenger door to jam during opening, delaying an emergency evacuation and resulting in injury to passengers or crew members.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-53-1154, Revision 2, dated March 7, 2003. That service bulletin describes procedures for replacing the upper guide rod fitting on each rear passenger door with an improved fitting. The improved fitting is stronger than the existing one due to an increase in thickness and different material.

Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified a previous revision of this service bulletin as mandatory and issued French airworthiness directive 2001-634(B), dated December 26, 2001, to ensure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are

certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 440 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 10 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$65 per work hour. Required parts would cost approximately \$2,200 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$1,254,000, or \$2,850 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions. The manufacturer may cover the cost of replacement parts associated with this proposed AD, subject to warranty conditions. As a result, the costs attributable to the proposed AD may be less than stated above.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant

economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 2002–NM–18–AD.

Applicability: Model A319, A320, and A321 series airplanes; certificated in any category; on which Airbus Modification 30821 has not been accomplished.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of an upper guide rod fitting, which could cause a rear passenger door to jam during opening, delaying an emergency evacuation and resulting in injury to passengers or crew members, accomplish the following:

Replacement

(a) Within 22 months after the effective date of this AD, replace the upper guide rod fitting on each rear passenger door with an improved fitting by doing all actions in and per the Accomplishment Instructions of Airbus Service Bulletin A320–53–1154, Revision 2, dated March 7, 2003.

Replacements Accomplished Previously

(b) Replacements accomplished before the effective date of this AD per the Accomplishment Instructions of Airbus Service Bulletin A320–53–1154, dated July 12, 2001; or Revision 1, dated August 28, 2002; are acceptable for compliance with the corresponding action required by this AD.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance for this AD.

Note 1: The subject of this AD is addressed in French airworthiness directive 2001–634(B), dated December 26, 2001.

Issued in Renton, Washington, on December 5, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–31064 Filed 12–16–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Parts 1 and 301

[REG–146893–02, REG–115037–00]

RIN 1545–BB31, 1545–AY38

Treatment of Services Under Section 482; Allocation of Income and Deductions From Intangibles; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking and notice of public hearing.

SUMMARY: This document contains corrections to a notice of proposed rulemaking and notice of public hearing that was published in the **Federal Register** on Wednesday, September 10, 2003 (68 FR 53448). The proposed regulations provide guidance regarding the treatment of controlled services transactions under section 482 and the allocation of income from intangibles in particular when one controlled taxpayer performs activities that increase (or are expected to increase) the value of an intangible owned by another controlled taxpayer.

FOR FURTHER INFORMATION CONTACT: J. Peter Luedtke or Helen Hong-George, (202) 435–5265 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking and notice of public hearing that is the subject of this correction is under section 482 of the Internal Revenue Code.

Need for Correction

As published, the notice of proposed rulemaking and notice of public hearing contains errors that may prove to be misleading and are in need of clarification.

Correction of Publication

Accordingly, the publication of the notice of proposed regulations and