

a report that operators may not have been provided with enough data to determine the accumulated life of certain propeller shafts. The FAA is issuing this AD to prevent the failure of the propeller shaft. The unsafe condition, if not addressed, could result in damage to the engine, damage to the airplane, and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For affected M601F model turboprop engines, before the propeller shaft accumulates 12,000 flight hours (FHs) since first installation on an engine, or before accumulating 350 FHs after the effective date of this AD, whichever occurs later, remove the propeller shaft and replace with a part eligible for installation.

(2) For affected M601D-11, M601E-11, M601E-11A, M601E-11AS, and M601E-11S model turboprop engines:

(i) Within 100 FHs after the effective date of this AD, calculate the total time since new of the propeller shaft in accordance with the Accomplishment Instructions, section 2.2 Group 2 Engines, paragraph 1., of the ASB.

(ii) Remove the propeller shaft prior to reaching its applicable life limit and replace with a part eligible for installation in accordance with the Accomplishment Instructions, section 2.2 Group 2 Engines, paragraph 2., of the ASB.

(h) Definitions

(1) For the purpose of this AD, a “part eligible for installation” on M601F, M601E-11, and M601E-11A model turboprop engines is a propeller shaft identified in the Configuration Description, paragraph 1.5, Table 1, of the ASB, as applicable to the engine model, with a calculated life that has not exceeded the applicable life limit.

(2) For the purpose of this AD, a “part eligible for installation” on M601D-11 model turboprop engines is a propeller shaft with P/N M601-6081.2, P/N M601-6081.4, or P/N M601-6081.5, with a calculated life that has not exceeded the applicable life limit.

(3) For the purpose of this AD, a “part eligible for installation” on M601E-11AS and M601E-11S model turboprop engines is a propeller shaft with P/N M601-6081.2, P/N M601-6081.5, or P/N M601-6081.6, with a calculated life that has not exceeded the applicable life limit.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021-0154, dated July 1, 2021, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0385.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) GE Aviation Czech Alert Service Bulletin (ASB) ASB-M601F-72-10-00-0056 [02], ASB-M601D-72-10-00-0072 [02], ASB-M601E-72-10-00-0103 [02], and ASB-M601Z-72-10-00-0056 [02] (single document; formatted as service bulletin identifier [revision number]), dated May 31, 2021.

(ii) [Reserved]

(3) For GE Aviation Czech service information identified in this AD, contact GE Aviation Czech s.r.o., Beranových 65, 199 02 Praha 9, Letňany, Czech Republic; phone: +420 222 538 111.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 29, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-15025 Filed 7-13-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0507; Project Identifier MCAI-2021-01372-T; Amendment 39-22114; AD 2022-14-09]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Support and Services (Formerly Known as Saab AB, Saab Aeronautics) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Saab AB, Support and Services Model 340A (SAAB/SF340A) and SAAB 340B airplanes. This AD was prompted by a report that there is no evidence that post-machining stress relief or de-embrittlement post-cadmium plating treatments were performed on certain torque arm center pins. This AD requires replacing each affected torque arm center pin on the main landing gear (MLG), as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD also prohibits the installation of affected parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 18, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 18, 2022.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0507.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0507; or in person at Docket

Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3220; email shahram.daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0273, dated December 8, 2021 (EASA AD 2021-0273) (also referred to as the MCAI), to correct an unsafe condition for certain Saab AB, Support and Services Model 340A (SAAB/SF340A) and SAAB 340B airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would

apply to certain Saab AB, Support and Services Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The NPRM published in the **Federal Register** on May 6, 2022 (87 FR 27035). The NPRM was prompted by a report that there is no evidence that post-machining stress relief or de-embrittlement post-cadmium plating treatments were performed on certain torque arm center pins. The NPRM proposed to require replacing each affected torque arm center pin on the MLG, as specified in EASA AD 2021-0273. The NPRM also proposed to prohibit the installation of affected parts.

The FAA is issuing this AD to address untreated torque arm center pins installed on any MLG, which, if not corrected, could lead to failure of the torque arm center pin and free swinging of the MLG, possibly resulting in loss of control of the airplane on ground, or loss of the MLG hydraulic braking function. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0273 specifies procedures for replacing each affected torque arm center pin on the MLG. EASA AD 2021-0273 also prohibits the installation of affected parts. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 43 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators *
8 work-hours × \$85 per hour = \$680	\$2,839	\$3,519	\$151,317

* According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–14–09 Saab AB, Support and Services (Formerly Known as Saab AB, Saab Aeronautics): Amendment 39–22114; Docket No. FAA–2022–0507; Project Identifier MCAI–2021–01372–T.

(a) Effective Date

This airworthiness directive (AD) is effective August 18, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Support and Services Model 340A (SAAB/SF340A) and SAAB 340B airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2021–0273, dated December 8, 2021 (EASA AD 2021–0273).

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Unsafe Condition

This AD was prompted by a report that there is no evidence that post-machining stress relief or de-embrittlement post-cadmium plating treatments were performed on certain torque arm center pins. The FAA is issuing this AD to address untreated torque arm center pins installed on any main landing gear (MLG), which, if not corrected, could lead to failure of the torque arm center pin and free swinging of the MLG, possibly resulting in loss of control of the airplane on ground, or loss of the MLG hydraulic braking function.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021–0273.

(h) Exceptions to EASA AD 2021–0273

(1) Where EASA AD 2021–0273 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021–0273 does not apply to this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: *9-AVS-AIR-730-AMOC@faa.gov*. Before using any

approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Saab AB, Support and Services’ EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3220; email *shahram.daneshmandi@faa.gov*.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0273, dated December 8, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0273, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; internet *www.easa.europa.eu*. You may find this EASA AD on the EASA website at *https://ad.easa.europa.eu*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fr.inspection@nara.gov*, or go to: *https://www.archives.gov/federal-register/cfr/ibr-locations.html*.

Issued on June 27, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–14970 Filed 7–13–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2021–0856; Airspace Docket No. 19–AAL–50]

RIN 2120–AA66

Establishment of United States Area Navigation (RNAV) Route T–381; Big Lake, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes United States Area Navigation (RNAV) route T–381 in the vicinity of Big Lake, AK in support of a large and comprehensive T-route modernization project for the state of Alaska.

DATES: Effective date 0901 UTC, September 8, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at *https://www.faa.gov/air_traffic/publications/*. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT: Jesse Acevedo, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it expands the availability of RNAV in Alaska and improve the efficient flow of air traffic