

Actions	Compliance	Procedures
(4) If corrosion or damage is found during any inspection required in paragraph (d)(3) of this AD: (i) replace or repair any damaged part in accordance with the procedures specified in the manufacturer's service bulletin; or (ii) if damage exceeds the limits defined in the manufacturer's service bulletin, obtain a repair scheme from the manufacturer through the FAA at the address specified in paragraph (f) of this AD; and (iii) incorporate this repair scheme.	Prior to further flight after the inspection in which the damage was found.	Repair in accordance with the repair scheme obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA92RW, Scotland. Obtain this repair scheme through the FAA at the address specified in paragraph (f) of this AD.

Note 1: Although not required by this AD, FAA highly recommends you accomplish *Highly Recommended Corrosion Prevention Tasks* in British Aerospace Jetstream Service Bulletin 55-JA020544, Original Issue: October 24, 2002, upon accomplishing the initial inspection of this AD and during repetitive inspections if damage is found.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standards Office.

Note 2: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may get copies of the documents referenced in this AD from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 672345; facsimile: (01292) 671625. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901

Locust, Room 506, Kansas City, Missouri 64106.

Note 3: The subject of this AD is addressed in British Aerospace Jetstream Mandatory Service Bulletin 55-JA020543, Original Issue: October 24, 2002. This service bulletin is classified as mandatory by the United Kingdom Civil Aviation Authority (CAA).

Issued in Kansas City, Missouri, on December 2, 2002.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-31129 Filed 12-9-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-218-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dornier Model 328-100 and -300 series airplanes. This proposal would require replacement of certain flight data recorder (FDR) and cockpit voice recorder (CVR) impact switches with certain new impact switches. This action is necessary to prevent the loss of data recorded on the FDR and CVR, which, in the event of an accident, could result in the inability to retrieve data from the FDR and CVR during the accident investigation. This loss of data could hinder the identification of the unsafe condition which caused the accident, and prevent the FAA from developing and mandating actions to

prevent additional accidents caused by that same unsafe condition.

DATES: Comments must be received by January 9, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-218-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-218-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from FAIRCHILD DORNIER, DORNIER Luftfahrt GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date

for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-218-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-218-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on certain Dornier Model 328-100 and -300 series airplanes. The LBA advises that it received a report indicating that 3g-impact switches were found to be installed in the flight data recorder (FDR) and cockpit voice recorder (CVR). The 3g-impact switches could turn off the FDR and CVR once the loads on the airplane reached 3g, and, thus, there would be no means of recording data when the loads exceeded 3g. An airplane acceleration of 4.25g could trip the switches and turn off the FDR and CVR. In the event of an accident, after experiencing 4.25g, the FDR and CVR could be turned off and data would not be recorded. Replacement of the 3g-

impact switches with new, 6g-impact switches is necessary to prevent the loss of data recorded on the FDR and CVR, which could result in the inability to retrieve data from the FDR and CVR in the event of an accident. This loss of data could hinder the identification of the unsafe condition which caused the accident, and prevent the FAA from developing and mandating actions to prevent additional accidents caused by that same unsafe condition.

FAA's Determination of Unsafe Condition

This action is necessary to prevent the loss of data recorded on the FDR and CVR. The loss of data does not directly affect the safety of the airplane. However, should an airplane with a 3g-impact switch have an unsafe condition which results in an accident, the data retrieved from the FDR and CVR would be incomplete. This lack of reliable data could hinder identification of the unsafe condition which caused the accident, and prevent the FAA from developing and mandating actions to prevent additional accidents caused by that same unsafe condition. Therefore, the FAA has determined that the proposed action is necessary.

It should be noted that the purpose of this action is not to enhance the safety of the Dornier Model 328-100 and -300 series airplanes, but rather to restore the level of safety provided by the originally approved FDR and CVR. Therefore, this AD is the appropriate regulatory vehicle to achieve this purpose.

Explanation of Relevant Service Information

Dornier has issued Service Bulletins SB-328-31-390 (for Model 328-100 series airplanes); and SB-328J-31-118 (for Model 328-300 series airplanes); both dated September 6, 2001. These service bulletins describe procedures for replacement of 3g-impact switches with new, 6g-impact switches for the FDR and the CVR. The LBA classified these service bulletins as mandatory and issued German airworthiness directives 2002-238 and 2002-239, both dated August 22, 2002, in order to assure the continued airworthiness of these airplanes in Germany.

FAA's Conclusions

These airplane models are manufactured in Germany and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has

kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since the loss of data recorded on the FDR and CVR may hinder the identification of an unsafe condition that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the applicable service bulletin described previously.

Cost Impact

The FAA estimates that 53 Model 328-100 series airplanes and 48 Model 328-300 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$1,346 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$142,006, or \$1,406 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not

a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Dornier Luftfahrt GmbH: Docket 2002-NM-218-AD.

Applicability: Airplanes listed in the following table of this AD, certificated in any category:

TABLE—APPLICABILITY

Model	Serial No.
328-100 series airplanes.	3005 through 3119 inclusive
328-300 series airplanes.	3105 through 3223 inclusive

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the loss of data recorded on the flight data recorder (FDR) and cockpit voice recorder (CVR), which, in the event of accident, could result in the inability to retrieve data from the FDR and CVR during the accident investigation, and hinder the identification of the unsafe condition which caused the accident, accomplish the following:

Switch Replacement

(a) For Model 328-100 series airplanes: Within 12 months after the effective date of this AD, replace the FDR and cockpit voice recorder CVR 3g-impact switches, with new, 6g-impact switches, per the Accomplishment Instructions of Dornier Service Bulletin SB-328-31-390, dated September 6, 2001.

(b) For Model 328-300 series airplanes: Within 12 months after the effective date of this AD, replace the FDR and CVR 3g-impact switches, with new, 6g-impact switches, per the Accomplishment Instructions of Dornier Service Bulletin SB-328J-31-118, dated September 6, 2001.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in German airworthiness directives 2002-238 and 2002-239, both dated August 22, 2002.

Issued in Renton, Washington, on December 4, 2002.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-31135 Filed 12-9-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-374-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, 737-700, 737-800, 757-200, and 757-300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 737-600, 737-700, 737-800, 757-200, and 757-300 series airplanes. This proposal would require replacing existing video distribution unit (VDU) connectors with new, improved connectors or new wire assemblies (jumpers), and performing related actions, as applicable. This action is necessary to prevent a short circuit in a VDU connector and consequent arcing and damage to wiring within the connector, which could result in damage to adjacent systems or structure and possible smoke or fire in the airplane cabin. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 24, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-374-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-374-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport