

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–21–04 Embraer S.A.: Amendment 39–22576; Docket No. FAA–2023–1708; Project Identifier MCAI–2023–00554–A.

(a) Effective Date

This airworthiness directive (AD) is effective December 11, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Embraer S.A. Model EMB–505 airplanes, as identified in paragraph (a) of Agência Nacional de Aviação Civil (ANAC) AD 2023–04–01, effective April 4, 2023 (ANAC AD 2023–04–01), certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3100, Indicating/recording system.

(e) Unsafe Condition

This AD was prompted by occurrences of an uncommanded change in the setting of the barometric pressure in both primary flight displays (PFDs). The FAA is issuing this AD to address the uncommanded change in the setting of the barometric pressure in both PFDs. The unsafe condition, if not addressed, could result in altitude mismanagement or spatial disorientation of the flight crew, with consequent deviation from the intended altitude and loss of control of the airplane, risk of air collision due to inadequate air traffic separation, or risk of controlled flight into terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD 2023–04–01.

(h) Exceptions to ANAC AD 2023–04–01

(1) Where ANAC AD 2023–04–01 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt paragraphs (c), (d), and (e) of ANAC AD 2023–04–01.

(i) No Reporting Required

Although the service information referenced in ANAC AD 2023–04–01 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (k) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329–4165; email: jim.rutherford@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Agência Nacional de Aviação Civil (ANAC) AD 2023–04–01, effective April 4, 2023.

(ii) [Reserved]

(3) For ANAC AD 2023–04–01, contact ANAC, Continuing Airworthiness Technical Branch (GTAC), Rua Doutor Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; phone: 55 (12) 3203–6600; email: pac@anac.gov.br; website: anac.gov.br/en/. You may find this material on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on October 26, 2023.

Caitlin Locke,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–24393 Filed 11–3–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2023–1717; Project Identifier MCAI–2023–00728–A; Amendment 39–22578; AD 2023–21–06]

RIN 2120–AA64

Airworthiness Directives; Embraer S.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. (Embraer) Model EMB–505 airplanes. This AD was prompted by analysis of certain monuments (the right-hand refreshment center and left-hand forward cabinet) that identified the need for installing structural reinforcements and replacing certain floor support rivets. This AD requires installing structural reinforcements on certain monuments and replacing certain floor support rivets, as specified in an Agência Nacional de Aviação Civil (ANAC) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 11, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 11, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2023–1717; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For the service information identified in this final rule, contact ANAC, Continuing Airworthiness Technical Branch (GTAC), Rua Doutor Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; phone: 55 (12) 3203–6600; email: pac@anac.gov.br;

website: anac.gov.br/en/. You may find this material on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available in the AD docket at regulations.gov under Docket No. FAA-2023-1717.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain serial-numbered Embraer Model EMB-505 airplanes. The NPRM published in the **Federal Register** on August 24, 2023 (88 FR 57907). The NPRM was prompted by AD 2023-05-03, effective June 2, 2023, issued by ANAC, which is the aviation authority for Brazil (ANAC AD 2023-04-01) (also referred to as the MCAI), to correct an unsafe condition for certain serial-numbered Embraer Model EMB-505 airplanes. The MCAI states that analysis identified certain monuments (the right-hand refreshment center and

left-hand forward cabinet) that might not withstand the loads expected for specific emergency landing conditions, which may cause the detachment of mass items and result in injuries to the airplane occupants. To address this unsafe condition, the MCAI specifies installing structural reinforcements on certain monuments and replacing applicable floor support rivets.

In the NPRM, the FAA proposed to require installing structural reinforcements on certain monuments and replacing certain floor support rivets, as specified in ANAC AD 2023-04-01. The FAA is issuing this AD to address the unsafe condition.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2023-1717.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant

data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

ANAC AD 2023-05-03 specifies procedures for installing structural reinforcements on certain monuments and replacing applicable fasteners on the floor support.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Differences Between This AD and the MCAI

The service information specified in ANAC AD 2023-05-03 allows the use of alternative or similar parts in place of the ones specified in the kits, provided these alternative or similar parts are approved by Embraer, but this AD requires approval from either the Manager, International Validation Branch, FAA; ANAC; or ANAC's authorized Designee.

Costs of Compliance

The FAA estimates that this AD affects 208 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Airplane groups 1 and 2—install structural reinforcements.	21.50 work-hours × \$85 per hour = \$1,827.50.	\$1,600	\$3,427.50	\$239,925 (70 airplanes).
Airplane groups 3, 4, 5, and 10—install structural reinforcements and replace floor fasteners.	13.50 work-hours × \$85 per hour = \$1,147.50.	\$600	\$1,747.50	\$214,942.50 (123 airplanes).
Airplane groups 6 and 8—install structural reinforcements and replace floor fasteners.	25.50 work-hours × \$85 per hour = \$2,167.50.	\$2,000	\$4,167.50	\$37,507.50 (9 airplanes).
Airplane group 7—install structural reinforcements.	19.50 work-hours × \$85 per hour = \$1,657.50.	\$1,600	\$3,257.50	\$16,287.50 (5 airplanes).
Airplane group 9—install structural reinforcements.	13.50 work-hours × \$85 per hour = \$1,147.50.	\$1,600	\$2,747.50	\$2,747.50 (1 airplane).

The FAA estimates the following costs for operators that did the actions in the original version of Embraer

Service Bulletin SB505-25-0046, dated March 31, 2021. The agency has no way

of determining the number of airplanes that might need these actions:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Inspect floor fasteners	8.50 work-hours × \$85 per hour = \$722.50	\$50	\$772.50
Replace floor fasteners	1 work-hour × \$85 per hour = \$85	\$50	\$135

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–21–06 Embraer S.A.: Amendment 39–22578; Docket No. FAA–2023–1717; Project Identifier MCAI–2023–00728–A.

(a) Effective Date

This airworthiness directive (AD) is effective December 11, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Embraer S.A. Model EMB–505 airplanes, as identified in Agência Nacional de Aviação Civil (ANAC) AD 2023–05–03, effective June 2, 2023 (ANAC AD 2023–05–03), certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2500, Cabin Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by analysis of certain monuments (the right-hand refreshment center and left-hand forward cabinet) that identified the need for installing structural reinforcements and replacing applicable floor support rivets. The FAA is issuing this AD to address the unsafe condition. The unsafe condition, if not addressed, could result in a monument not withstanding the loads expected for specific emergency landing conditions, which may cause the detachment of mass items and result in injuries to the airplane occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD 2023–05–03.

(h) Exceptions to ANAC AD 2023–05–03

(1) Where ANAC AD 2023–05–03 refers to its effective date, this AD requires using the effective date of this AD.

(2) The service information referenced in ANAC AD 2023–05–03 allows the use of alternative or similar parts in place of the ones specified in the kits, provided that these alternative or similar parts are approved by Embraer. This AD requires approval from either the Manager, International Validation Branch, FAA; ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(3) Where the service information referenced in ANAC AD 2023–05–03 specifies discarding parts, this AD requires removing those parts from service.

(4) This AD does not adopt paragraph (d) of ANAC AD 2023–05–03.

(i) No Reporting Requirement

Although the service information referenced in ANAC AD 2023–05–03 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (k) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329–4165; email: jim.rutherford@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Agência Nacional de Aviação Civil (ANAC) AD 2023–05–03, effective June 2, 2023.

(ii) [Reserved]

(3) For ANAC AD 2023–05–03, contact ANAC, Continuing Airworthiness Technical Branch (GTAC), Rua Doutor Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; phone: 55 (12) 3203–6600; email: pac@anac.gov.br; website: anac.gov.br/en/. You may find this material on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on October 26, 2023.

Caitlin Locke,

Director, Compliance & Airworthiness
Division, Aircraft Certification Service.

[FR Doc. 2023-24387 Filed 11-3-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1314; Project Identifier AD-2021-00811-E; Amendment 39-22579; AD 2023-21-07]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2018-03-13 for certain General Electric Company (GE) Model CT7-5A2, CT7-5A3, CT7-7A, CT7-7A1, CT7-9B, CT7-9B1, CT7-9B2, CT7-9C, and CT7-9C3 engines. AD 2018-03-13 required initial and repetitive visual inspections and fluorescent penetrant inspections (FPIs) of the main propeller shaft. This AD was prompted by an in-flight failure of a main propeller shaft on a GE Model CT7-9B engine, resulting in the loss of the propeller. This AD requires initial and repetitive visual inspections, FPIs, and ultrasonic inspections (USIs) of the main propeller shaft. Depending on the results of these inspections, this AD requires replacement of the main propeller shaft. As an optional terminating action to these inspections, this AD requires revising the airworthiness limitations section (ALS) of the existing maintenance manual (MM) and the operator's existing approved maintenance program or inspection program, as applicable, to incorporate incorporating the tasks and reduced inspection thresholds for the main propeller shaft. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 11, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 11, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2022-1314; or in person at Docket Operations between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For GE service information identified in this final rule, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ae.ge.com; website: ge.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at *regulations.gov* under Docket No. FAA-2022-1314.

FOR FURTHER INFORMATION CONTACT:

Sungmo Cho, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7241; email: Sungmo.D.Cho@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to supersede AD 2018-03-13, Amendment 39-19186 (83 FR 6125, February 13, 2018) (AD 2018-03-13). AD 2018-03-13 applied to certain GE Model CT7-5A2, CT7-5A3, CT7-7A, CT7-7A1, CT7-9B, CT7-9B1, CT7-9B2, CT7-9C and CT7-9C3 engines. The SNPRM published in the **Federal Register** on July 11, 2023 (88 FR 44068). The SNPRM was prompted by a comment from GE Aerospace on the notice of proposed rulemaking (NPRM). GE Aerospace stated that certain engine models were included in incorrect Figures within the Required Actions paragraph of the NPRM, which would attribute inaccurate inspection thresholds to those engine models. Therefore, the FAA issued the SNPRM with a revision to Figures 1 and 2 to include the correct engine models. The FAA also updated the affected engine models listed in paragraphs (g)(1) and (g)(2) of the SNPRM to correspond with the corrected engine models referenced in Figures 1 and 2.

In the SNPRM, the FAA proposed to require initial and repetitive visual inspections, FPIs, and USIs of the main propeller shaft. Depending on the results of these inspections, the SNPRM

proposed to require replacing the main propeller shaft. As an optional terminating action to these inspections, the SNPRM proposed to require revising the ALS of the existing MM and the operator's existing approved maintenance program or inspection program, as applicable, to incorporate the tasks and reduced inspection thresholds for the main propeller shaft. The FAA is issuing this AD to address the unsafe condition on these products.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from one commenter, GE Aerospace. The following presents the comment received on the SNPRM and the FAA's response to that comment.

Request To Remove Typographical Error From SNPRM

GE noted that there is a typological [typographical] error in the "Proposed AD Requirements in This SNPRM" paragraph of the SNPRM in which the words "at least" are repeated in succession.

The FAA agrees, however, the "Proposed AD Requirements in This SNPRM" paragraph is not included in this Final Rule. The FAA did not change this AD as a result of this comment.

Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting the AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes and any other changes described previously, this AD is adopted as proposed in the SNPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 14 CFR Part 51

The FAA reviewed GE Service Bulletin (SB) CT7-TP 72-0541 R01, dated November 18, 2021 (GE SB CT7-TP 72-0541). This service information specifies procedures for performing initial and repetitive visual inspections, FPIs, and USIs of the main propeller shaft.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.