

identification number shall consist of the State's two-letter postal abbreviation followed by the premises' assigned number. A premises identification number may be used in conjunction with a producer's own livestock production numbering system to provide a unique identification number for an animal.

Recognized slaughtering establishment. A slaughtering establishment² operating under the Federal Meat Inspection Act (21 U.S.C. 601 *et seq.*) or a State inspected slaughtering establishment.

State. Any of the 50 States, the Commonwealth of Puerto Rico, the Commonwealth of the Northern Mariana Islands, the District of Columbia, and any territories and possessions of the United States.

State animal health official. The State official responsible for livestock and poultry disease control and eradication programs.

State representative. An individual employed in animal health work by a State or political subdivision of a State, and who is authorized by the State or political subdivision to perform tasks required by this part.

§ 80.2 General restrictions.

Domestic animals that are positive to an official Johne's disease test may not be moved interstate except in compliance with this part.

§ 80.3 Movement of domestic animals that are positive to an official Johne's disease test.

(a) **Movement of domestic animals for slaughter.** Domestic animals that are positive to an official Johne's disease test may be moved interstate for slaughter if:

(1) The animals are moved directly to a recognized slaughtering establishment or to an approved livestock facility for sale to a recognized slaughtering establishment;

(2) An owner-shipper statement that identifies the animals as positive to an official Johne's disease test accompanies the animals during the movement and is delivered to the consignee;

(3) Each animal bears an official eartag; and

(4) The animals are moved to the destination in one continuous movement without unloading.

(b) **Other movements.** The Administrator may, upon request in specific cases, allow domestic animals that are positive to an official Johne's

disease test to be moved interstate other than as provided in paragraph (a) of this section, under such conditions as the Administrator may prescribe in each case to prevent the spread of Johne's disease. The Administrator will promptly notify the State animal health officials of the States involved of any such action.

(c) **Cleaning and disinfecting.** Each means of conveyance used to transport the animals must be cleaned and disinfected in accordance with § 71.6 of this chapter. The facilities in which the animals were maintained must be cleaned and disinfected in accordance with § 71.7 of this chapter.

§ 80.4 Segregation of animals positive to an official Johne's disease test during interstate movement.

Animals that are positive to an official Johne's disease test may not be moved interstate in a railroad car, boat, truck, or other vehicle containing healthy animals susceptible to Johne's disease unless all of the animals are for immediate slaughter, or unless the positive animals are kept separate from the other animals by a partition that is securely affixed to the sides of the vehicle and prevents the transfer of fecal matter from the animals positive to an official Johne's disease test to the healthy animals in the vehicle.

Done in Washington, DC, this 5th day of April 2000.

Bobby R. Acord,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 00-8780 Filed 4-7-00; 8:45 am]

BILLING CODE 3410-34-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-84-AD; Amendment 39-11663; AD 2000-07-09]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, and 800 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Boeing Model 737-600, -700, and 800 series airplanes. This action requires a one-time inspection to detect loose nuts installed on the bolts

at each end of the input rods connected to each elevator power control unit (PCU), and corrective action, if necessary. This amendment is prompted by reports of loose nuts on the bolts that connect the lower input crank arm and the vernier adjustment input rod of the elevator PCU. The actions specified in this AD are intended to detect and correct loose nuts on the bolts of the input crank arms of the elevator PCU, which could result in the loss of pivot bolts on the PCU and consequent loss of control of the airplane during takeoff and landing.

DATES: Effective April 25, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 25, 2000.

Comments for inclusion in the Rules Docket must be received on or before June 9, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-84-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Kenneth W. Frey, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2673; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: The FAA received several reports indicating that operators found loose nuts on the bolts that connect the lower input crank arm and the vernier adjustment input rod of the elevator power control unit (PCU). Apparently, maintenance had not been accomplished on the PCU's since delivery of the airplanes from the manufacturer. One of the loose PCU input rod nuts was found on a production airplane during a line check. The loose nuts reported had been finger tightened, but had not been properly torqued on the bolts.

Loose nuts on the bolts of the input rod of the elevator PCU could result in the loss of pivot bolts on the crank arms of the elevator PCU's, and consequent

² A list of recognized slaughtering establishments in any State may be obtained from an APHIS representative, the State animal health official, or a State representative.

loss of control of the airplane during takeoff and landing.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Telegraphic Service Letter 737–SL–27–150, dated February 14, 2000, which describes procedures for a one-time visual inspection to determine if the nuts installed on the bolts at each end of the input rods connected to each elevator power control unit (PCU) are installed correctly, and tightening of any loose nut that is found.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other Boeing Model 737–600, –700, and –800 series airplanes of the same type design, this AD is being issued to prevent loss of control of the airplane during takeoff and landing due to loose nuts on the bolts of the input crank arms of the elevator PCU, and consequent loss of pivot bolts on the PCU. This AD requires a one-time general visual inspection to determine if the nuts installed on the bolts at each end of the input rods connected to each elevator PCU are installed correctly, and corrective action, if necessary. The actions are required to be accomplished in accordance with the telegraphic service letter described previously.

This AD also requires that operators report findings of loose nuts to the FAA.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and

suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000–NM–84–AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000–07–09 Boeing: Amendment 39–11663. Docket 2000–NM–84–AD.

Applicability: Model 737–600, –700, and –800 series airplanes, line numbers 1 through 477 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of control of the airplane during takeoff and landing due to loose nuts on the bolts of the input crank arms of the elevator power control unit (PCU), and consequent loss of pivot bolts, accomplish the following:

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(a) Within 30 days after the effective date of this AD, perform a one-time general visual inspection to determine if the nuts installed on the bolts at each end of the input rods connected to each elevator PCU are installed correctly, in accordance with Boeing Telegraphic Service Letter 737–SL–27–150, dated February 14, 2000.

(1) If all bolts are protruding through the nuts, no further action is required by this AD.

(2) If any bolt does not protrude through the nut, prior to further flight, tighten the nut in accordance with the telegraphic service letter.

(b) Within 10 days after accomplishing the inspection required by this AD; or within 10 days after the effective date of this AD if the inspection was accomplished prior to the

effective date of this AD: Submit a report of any findings of loose nuts to the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; fax (425) 227-1181. The report must include the operator's name, the date the inspection was accomplished, the airplane line number, and the number of loose nuts found on that airplane. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Boeing Telegraphic Service Letter 737-SL-27-150, dated February 14, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on April 25, 2000.

Issued in Renton, Washington, on March 30, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-8392 Filed 4-7-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-87-AD; Amendment 39-11664; AD 2000-07-10]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-200B, -300, -400, -400D, and -400F Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Boeing Model 747-200B, -300, -400, -400D, and -400F series airplanes. This action requires repetitive inspections to detect cracking of fire extinguisher discharge tubes in certain engine struts, and corrective action, if necessary. For certain airplanes, this action also provides for a modification of the fire extinguisher discharge tubes, which constitutes terminating action for the repetitive inspections. This amendment is prompted by reports that cracked fire extinguisher discharge tubes have been found in the engine struts on certain airplanes. The actions specified in this AD are intended to detect and correct cracked fire extinguishing tubes in the engine struts. In the event of an engine fire, such cracked tubes could reduce the amount of fire extinguishing agent that can be delivered to the engine, and could result in a fire spreading from the engine to the wing of the airplane.

DATES: Effective April 25, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 25, 2000.

Comments for inclusion in the Rules Docket must be received on or before June 9, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-87-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of

the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Sulmo Mariano, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2686; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: The FAA has recently received reports indicating that several operators have found cracked fire extinguisher discharge tubes in the number 2 and number 3 struts on several Boeing Model 747-400 series airplanes that are equipped with General Electric (GE) CF6-80C2 series engines. Further investigation revealed similarly cracked fire extinguisher discharge tubes on Boeing Model 747-400 series airplanes equipped with Pratt & Whitney PW4000 series engines, which incorporate a similar tube installation. The cause of the cracking has been attributed to installation preload and flexing of the tube due to motion between the wing and the strut.

The subject fire extinguisher discharge tubes extend from the fire extinguisher bottles to the number 2 and number 3 engine struts, and are intended to deliver fire extinguishing agent to the engine in the event of an engine fire. Similar designs exist in Boeing Model 747-200B and -300 series airplanes equipped with GE CF6-80C2 series engines. A cracked tube could reduce the amount of fire extinguishing agent that can be delivered to the engine. In the worst case (a broken tube), no fire-extinguishing agent would be delivered to the engine. This condition, if not corrected, could result in a fire spreading from the engine to the wing of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-26A2266, dated March 3, 2000. That alert service bulletin describes procedures for repetitive detailed visual inspections to detect cracking of fire extinguisher discharge tubes in the number 2 and number 3 engine struts. The alert service bulletin also describes procedures for replacement of any cracked tube with a new or serviceable tube.

The FAA also has reviewed and approved Boeing Service Bulletin 747-26-2233, dated May 11, 1995. That service bulletin applies to Model 747-400 series airplanes equipped with Pratt & Whitney PW4000 series engines and describes procedures for a modification