

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2020–04–17 Airbus SAS:** Amendment 39–19854; Docket No. FAA–2019–0865; Product Identifier 2019–NM–158–AD.

#### (a) Effective Date

This AD is effective May 4, 2020.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Reason

This AD was prompted by reports of passenger door girt bar fitting assembly safety hooks being stuck in the upward position. The FAA is issuing this AD to address this condition, which could lead to girt bar disengagement from the girt bar fitting assembly and consequent failure of the passenger door slide deployment during an emergency, possibly preventing safe evacuation of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0207, dated August 22, 2019 (“EASA AD 2019–0207”).

#### (h) Exceptions to EASA AD 2019–0207

(1) Where EASA AD 2019–0207 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019–0207 does not apply to this AD.

(3) Paragraph (4) of EASA AD 2019–0207 specifies to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(3)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 90 days after the conclusion of the maintenance visit or check where the inspection was completed.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 90 days after the effective date of this AD.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019–0207 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Paperwork Reduction Act Burden Statement:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

#### (j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218; email [kathleen.arrigotti@faa.gov](mailto:kathleen.arrigotti@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019–0207, dated August 22, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019–0207, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0865.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 25, 2020.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–06480 Filed 3–27–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2019–0719; Product Identifier 2019–NM–137–AD; Amendment 39–19876; AD 2020–05–26]

**RIN 2120–AA64**

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain

The Boeing Company Model 787–8 airplanes. This AD was prompted by a report of failure of a wing strut leak test due to a missing bolt on the firewall. This AD requires a one-time leak test of the strut upper spar areas for the left and right wing struts, and corrective action if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 4, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0719; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Tak Kobayashi, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3553; email: [takahisa.kobayashi@faa.gov](mailto:takahisa.kobayashi@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 787–8 airplanes. The NPRM published in the **Federal Register** on November 1, 2019 (84 FR 58636). The NPRM was prompted by a report of failure of a wing strut leak test due to a missing bolt on the firewall. The NPRM proposed to require a one-time leak test of the strut upper spar areas for the left and right wing struts, and corrective action if necessary.

The FAA is issuing this AD to address a hole in the firewall, which could

allow flammable fluid to leak from the strut compartment to the engine compartment when the drainage provision is overwhelmed. Flammable fluid leakage into the engine compartment could result in an uncontrollable engine fire and consequent structural failure of the wing.

#### Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA’s response to each comment.

#### Support for the NPRM

Two commenters, Patrick Imperatrice and Seth Stewart, indicated support for the NPRM.

#### Request To Change the Unsafe Condition

Boeing asked that the current language for the unsafe condition specified in the proposed AD, which states, in part, “. . . which could allow flammable fluid leakage in the strut area. This leakage could overwhelm the drainage provision, enter the engine compartment . . .” be changed to “. . . which could allow flammable fluid to leak from the strut compartment to the engine core compartment . . .” Boeing stated that the hole in the firewall due to a missing bolt does not affect the drain provision from the strut system tubing shroud. Boeing added that a missing bolt does create an unintended drain path from the strut flammable fluid compartment to the engine core compartment fire zone.

The FAA agrees with the commenter’s request for the reason provided. The FAA has revised the Discussion section and paragraph (e) of this AD to include the suggested language.

#### Request To Clarify Certain Language

Boeing asked that the language specified in paragraph (g)(2) of the proposed AD, be changed from “strut upper spar (strut areas . . .)” to “systems tubing shroud (area . . .).” Boeing stated that the water must be applied in the systems tubing shroud, not to the strut upper spar. Boeing added that the strut upper spar between the forward and mid-vapor barriers is a dry bay, but the systems tubing shroud is a flammable leakage zone.

The FAA agrees with the commenter’s request to clarify the language to be consistent with Boeing’s terminology. This procedure is also provided in the Boeing 787 Aircraft Maintenance Manual (AMM), specified as additional

guidance in this AD. The FAA has revised paragraph (g)(2) of this AD as suggested by the commenter.

#### Request To Remove Leak Test Requirement

Boeing asked that the FAA remove the leak test required by paragraph (g) of the proposed AD and either require or include an option for a visual inspection for proper installation of the bolt on the firewall, as specified in planned Boeing Service Bulletin 787–54A0021–I001. Boeing stated that paragraph (e) of the proposed AD specified that the unsafe condition was caused by a missing bolt that plugs a penetration on the strut firewall. Boeing added that a visual inspection done using the planned Boeing service information will verify the proper installation of the bolt, and ensure firewall integrity, in addition to less maintenance time than a leak test, resulting in lower costs for the airlines. Boeing also stated that the service bulletin is scheduled for release in June 2020, and will include instructions to inspect for a missing bolt, as well as corrective action to correctly install a missing bolt and perform a leak test to ensure proper drainage.

The FAA acknowledges the commenter’s request, but does not agree to revise this AD. The leak test required by this AD provides a practical means to address the unsafe condition, and this method is adequate since the service information is not yet approved or available. The FAA may not require any document that does not yet exist in an AD. In general terms, the FAA is required by Office of the Federal Register (OFR) regulations for approval of materials incorporated by reference, as specified in 1 CFR 51.1(f), to either publish the service document contents as part of the actual AD language; or submit the service document to the OFR for approval as referenced material, in which case the FAA may only refer to such material in the text of an AD. Since no service information for the visual inspection has been provided to the FAA, the agency is unable to evaluate or approve an inspection method. The FAA finds that delaying this action is inappropriate in light of the identified unsafe condition. If service information for this inspection becomes available later, it may be submitted to the FAA for approval of an alternative method of compliance under the provisions of paragraph (h) of this AD. The FAA has not changed this AD in this regard.

#### Request To Clarify a Procedure

Boeing asked that the FAA add the language “remove the tubing shroud cover” to the end of paragraph (g)(1) of

the proposed AD to clarify the procedure. Boeing stated that if the tubing shroud cover is not removed, water cannot be poured into the systems tubing and side shroud areas.

The FAA partially agrees with the commenter's request. The FAA determined that only the steps necessary for properly accomplishing the leak test—not the general steps necessary to prepare for the test—are included in the AD requirements. For additional guidance, Note 1 to paragraph (g) of this AD provides information related to the procedures in the applicable section of the Boeing 787 AMM. That section includes all relevant general steps for accomplishing the required leak test. Therefore, the FAA has not changed this AD in this regard.

#### Request for Correction of a Paragraph Identifier

Boeing stated that there are two paragraph identifiers that are identical. Boeing noted that paragraph identifier (g)(5)(ii) of the proposed AD is repeated, and the second paragraph identifier should be (g)(5)(iii).

The FAA agrees with the commenter and has corrected the paragraph identifier accordingly.

#### Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes.

The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

#### Costs of Compliance

The FAA estimates that this AD affects 2 airplanes of U.S. registry. The agency estimates the following costs to comply with this AD:

#### ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
3 work-hours × \$85 per hour = \$255 .....	\$0	\$255	\$510

The FAA estimates the following costs to do any necessary on-condition action that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need this on-condition action:

#### ESTIMATED COSTS OF ON-CONDITION ACTION

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85 .....	Minimal .....	\$85

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2020–05–26 The Boeing Company:

Amendment 39–19876; Docket No. FAA–2019–0719; Product Identifier 2019–NM–137–AD.

#### (a) Effective Date

This AD is effective May 4, 2020.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to The Boeing Company Model 787–8 airplanes, certificated in any category, line numbers 6, 11, 17, 19, 20, 21, 23, 25 through 30 inclusive, and 32 through 38 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 54, Nacelles/Pylons.

**(e) Unsafe Condition**

This AD was prompted by a report of failure of a wing strut leak test due to a missing bolt on the firewall. The FAA is issuing this AD to address a hole in the firewall, which could allow flammable fluid to leak from the strut compartment to the engine compartment when the drainage provision is overwhelmed. Flammable fluid leakage into the engine compartment could result in an uncontrollable engine fire and consequent structural failure of the wing.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Leak Test and Corrective Action**

Within 12 months after the effective date of this AD: Do a one-time leak (functional) test of the strut upper spar areas for the left and right wing struts, by doing the actions specified in paragraphs (g)(1) through (5) of this AD. A review of airplane maintenance records is acceptable in lieu of this test if it can be conclusively determined from that review that the leak test was previously accomplished and successfully completed.

(1) Put a plug in the strut forward drain outlet (this drain outlet is labeled as "pylon strut"). Put an empty container below the strut forward drain outlet to collect water drained through this outlet.

(2) Apply 381 to 387 fluid ounces (11.3 to 11.4 liters) of water in 2.5 to 3.5 minutes, to the systems tubing shroud (area between the forward and mid-vapor barriers).

(3) Make sure that no leakage occurred after doing the action specified in paragraph (g)(2) of this AD.

(4) Remove the plug from the strut forward drain outlet and make sure that the water is drained through the strut forward drain outlet only.

(5) After 3 minutes from accomplishing the action specified in paragraph (g)(4) of this AD, measure the water collected in the container, and do the applicable actions specified in paragraphs (g)(5)(i) through (iii) of this AD.

(i) If leaks were found, do corrective action before further flight using a method approved in accordance with the procedures specified in paragraph (h) of this AD.

(ii) If no leaks were found and less than 354 fluid ounces (10.5 liters) of water is collected in the container, do corrective action before further flight using a method approved in accordance with the procedures specified in paragraph (h) of this AD.

(iii) Before further flight after accomplishing any corrective action required by paragraph (g)(5)(i) or (ii) of this AD, repeat the actions specified in paragraphs (g)(1)

through (5) of this AD until successful completion of the test (*i.e.*, no leaks are found and 354 fluid ounces (10.5 liters) of water or more is measured in the container).

Note 1 to paragraph (g): Additional guidance for performing the leak (functional) test can be found in Boeing 787 Aircraft Maintenance Manual (AMM), 54-65-01, Strut Spar—Upper—Functional Test.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(i) Related Information**

(1) For more information about this AD, contact Tak Kobayashi, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3553; email: [takahisa.kobayashi@faa.gov](mailto:takahisa.kobayashi@faa.gov).

(2) For service information identified in this AD that is not incorporated by reference, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. For information on the availability of this material at the FAA, call 206-231-3195.

**(j) Material Incorporated by Reference**

None.

Issued on March 10, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-06459 Filed 3-27-20; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2019-0438; Product Identifier 2019-NM-033-AD; Amendment 39-19875; AD 2020-05-25]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all The Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes. This AD was prompted by a report that during a maintenance check an operator discovered cracking of the aft cargo compartment frames in the station 1460 frame web and inner chord between certain stringers. This AD requires an inspection of the fuselage frames for any existing repair, repetitive surface high frequency eddy current (HFEC) inspections of the fuselage frames with a cargo liner support channel for any cracking, and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 4, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 4, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0438.