

Rules and Regulations

Federal Register

Vol. 67, No. 151

Tuesday, August 6, 2002

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Animal and Plant Health Inspection Service

9 CFR Part 77

[Docket No. 02-021-2]

Tuberculosis in Cattle and Bison; State and Zone Designations; Texas

AGENCY: Animal and Plant Health Inspection Service, USDA.

ACTION: Notice of reopening and extension of comment period.

SUMMARY: We are reopening and extending the comment period for an interim rule that amended the bovine tuberculosis regulations regarding State and zone classifications by removing the split-State status of Texas and classifying the entire State as modified accredited advanced. The interim rule also solicited comments on the current regulatory provisions of the domestic bovine tuberculosis eradication program. This action will allow interested persons additional time to prepare and submit comments.

DATES: We will consider all comments that we receive on or before September 5, 2002.

ADDRESSES: You may submit comments by postal mail/commercial delivery or by e-mail. If you use postal mail/commercial delivery, please send four copies of your comment (an original and three copies) to: Docket No. 02-021-1, Regulatory Analysis and Development, PPD, APHIS, Station 3C71, 4700 River Road Unit 118, Riverdale, MD 20737-1238. Please state that your comment refers to Docket No. 02-021-1. If you use e-mail, address your comment to regulations@aphis.usda.gov. Your comment must be contained in the body of your message; do not send attached files. Please include your name and address in your message and "Docket No. 02-021-1" on the subject line.

You may read any comments that we receive on Docket No. 02-021-1 in our reading room. The reading room is located in room 1141 of the USDA South Building, 14th Street and Independence Avenue SW., Washington, DC. Normal reading room hours are 8 a.m. to 4:30 p.m., Monday through Friday, except holidays. To be sure someone is there to help you, please call (202) 690-2817 before coming.

APHIS documents published in the **Federal Register**, and related information, including the names of organizations and individuals who have commented on APHIS dockets, are available on the Internet at <http://www.aphis.usda.gov/ppd/rad/webrepor.html>.

FOR FURTHER INFORMATION CONTACT: Dr. Joseph Van Tiem, Senior Staff Veterinarian, National Animal Health Programs, VS, APHIS, 4700 River Road Unit 43, Riverdale, MD 20737-1231; (301) 734-7716.

SUPPLEMENTARY INFORMATION:

Background

On June 6, 2002, we published an interim rule in the **Federal Register** (67 FR 38841-38844, Docket No. 02-021-1). In that document, we amended the bovine tuberculosis regulations regarding State and zone classifications by removing the split-State status of Texas and classifying the entire State as modified accredited advanced. In addition to requesting comments on the change in the tuberculosis classification status of Texas, we requested comments on the current regulatory provisions of the domestic bovine tuberculosis eradication program.

Comments were required to be received or postmarked by August 5, 2002. Based on requests received during the comment period, we are reopening and extending the comment period for Docket 02-021-1 until September 5, 2002. This action will allow interested persons additional time to prepare and submit comments.

Authority: 7 U.S.C. 8301-8317; 7 CFR 2.22, 2.80, and 371.4.

Done in Washington, DC, this 31st day of July, 2002.

Peter Fernandez,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 02-19769 Filed 8-5-02; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-25-AD; Amendment 39-12837; AD 2002-15-07]

RIN 2120-AA64

Airworthiness Directives; MD Helicopters, Inc., Model MD900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for MD Helicopters, Inc., Model MD900 helicopters that requires, for the lateral-mixer bellcrank assembly (bellcrank), establishing a life limit, creating a component history card or equivalent record, determining the hours time-in-service (TIS), and applying a serial number (S/N). This amendment is prompted by additional testing that revealed that the original load test to establish the life limits of the bellcrank did not accurately represent the actual loading. The actions specified by this AD are intended to prevent fatigue failure of the bellcrank and subsequent loss of lateral control of the helicopter.

DATES: Effective September 10, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 10, 2002.

ADDRESSES: The service information referenced in this AD may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the Web at www.mdhelicopters.com. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or

at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Jon Mowery, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5322, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for MD Helicopters, Inc. Model MD900 helicopters was published in the **Federal Register** on January 16, 2002 (67 FR 2145). That action proposed to require, before further flight, the following for the bellcrank on an affected helicopter:

- Create a component history card or equivalent record.
- Determine the hours TIS of the bellcrank.
- Apply a S/N.
- Remove any affected bellcrank that exceeds the life limit.

This AD would revise the Limitations section of the maintenance manual by establishing a life limit of 13,300 hours TIS for the bellcrank, P/N 900C2010203-105.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 30 helicopters of U.S. registry will be affected by this AD, that it will take approximately ½ work hour per helicopter to accomplish the required actions for the bellcrank, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$10,120 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$304,500, assuming replacement of the bellcranks in all 30 helicopters.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2002-15-07 MD Helicopters, Inc.:

Amendment 39-12837. Docket No. 2001-SW-25-AD.

Applicability: Model MD900 helicopters, serial number (S/N) 900-00008, 900-00010 through 900-00098, and 900-00100, with a lateral-mixer bellcrank assembly (bellcrank), part number (P/N) 900C2010203-105, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Before further flight, unless accomplished previously.

To prevent fatigue failure of the bellcrank and subsequent loss of lateral control of the helicopter, accomplish the following:

(a) Create a component history card or equivalent record for each bellcrank and record the hours time-in-service (TIS) of the

bellcrank. If the hours TIS of the bellcrank cannot be determined, use the helicopter's total hours TIS as the hours TIS for the bellcrank.

(b) Apply a S/N to the bellcrank in accordance with the Accomplishment Instructions, paragraph (1)(a) and (1)(b), of MD Helicopters, Inc. Service Bulletin SB 900-084, dated December 3, 2001.

(c) Remove any bellcrank that has exceeded 13,300 hours TIS.

(d) This AD revises the Limitations section of the maintenance manual by establishing a life limit of 13,300 hours TIS for bellcrank, P/N 900C2010203-105.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (LAACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, LAACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the LAACO.

(f) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(g) The marking of the S/N shall be done in accordance with the Accomplishment Instructions, paragraphs (1)(a) and (1)(b), of MD Helicopters, Inc. Service Bulletin SB 900-084, dated December 3, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the Web at www.mdhelicopters.com.

Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on September 10, 2002.

Issued in Fort Worth, Texas, on July 24, 2002.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02-19487 Filed 8-5-02; 8:45 am]

BILLING CODE 4910-13-P