

*code_of_federal_regulations/
ibr_locations.html.*

Issued in Renton, Washington, on
December 26, 2006.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7-1204 Filed 1-29-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26217; Directorate
Identifier 2006-NM-209-AD; Amendment
39-14886; AD 2007-01-14]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-400 Series Airplanes

AGENCY: Federal Aviation
Administration (FAA), Department of
Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new
airworthiness directive (AD) for certain
Bombardier Model DHC-8-400 series
airplanes. This AD requires revising the
Airworthiness Limitations Items (ALI)
of the maintenance requirements
manual to require additional inspection
requirements of the maintenance
requirements manual for certain
principal structural elements (PSEs)
related to fuselage cutouts and to reduce
an inspection threshold for an existing
ALI task on the aft entry door. This AD
results from data obtained from the
manufacturer's fatigue testing. We are
issuing this AD to detect and correct
fatigue cracking of certain PSEs, which
could result in reduced structural
integrity of the airplane.

DATES: This AD becomes effective
March 6, 2007.

The Director of the Federal Register
approved the incorporation by reference
of certain publications listed in the AD
as of March 6, 2007.

ADDRESSES: You may examine the AD
docket on the Internet at [http://
dms.dot.gov](http://dms.dot.gov) or in person at the Docket
Management Facility, U.S. Department of
Transportation, 400 Seventh Street,
SW., Nassif Building, Room PL-401,
Washington, DC.

Contact Bombardier, Inc., Bombardier
Regional Aircraft Division, 123 Garratt
Boulevard, Downsview, Ontario M3K
1Y5, Canada, for service information
identified in this AD.

FOR FURTHER INFORMATION CONTACT:
George Duckett, Aerospace Engineer,

Airframe and Propulsion Branch, ANE-
171, FAA, New York Aircraft
Certification Office, 1600 Stewart
Avenue, suite 410, Westbury, New York
11590; telephone (516) 256-7525; fax
(516) 794-5531.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness
directive (AD) docket on the Internet at
<http://dms.dot.gov> or in person at the
Docket Management Facility office
between 9 a.m. and 5 p.m., Monday
through Friday, except Federal holidays.
The Docket Management Facility office
(telephone (800) 647-5227) is located on
the plaza level of the Nassif Building at
the street address stated in the
ADDRESSES section.

Discussion

The FAA issued a notice of proposed
rulemaking (NPRM) to amend 14 CFR
part 39 to include an AD that would
apply to certain Bombardier Model
DHC-8-400 series airplanes. That
NPRM was published in the **Federal
Register** on November 2, 2006 (71 FR
64482). That NPRM proposed to require
revising the Airworthiness Limitations
Items (ALI) of the maintenance
requirements manual to require
additional inspection requirements of
the maintenance requirements manual
for certain principal structural elements
(PSEs) related to fuselage cutouts and to
reduce an inspection threshold for an
existing ALI task on the aft entry door.

Comments

We provided the public the
opportunity to participate in the
development of this AD. We received no
comments on the NPRM or on the
determination of the cost to the public.

Conclusion

We have carefully reviewed the
available data and determined that air
safety and the public interest require
adopting the AD as proposed.

Costs of Compliance

This AD affects about 21 airplanes of
U.S. registry. The required actions take
about 1 work hour per airplane, at an
average labor rate of \$80 per work hour.
Based on these figures, the estimated
cost of this AD for U.S. operators is
\$1,680, or \$80 per airplane.

Authority for this Rulemaking

Title 49 of the United States Code
specifies the FAA's authority to issue
rules on aviation safety. Subtitle I,
Section 106, describes the authority of
the FAA Administrator. Subtitle VII,
Aviation Programs, describes in more

detail the scope of the Agency's
authority.

We are issuing this rulemaking under
the authority described in Subtitle VII,
Part A, Subpart III, Section 44701,
"General requirements." Under that
section, Congress charges the FAA with
promoting safe flight of civil aircraft in
air commerce by prescribing regulations
for practices, methods, and procedures
the Administrator finds necessary for
safety in air commerce. This regulation
is within the scope of that authority
because it addresses an unsafe condition
that is likely to exist or develop on
products identified in this rulemaking
action.

Regulatory Findings

We have determined that this AD will
not have federalism implications under
Executive Order 13132. This AD will
not have a substantial direct effect on
the States, on the relationship between
the national government and the States,
or on the distribution of power and
responsibilities among the various
levels of government.

For the reasons discussed above, I
certify that this AD:

- (1) Is not a "significant regulatory
action" under Executive Order 12866;
- (2) Is not a "significant rule" under
DOT Regulatory Policies and Procedures
(44 FR 11034, February 26, 1979); and
- (3) Will not have a significant
economic impact, positive or negative,
on a substantial number of small entities
under the criteria of the Regulatory
Flexibility Act.

We prepared a regulatory evaluation
of the estimated costs to comply with
this AD and placed it in the AD docket.
See the **ADDRESSES** section for a location
to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation
safety, Incorporation by reference,
Safety.

Adoption of the Amendment

■ Accordingly, under the authority
delegated to me by the Administrator,
the FAA amends 14 CFR part 39 as
follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39
continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation
Administration (FAA) amends § 39.13
by adding the following new
airworthiness directive (AD):

2007-01-14 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-14886. FAA-2006-26217; Directorate Identifier 2006-NM-209-AD.

Effective Date

(a) This AD becomes effective March 6, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier Model DHC-8-400 series airplanes, serial numbers 4001, 4003, 4004, 4006, and 4008 through 4126 inclusive, certificated in any category.

Unsafe Condition

(d) This AD results from data obtained from the manufacturer's fatigue testing. We are issuing this AD to detect and correct fatigue cracking of certain principal structural elements, which could result in reduced structural integrity of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (g) of this AD. The request should include a description of changes to the required inspections that will ensure the continued damage tolerance of the affected structure. The FAA has provided guidance for this determination in Advisory Circular (AC) 25-1529-1.

Maintenance Requirements Manual Revision

(f) Within 60 days after the effective date of this AD, revise the Airworthiness Limitations Items (ALI), Part 2, Section 2, of the Bombardier Q400 Dash 8 Maintenance Requirements Manual, PSM 1-84-7, by incorporating the information in Bombardier Q400 Dash 8 Temporary Revisions (TR) ALI-53, dated February 16, 2006; and ALI-54, dated March 27, 2006. Thereafter, except as provided in paragraph (g) of this AD, no alternative structural inspection intervals may be approved for the fuselage and doors as specified in the TRs.

Note 2: The actions required by paragraph (f) of this AD may be done by inserting copies of TR ALI-53, dated February 16, 2006, and TR ALI-54, dated March 27, 2006; into the ALI, Part 2, Section 2, of the Bombardier Q400 Dash 8 Maintenance Requirements Manual, PSM 1-84-7. When TRs ALI-53 and ALI-54 have been included in the general revisions of the maintenance requirements manual, the general revisions may be inserted into the maintenance requirements

manual, provided the relevant information in the general revision is identical to that in TRs ALI-53 and ALI-54.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(h) Canadian airworthiness directive CF-2006-10, dated May 12, 2006, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Bombardier Q400 Dash 8 Temporary Revision ALI-53, dated February 16, 2006, to the Airworthiness Limitations Items, Part 2, Section 2, of the Bombardier Q400 Dash 8 Maintenance Requirements Manual, PSM 1-84-7; and Bombardier Q400 Dash 8 Temporary Revision ALI-54, dated March 27, 2006, to the Airworthiness Limitations Items, Part 2, Section 2, of the Bombardier Q400 Dash 8 Maintenance Requirements Manual, PSM 1-84-7; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 26, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-1209 Filed 1-29-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25079; Directorate Identifier 2006-NM-065-AD; Amendment 39-14885; AD 2007-01-13]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310-300 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A310-300 airplanes. This AD requires replacing the existing non-return valve (NRV) of the auxiliary center tanks (ACTs) of the fuel system with a new, improved NRV. This AD results from a report that it was not possible to transfer fuel from ACTs 1 and 2 during flight, and no electronic centralized aircraft monitor warnings were triggered. Investigation revealed a faulty static inverter and blown fuse, resulting in failure of certain fueling bus bars and subsequent failure of the automatic ACT fuel transfer. We are issuing this AD to prevent these failures, combined with failure of the NRV to close. If the NRV is open during flight, the fuel supply to the engines may be reduced during cross-feed operation to the extent that fuel starvation could occur and result in engine flameout.

DATES: This AD becomes effective March 6, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 6, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: