Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections

(f) Perform detailed inspections to detect scribe lines and cracks of the fuselage skin, lap joints, circumferential butt splice strap, and external and internal approved repairs; and perform related investigative and corrective actions. Do the actions in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, except as required by paragraph (g) of this AD. Do the actions within the applicable compliance times specified in paragraph 1.E. of the service bulletin, except as required by paragraph (h) of this AD.

Exceptions to Service Bulletin Specifications

(g) Where Boeing Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, specifies to contact Boeing for appropriate repair instructions, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Boeing Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, specifies compliance times relative to the date of issuance of the service bulletin; however, this AD requires compliance before the specified compliance time relative to the effective date of the AD.

Credit for Prior Accomplishment

(i) Inspections done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 757–53A0092, dated September 18, 2006, are acceptable for compliance with the corresponding requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

Material Incorporated by Reference

(k) You must use Boeing Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, to perform the actions that are required

by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030. or go to http://www.archives.gov/federalregister/cfr/ibr-locations.html.

Issued in Renton, Washington, on October 15, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–20816 Filed 10–23–07; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket FAA No. FAA-2007-27911; Airspace Docket No. 07-ANM-8]

Establishment of Class E Airspace; Hailey, ID

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule; correction.

SUMMARY: This action corrects a final rule published in the Federal Register August 30, 2007 (72 FR 50046), Airspace Docket No. 07–ANM–8, FAA Docket No. FAA–2007–27911. In that rule, an error was made in the legal description for Hailey, ID. Specifically, the longitude referencing Friedman Memorial Airport, ID stated "* * *long.114°17′45" W." instead of "* * *long.114°17′44" W." This action corrects that error.

DATES: Effective Date: 0901 UTC, December 20, 2007. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Eldon Taylor, Federal Aviation Administration, System Support Group, Western Service Area, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 917–6726.

SUPPLEMENTARY INFORMATION:

History

On August 30, 2007, a final rule for Airspace Docket No. 07–ANM–8, FAA

Docket No. FAA–2007–27911 was published in the **Federal Register** (72 FR 50046), establishing Class E airspace in Hailey, ID. The longitude referencing Friedman Memorial Airport, ID was incorrect in that the longitude stated "* * *114°17′45" W." instead of "* * *long.114°17′44" W." This action corrects that error.

Correction to Final Rule

■ Accordingly, pursuant to the authority delegated to me, the legal description as published in the **Federal Register** on August 30, 2007 (72 FR 50046), Airspace Docket No. 07–ANM–8, FAA Docket No. FAA–2007–27911, and incorporated by reference in 14 CFR 71.1, is corrected as follows:

§71.1 [Amended]

■ On page 50047, correct the legal description for Hailey, ID, to read as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

Friedman Memorial Airport, ID (lat. 43°30′14″ N., long. 114°17′44″ W.)

ANM ID, E5 Hailey, ID [Corrected]

That airspace extending upward from 700 feet above the surface within a 5.5-mile radius of Friedman Memorial Airport, and within 2 miles west and 5.5 miles east of the 328° bearing from the airport extending from the 5.5-mile radius to 10 miles northwest of the airport, and within 2 miles west and 4 miles east of the 159° bearing from the airport extending from the 5.5-mile radius to 15.5 miles southeast of the airport; that airspace extending upward from 1,200 feet above the surface bounded by a line beginning at lat. 44°00′00″ N., long. 114°55′00″ W., thence to lat. 44°00'00" N., long. 113°53'00" W., thence to lat. 43°00′00" N., long. 113°49′00" W., thence to lat. 43°00'00" N., long. 114°55'00" W., thence to point of beginning.

Issued in Seattle, Washington, on October 5, 2007.

Clark Desing,

Manager, System Support Group, Western Service Center.

[FR Doc. E7–20796 Filed 10–23–07; 8:45 am]