

regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-08-03 Pacific Aerospace Limited:
Amendment 39-15455; Docket No. FAA-2008-0175; Directorate Identifier 2007-CE-105-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective May 19, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Pacific Aerospace Limited Model 750XL airplanes, serial numbers 101 through 107, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 31: Instruments.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

To prevent electrical malfunction from causing damage to the wiring that may result in arcing or fire, accomplish Pacific Aerospace Service Bulletin PACSB/XL/008.

The MCAI requires the addition and replacement of certain pitot heat sensor circuit breakers and the addition of a cooling fan circuit.

Actions and Compliance

(f) Unless already done, within 100 hours time-in-service May 19, 2008 (the effective date of this AD), do the following actions following Pacific Aerospace Corporation Limited Mandatory Service Bulletin PACSB/XL/008, dated July 8, 2004:

(1) For airplanes only authorized to operate under visual flight rules (VFR) flight:

(i) Add a ten-amp circuit breaker supplying the pitot heat system to the left hand switch panel;

(ii) Replace the switching circuit breaker used as the pitot heat selector with a switch; and

(iii) Add a three-amp fuse at the power bus at the supply to the avionics cooling fan connection.

(2) For airplanes with serial numbers 101 through 107 that have been modified to operate under instrument flight rules (IFR) flight, contact Pacific Aerospace Corporation Limited at Pacific Aerospace Limited, Private Bag HN3027, Hamilton, New Zealand, telephone: +(64) 7-843-6144, fax: +(64) 7-843-6134, e-mail: pacific@aerospace.co.nz, for FAA-approved procedures to comply with this AD, and follow the procedures prior to further flight.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Civil Aviation Authority of New Zealand AD DCA/750XL/2, dated September 30, 2004; and Pacific Aerospace Corporation Limited Mandatory Service Bulletin PACSB/XL/008, dated July 8, 2004, for related information.

Material Incorporated by Reference

(h) You must use Pacific Aerospace Corporation Limited Mandatory Service Bulletin PACSB/XL/008, dated July 8, 2004; Pacific Aerospace Corporation Ltd 750XL Maintenance Manual Drawing 11-81101,

Assembly, Switch Panel—LH, dated October 15, 2003; and Pacific Aerospace Corporation Ltd 750XL Maintenance Manual Drawing 11-81519, Schematics Miscellaneous Circuits, dated October 10, 2003, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Pacific Aerospace Corporation Limited at Pacific Aerospace Limited, Private Bag HN3027, Hamilton, New Zealand, telephone: +(64) 7-843-6144, fax: +(64) 7-843-6134, e-mail: pacific@aerospace.co.nz.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 31, 2008.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7167 Filed 4-11-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0227; Directorate Identifier 2007-NM-159-AD; Amendment 39-15454; AD 2008-08-02]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 727 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Boeing Model 727 airplanes. This AD requires repetitive inspections for cracking or corrosion of the threaded end of the lower segment of the main landing gear (MLG) side strut, and corrective actions if necessary. This AD also requires prior or concurrent inspection for cracking or corrosion of the threads and thread relief area of the lower segment, corrective action if necessary, and re-assembly using corrosion inhibiting compound. This AD results from reports of the threads cracking on the MLG side strut lower segment. We are issuing this AD to

prevent a fractured side strut, which could result in collapse of the MLG.

DATES: This AD is effective May 19, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of May 19, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Berhane Alazar, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6577; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to all Boeing Model 727 airplanes. That NPRM was published in the **Federal Register** on November 26, 2007 (72 FR 65913). That NPRM proposed to require repetitive inspections for cracking or corrosion of the threaded end of the lower segment of the main landing gear (MLG) side strut, and corrective actions if necessary. That NPRM also proposed to require prior or concurrent inspection

for cracking or corrosion of the threads and thread relief area of the lower segment, corrective action if necessary, and re-assembly using corrosion inhibiting compound.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the single comment received. Boeing supports the NPRM.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are about 842 airplanes of the affected design in the worldwide fleet. This AD affects about 459 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this AD. The average labor rate is \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Cost per airplane	Fleet cost
Inspection	12	\$80	\$960, per inspection cycle	\$440,640, per inspection cycle.
Prior/concurrent actions	Up to 6	80	Up to \$480	Up to \$220,320.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national

government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2008-08-02 Boeing: Amendment 39-15454. Docket No. FAA-2007-0227; Directorate Identifier 2007-NM-159-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Model 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from reports of the threads cracking on the main landing gear (MLG) side strut lower segment. We are issuing this AD to prevent a fractured side strut, which could result in collapse of the MLG.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections and Corrective Actions

(f) At the latest applicable time in paragraph (f)(1), (f)(2), or (f)(3) of this AD: Do detailed and magnetic particle inspections for cracking or corrosion of the threaded end of the lower segment of the MLG side strut and do all applicable corrective actions as specified in the Accomplishment Instructions of Boeing Special Attention

Service Bulletin 727–32–0338, Revision 4, dated April 7, 2007. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 120 months.

(1) Within 48 months after the last MLG overhaul.

(2) Within 6 months after the effective date of this AD.

(3) Within 120 months after the last MLG overhaul for airplanes on which the actions in Boeing Special Attention Service Bulletin 727–32–0338, Revision 4, dated April 7, 2007, have been accomplished before the effective date of this AD.

Prior/Concurrent Requirements

(g) Prior to or concurrently with the actions required by paragraph (f) of this AD: Do all applicable actions specified in the service bulletins listed in Table 1 of this AD. Where the lubrication and corrosion protection procedures in any service bulletin listed in Table 1 of this AD differ from those in Boeing Special Attention Service Bulletin 727–32–0338, Revision 4, dated April 7, 2007, use the procedures in Boeing Special Attention Service Bulletin 727–32–0338, Revision 4.

TABLE 1.—PRIOR/CONCURRENT REQUIREMENTS

For—	Service Bulletin—	Describes procedures for these prior or concurrent actions—
(1) All airplanes	Boeing Special Attention 727–32–0411, Revision 1, dated February 19, 2007.	Inspecting for corrosion or cracking of the threads and thread relief area of the swivel clevis, and improving the corrosion protection of the swivel clevis fitting threads in commonly affected airplanes.
(2) Airplanes specified as Options III, IV and V configurations in Boeing Special Attention Service Bulletin 727–32–0338, Revision 4.	Boeing 727 Service Bulletin 32–79, Revision 1, dated February 27, 1967.	Modifying the MLG side strut universal joint.
	Boeing 727 Service Bulletin 32–157, dated August 30, 1968.	Replacing the MLG side strut swivel bushing, incorporating only parts kit 65–89855–1, and not installing the lube fitting in the lower segment.
(3) Airplanes specified as Option V configuration in Boeing Special Attention Service Bulletin 727–32–0338, Revision 4.	Boeing Service Bulletin 727–32–268, Revision 2, dated February 20, 1981.	Inspecting and modifying the MLG side strut.
	Boeing Service Bulletin 727–57–163, dated September 17, 1982.	Resolving the interference between the MLG gear beam and the MLG side strut.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair

required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(i) You must use the applicable service information listed in Table 2 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of

this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

(3) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Service Bulletin	Revision	Date
Boeing Special Attention Service Bulletin 727–32–0338	4	April 7, 2007.
Boeing Special Attention Service Bulletin 727–32–0411	1	February 19, 2007.
Boeing 727 Service Bulletin 32–157	Original	August 30, 1968.
Boeing 727 Service Bulletin 32–79	1	February 27, 1967.
Boeing Service Bulletin 727–32–268	2	February 20, 1981.
Boeing Service Bulletin 727–57–163	Original	September 17, 1982.

Issued in Renton, Washington, on March 28, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8-7176 Filed 4-11-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25173; Directorate Identifier 2006-NE-24-AD; Amendment 39-15453; AD 2008-08-01]

RIN 2120-AA64

Airworthiness Directives; McCauley Propeller Systems Propeller Models B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding three existing airworthiness directives (ADs) for McCauley Propeller Systems propeller models B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0. Those ADs currently require fluorescent penetrant inspections (FPI) and eddy current inspections (ECI) of propeller blades for cracks, and if any crack indications are found, removing the blade from service. This AD requires the same initial inspections, but extends the compliance times and intervals, adds repetitive inspections, and mandates a life limit for the blades. This AD results from our determination that we must require repetitive inspections for cracks, and from reports of blunt leading edges of the propeller blades due to erosion. We are issuing this AD to detect cracks in the propeller blade that could cause failure and separation of the propeller blade and loss of control of the airplane, and to detect blunt leading edges on the propeller blades, which could cause airplane single engine climb performance degradation and could result in an increased risk of collision with terrain.

DATES: This AD becomes effective May 19, 2008. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of May 19, 2008.

ADDRESSES: You can get the service information identified in this AD from

McCauley Propeller Systems, P.O. Box 7704, Wichita, KS 67277-7704, telephone (800) 621-7767.

The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

FOR FURTHER INFORMATION CONTACT: Jeff Janusz, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, Small Airplane Directorate, 1801 Airport Road, Room 100, Wichita, KS 67209; e-mail: jeff.janusz@faa.gov; telephone: (316) 946-4148; fax: (316) 946-4107.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 by superseding AD 2003-15-01, Amendment 39-13243 (68 FR 42244, July 17, 2003); AD 2003-17-10, Amendment 39-13285 (68 FR 50462, August 21, 2003); and AD 2006-15-13, Amendment 39-14693 (71 FR 42258, July 26, 2006), with a proposed AD. The proposed AD applies to McCauley Propeller Systems propeller models B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0. We published the proposed AD in the **Federal Register** on November 1, 2007 (72 FR 61824). That action proposed to require the same initial inspections as the three ADs being superseded, but to extend the compliance times and intervals, to add repetitive inspections, and to mandate a life limit for the blades.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the one comment received. The commenter supports the proposal. We also found we needed to clarify that blades that had crack indications were no longer eligible for installation on any other airframe or in any other configuration. We clarified the AD on the point.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD will affect 22 propeller assemblies installed on airplanes of U.S. registry. We estimate that it will take about 47 work-hours per propeller to perform the required actions, and that the average labor rate is \$80 per work-hour. Required parts will cost about \$260 per propeller. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$88,440.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in