

Rules and Regulations

Federal Register

Vol. 66, No. 164

Thursday, August 23, 2001

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Office of the Secretary

7 CFR Part 20

RIN 0551-AA51

Export Sales Reporting Requirements

AGENCY: Office of the Secretary, USDA.

ACTION: Delay of the effective date.

SUMMARY: On July 25, 2001, USDA published a final rule in the **Federal Register** (66 FR 38526-38528) amending the Export Sales Reporting Requirements Regulation (7 CFR part 20) to add fresh, chilled, or frozen muscle cuts of beef to such regulation, effective August 24, 2001. At that time, USDA believed the current reporting system used for all other agricultural commodities covered by the regulation would require only minor modifications to accommodate beef reporting. The desired changes, however, are more extensive than originally anticipated, and USDA is not fully prepared to begin accepting and reporting export sales of beef. The delay of the effective date would provide USDA the additional time needed to modify and test its reporting system and develop detailed reporting instructions for the reporting entities. This notice advises the public the effective date of the final rule will be delayed.

DATES: The effective date of the amendment to 7 CFR part 20 published at 66 FR 38526-38528 has been delayed to January 11, 2002.

FOR FURTHER INFORMATION CONTACT: Denise Huttenlocker, Director, Marketing Operations Staff, Foreign Agricultural Service, 1400 Independence Avenue SW., Stop 1042, U.S. Department of Agriculture, Washington, DC 20250-1021, or telephone at 202-720-4327, or e-mail at HuttenlockerD@fas.usda.gov.

Signed at Washington, DC on August 21, 2001.

Mattie R. Sharpless,

Acting Administrator, Foreign Agricultural Service.

[FR Doc. 01-21422 Filed 8-22-01; 8:45 am]

BILLING CODE 3410-10-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-257-AD; Amendment 39-12385; AD 2001-16-16]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A330 and A340 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Airbus Model A330 and A340 series airplanes. This action requires a one-time inspection to detect cracking of the bogie beams of the main landing gear (MLG), and follow-on actions, if necessary. This action is necessary to detect and correct cracking of the MLG bogie beams, which could result in failure of the beams and consequent loss of the landing gear wheels and brakes, and structural damage to the MLG strut and airframe. This action is intended to address the identified unsafe condition.

DATES: Effective September 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 7, 2001.

Comments for inclusion in the Rules Docket must be received on or before September 24, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-257-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be

submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-257-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified the FAA that an unsafe condition may exist on all Airbus Model A330 and A340 series airplanes. The DGAC advises that, during a C-check on a Model A330 series airplane, a crack was discovered in the upper part of the left-hand bogie beam of the main landing gear (MLG), in the area of the forward bogie stop pad. The crack was 120 mm (6 inches) long and 12 mm (0.4 inch) deep, and extended longitudinally along the bogie, underneath the stop pad. The airplane had accumulated a total of approximately 10,000 flight hours and 6,000 flight cycles.

The retraction link on that MLG had previously failed, leading to an undamped extension of the MLG. The failure occurred approximately 1,000 flight cycles and 11 months before the crack was discovered in the bogie beam. Analysis has shown that, due to the retraction link failure, loading in this area of the bogie is significantly greater than normally expected. Detailed analysis has not identified any other situation in which the load would cause such damage.

There have been four in-service retraction link failures. In two cases, the

affected landing gears were replaced. There was a similar visible crack discovered on one of the bogies, which was installed on an airplane that had accumulated approximately 16,000 total flight hours and 7,000 total flight cycles. Another was put in storage following the retraction failure and was subsequently inspected, revealing a crack. Inspection of a number of spare bogies that had been removed from service and had not been involved in retraction link failure incidents has revealed no similar cracks. It should be noted, however, that no proven connection has been made between failure of the retraction links and cracking in the bogie beams.

Cracking of the MLG bogie beam could result in failure of the beam and consequent loss of the landing gear wheels and brakes, and structural damage to the MLG strut and airframe.

Explanation of Relevant Service Information

Airbus has issued All Operators Telex (AOT) A330-32A3137, dated July 19, 2001; and AOT A340-32A4174, dated July 19, 2001. The AOTs describe procedures for a one-time visual inspection to detect cracking of the bogie beams of the MLG, in the area around the bogie stop pad. The AOTs also describe procedures for follow-on actions for certain conditions, if necessary. The DGAC classified these AOTs as mandatory and issued French telegraphic airworthiness directive T2001-320(B), dated July 20, 2001, to ensure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to detect and correct cracking of the MLG bogie beams, which could result in failure of

the beams and consequent loss of the landing gear wheels and brakes, and structural damage to the MLG strut and airframe. This AD requires accomplishment of the actions specified in the AOTs described previously, except as discussed below.

Difference Between AD and AOTs

Although the AOTs specify that the manufacturer may be contacted for disposition of certain inspection findings, this AD requires follow-on actions to be accomplished in accordance with a method approved by either the FAA or the DGAC (or its delegated agent).

Interim Action

This is considered to be interim action. The manufacturer has indicated its intent to investigate the cracked MLG bogie beams and any additional findings to confirm the cause of the cracking. If final action is developed in the future to address the identified unsafe condition, the FAA may consider further rulemaking.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a

request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket 2001-NM-257-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-16-16 **Airbus Industrie:** Amendment 39-12385. Docket 2001-NM-257-AD.

Applicability: All Model A330 and A340 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracking of the bogie beams of the main landing gear (MLG), which could result in failure of the beams and consequent loss of the landing gear wheels and brakes, and structural damage to the MLG strut and airframe, accomplish the following:

Inspection

(a) Within 14 days or 50 flight cycles after the effective date of this AD, whichever occurs first: Perform a one-time general visual inspection to detect cracking of both MLG bogie beams, in accordance with Airbus All Operators Telex (AOT) A330-32A3137 (for Model A330 series airplanes) or A340-32A4174 (for Model A340 series airplanes), both dated July 19, 2001.

(1) If any cracking of the base metal is detected, prior to further flight, replace the bogie beam assembly with a new assembly, in accordance with the AOT.

(2) If any cracking is detected, but it is not possible to determine whether the crack is in the base metal, or only in the paint finish and/or sealant: Prior to further flight, perform follow-on actions in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect

obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) Except as required by paragraph (a)(2) of this AD: The actions shall be done in accordance with Airbus All Operators Telex A330-32A3137, dated July 19, 2001; or Airbus All Operators Telex A340-32A4174, dated July 19, 2001; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in French telegraphic airworthiness directive T2001-320(B), dated July 20, 2001.

Effective Date

(e) This amendment becomes effective on September 7, 2001.

Issued in Renton, Washington, on August 15, 2001.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 01-21105 Filed 8-22-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-223-AD; Amendment 39-12384; AD 2001-16-15]

RIN 2120-AA64

Airworthiness Directives; BAe Systems (Operations) Limited Model Avro 146-RJ85A and 146-RJ100A Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain BAe Systems (Operations) Limited Model Avro 146-RJ85A and 146-RJ100A series airplanes. This action requires replacement of bolts in the wing rear spar at the center fuel tank. This action is prompted by mandatory continuing airworthiness information from a foreign civil airworthiness authority. This action is necessary to prevent the failure of bolts in the wing rear spar at the center fuel tank, which could result in reduced structural integrity of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective September 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 7, 2001.

Comments for inclusion in the Rules Docket must be received on or before September 24, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket Number 2001-NM-223-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-223-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from British