

inclusive, 6057 through 6066 inclusive, 6069 through 6071 inclusive, and 6073 through 6077 inclusive.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Unsafe Condition

This AD was prompted by reports of wheel inserts becoming loose and damaging brake assemblies on Model 560XL airplanes. We are issuing this AD to prevent brake failure, which could result in an airplane not being able to stop on the runway.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection, Corrective Action, and Replacement

Within 1 year after the effective date of this AD, or during the next tire change accomplished after the effective date of this AD, whichever occurs first: Do the actions specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD on both main wheels, in accordance with the Accomplishment Instructions of Cessna Service Bulletin SB560XL-32-41, Revision 1, dated May 5, 2011, including Supplemental Data, dated February 25, 2011. Do all applicable repairs and replacements before further flight.

(1) Do a general visual inspection of the torque lug and surrounding components (wheel base, side rim, lock ring) for damage (such as corrosion, cracks, dents, bent areas, damaged or missing paint or primer, or wear on the metal), and of the bearing cup for corrosion, turned cup, or clearance that exceeds limits, and all applicable repairs.

(2) Measure the torque lugs for width and replace screws and inserts with new, improved screws and inserts.

(3) Re-identify the wheel assembly.

Note 1 to paragraph (g) of this AD: Cessna Service Bulletin SB560XL-32-41, Revision 1, dated May 5, 2011, including Supplemental Data, dated February 25, 2011, refers to Goodrich Service Bulletin 3-1571-32-7, dated February 25, 2011, as an additional source of guidance on inspecting and repairing the torque lugs, surrounding components, and bearing cup, and re-identifying the wheel assemblies.

(h) Definition

For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(i) Parts Installation

As of the effective date of this AD, no person may install, on any airplane, a wheel assembly having P/N 3-1571-3 or 3-1571-4, unless it has been inspected, measured, and re-identified, in accordance with paragraph (g) of this AD, and all applicable repairs or replacements have been done.

(j) Credit for Previous Actions

This paragraph provides credit for actions, as required by paragraph (g) of this AD, if those actions were done before the effective date of this AD in accordance with Cessna Service Bulletin SB560XL-32-41, dated February 25, 2011.

(k) No Reporting Required

Although Cessna Service Bulletin SB560XL-32-41, Revision 1, dated May 5, 2011, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(m) Related Information

For more information about this AD, contact contact David Fairback, Aerospace Engineer, Mechanical Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, KS 67209; phone: 316-946-4154; fax: 316-946-4107; email: david.fairback@faa.gov.

(n) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(2) The Director of the Federal Register approved the incorporation by reference (IBR) under 5 U.S.C. 552(a) and 1 CFR part 51 of the following service information:

(i) Cessna Service Bulletin SB560XL-32-41, Revision 1, dated May 5, 2011, including Supplemental Data, dated February 25, 2011.

(3) For Cessna service information identified in this AD, contact Cessna Aircraft Co., P.O. Box 7706, Wichita, Kansas 67277; telephone 316-517-6215; fax 316-517-5802; email citationpubs@cessna.texttron.com; Internet <https://www.cessnasupport.com/newlogin.html>.

(4) For Goodrich service information identified in this AD, contact Goodrich Corporation, Aircraft Wheels & Brakes, P.O. Box 340, Troy, Ohio 45373-3872; telephone

937-440-2130; fax 937-440-2055; email WBPubs-Admin@goodrich.com; Internet <http://www.goodrich.com/TechPubs>.

(5) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 24, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-10473 Filed 5-2-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1410; Directorate Identifier 2011-NM-033-AD; Amendment 39-17038; AD 2012-09-03]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aerosystems Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Saab AB, Saab Aerosystems Model SAAB 2000 airplanes. This AD was prompted by reports of hydraulic accumulator failure. This AD requires replacing certain hydraulic accumulators with stainless steel hydraulic accumulators, and structural modifications in the nose landing gear bay. We are issuing this AD to prevent failure of hydraulic accumulators, which may result in damage to the airplane and injury to occupants.

DATES: This AD becomes effective June 7, 2012.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 7, 2012.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on December 29, 2011 (76 FR 81889). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Three cases of failure have been reported, affecting the same type of hydraulic accumulator as installed on SAAB 2000 aeroplanes, although all occurred on other aeroplane types. The reported cause of these failures has been traced to corrosion. Any of the end parts on the accumulator may depart from the pressure vessel if they are affected by corrosion.

This condition, if not detected and corrected, may lead to fatigue failure of a hydraulic accumulator, possibly resulting in damage to the aeroplane and injury to occupants. In addition, a quality issue during the replacement of the base material in the end parts of the accumulator may have affected the service life of the accumulator.

To address this unsafe condition, SAAB has introduced a new type of hydraulic accumulator, which is made of stainless steel.

For the reasons described above, this [EASA] AD requires the replacement of all Part Number (P/N) 08 8423 030 1 hydraulic accumulators with stainless steel P/N 40800-2050 hydraulic accumulators and associated structural modifications in the nose landing gear bay.

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received.

Request To Include a Statement From the Service Information

Saab AB (the commenter) requested that we revise the NPRM (76 FR 81889, December 29, 2011) to include a statement as follows: "In addition, a quality issue during the replacement of the base material in the end parts of the accumulator may have affected the service life of the accumulator."

We infer that the commenter requested that we add the statement to the Discussion section of the NPRM (76

FR 81889, December 29, 2011). We agree that Saab Service Bulletin 2000-29-024, Revision 01, dated November 5, 2010, states, "In addition, a qualification issue during the change of the base material, for the end parts of the accumulator back in 1993, can have affected the life limit of the accumulator." However, we have not included the statement in the final rule because we do not restate the Discussion section in the final rule. We have not changed the AD in this regard.

Explanation of Additional Change Made to This AD

We have revised the heading and wording in paragraph (i) of this AD; this change has not changed the intent of that paragraph.

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the changes described previously—except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (76 FR 81889, December 29, 2011) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (76 FR 81889, December 29, 2011).

Costs of Compliance

We estimate that this AD will affect 8 products of U.S. registry. We also estimate that it will take about 12 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$9,995 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$88,120, or \$11,015 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII,

Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM (76 FR 81889, December 29, 2011), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2012–09–03 Saab AB, Saab Aerosystems:
Amendment 39–17038. Docket No. FAA–2011–1410; Directorate Identifier 2011–NM–033–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective June 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aerosystems Model SAAB 2000 airplanes, certificated in any category; all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 29: Hydraulic Power.

(e) Reason

This AD was prompted by reports of hydraulic accumulator failure. We are issuing this AD to prevent failure of hydraulic accumulators, which may result in damage to the airplane and injury to occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 12 months after the effective date of this AD, replace all hydraulic accumulators having part number (P/N) 08 8423 030 1, with stainless steel hydraulic accumulators having P/N 40800–2050, and do the structural modifications in the nose landing gear bay, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010.

(h) Parts Installation

After replacing hydraulic accumulators having P/N 08 8423 030 1 with hydraulic accumulators having P/N 40800–2050, and doing the structural modifications in the nose landing gear bay, as required by paragraph (g) of this AD, no person may install any hydraulic accumulator having P/N 08 8423 030 1 on any airplane.

(i) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Saab Service Bulletin 2000–29–024, dated November 18, 2009.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, ANM–116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1112; fax (425) 227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011–0004, dated January 17, 2011; and Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010; for related information.

(l) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51:

(i) Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010. (2) For service information identified in this AD, contact Saab AB, Saab Aerosystems, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 23, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–10469 Filed 5–2–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2012–0227; Airspace Docket No. 12–ACE–1]

Modification of VOR Federal Airway V–14; Missouri

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule, technical amendment.

SUMMARY: This action amends VOR Federal airway V–14 in the vicinity of St. Louis, MO. The FAA is taking this action to correct the V–14 description contained in Part 71 to ensure it matches the information contained in the FAA’s aeronautical database, matches the depiction on the associated charts, and to ensure the safety and efficiency of the National Airspace System (NAS).

DATES: Effective date 0901 UTC May 3, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Colby Abbott, Airspace, Regulations and ATC Procedures Group, Office of Mission Support Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

History

After a recent review of aeronautical data, the Aeronautical Navigation Products Group identified the VOR Federal airway V–14 description published in FAA Order 7400.9, Airspace Designations and Reporting Points, did not match the airway information contained in the FAA’s aeronautical database or the charted depiction of the airway. When V–14 was amended in the **Federal Register** of May 7, 1990 (55 FR 18862), the St. Louis, MO, VOR/DME was deleted from the description in error. The FAA aeronautical database retained the