

used. Suggested default values are a 1 kHz sine wave with 80 percent depth of modulation in the frequency range from 10 kHz to 400 MHz and 1 kHz square wave with greater than 90 percent depth of modulation from 400 MHz to 18 GHz. For frequencies where the unmodulated signal would cause deviations from normal operation, several different modulating signals with various waveforms and frequencies should be applied.

Applicants must perform a preliminary hazard analysis to identify electrical/electronic systems that perform critical functions. The term "critical" means those functions whose failure would contribute to or cause an unsafe condition that would prevent the continued safe flight and landing of the helicopters. The systems identified by the hazard analysis as performing critical functions are required to have HIRF protection. A system may perform both critical and non-critical functions. Primary electronic flight display systems and their associated components perform critical functions such as attitude, altitude, and airspeed indications. HIRF requirements would apply only to the systems that perform critical functions, including control and display.

Acceptable system performance would be attained by demonstrating that the critical function components of the system under consideration continue to perform their intended function during and after exposure to required electromagnetic fields. Deviations from system specifications may be acceptable but must be independently assessed by the FAA on a case-by-case basis.

TABLE 1.—VFR ROTORCRAFT
Field strength volts/meter

Frequency	Peak	Average
10 kHz—100 kHz	150	150
100 kHz—500 kHz	180	150
500 kHz—2 MHz	140	140
2 MHz—30 MHz	610	610
30 MHz—70 MHz	80	80
70 MHz—100 MHz	150	150
100 MHz—200 MHz	300	140
200 MHz—400 MHz	160	140
400 MHz—700 MHz	540	400
700 MHz—1 GHz	2400	400
1 GHz—2 GHz	7000	250
2 GHz—4 GHz	8600	840
4 GHz—6 GHz	13700	1270
6 GHz—8 GHz	1800	800
8 GHz—12 GHz	8000	500
12 GHz—18 GHz	3300	560
18 GHz—40 GHz	1800	700

TABLE 2.—VFR ROTORCRAFT
Field strength volts/meter

Frequency	Peak	Average
10 kHz—100 kHz	50	50
100 kHz—500 kHz	60	60
500 kHz—2 MHz	70	70
2 MHz—30 MHz	200	200
30 MHz—70 MHz	30	30
70 MHz—100 MHz	30	30
100 MHz—200 MHz	150	30
200 MHz—400 MHz	70	70
400 MHz—700 MHz	700	80
700 MHz—1 GHz	1700	240
1 GHz—2 GHz	5000	360
2 GHz—4 GHz	4500	360
4 GHz—6 GHz	7200	300
6 GHz—8 GHz	2000	330
8 GHz—12 GHz	3500	270
12 GHz—18 GHz	3500	330
18 GHz—40 GHz	780	20

Applicability

As previously discussed, this special condition is applicable to Eurocopter Model EC-155 helicopters. Should Eurocopter apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special condition would apply to that model as well under the provisions of § 21.101(a)(1).

Conclusion

This action affects only certain novel or unusual design features on one model series of helicopters. It is not a rule of general applicability and affects only the applicant who applied to the FAA for approval of these features on the helicopter.

The substance of this special condition has been subjected to the notice and comment period in several prior instances and has been derived without substantive change from those previously issued. It is unlikely that prior public comment would result in a significant change from the substance contained herein. For this reason and because a delay would significantly affect the certification of the helicopter, which is imminent, the FAA has determined that prior public notice and comment are unnecessary and impracticable, and good cause exists for adopting this special condition upon issuance. The FAA is requesting comments to allow interested persons to submit views that may not have been submitted in response to the prior opportunities for comment described above.

List of Subjects in 14 CFR Part 29

Aircraft, Air transportation, Aviation safety, Rotorcraft, Safety.

Authority: The authority citation for these special conditions is as follows: 42 U.S.C. 7572; 49 U.S.C. 106(g), 40105, 40113, 44701–44702, 44704, 44709, 44711, 44713, 44715, 45303.

The Special Condition

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special condition is issued as part of the type certification basis for Eurocopter Model EC-155 helicopters.

Protection for Electrical and Electronic Systems From High-Intensity Radiated Fields

Each system that performs critical functions must be designed and installed to ensure that the operation and operational capabilities of these critical functions are not adversely affected when the helicopter is exposed to high-intensity radiated fields external to the helicopter.

Issued in Fort Worth, Texas, on October 31, 2000.

Mark R. Schilling,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00–30303 Filed 11–27–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97–NM–273–AD; Amendment 39–11999; AD 2000–23–26]

RIN 2120–AA64

Airworthiness Directives; Aerospatiale Model ATR72 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all Aerospatiale Model ATR72 series airplanes, that requires a revision to the Airworthiness Limitations Section of the Instructions for Continued Airworthiness to incorporate inspections to detect fatigue cracking in certain structure, inspection intervals, and life limits for certain components. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to ensure that fatigue cracking of certain structural elements is detected and corrected; such fatigue cracking

could adversely affect the structural integrity of these airplanes.

DATES: Effective January 2, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 2, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Aerospatiale Model ATR72 series airplanes was published as a supplemental notice of proposed rulemaking (NPRM) in the *Federal Register* on August 23, 2000 (65 FR 51260). That action proposed to require a revision to the Airworthiness Limitations Section of the Instructions for Continued Airworthiness to incorporate inspections to detect fatigue cracking in certain structure, inspection intervals, and life limits for certain components.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received in response to the supplemental NPRM.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 39 Aerospatiale Model ATR72 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the

cost impact of the AD on U.S. operators is estimated to be \$2,340, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-23-26 Aerospatiale: Amendment 39-11999. Docket 97-NM-273-AD.

Applicability: All Model ATR72 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To ensure continued structural integrity of these airplanes, accomplish the following:

Airworthiness Limitations Revision

(a) Within 30 days after the effective date of this AD, revise the Airworthiness Limitations Section of the Instructions for Continued Airworthiness by incorporating the "Time Limits" section of the ATR72 Maintenance Planning Document, Revision 4, dated July 1999, into the Airworthiness Limitations Section.

(b) Except as provided in paragraph (c) of this AD: After the actions specified in paragraph (a) of this AD have been accomplished, no alternative inspections or inspection intervals may be approved for the structural elements specified in the documents listed in paragraph (a) of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The Airworthiness Limitations revision shall be done in accordance with the "Time Limits" section of the ATR72 Maintenance Planning Document, Revision 4, dated July 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. Copies

may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in French airworthiness directive 95-105-026 (B), dated May 24, 1995.

Effective Date

(f) This amendment becomes effective on January 2, 2001.

Issued in Renton, Washington, on November 14, 2000.

Donald L. Riffin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-29607 Filed 11-27-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-359-AD; Amendment 39-12000; AD 2000-23-27]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-102, -103, and -301 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Bombardier Model DHC-8-102, -103, and -301 series airplanes, that currently requires a one-time inspection for wear and breakage of wire segments of the individual lighting units of the ceiling and sidewall lights, and replacement of any damaged wiring. The existing AD also requires installation of teflon spiral wrap on the wiring of the ceiling and sidewall lights. This amendment adds a requirement for a one-time inspection to determine if teflon spiral wrap is installed on the wiring of the lavatory lighting system, and installation, if necessary. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent the possibility of a fire on an airplane due to such chafing and consequent short circuiting, overheating, and smoking of the wires on the aircraft structure.

DATES: Effective January 2, 2001.

The incorporation by reference of Bombardier Service Bulletin S.B. 8-33-35, Revision B, dated September 25,

1998, as listed in the regulations, is approved by the Director of the Federal Register as of January 2, 2001.

The incorporation by reference of de Havilland Service Bulletin S.B. 8-33-35, dated September 1, 1995, as listed in the regulations, was approved previously by the Director of the Federal Register as of July 6, 1998 (63 FR 29546, June 1, 1998).

ADDRESSES: The service information referenced in this AD may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Luciano Castracane, Aerospace Engineer, New York Aircraft Certification Office, Systems & Flight Test Branch (ANE-172), FAA, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7535; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-11-21, amendment 39-10546 (63 FR 29546, July 6, 1998), which is applicable to certain Bombardier Model DHC-8-102, -103, and -301 series airplanes, was published in the **Federal Register** on August 23, 2000 (65 FR 51256). The action proposed to continue to require a one-time inspection for wear and breakage of wire segments of the individual lighting units of the ceiling and sidewall lights, and replacement of any damaged wiring. The action also proposed to continue to require installation of teflon spiral wrap on the wiring of the ceiling and sidewall lights. Additionally, the action proposed to add a requirement for a one-time inspection to determine if teflon spiral wrap is installed on the wiring of the lavatory lighting system, and installation, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 73 airplanes of U.S. registry that will be affected by this AD.

The actions that are currently required by AD 98-11-21 take approximately 30 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts cost approximately \$250 per airplane. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$149,650, or \$2,050 per airplane.

The new inspection that is required by this AD will take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the new requirements of this AD on U.S. operators is estimated to be \$8,760, or \$120 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is