

Rules and Regulations

Federal Register

Vol. 74, No. 38

Friday, February 27, 2009

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0150; Directorate Identifier 2009-CE-010-AD; Amendment 39-15830; AD 2009-05-06]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-500 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

There is a possibility that during a go around procedure with a flap system failed the stall warning and the stick pusher triggering angles are anticipated reducing the margin between the real angle of attack and the stick pusher triggering angle. If the stick pusher is activated at a low altitude the pilot may be not able to recover the airplane control. Since this condition affects flight safety, an immediate corrective action is required. Thus, sufficient reason exists to request compliance with this EAD in the indicated time limit without prior notice.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective February 27, 2009.

We must receive comments on this AD by March 30, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

The AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL—BRAZIL, which is the aviation authority for Brazil, has issued EAD No.: 2009-02-04, dated February 13, 2009 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

There is a possibility that during a go around procedure with a flap system failed the stall warning and the stick pusher triggering angles are anticipated reducing the margin between the real angle of attack and the stick pusher triggering angle. If the stick pusher is activated at a low altitude the pilot may be not able to recover the airplane control. Since this condition affects flight safety, an immediate corrective action is required. Thus, sufficient reason exists to request compliance with this EAD in the indicated time limit without prior notice.

You may obtain further information by examining the MCAI in the AD docket.

FAA's Determination and Requirements of the AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might have also required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the AD. These requirements take precedence over those copied from the MCAI.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because if the stick pusher is activated at a low altitude the pilot may not be able to recover the airplane control. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant

data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0150; Directorate Identifier 2009-CE-010-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2009-05-06 Empresa Brasileira de Aeronautica S.A. (EMBRAER):
Amendment 39-15830; Docket No. FAA-2009-0150; Directorate Identifier 2009-CE-010-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective February 27, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Models EMB-500 airplanes, all serial numbers, equipped with the stall warning computer part number (P/N) C100106-1, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: There is a possibility that during a go around procedure with a flap system failed the stall warning and the stick pusher triggering angles are anticipated reducing the margin between the real angle of attack and the stick pusher triggering angle. If the stick pusher is activated at a low altitude the pilot may be not able to recover the airplane control. Since this condition affects flight safety, an immediate corrective action is required. Thus, sufficient reason exists to request compliance with this EAD in the indicated time limit without prior notice.

Actions and Compliance

(f) Unless already done, before further flight, incorporate into the airplane flight manual (AFM) the following procedures and limitations section revisions. You may insert a copy of this AD into the appropriate sections of the AFM to comply with the requirements of this AD.

(1) Revise the AFM by adding Figure 1 of this AD to the Limitations section 2.30.

BILLING CODE 4910-13-P

Figure 1 – AFM Limitations Section 2.30 Revision

FLAPS

Flap FULL must not be used to land in no icing condition.

(2) Replace the GO-AROUND procedure in AFM Section 3-03, page 2, with the procedure in Figure 2 of this AD.

Figure 2 – AFM Section 3-03, GO-AROUND Procedure

FLAPS MUST NOT BE RETRACTED DURING GO-AROUND MANEUVER

GO-AROUND

TO/GA ButtonsPRESS

Thrust Levers.....TO/GA

Rotate the airplane following the flight director guidance.

In case of flight director is inoperative, rotate the airplane according to the table below.

LANDING FLAPS POSITION	GO-AROUND PITCH ANGLE
2	7.5°

With positive rate of climb:

LDG GEAR LeverUP

Minimum Airspeed.....V_{AC}

At the acceleration altitude proceed as in a normal takeoff.

(3) Replace the ONE ENGINE
INOPERATIVE PROCEDURE APPROACH
AND LANDING procedure in AFM Section

4-01, page 17, with the procedure in Figure
3 of this AD.

APPROACH AND LANDING Procedure

During descent:

Landing configuration:

CAUTION: MULTIPLY THE FULL FLAPS UNFACTORED LANDING DISTANCE BY 1.25.

If a go around is required:

CAUTION: DO NOT PRESS THE TO/GA BUTTON AFTER SELECTING GO AROUND FLAP.

Rotate the airplane to 7.5° nose up.

With positive rate of climb:

LDG GEAR Lever..... UP
Airspeed..... APPROACH
CLIMB SPEED

(4) Revise AFM Section 5-02 by adding the statement in Figure 4 of this AD.

Figure 4 – AFM Section 5-02 Revision

WARNING: OPERA LANDING PERFORMANCE FOR NO ICE CONDITIONS (ANTI-ICE OFF) MUST NOT BE USED.

(5) Replace the AFM performance tables (ANTI-ICE OFF) in Section 5-20, pages 2 and 3, with the table in Figure 5 of this AD.

Figure 5 – AFM Section 5-20, Performance Tables (ANTI-ICE OFF)

APPROACH FLAPS 2 AND LANDING FLAPS 2		
ANTI-ICE OFF		
WEIGHT (kg)	APPROACH	LANDING (CLIMB/REFERENCE)
	FLAPS 2	FLAPS 2
	V_{AC} – KIAS	V_{REF} – KIAS
3200	92	91
3300	93	91
3400	94	92
3500	95	93
3600	97	95
3700	98	96
3800	99	97
3900	100	98
4000	101	100
4100	102	101
4200	103	102
4300	104	104
4400	105	105
4500	107	106

(6) Replace the AFM performance tables (ANTI-ICE OFF) in Section 5-25, pages 2 and 3, with the table in Figure 6 of this AD.

Figure 6 – AFM Section 5-25, Performance Tables (ANTI-ICE OFF)

MAXIMUM LANDING WEIGHT – CLIMB LIMITED APPROACH FLAPS 2 – LANDING FLAPS 2 – ANTI-ICE OFF						
TEMP (°C)	MAXIMUM LANDING WEIGHT (kg)					
	Altitude (ft)					
	-1000 ft	0 ft	1000 ft	2000 ft	3000 ft	4000 ft
-40	4430 (S)	4430 (S)	4430 (S)	4426 (A)	4275 (A)	4125 (A)
-35	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4279 (A)	4129 (A)
-30	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4283 (A)	4133 (A)
-25	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4287 (A)	4137 (A)
-20	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4290 (A)	4141 (A)
-15	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4294 (A)	4145 (A)
-10	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4297 (A)	4148 (A)
-5	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4301 (A)	4152 (A)
0	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4304 (A)	4156 (A)
5	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4305 (A)	4157 (A)
10	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4301 (A)	4154 (A)
15	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4297 (A)	4151 (A)
20	4430 (S)	4430 (S)	4430 (S)	4430 (S)	4284 (A)	4137 (A)
25	4430 (S)	4430 (S)	4430 (S)	4338 (A)	4169 (A)	3998 (A)
30	4430 (S)	4430 (S)	4311 (A)	4126 (A)	3954 (A)	3788 (A)
35	4430 (S)	4262 (A)	4080 (A)	3908 (A)	3744 (A)	3584 (A)
40	4191 (A)	4030 (A)	3866 (A)	3701 (A)	3544 (A)	3397 (A)
45	3977 (A)	3826 (A)	3665 (A)	3509 (A)	-	-
50	3773 (A)	3629 (A)	-	-	-	-

TEMP (°C)	MAXIMUM LANDING WEIGHT (kg)					
	Altitude (ft)					
	5000 ft	6000 ft	7000 ft	8000 ft	9000 ft	10000 ft
-40	3977 (A)	3847 (A)	3723 (A)	3603 (A)	3485 (A)	3410 (A)
-35	3981 (A)	3850 (A)	3727 (A)	3606 (A)	3488 (A)	3412 (A)
-30	3984 (A)	3854 (A)	3730 (A)	3610 (A)	3492 (A)	3415 (A)
-25	3988 (A)	3857 (A)	3734 (A)	3613 (A)	3495 (A)	3417 (A)
-20	3992 (A)	3861 (A)	3737 (A)	3616 (A)	3498 (A)	3419 (A)
-15	3995 (A)	3864 (A)	3740 (A)	3619 (A)	3501 (A)	3422 (A)
-10	3998 (A)	3867 (A)	3743 (A)	3623 (A)	3504 (A)	3424 (A)
-5	4002 (A)	3870 (A)	3747 (A)	3626 (A)	3508 (A)	3426 (A)
0	4005 (A)	3874 (A)	3750 (A)	3629 (A)	3511 (A)	3429 (A)
5	4007 (A)	3877 (A)	3752 (A)	3631 (A)	3513 (A)	3431 (A)
10	4006 (A)	3874 (A)	3750 (A)	3630 (A)	3512 (A)	3429 (A)
15	4005 (A)	3872 (A)	3747 (A)	3627 (A)	3509 (A)	3409 (A)
20	3987 (A)	3828 (A)	3678 (A)	3535 (A)	3378 (A)	3223 (A)
25	3821 (A)	3654 (A)	3496 (A)	3345 (A)	3198 (A)	3124 (A)
30	3619 (A)	3455 (A)	3302 (A)	3175 (A)	3124 (A)	3124 (A)
35	3416 (A)	3268 (A)	3154 (A)	-	-	-
40	3242 (A)	-	-	-	-	-

BILLING CODE 4910-13-C

Note 1: The above limitation and procedures are considered an interim solution until a final action is identified, at which time AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL—BRAZIL (ANAC) and the FAA may consider further AD action.

Note 2: Operation in icing conditions is not affected by the above limitations and procedures.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI ANAC, EAD No.: 2009-02-04, dated February 13, 2009.

Issued in Kansas City, Missouri, on February 20, 2009.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-4099 Filed 2-26-09; 8:45 am]

BILLING CODE 4910-13-C

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-1065; Directorate Identifier 2008-NM-126-AD; Amendment 39-15827; AD 2009-05-03]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 727 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 727 airplanes. This AD requires among other actions, installing new ground fault interrupter (GFI) relays for the main fuel tanks and the auxiliary fuel tank pumps. This AD also

requires revising the FAA-approved maintenance program to incorporate new Airworthiness Limitations for the GFI of the boost pumps and for the uncommanded on system for the auxiliary fuel tank pumps. This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent an electrical fault in the fuel pump system, which might cause a connector or end cap to burn through and a subsequent fire or explosion inside the fuel pump or wing spar area. We are also issuing this AD to prevent uncommanded operation of the auxiliary fuel tank pumps, which can cause them to run dry. This condition will increase pump temperature and could supply an ignition source to fumes in the fuel tank, which can result in a consequent fire or explosion.

DATES: This AD is effective April 3, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 3, 2009.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Binh Tran, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6485; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness

directive (AD) that would apply to certain Boeing Model 727 airplanes. That NPRM was published in the **Federal Register** on October 7, 2008 (73 FR 58509). That NPRM proposed to require, among other actions, installing new ground fault interrupter (GFI) relays for the main fuel tanks and the auxiliary fuel tank pumps. This AD also requires revising the FAA-approved maintenance program to incorporate new Airworthiness Limitations for the GFI of the boost pumps and for the uncommanded on system for the auxiliary fuel tank pumps.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Support for the NPRM

Boeing concurs with the contents of the NPRM.

General Comment Disagreeing With NPRM

Another commenter, Ralph Pascale, asserts that the current configuration of the boost pump circuits is adequate and does not need to be changed. The commenter feels that by installing the GFIs on the boost pumps according to the NPRM, there could be a condition where during a loss of all generators due to thunderstorms, electrical power is lost to the boost pumps and the possibility of the GFI tripping due to high voltage (getting hit by lightning) will prevent the boost pumps from supplying boosted pressure when electrical power is re-established, causing a triple flameout.

We infer that the commenter is requesting that we withdraw the NPRM. We do not concur. Loss of all generators resulting in loss of all boost pumps is a rare event, even without GFI installed for the boost pumps. The GFI has been tested for lightning threat to a level that is higher than the worst-case lightning threat that a Model 727 airplane would typically experience. Therefore, the risk to the boost pumps has not increased. We have not changed this final rule in light of the comment.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD will affect 199 airplanes of U.S. registry. The following table provides the estimated