

TABLE 1 TO PARAGRAPH (b)(10)

Preservative	Analytical method	Referee method
Pentachlorophenol	XRF, Lime Ignition, Copper Pyridine	Lime Ignition, Copper Pyridine.
Creosote	Toluene Extraction	Toluene Extraction.
Waterborne	XRF	XRF.
Copper Naphthenate	XRF	ICP, GC.
DCOI	XRF, HPLC	HPLC.

Note 1 to table 1 to paragraph (b)(10): XFR means X-ray fluorescence; HPLC means High Performance Liquid Chromatography; ICP means Inductively coupled plasma; and GC means Gas Chromatography.

* * * * *

(d) *Preservatives.* Creosote, waterborne preservatives, pentachlorophenol, DCOI, and copper naphthenate shall conform to current AWP A U1 (incorporated by reference in § 1728.97).

(e) * * *

(5) * * *

Note 2 to table 2 to paragraph (e)(5): Retention and penetration requirements for each different species and preservative are listed in Table 8 of Appendix A, RUS Bulletin 1728F–700, Specification for Wood Poles, Stubs and Anchor Logs (incorporated by reference at § 1728.97).

* * * * *

(7) Penetration compliance of both poles and crossarms shall be determined in accordance with the standard AWP A A15 (incorporated by reference at § 1728.97). Chrome Azurol S shall be used to determine the penetration of copper containing preservatives AWP A A69 (incorporated by reference at § 1728.97), Penta-Check shall be used to determine the penetration of penta

AWP A A70 (incorporated by reference at § 1728.97), and Red-O dye for penetration of DCOI AWP A A71 (incorporated by reference at § 1728.97), respectively.

* * * * *

(g) * * *

(2) Third-party inspectors shall verify their acceptance of untreated crossarms that have been offered by the producer as conforming by marking each accepted piece in one end with a clear, legible hammer stamp. Following treatment, inspectors shall verify their acceptance of treated crossarms that have been offered by the producer as conforming by marking each accepted piece in the opposing end with a clear, legible hammer stamp. The inspector shall personally mark each piece for acceptance and shall not delegate this responsibility to any other individual.

PART 1755—TELECOMMUNICATIONS POLICIES ON SPECIFICATIONS, ACCEPTABLE MATERIALS, AND STANDARD CONTRACT FORMS

■ 6. The authority citation for part 1755 continues to read as follows:

Authority: 7 U.S.C. 901 *et seq.*, 1921 *et seq.*, 6941 *et seq.*

■ 7. Amend § 1755.97 by revising paragraph (b)(13) to read as follows:

§ 1755.97 Telephone standards and specifications.

* * * * *

(b) * * *

(13) Bulletin 1728F–700, RUS Specification for Wood Poles, Stubs and Anchor Logs, September 9, 2021.

■ 8. Amend § 1755.98 by revising paragraph (a) to read as follows:

§ 1755.98 List of telecommunications specifications included in other 7 CFR parts.

* * * * *

Section	Issue date	Title
(a) 1728.202	9.9.2021	RUS Specification for Quality Control and Inspection of Timber Products.
* * * * *		

Christopher A. McLean,
Acting Administrator, Rural Utilities Service.
[FR Doc. 2021–22255 Filed 10–13–21; 8:45 am]
BILLING CODE 3410–15–P

**DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration**

14 CFR Part 39
[Docket No. FAA–2021–0569; Project Identifier MCAI–2020–01692–T; Amendment 39–21752; AD 2021–20–14]
RIN 2120–AA64

Airworthiness Directives; Dassault Aviation Airplanes
AGENCY: Federal Aviation Administration (FAA), DOT.
ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Dassault Aviation Model FALCON 7X, FALCON 900EX, and FALCON 2000EX

airplanes. This AD was prompted by a report of a manufacturing issue involving misalignment of a cabin seat pin and plate that can prevent the recline locking mechanism from properly engaging when the seat is in taxi, take-off, or landing position. This AD requires an inspection of certain cabin seats for discrepancies and corrective action, as specified in European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 18, 2021.

The Director of the Federal Register approved the incorporation by reference

of a certain publication listed in this AD as of November 18, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0569.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0569; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th

St., Des Moines, WA 98198; telephone and fax 206-231-3226; email tom.rodriguez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0284, dated December 18, 2020 (EASA AD 2020-0284) (also referred to as the MCAI), to correct an unsafe condition for Dassault Aviation Model FALCON 7X, FALCON 900EX, and FALCON 2000EX airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Dassault Aviation Model FALCON 7X, FALCON 900EX, and FALCON 2000EX airplanes. The NPRM published in the **Federal Register** on July 15, 2021 (86 FR 37255). The NPRM was prompted by a report of a manufacturing issue involving misalignment of a cabin seat pin and plate that can prevent the recline locking mechanism from properly engaging when the seat is in taxi, take-off, or landing position. The NPRM proposed to require an inspection of certain cabin seats for discrepancies and corrective action, as specified in EASA AD 2020-0284.

The FAA is issuing this AD to address cabin seats having improper or no engagement of the recline locking mechanism during taxi, take-off, or landing, which could result in reduced seat performance under crash loads and possible injury to seat occupants. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

EASA AD 2020-0284 specifies procedures for an inspection of certain cabin seats for discrepancies (a gap between the seat pin and plate), and corrective action (adjustment, deactivation, or repair), as applicable. EASA AD 2020-0284 also prohibits installation of certain cabin seats. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 565 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	None	\$85	\$48,025

The FAA estimates the following costs to do any necessary on-condition adjustments or deactivations that would

be required based on the results of any required actions. The FAA has no way of determining the number of aircraft

that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85	\$0	\$85

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this AD.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control

warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–20–14 Dassault Aviation:

Amendment 39–21752; Docket No. FAA–2021–0569; Project Identifier MCAI–2020–01692–T.

(a) Effective Date

This airworthiness directive (AD) is effective November 18, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Dassault Aviation Model FALCON 7X, FALCON 900EX, and FALCON 2000EX airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Reason

This AD was prompted by a report of a manufacturing issue involving misalignment of a seat pin and plate that can prevent the recline locking mechanism from properly engaging when the seat is in taxi, take-off, or landing position. The FAA is issuing this AD to address cabin seats having improper or no engagement of the recline locking mechanism during taxi, take-off, or landing, which could result in reduced seat performance under crash loads and possible injury to seat occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0284, dated December 18, 2020 (EASA AD 2020–0284).

(h) Exceptions to EASA AD 2020–0284

(1) Where EASA AD 2020–0284 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not mandate compliance with the "Remarks" section of EASA AD 2020–0284.

(3) Where paragraph (2) of EASA AD 2020–0284 specifies action if "any discrepancy" is detected for this AD, a discrepancy is a gap between the seat pin and plate.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2020–0284 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with

14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226; email tom.rodriguez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0284, dated December 18, 2020.

(ii) [Reserved]

(3) For EASA AD 2020–0284, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on September 21, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–22294 Filed 10–13–21; 8:45 am]

BILLING CODE 4910–13–P