

valves, or within 600 flight hours after the effective date of this AD, whichever occurs later, do the actions required by paragraphs (a)(1) and (a)(2) of this AD.

(1) Inspect to determine whether any selector valve having part number (P/N) A25199-0-2 is installed.

(2) Replace any selector valve having P/N A25199-0-2 with a new selector valve having P/N A25199-0-3, in accordance with Airbus Service Bulletin A300-32-0438, Revision 01, dated November 20, 2001.

Operational Test

(b) For airplanes installed with selector valves having P/N A25199-0-3 only: Before the accumulation of 32,000 total flight cycles on the landing gear selector valves, or within 600 flight hours after the effective date of this AD, whichever occurs later, perform an operational test of the selector valves. Do the test in accordance with the Accomplishment Instructions of Airbus Service Bulletins A300-32-0438 (for Model A300 B2 and A300 B4 series airplanes), A300-32-6082 (for Model A300-600 series airplanes and Model A300 C4-605R Variant F airplanes), and A310-32-2118 (for Model A310 series airplanes); all Revision 01, dated November 20, 2001; as applicable. Before further flight, replace any valve that fails the operational test with a new valve having P/N A25199-0-3, in accordance with the applicable service bulletin.

Follow-on and Corrective Actions

(c) For Model A300 B2 and A300 B4 series airplanes that have not been modified in accordance with Airbus Modification 3083 (Airbus Service Bulletin A300-32-0269): Within 3,000 flight hours after the accumulation of 32,000 total flight cycles on the valve, or within 3,000 flight hours after performing the operational test required by paragraph (b) of this AD, whichever occurs later, do task 323112-0503-2 of the Airbus A300 Maintenance Planning Document (MPD). Repeat the MPD task thereafter at intervals not to exceed 3,000 flight hours.

(d) For Model A300 B2 and A300 B4 series airplanes that have been modified in accordance with Airbus Modification 3083 (Airbus Service Bulletin A300-32-0269), and for Model A300-600 and A310 series airplanes and Model A300 C4-605R Variant F airplanes: Repeat the operational test specified in paragraph (b) of this AD at the later of the times specified by paragraphs (d)(1) and (d)(2) of this AD. Thereafter, repeat the test at intervals not to exceed 18 months or 2,800 flight cycles, whichever occurs first.

(1) Within 18 months or 2,800 flight cycles, whichever occurs first, after the accumulation of 32,000 total flight cycles on the valve.

(2) Within 18 months or 2,800 flight cycles, whichever occurs first, after performing the initial operational test required by paragraph (b) of this AD.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(f) Unless otherwise specified in this AD, the actions must be done in accordance with Airbus Service Bulletin A300-32-0438, Revision 01, including Appendix 01, dated November 20, 2001; Airbus Service Bulletin A300-32-6082, Revision 01, including Appendix 01, dated November 20, 2001; and Airbus Service Bulletin A310-32-2118, Revision 01, including Appendix 01, dated November 20, 2001; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 1: The subject of this AD is addressed in French airworthiness directive 2001-603(B), dated December 12, 2001.

Effective Date

(g) This amendment becomes effective on April 13, 2004.

Issued in Renton, Washington, on February 27, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-4921 Filed 3-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2004-NM-03-AD; Amendment 39-13514; AD 2004-05-19]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. This action requires an inspection of the rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section for damage; and follow-on or corrective actions, as applicable. This action is necessary to detect and correct damaged rear spar attach pins or front spar attach bolts, which may lead to failure of the

bolts or pins, and consequent loss of the stabilizer and loss of controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective March 24, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of March 24, 2004.

Comments for inclusion in the Rules Docket must be received on or before May 10, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2004-NM-03-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2004-NM-03-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6440; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA has received numerous reports indicating that, during incorporation of Boeing Service Bulletin 737-55-1074, damaged rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section were found on Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. The damaged bolts and pins have premature wear, corrosion, pitting, and galling. Such damaged rear spar attach pins or front spar attach bolts, if not corrected, may lead to failure of the bolts or pins, which could result in loss of the

stabilizer and consequent loss of controllability of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 737–55–1086, dated December 11, 2003. The service bulletin describes procedures for an initial detailed inspection of the rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section for damage (e.g., pitting, corrosion, no plating (pins only), galling (bolts only), or wear); and follow-on or corrective actions, as applicable. The follow-on actions include repetitive detailed inspections. The corrective actions include repair of any damaged part; replacement of any damaged pin and/or bolt with a new one; and a detailed inspection of a stripped pin for pitting, corrosion, or galling.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD requires accomplishment of the actions specified in the service bulletin described previously.

Interim Action

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that

supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2004–NM–03–AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the

Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004–05–19 Boeing: Amendment 39–13514. Docket 2004–NM–03–AD.

Applicability: All Model 737–600, –700, –700C, –800, and –900 series airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct damaged rear spar attach pins or front spar attach bolts, which may lead to failure of the bolts or pins, and consequent loss of the stabilizer and loss of controllability of the airplane, accomplish the following:

Initial Inspection

(a) Do a detailed inspection of the rear spar attach pins and front spar attach bolts that attach the horizontal stabilizers to the horizontal stabilizer center section for damage (e.g., pitting, corrosion, no plating (pins only), galling (bolts only), or wear), per the Accomplishment Instructions of Boeing Service Bulletin 737–55–1086, dated December 11, 2003. The inspection must be done at the later of the times specified in the threshold and applicable grace period columns in Table 1 of this AD.

TABLE 1.—INITIAL COMPLIANCE TIME

Threshold	Grace period
Prior to the accumulation of 15,000 total flight cycles or 60 months since the date of issuance of the original Airworthiness Certificate or the date of issuance of the Export Certificate of Airworthiness, whichever occurs first.	For airplanes on which Boeing Service Bulletin 737–55–1074, dated August 15, 2002, has not been done as of the effective date of this AD: Within 90 days after the effective date of this AD.

TABLE 1.—INITIAL COMPLIANCE TIME—
Continued

Threshold	Grace period
	For airplanes on which Boeing Service Bulletin 737–55–1074, dated August 15, 2002, has been done as of the effective date of this AD: Within 24 months or 6,000 flight cycles since accomplishment of the service bulletin.

Note 1: For the purposes of this AD, a detailed inspection is defined as: “An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

Not Damaged and Not A Replaced or Repaired Pin or Bolt: Repetitive Inspections

(b) If no damaged rear spar attach pin or front spar attach bolt is found during any detailed inspection required by paragraph (a) of this AD, and if that pin or bolt has not been replaced per paragraph (c) of this AD or repaired per Boeing Service Bulletin 737–55–1086, dated December 11, 2003, repeat the detailed inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 9,000 flight cycles or 36 months, whichever occurs first, for that pin or bolt only.

Damaged Pin or Bolt: Corrective Actions

(c) If any damaged rear spar attach pin or front spar attach bolt is found during any inspection required by this AD, before further flight, accomplish applicable corrective actions (e.g., repair; replacement of pin and/or bolt with a new one; and detailed inspection of a stripped pin for pitting, corrosion, or galling) per the Accomplishment Instructions of Boeing Service Bulletin 737–55–1086, dated December 11, 2003.

Replaced or Repaired Pin or Bolt: Repetitive Inspections

(d) If any rear spar attach pin or front spar attach bolt has been replaced with a new part per paragraph (c) of this AD, repeat the detailed inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 15,000 flight cycles or 60 months, whichever occurs first, for the replaced pin or bolt only.

(e) If any rear spar attach pin or front spar attach bolt has been repaired per paragraph (c) of this AD, repeat the detailed inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 9,000

flight cycles or 36 months, whichever occurs first, for the replaced pin or bolt only.

Alternative Methods of Compliance

(f)(1) In accordance with 14 CFR 39.19, the Manager, Seattle ACO, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

(2) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings.

Incorporation by Reference

(g) The actions shall be done in accordance with Boeing Service Bulletin 737–55–1086, dated December 11, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(h) This amendment becomes effective on March 24, 2004.

Issued in Renton, Washington, on February 25, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04–4898 Filed 3–8–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Federal Emergency Management Agency

44 CFR Part 65

[Docket No. FEMA–D–7553]

Changes in Flood Elevation Determinations

AGENCY: Federal Emergency Management Agency (FEMA), Emergency Preparedness and Response Directorate, Department of Homeland Security.

ACTION: Interim rule.

SUMMARY: This interim rule lists communities where modification of the Base (1% annual chance) Flood Elevations (BFEs) is appropriate because of new scientific or technical data. New flood insurance premium rates will be calculated from the modified BFEs for new buildings and their contents.

DATES: These modified BFEs are currently in effect on the dates listed in the table and revise the Flood Insurance Rate Map(s) (FIRMs) in effect prior to this determination for each listed community.

From the date of the second publication of these changes in a newspaper of local circulation, any person has ninety (90) days in which to request through the community that the Director reconsider the changes. The modified elevations may be changed during the 90-day period.

ADDRESSES: The modified BFEs for each community are available for inspection at the office of the Chief Executive Officer of each community. The respective addresses are listed in the table below.

FOR FURTHER INFORMATION CONTACT:

Doug Bellomo, P.E., Hazard Identification Section, Emergency Preparedness and Response Directorate, FEMA, 500 C Street, SW., Washington, DC 20472, (202) 646–2903.

SUPPLEMENTARY INFORMATION: The modified BFEs are not listed for each community in this interim rule. However, the address of the Chief Executive Officer of the community where the modified BFE determinations are available for inspection is provided.

Any request for reconsideration must be based upon knowledge of changed conditions, or upon new scientific or technical data.

The modifications are made pursuant to Section 201 of the Flood Disaster Protection Act of 1973, 42 U.S.C. 4105, and are in accordance with the National Flood Insurance Act of 1968, 42 U.S.C. 4001 *et seq.*, and with 44 CFR part 65.

For rating purposes, the currently effective community number is shown and must be used for all new policies and renewals.

The modified BFEs are the basis for the floodplain management measures that the community is required to either adopt or to show evidence of being already in effect in order to qualify or to remain qualified for participation in the National Flood Insurance Program (NFIP).

These modified elevations, together with the floodplain management criteria required by 44 CFR 60.3, are the minimum that are required. They should not be construed to mean that the community must change any existing ordinances that are more stringent in their floodplain management requirements. The community may at any time enact stricter requirements of its own, or pursuant to policies established by other Federal, State or regional entities.