

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all The Boeing Company Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747–400, 747–400D, 747–400F, 747SP, and 747SR series airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 32, Landing gear.

**(e) Unsafe Condition**

This AD was prompted by a report of improper inner diameter grinding of landing gear outer cylinders, resulting in possible heat damage to the outer cylinder of the nose landing gear (NLG), body landing gear (BLG), and wing landing gear (WLG). The FAA is issuing this AD to address heat damage to the outer cylinder of the NLG, BLG, and WLG. The unsafe condition, if not addressed, could cause failure of a principal structural element to sustain its limit load or collapse of the landing gear, which may result in loss of control of the airplane or a runway departure.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified in paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 747–32A2535, dated January 22, 2024, which is referred to in Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024.

**(h) Exceptions to Requirements Bulletin Specifications**

(1) Where the “Boeing Recommended Compliance Time” column in the table under the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024, refers to “the Original Issue date of Requirements Bulletin 747–32A2535 RB,” this AD requires using the effective date of this AD.

(2) Where Appendix B of Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024, specifies two-digit serial numbers, add two leading zeros (e.g., serial number 47 should be 0047).

(3) Where Appendix B of Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024, specifies three-digit serial numbers, add one leading zero (e.g., serial number 109 should be 0109).

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: *AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

(1) For more information about this AD, contact Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone 206–231–3964; email *stefanie.n.roesli@faa.gov*.

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 747–32A2535 RB, dated January 22, 2024.

(ii) [Reserved]

(3) For The Boeing Company material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Boulevard, MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit *www.archives.gov/federal-register/cfr/ibr-locations* or email *fr.inspection@nara.gov*.

Issued on January 16, 2025.

**Suzanne Masterson,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2025–02398 Filed 2–7–25; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2023–1488; Project Identifier AD–2023–00182–T; Amendment 39–22946; AD 2025–02–13]**

**RIN 2120–AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 757–200, –200CB, and –200PF series airplanes. This AD was prompted by a report indicating an operator has found cracks on three Model 757–200PF airplanes at the main deck cargo door cutout forward and aft hinge attachment holes. This AD requires a maintenance record check for repairs at the forward and aft hinge areas of the main deck cargo door cutout; repetitive open-hole high frequency eddy current (HFEC) inspections for cracks in the unrepaired areas of the bear strap, skin, doubler, and upper sill chord at the main deck cargo door forward and aft hinge attachment holes; and applicable corrective actions. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 17, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 17, 2025.

**ADDRESSES:**

**AD Docket:** You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–1488; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1488.

**FOR FURTHER INFORMATION CONTACT:** Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562-627-5238; email: [wayne.ha@faa.gov](mailto:wayne.ha@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 757-200, -200CB, and -200PF series airplanes. The NPRM published in the **Federal Register** on August 4, 2023 (88 FR 51745). The NPRM was prompted by a report of cracks found at the main deck cargo door forward and aft hinge attachment holes. In the NPRM, the FAA proposed to require a maintenance records check for repairs at the forward and aft hinge areas of the main deck cargo door cutout; repetitive open-hole high frequency eddy current (HFEC) inspections for cracks in the unrepaired areas of the bear strap, skin, doubler, and upper sill chord at the main deck cargo door forward and aft hinge attachment holes; and corrective actions. The FAA is issuing this AD to detect and correct cracks in the main deck cargo door hinge area, which could result in reduced structural integrity of the airplane.

The FAA issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 757-200, -200CB, and -200PF series airplanes. The SNPRM published in the **Federal Register** on April 29, 2024 (89 FR 33294). The SNPRM was prompted by a determination that airplanes that have been modified from a passenger to a freighter configuration using VT Mobile Aerospace Engineering (VT MAE) Supplemental Type Certificate (STC) ST03562AT, ST03952AT, or ST04242AT were inadvertently omitted in the NPRM. The SNPRM proposed to add airplanes to the applicability. The

FAA is issuing this AD to address the unsafe condition on these products.

**Discussion of Final Airworthiness Directive**

**Comments**

The FAA received a comment from Boeing who supported the SNPRM without change.

The FAA received additional comments from FedEx Express (FedEx) and VT Mobile Aerospace Engineering (VT MAE). The following presents the comments received on the SNPRM and the FAA's response to each comment.

**Requests To Extend Compliance Time for Certain Airplanes**

FedEx stated that the FAA is placing an unrealistic timeline and burden, without any data, on operators with airplanes modified by VT MAE STC ST03562AT. Within paragraph (g)(1) of the proposed AD and paragraph 3, Compliance, of Boeing Alert Requirements Bulletin 757-53A0106 RB, dated January 3, 2023, the FAA is granting airplanes identified in paragraph (c)(1)(i) of the proposed AD and paragraph 1, Effectivity, of Boeing Alert RB 757-53A0106 RB, dated January 3, 2023, a minimum of 2,800 flight cycles, but the modified VT MAE STC ST03562AT airplanes only get 30 days. FedEx stated that there is no way FedEx can comply with a 30-day maintenance record check on 118 airplanes. This unsubstantiated 30-day compliance time will end up grounding a majority of the FedEx 757-200 fleet. If the FAA keeps this proposed 30-day maintenance record check compliance, FedEx will immediately request approval to extend the compliance time via an alternative method of compliance (AMOC). However, AMOC processing by the FAA could take 30 days to approve and still result in a FedEx 757-200 fleet grounding, even if the FAA agrees to the extension.

Similarly, VT MAE stated that it is impossible for their operators to comply with the requirements within 30 days after the effective date of the AD. This is particularly true for FedEx, which operates 118 Boeing Model 757-200 special freighter airplanes converted per VT MAE STC ST03562AT (14 pallet configuration). VT MAE added that for the airplanes converted per VT MAE STC ST03562AT (14 Pallet Configuration), VT MAE STC ST03952AT (14 pallet configuration), and VT MAE STC ST04242AT (15 pallet configuration), the installation of the main deck cargo door hinge is identical to the Boeing 757-200 Special Freighter (SF) airplanes converted per Boeing STC

ST00916WI-D. The installation of the main deck cargo door hinge in Drawing 657N3270 that is applicable to both Boeing Model 757-200SF series airplanes and modified VT MAE STC airplanes per VT MAE STC ST03562AT (14 pallet configuration), VT MAE STC ST03952AT (14 pallet configuration), and VT MAE STC ST04242AT (15 pallet configuration).

The FAA agrees with the requests. The FAA did not intend to require a maintenance record check for any repair at the forward and aft hinge areas of the main deck cargo door cutout in paragraph (g)(2) of the proposed AD. The FAA has changed paragraph (g)(2) of this AD to require obtaining inspection instructions and applicable repair instructions using a method approved by the FAA. The FAA agrees that the Boeing Model 757 airplanes that have been modified by VT MAE STC ST03562AT (14 pallet configuration), ST03952AT (14 pallet configuration), and ST04242AT (15 pallet configuration) are affected by this AD, because these airplane configurations have the main deck cargo door cutouts.

**Request To Use Work Instructions for Group 2 in Boeing Alert Requirements Bulletin 757-53A0106 RB for Modified VT MAE STC Airplanes**

FedEx referred to paragraph (g)(2) of the proposed AD, which would require obtaining inspection instructions and applicable repair instructions using a method approved by the FAA. Boeing STC ST00916WI-D and VT MAE STC ST03562AT are identical. The VT MAE STC ST03562AT main deck cargo door hinge installation is done in accordance with Boeing Drawing 657N3270, which is applicable to Model Boeing 757-200SF airplanes. According to Boeing Letter FED-SU-1901571 and VT MAE Document No. 337/STR-100, both Boeing and VT MAE own the technical data for VT MAE STC ST03562AT. For repairs, service bulletins, ADs, etc., on Boeing Model 757-200 airplanes, Boeing and VT MAE provide direction and approval to FedEx. As stated in the initial comment period by FedEx and VTMAE, FedEx will be utilizing the Group 2 instructions in Boeing Alert Requirements Bulletin 757-53A0106 RB, dated January 3, 2023, to address the unsafe condition identified in the SNPRM. If this is not acceptable to the FAA, FedEx requested that the FAA provide a method of compliance (MOC) for VT MAE STC ST03562AT airplanes to comply with the SNPRM. According to FedEx and VT MAE (design approval holder), utilizing the Group 2 instructions in Boeing Alert Requirements Bulletin 757-53A0106

RB, dated January 3, 2023, will address the unsafe condition identified in the SNPRM.

Therefore, FedEx requested a change to the requirements for airplanes converted to a freighter configuration using VT MAE STC ST03562AT, ST03952AT, or ST04242AT. Specifically, FedEx requested that those airplanes be required to use instructions for Group 2 in Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023.

Similarly, VT MAE proposed to utilize the inspections, methods, and intervals<sup>1</sup> in Group 2 of Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023, for the modified airplanes per VT MAE STC ST03562AT (14 pallet configuration), VT MAE STC ST03952AT (14 pallet configuration), and VT MAE STC ST04242AT (15 pallet configuration).

The FAA does not agree with the requests. At this time, whether the VT MAE and Boeing STCs are identical in the areas affected by this proposed AD or using the compliance methods and times for Group 2 airplanes adequately address the identified unsafe condition has not been determined. FedEx and VT MAE are to request that the FAA provide a method of compliance (MOC) for airplanes with VT MAE STC ST03562AT (14 pallet configuration), VT MAE STC ST03952AT (14 pallet configuration), and VT MAE STC ST04242AT (15 pallet configuration) to comply with the SNPRM. The FAA has not changed this AD in response to this request.

The FAA does not agree to change paragraph (g)(2) as FedEx specifically requested but has changed paragraph (g)(2) of this AD from a requirement to perform a maintenance record check for

repairs to a requirement to obtain inspection instructions and applicable repair instructions.

#### Request To Base Compliance Time on AD Type

FedEx stated that a 30-day compliance time is designated for emergency ADs. The commenter stated that as paragraph (g)(2) of the proposed AD is written, the FAA is forcing an emergency AD on VT MAE STC ST03562AT airplanes in paragraph (c)(1)(ii) of the proposed AD with no substantiating data, while airplanes identified in paragraph (c)(1)(i) of the proposed AD, Group 2 (Boeing STC ST00916WI–D airplanes) are allowed to maintain the original compliance time (27,500 flight cycles after conversion or 2,800 flight cycles after the AD's effective date, whichever occurs later). FedEx pointed out that the FAA is applying inconsistent compliance times for airplanes modified per Boeing STC ST00916WI–D and airplanes modified by VT MAE STC ST03562AT airplanes—and, as stated in a previous comment, these are identical STCs.

The FAA does not agree with this request. There is no merit to FedEx's statement that a 30-day compliance time is designated for emergency ADs. The compliance time does not determine the type of AD, and the AD type is not limited to a compliance time range. This is not an emergency AD. The 30-day compliance time is to allow for FedEx and VT MAE to request the FAA to provide a method of compliance (MOC) for airplanes modified with VT MAE STCs to comply with the AD. Boeing and VT MAE own the technical data, which can be provided for justification prior to the compliance time ending.

The FAA has not changed this AD in response to this request.

#### Conclusion

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the SNPRM. None of the changes will increase the economic burden on any operator.

#### Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023. This material specifies procedures for a maintenance record check for repairs at the forward and aft hinge areas of the main deck cargo door cutout; repetitive open-hole HFEC inspections for cracks in the unrepaired areas of the bear strap, skin, doubler, and upper sill chord at the main deck cargo door forward and aft hinge attachment holes; and corrective actions including obtaining and following procedures for alternative inspections and crack repairs.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### Costs of Compliance

The FAA estimates that this AD affects 564 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

#### ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Maintenance record check .....	1 work-hour * × \$85 per hour = \$85 .....	\$0	\$85 .....	\$47,940.
HFEC inspections .....	26 work-hours × \$85 per hour = \$2,210, per inspection cycle.	0	\$2,210 per inspection cycle.	\$1,246,440 per inspection cycle.

\* The time to do the maintenance record check will vary by operator but would likely take no more than 1 work-hour per airplane.

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

<sup>1</sup> Initial compliance time of 27,500 flight cycles from the freighter conversion date or 2,800 flight

cycles after the effective date of the AD, with

repetitive inspections at intervals not to exceed 7,000 flight cycles.

develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2025–02–13 The Boeing Company:

Amendment 39–22946; Docket No. FAA–2023–1488; Project Identifier AD–2023–00182–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective March 17, 2025.

#### (b) Affected ADs

None.

#### (c) Applicability

(1) This AD applies to The Boeing Company Model 757–200, –200CB, and –200PF series airplanes specified in paragraph (c)(1)(i) or (ii) of this AD, certificated in any category.

(i) Airplanes identified in Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023.

(ii) Airplanes converted to a freighter configuration using VT MAE Supplemental Type Certificate (STC) ST03562AT, ST03952AT, or ST04242AT.

(2) Installation of STC ST01518SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Unsafe Condition

This AD was prompted by a report indicating an operator has found cracks on three Model 757–200PF airplanes at the main deck cargo door cutout forward and aft hinge attachment holes. The FAA is issuing this AD to detect and correct cracks in the main deck cargo door hinge area. Undetected cracks in the main deck cargo door hinge area could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

(1) For the airplanes identified in paragraph (c)(1)(i) of this AD: Except as specified by paragraph (h) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023.

**Note 1 to paragraph (g)(1):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757–53A0106, dated January 3, 2023, which is referred to in Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023.

(2) For the airplanes identified in paragraph (c)(1)(ii) of this AD: Within 30 days after the effective date of this AD, obtain inspection instructions and applicable repair instructions using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA. Comply with all applicable instructions at the time specified in the instructions.

#### (h) Exceptions to Service Information Specifications

(1) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023, use the phrase the original issue date of Requirements Bulletin 757–53A0106 RB, this AD requires using the effective date of this AD.

(2) Where Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023, specifies contacting Boeing for repair instructions or for alternative inspections, this AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions using a method approved

in accordance with the procedures specified in paragraph (i) of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Related Information

(1) For more information about this AD, contact Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562–627–5238; email: [wayne.ha@faa.gov](mailto:wayne.ha@faa.gov).

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757–53A0106 RB, dated January 3, 2023.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations), or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 21, 2025.

**Suzanne Masterson,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2025-02395 Filed 2-7-25; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2024-2023; Project Identifier MCAI-2023-01246-T; Amendment 39-22934; AD 2025-02-01]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This AD was prompted by uncommanded horizontal stabilizer motion during several in-service events caused by a problem with the trim switch wiring. This AD requires installing the pitch/roll trim switch relays. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 17, 2025.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 17, 2025.

#### ADDRESSES:

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2023; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### *Material Incorporated by Reference:*

- For Bombardier material identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; phone 514-855-2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); website [bombardier.com](https://www.bombardier.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2023.

#### FOR FURTHER INFORMATION CONTACT:

Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model BD-100-1A10 airplanes. The NPRM published in the **Federal Register** on August 21, 2024 (89 FR 67577). The NPRM was prompted by AD CF-2023-77, dated December 7, 2023, issued by Transport Canada, which is the aviation authority for Canada (Transport Canada AD CF-2023-77) (referred to after this as the MCAI). The MCAI states that during several in-service events, following a STAB TRIM FAULT advisory message and an autopilot disconnect, both pilot and co-pilot commands to trim the horizontal stabilizer nose-up resulted in a nose-down movement of the horizontal stabilizer. In some events, the horizontal stabilizer reached the full travel nose-down position before the crew recognized the nature of the problem, and quickly recovered control of the airplane for safe landing. An issue with the trim switch wiring installation was identified as the main cause of the in-service unintended horizontal stabilizer motion events. The current wiring of the system is such that, if trim is enabled via the copilot-side trim switch, and the pilot-side trim switch malfunctions, it is possible for trim to move uncommanded or opposite to the intended direction.

In the NPRM, the FAA proposed to require installing the pitch/roll trim switch relays. The FAA is issuing this AD to address the problem with the trim switch wiring, which is the main cause of the uncommanded horizontal stabilizer motion. The unsafe condition, if not addressed, could result in increased crew workload and reduced safety margins, and if the flightcrew is unable to regain control of the horizontal stabilizer, would result in loss of control of the airplane and high control forces.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2023.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received a comment from an individual. The following presents the comment received on the NPRM and the FAA's response to that comment.

#### Request To Develop a Preventive Maintenance Program To Assess Affected Airplanes

The commenter suggested that Bombardier should develop a preventive maintenance program to assess if the proposed AD would apply to the same airplanes of different serial numbers. The commenter referenced another AD (PA-28 wing spar), pointing out that operators were only required to repair the affected part if damage or failure was detected. The commenter noted that a preventive replacement of the affected part was not required, and that is something that Bombardier should consider researching. The commenter further asserted that this would only be considered if engineers and researchers can show with evidence that periodic inspections outweigh the cost of a preventive repair.

The FAA does not agree. The NPRM specifically stated that "The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design." Bombardier has confirmed that airplanes having serial number 20937 and subsequent, also subject to the unsafe condition addressed in this AD, were modified in production. Further, this AD bypasses any type of preventive maintenance inspection prior to modifying the trim switches because Bombardier has determined that the trim switches have a problem with the wiring installation, which is why all affected trim switches must be rewired (not simply inspected and repaired only if damage or failure is found). No change has been made to this AD in this regard.

#### Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD