

Proposed Rules

Federal Register

Vol. 79, No. 108

Thursday, June 5, 2014

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0072; Directorate Identifier 2013-NE-04-AD]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Division Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede airworthiness directive (AD) 2013-15-09, which applies to all Pratt & Whitney Division (PW) PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engine models with certain second-stage high-pressure turbine (HPT) air seals, installed. AD 2013-15-09 currently requires initial and repetitive inspections for cracks in second-stage HPT air seals. Since we issued AD 2013-15-09, we received reports of cracking in the original location on two additional part numbers (P/Ns) as well as reports of through-cracks in a new location in the second-stage HPT air seal. PW has developed a redesigned second-stage HPT air seal that addresses the cracking condition in both locations. This proposed AD would expand the applicability of AD 2013-15-09 to include additional P/Ns, require replacement of the mating hardware if the second-stage HPT air seal is found with a through-crack, and add mandatory terminating action to the repetitive inspections. We are proposing this AD to prevent failure of the second-stage HPT air seal, which could lead to uncontained engine failure and damage to the airplane.

DATES: We must receive comments on this proposed AD by August 4, 2014.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Pratt & Whitney Division, 400 Main St., East Hartford, CT 06108; phone: (860) 565-8770; fax: (860) 565-4503. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2013-0072; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

James Gray, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7742; fax: (781) 238-7199; email: james.e.gray@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-0072; Directorate Identifier 2013-NE-04-AD" at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On July 19, 2013, we issued AD 2013-15-09, Amendment 39-17525 (78 FR 49111, August 13, 2013), ("AD 2013-15-09"), for all PW PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engine models with second-stage HPT air seal, P/N 54L041, installed. AD 2013-15-09 requires initial and repetitive inspections for cracks in second-stage HPT air seals and replacement of air seals that fail inspection. AD 2013-15-09 resulted from the discovery of cracks in second-stage HPT air seals. We issued AD 2013-15-09 to prevent failure of the second-stage HPT air seal, which could lead to uncontained engine failure and damage to the airplane.

Actions Since AD 2013-15-09 Was Issued

Since we issued AD 2013-15-09, we received multiple reports of through-cracks in a different location on second-stage HPT air seal, P/N 50L041, and reports of cracking in the original location in two additional second-stage HPT air seal P/Ns, 50L960 and 50L976. The cracking in the two additional P/Ns requires that they be added to the applicability of this proposed AD. PW has developed a redesigned second-stage HPT air seal that corrects the cracking condition in both locations.

The new cracking location in the second-stage HPT air seal, P/N 50L041, is in the front forward fillet radius. PW determined that through-cracks in the front forward fillet radius increase the stresses in the mating hardware in the HPT rotor and that increased stress reduces the life of the first-stage HPT hub, second-stage HPT hub, and second-stage HPT blade retaining plate. Therefore, the first-stage HPT hub, second-stage HPT hub, and second-stage

HPT blade retaining plate must be removed from service if the second-stage HPT air seal, P/N 50L041, is found with a through-crack.

Relevant Service Information

We reviewed PW Alert Service Bulletin (ASB) No. PW4G-112-A72-330, Revision 2, dated July 11, 2013, which describes procedures for inspecting the second-stage HPT air seal for cracks and PW Service Bulletin (SB) No. PW4G-112-72-332, Revision 2, dated April 9, 2014, which describes procedures for replacing the second-stage HPT air seal.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would expand the population of affected P/Ns, require removal from service of two newly identified P/Ns, require replacement of the mating hardware if the second-stage HPT air seal is found with a through-crack, and add mandatory terminating action to the repetitive inspection requirements.

Costs of Compliance

We estimate that this proposed AD would affect 116 engines installed on airplanes of U.S. registry. We also estimate that it would take about 5 hours to perform the inspection required by this proposed AD. The average labor rate is \$85 per hour. We estimate that two engines will also require replacement of the first-stage HPT hub, second-stage HPT hub, and second-stage HPT blade retaining plate. We estimate that parts would cost about \$698,920 per engine. Based on these figures, we estimate the total cost of this proposed AD to U.S. operators to be \$23,420,020.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2013-15-09, Amendment 39-17525 (78 FR 49111, August 13, 2013), and adding the following new AD:

Pratt & Whitney Division: Docket No. FAA-2013-0072; Directorate Identifier 2013-NE-04-AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by August 4, 2014.

(b) Affected ADs

This AD supersedes AD 2013-15-09, Amendment 39-17525 (78 FR 49111, August 13, 2013).

(c) Applicability

This AD applies to all Pratt & Whitney Division (PW) PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engine models with second-stage high-pressure turbine (HPT) air seal, part number (P/N) 54L041, 50L960, or 50L976, installed.

(d) Unsafe Condition

This AD was prompted by additional reports of cracking in the second-stage HPT air seal. We are issuing this AD to prevent failure of the second-stage HPT air seal, which could lead to uncontained engine failure and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

- (1) At the next piece-part exposure after the effective date of this AD, do the following:

- (i) Remove from service second-stage HPT air seals, P/N 50L960, 50L976, and 50L041.

- (ii) Fluorescent-penetrant inspect (FPI) second-stage HPT air seal, P/N 50L041, for a through-crack in the front forward fillet radius.

- (iii) If a through-crack in the front forward fillet radius is found, remove the first-stage HPT hub, second-stage HPT hub, and second-stage HPT blade retaining plate from service. Do not reinstall the first-stage HPT hub, second-stage HPT hub, or second-stage HPT blade retaining plate into any engine.

- (2) For engines with second-stage HPT air seals, P/N 50L041, installed, perform initial and repetitive inspections for cracks on-wing until the part is removed from the engine as follows:

- (i) Perform an initial eddy current inspection (ECI) for cracks prior to reaching 2,200 cycles-since-new or within 100 cycles-in-service after the effective date of this AD, whichever occurs later.

- (ii) Thereafter, repeat the ECI every 1,200 cycles since last inspection, or fewer, depending on the results of the inspection.

- (iii) Use section 4.0 of the appendix of PW Alert Service Bulletin (ASB) No. PW4G-112-A72-330, Revision 2, dated July 11, 2013, to perform the inspection and use paragraph 8 of the Accomplishment Instructions of PW ASB No. PW4G-112-A72-330, Revision 2, dated July 11, 2013, to disposition the results of the inspection.

(f) Installation Prohibition

After the effective date of this AD, do not install any second-stage HPT air seal P/N 50L041, P/N 50L960, or P/N 50L976 into any engine.

(g) Definitions

- (1) For the purpose of this AD, piece-part exposure is when the second-stage HPT air seal is removed from the engine and fully disassembled.

- (2) For the purpose of this AD, a through-crack is a crack that has propagated through

the thickness of the part and can be seen on both the inner diameter and outer diameter of the front forward fillet radius.

(h) Credit for Previous Actions

(1) If you performed an ECI of the second-stage HPT air seal before the effective date of this AD, using PW ASB No. PW4G-112-A72-330, Revision 1, dated February 14, 2013, or earlier version, you have met the requirements of paragraph (e)(2)(i) of this AD.

(2) If you performed an in-shop FPI of the second-stage HPT air seal before the effective date of this AD, you have met the requirements of paragraph (e)(2)(i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(j) Related Information

(1) For more information about this AD, contact James Gray, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7742; fax: (781) 238-7199; email: james.e.gray@faa.gov.

(2) For service information identified in this AD, contact Pratt & Whitney Division, 400 Main St., East Hartford, CT 06108; phone: (860) 565-8770; fax: (860) 565-4503.

(3) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

Issued in Burlington, Massachusetts, on May 28, 2014.

Colleen M. D'Alessandro,

Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2014-13024 Filed 6-4-14; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 49

[EPA-HQ-OAR-2011-0151; FRL-9910-71-OAR]

RIN 2060-AS27

Managing Emissions From Oil and Natural Gas Production in Indian Country

AGENCY: Environmental Protection Agency (EPA).

ACTION: Advance notice of proposed rulemaking.

SUMMARY: The purpose of this Advance Notice of Proposed Rulemaking (ANPR) is to solicit broad feedback on the most effective and efficient means of implementing the Environmental

Protection Agency's (EPA) Indian Country Minor New Source Review program for sources in the oil and natural gas production segment of the oil and natural gas sector. In particular, this ANPR discusses potential new source permitting approaches to address emissions from proposed new and modified oil and natural gas production activities. One approach is a general permit, which could serve as a streamlined permitting approach for addressing emissions from new and modified minor sources and minor modifications at major sources under the Indian Country Minor NSR rule. Another approach is a Federal Implementation Plan, which could address emissions from new and modified minor sources and minor modifications at major sources. Other possible approaches include a permit by rule, which is another streamlined permitting approach. The EPA is requesting comments on all available new source permitting approaches and will take this feedback into consideration in developing a notice of proposed rulemaking for this sector under the Indian Country Minor NSR program.

In addition, while the focus of this ANPR is on permitting approaches for proposed new oil and natural gas production activities, the EPA believes that managing emissions from existing oil and natural gas sources in Indian country would result in greater consistency with surrounding state requirements. Addressing existing sources may be particularly important given the significant activity associated with the sector in Indian country and the resultant need to protect public health, balanced with tribes' inherent sovereignty and interest in promoting economic development. If the EPA decides to address existing oil and natural gas production sources, then we will be interested in considering comments regarding whether a FIP should be the mechanism used to establish permitting requirements for new and existing sources, especially in areas where surrounding states regulate existing sources.

DATES: Comments must be received on or before July 21, 2014.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-HQ-OAR-2011-0151, by one of the following methods:

- www.regulations.gov: Follow the on-line instructions for submitting comments.
- Email: a-and-r-docket@epa.gov. Include Docket ID No. EPA-HQ-OAR-

2011-0151 in the subject line of the message.

Fax: (202) 566-9744, attention Docket ID No. EPA-HQ-OAR-2011-0151.

Mail: Attention Docket ID No. EPA-HQ-OAR-2011-0151, EPA, Mailcode: 6102T, 1200 Pennsylvania Ave. NW., Washington, DC 20460. Please include a total of two copies.

Hand Delivery: The EPA Docket Center, Public Reading Room, EPA West, Room 3334, 1301 Constitution Ave. NW., Washington, DC 20460, Attention Docket ID No. EPA-HQ-OAR-2011-0151. Such deliveries are only accepted during the Docket's normal hours of operation, and special arrangements should be made for deliveries of boxed information.

Instructions: Direct your comments to Docket ID No. EPA-HQ-OAR-2011-0151. The EPA's policy is that all comments received will be included in the public docket without change and may be made available online at www.regulations.gov, including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through www.regulations.gov or email. The www.regulations.gov Web site is an "anonymous access" system, which means the EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an email comment directly to the EPA without going through www.regulations.gov, your email address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the internet. If you submit an electronic comment, the EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If the EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, the EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses. For additional instructions on submitting comments, go to Section I.C of the **SUPPLEMENTARY INFORMATION** section of this document.

Docket: The EPA has established a docket for this action under Docket ID Number EPA-HQ-OAR-2011-0151. All documents in the docket are listed in the www.regulations.gov index. Although listed in the index, some information is not publicly available,