

information and findings of fact, if any. The revoking official may extend that period for good cause.

(b) The revoking official sends you written notice, pursuant to § 103.6, that the official decided either—

(1) Not to revoke your privilege to conduct business with SBA; or

(2) To revoke your privilege to conduct business with SBA. In this event, the notice:

(i) Refers to the Notice of Proposed Revocation;

(ii) Specifies the reasons for your revocation; and

(iii) States the period of your revocation, including the effective dates.

**§ 103.35 May I ask the revoking official to reconsider a decision to revoke my privilege to conduct business with SBA?**

Yes, you may ask the revoking official to reconsider the revocation decision or to reduce the time period or scope of the revocation. However, you must put your request in writing and support it with documentation.

**§ 103.36 What factors may influence the revoking official during reconsideration?**

The revoking official may reduce or terminate your revocation based on—

(a) Newly discovered material evidence not previously available;

(b) A reversal of the conviction or civil judgment upon which your revocation was based;

(c) A bona fide change in ownership or management;

(d) Elimination of other causes for which the revocation was imposed; or

(e) Other reasons the revoking official finds appropriate.

**§ 103.37 May the revoking official extend a revocation?**

(a) Yes, the revoking official may extend a revocation for an additional period, if that official determines that an extension is necessary to protect the public interest.

(b) However, the revoking official may not extend a revocation solely on the basis of the facts and circumstances upon which the initial revocation action was based.

(c) If the revoking official decides that a revocation for an additional period is necessary, the revoking official must follow the applicable procedures in this part to extend the revocation, at §§ 103.21 through 103.36 of this part.

**§ 103.38 May the Agency impute conduct of one person to another?**

For purposes of actions taken under this rule, SBA may impute conduct as follows:

(a) Conduct imputed from an individual to an organization. SBA may

impute the fraudulent, criminal, or other improper conduct of any officer, director, shareholder, partner, employee, or other individual associated with an organization, to that organization when the improper conduct occurred in connection with the individual's performance of duties for or on behalf of that organization, or with the organization's knowledge, approval or acquiescence. The organization's acceptance of the benefits derived from the conduct is evidence of knowledge, approval or acquiescence.

(b) Conduct imputed from an organization to an individual, or between individuals. SBA may impute the fraudulent, criminal, or other improper conduct of any organization to an individual, or from one individual to another individual, if the individual to whom the improper conduct is imputed either participated in, had knowledge of, or reason to know of the improper conduct.

(c) Conduct imputed from one organization to another organization. SBA may impute the fraudulent, criminal, or other improper conduct of one organization to another organization when the improper conduct occurred in connection with a partnership, joint venture, joint application, association or similar arrangement, or when the organization to whom the improper conduct is imputed has the power to direct, manage, control or influence the activities of the organization responsible for the improper conduct. Acceptance of the benefits derived from the conduct is evidence of knowledge, approval or acquiescence.

**PART 124—8(a) BUSINESS DEVELOPMENT/SMALL DISADVANTAGED BUSINESS STATUS DETERMINATIONS**

■ 13. The authority citation for part 124 is revised to read as follows:

**Authority:** 15 U.S.C. 634(b)(6), 636(j), 637(a), 637(d); 42 U.S.C. 9815; Pub. L. 99–661; Pub. L. 100–656; sec. 1207, Pub. L. 101–37; Pub. L. 101–574; sec. 8021, Pub. L. 108–87.

**§ 124.4 [Amended]**

■ 14. Amend § 124.4 by removing paragraph (c) and redesignating paragraph (d) as paragraph (c).

**PART 134—RULES OF PROCEDURE GOVERNING CASES BEFORE THE OFFICE OF HEARINGS AND APPEALS**

■ 15. The authority citation for part 134 continues to read as follows:

**Authority:** 5 U.S.C. 504; 15 U.S.C. 632, 634(b)(6), 637(a), 648(l), 656(i), and 687(c);

E.O. 12549, 51 FR 6370, 3 CFR, 1986 Comp., p. 189.

**§ 134.102 [Amended]**

■ 16. Amend § 134.102 by removing and reserving paragraphs (c) and (p).

**Maria Contreras-Sweet,**  
*Administrator.*

[FR Doc. 2014–22521 Filed 10–14–14; 8:45 am]

**BILLING CODE 8025–01–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2014–0751; Directorate Identifier 2013–NM–188–AD]

**RIN 2120–AA64**

**Airworthiness Directives; Kidde Graviner**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Kidde Graviner hand-operated fire extinguishers as installed on, but not limited to, various transport and small airplanes. This proposed AD was prompted by a report that a fire extinguisher failed to operate when the activation lever was pressed. This proposed AD would require modifying the affected fire extinguishers. We are proposing this AD to prevent fire extinguishers from failing to operate in the event of a fire, which could jeopardize occupants' safety and continuation of safe flight and landing.

**DATES:** We must receive comments on this proposed AD by December 1, 2014.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Kidde

Graviner Limited, Mathisen Way, Colnbrook, Slough, Berkshire, SL3 0HB, United Kingdom; telephone +44 (0) 1753 583245; fax +44 (0) 1753 685040. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0751; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Caspar Wang, Aerospace Engineer, Boston Aircraft Certification Office (ACO), FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7799; fax: 781-238-7170; email: [caspar.wang@faa.gov](mailto:caspar.wang@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2014-0751; Directorate Identifier 2013-NM-188-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2012-0037, dated March 9, 2012 (referred to after this as the Mandatory Continuing

Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Kidde Graviner hand-operated fire extinguishers as installed on, but not limited to, various transport and small airplanes. The MCAI states:

An instance occurred where an operator tried to use the fire extinguisher, but the extinguisher failed to operate when the activation lever was pressed.

This condition, if not detected and corrected, could lead, in case of need to use the device to extinguish a fire on an aircraft, to jeopardize the occupants' safety as well as the flight continuation and safe landing.

The part manufacturer Kidde Graviner has introduced a design change to remove the root cause of the possible failure.

This AD requires to modify all potentially defective fire extinguishers [including applying adhesive to the gland nut].

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0751.

#### Relevant Service Information

Kidde Graviner has issued Alert Service Bulletin A26-081, Revision 1, dated January 31, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Costs of Compliance

We estimate that this proposed AD affects 400 appliances installed on, but not limited to, various transport and small airplanes of U.S. registry.

We also estimate that it would take about 25 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be up to \$850,000, or \$2,125 per appliance.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this proposed regulation:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Kidde Gravier:** Docket No. FAA-2014-0751; Directorate Identifier 2013-NM-188-AD.

**(a) Comments Due Date**

We must receive comments by December 1, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Kidde Gravier hand-operated fire extinguishers having part numbers 56412-001 (34H), 56411-001 (35H), and 56412-002 (38H). These fire extinguishers may be installed on, but not limited to, various transport and small airplanes, certificated in any category, specified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), (c)(5), and (c)(6) of this AD.

(1) BAE Systems (Operations) Limited Model ATP airplanes.

(2) BAE Systems (Operations) Limited Model 4101 airplanes.

(3) EADS CASA (Type Certificate previously held by Construcciones Aeronauticas, S.A.) Model C-212-CB, C-212-CC, C-212-CD, C-212-CE, C-212-CF, C-212-DE, and C-212-DF airplanes.

(4) Fokker Services B.V. Model F.27 Mark 050, 100, 200, 300, 400, 500, 600, and 700 airplanes.

(5) Short Brothers PLC Model SD3-60 SHERPA, SD3-SHERPA, SD3-30, and SD3-60 airplanes.

(6) SHORT BROTHERS & HARLAND LTD SC-7 Series 2 and SC-7 Series 3 airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 26, Fire Protection.

**(e) Reason**

This AD was prompted by a report that a fire extinguisher failed to operate when the activation lever was pressed. We are issuing this AD to prevent fire extinguishers from failing to operate in the event of a fire, which could jeopardize occupants' safety and continuation of safe flight and landing.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Modification**

Within 6 months after the effective date of this AD, modify all Kidde Gravier hand-operated fire extinguishers having part numbers 56412-001 (34H), 56411-001 (35H), and 56412-002 (38H), in accordance with the Accomplishment Instructions of Kidde Gravier Alert Service Bulletin A26-081, Revision 1, dated January 31, 2012.

**(h) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Kidde Gravier Alert Service Bulletin A26-081, dated August 23, 2011, which is not incorporated by reference in this AD.

**(i) Parts Installation Prohibition**

As of the effective date of this AD, no person may install any Kidde Gravier hand-operated fire extinguisher having part number 56412-001 (34H), 56411-001 (35H), or 56412-002 (38H) on any airplane unless the fire extinguisher has been modified as specified in paragraph (g) of this AD.

**(j) Other FAA AD Provision**

The following provision for Alternative Methods of Compliance (AMOCs) also applies to this AD: The manager of the office having certificate responsibility for the affected product has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. The Manager, Boston Aircraft Certification Office (ACO), FAA, will coordinate requests for approval of AMOCs with the manager of the appropriate office for the affected product. Send information to ATTN: Caspar Wang, Aerospace Engineer, Boston Aircraft Certification Office (ACO), FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7799; fax: 781-238-7170; email: [caspar.wang@faa.gov](mailto:caspar.wang@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

**(k) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) Airworthiness Directive 2012-0037, dated March 9, 2012, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0751.

(2) For service information identified in this AD, contact Kidde Gravier Limited, Mathisen Way, Colnbrook, Slough, Berkshire, SL3 0HB, United Kingdom; telephone +44 (0) 1753 583245; fax +44 (0) 1753 685040. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 23, 2014.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-24556 Filed 10-15-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2014-0748; Directorate Identifier 2014-NM-013-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Airbus Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Airbus Model A318, A319, and A321 series airplanes; and Model A320-211, -212, -214, -231, -232, and -233 airplanes. This proposed AD was prompted by reports of wear of the trimmable horizontal stabilizer actuator (THSA). This proposed AD would require repetitive inspections of the THSA for damage, and replacement if necessary; and replacement of the THSA after reaching a certain life limit. We are proposing this AD to detect and correct wear on the THSA, which would reduce the remaining life of the THSA, possibly resulting in premature failure and consequent reduced control of the airplane.

**DATES:** We must receive comments on this proposed AD by December 1, 2014.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—ELAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport