

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Staff, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) AMOCs approved for AD 2003-07-06 are not approved for this AD.

(3) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(4) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Refer to MCAI Civil Aviation Authority AD No. G-2004-0029, dated December 20, 2004; BAE Systems British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JA030644, dated October 6, 2003; BAE Systems British Aerospace Jetstream Mandatory Service Bulletin 32-JA020741, Original Issue: November 2, 2002; APPH Ltd. Service Bulletin 32-76, Revision 1, dated August 2003; and APPH Ltd. Service Bulletin 32-76, pages 1, 2, and 4 through 7, dated October 2002; and page 3, Erratum 1, dated November 2002, for related information.

Material Incorporated by Reference

(j) You must use APPH Ltd. Service Bulletin 32-76, Revision 1, dated August 2003; as referenced in BAE Systems British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JA030644, dated October 6, 2003; and APPH Ltd. Service Bulletin 32-76, pages 1, 2, and 4 through 7, dated October 2002; and page 3, Erratum 1, dated November 2002; as referenced in BAE Systems British Aerospace Jetstream Mandatory Service Bulletin 32-JA020741, Original Issue: November 2, 2002; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of APPH Ltd. Service Bulletin 32-76, Revision 1, dated August 2003; as referenced in BAE Systems British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JA030644, dated October 6, 2003, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On May 22, 2003 (68 FR 16195, April 3, 2003), the Director of the Federal Register approved the incorporation by reference of APPH Ltd. Service Bulletin 32-76, pages 1, 2, and 4 through 7, dated October 2002; and page 3, Erratum 1, dated November 2002, as referenced in BAE Systems British Aerospace Jetstream Mandatory Service Bulletin 32-JA020741, Original Issue: November 2, 2002.

(3) For service information identified in this AD, contact BAE Systems, Prestwick International Airport, Ayshire, KA9 2RW, Scotland; telephone: (01292) 675207; fax: (01292) 675704.

(4) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 9, 2007.

Charles L. Smalley,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 07-2522 Filed 5-21-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26112; Directorate Identifier 2006-NE-35-AD; Amendment 39-14837; AD 2006-24-08]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Canada (P&WC) PW535A Turbofan Engines; Correction

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting airworthiness directive (AD) 2006-24-08. That AD applies to Pratt & Whitney Canada (P&WC) PW535A turbofan engines. We published that AD in the **Federal Register** on December 4, 2006 (71 FR 70284). The fuel manifold part number (P/N) 3025267-01 listed in paragraph (c) is incorrect. This document corrects that P/N. In all other respects, the original document remains the same.

EFFECTIVE DATE: Effective May 22, 2007.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA, 01803; telephone (781) 238-7178; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: On December 4, 2006 (71 FR 70284), we published a final rule AD, FR Doc. E6-20204, in the **Federal Register**. That AD applies to P&WC PW535A turbofan engines. We need to make the following correction:

§ 39.13 [Corrected]

On page 70286, in the second column, in paragraph (c), in the fourth line, “3025267-01” is corrected to read “3052627-01”.

Issued in Burlington, Massachusetts, on May 14, 2007.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E7-9719 Filed 5-21-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-22430; Directorate Identifier 2005-NE-34-AD; Amendment 39-15063; AD 2007-11-06]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Arrius 2F Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) for Turbomeca Arrius 2F turbofan engines. That AD currently requires removing from service certain serial number (SN) fuel control units (FCUs) or replacing the constant delta pressure (delta P) diaphragm in those FCUs. This AD requires replacing all FCUs not incorporating modification Tf 55 with FCUs that incorporate modification Tf 55. This AD results from the European Aviation Safety Agency (EASA) and Turbomeca expanding the applicability to the full population of FCUs installed on Arrius 2F turbofan engines. FCUs not incorporating modification Tf 55 are susceptible to having an improperly assembled constant delta P diaphragm. We are issuing this AD to prevent an uncommanded engine in-flight shutdown on a single-engine helicopter, resulting in a forced autorotation landing or an accident.

DATES: This AD becomes effective June 26, 2007.

ADDRESSES: You can get the service information identified in this AD from