

Rules and Regulations

Federal Register

Vol. 79, No. 116

Tuesday, June 17, 2014

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0340; Directorate Identifier 2014-NM-084-AD; Amendment 39-17867; AD 2014-12-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Airbus Model A310 series airplanes. This AD requires inspections of the external area of the aft cargo door sill beam for cracking, and repair if necessary. This AD was prompted by reports of fatigue cracks on the cargo door sill beam, lock fitting, and torsion box plate. We are issuing this AD to detect and correct fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, which could result in the loss of the door locking function and, subsequently, complete loss of the cargo door in flight with the risk of rapid decompression.

DATES: This AD becomes effective July 2, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 2, 2014.

We must receive comments on this AD by August 1, 2014.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0340; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent

for the Member States of the European Community, has issued EASA Emergency Airworthiness Directive 2014-0097-E, dated April 23, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Airbus Model A310 series airplanes. The MCAI states:

During accomplishment of Maintenance Review Board Report (MRBR) task 531625-01-1 on an A300-600 aeroplane having accumulated more than 25,000 flight cycles (FC) since aeroplane first flight, multiple fatigue cracks were found on the following parts:

- Aft cargo door sill beam Part Number (P/N) A53973085210
- Lock fitting P/N A53978239002
- Torsion box plate P/N A53973318206.

Prompted by these findings, a stress analysis was performed during which it was discovered that there is no dedicated scheduled maintenance task to inspect the affected area for fatigue damage.

The loss of more than one lock fitting could lead to loss of the door locking function and, subsequently, complete loss of the cargo door in flight with associated risk of rapid decompression.

To address this unsafe condition, Airbus issued Alert Operators Transmission (AOT) A53W005-14 providing instructions for inspection of the affected area.

For the reason described above, this [EASA] AD requires repetitive ultrasonic inspections or detailed inspections (DET) for cracking of the aft cargo door sill beam external area, or a one-time High Frequency Eddy Current (HFEC) inspection [for cracking] of the aft cargo door sill beam internal structure and, depending on findings, accomplishment of corrective action(s) [e.g. repair].

This [EASA] AD is considered an interim measure and further AD action may follow.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0340.

Relevant Service Information

Airbus has issued Alert Operators Transmission A53W005-14, dated April 22, 2014. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Interim Action

We consider this AD interim action. If final action is later identified, we might consider further rulemaking then.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate could result in the loss of the door locking function and subsequently, complete loss of the cargo door in flight with the risk of rapid decompression. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0340; Directorate Identifier 2014-NM-084-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 170 airplanes of U.S. registry.

We also estimate that it will take about 11 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$158,950, or \$935 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120-0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-12-06 Airbus: Amendment 39-17867. Docket No. FAA-2014-0340; Directorate Identifier 2014-NM-084-AD.

(a) Effective Date

This AD becomes effective July 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), and (c)(5) of this AD, certificated in any category, all certified models, all manufacturer serial numbers on which Airbus Modification 05438 has been embodied in production, except those on which Modification 12046 has been embodied in production.

(1) Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.

(2) Airbus Model A300 B4-605R and B4-622R airplanes.

(3) Airbus Model A300 F4-605R and F4-622R airplanes.

(4) Airbus Model A300 C4-605R Variant F airplanes.

(5) Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of fatigue cracks on the cargo door sill beam, lock fitting, and torsion box plate. We are issuing this AD to detect and correct fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, which could result in the loss of the door locking function and subsequently, complete loss of the cargo door in flight with the risk of rapid decompression.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Repair

(1) Within the compliance time identified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD, as applicable, do an ultrasonic inspection or detailed inspection of the aft cargo door sill beam external area for cracking, in accordance with Airbus Alert Operators Transmission (AOT) A53W005-14, dated April 22, 2014. Repeat the inspection thereafter at intervals not to exceed 275 flight cycles.

(i) For airplanes that have accumulated 30,000 flight cycles or more since the airplane's first flight as of the effective date of this AD: Within 50 flight cycles after the effective date of this AD.

(ii) For airplanes that have accumulated 18,000 flight cycles or more, but less than 30,000 flight cycles since the airplane's first flight as of the effective date of this AD: Within 275 flight cycles after the effective date of this AD.

(iii) For airplanes that have accumulated less than 18,000 flight cycles since the airplane's first flight as of the effective date of this AD: Before exceeding 18,275 flight cycles since the airplane's first flight.

(2) If any crack is found during any inspection required by paragraph (g)(1) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent, or the Design Approval Holder (DAH) with EASA design organization approval).

(h) Optional Terminating Action

Accomplishment of the high frequency eddy current (HFEC) inspection for cracking in accordance with Airbus AOT A53W005-14, dated April 22, 2014, terminates the repetitive inspections required by paragraph (g)(1) of this AD for that airplane. If any cracking is found during the HFEC inspection, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA (or

its delegated agent, or the DAH with EASA design organization approval).

(i) Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g)(1) of this AD to Airbus as specified in paragraph 7., "Reporting" of the Airbus AOT A53W005-14, dated April 22, 2014, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include inspection results, including no findings.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or the DAH with a State of Design Authority's design organization approval, as applicable). You are required to ensure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments

concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Emergency Airworthiness Directive 2014-0097-E, dated April 23, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0340.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A53W005-14, dated April 22, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on: June 4, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-13832 Filed 6-16-14; 8:45 am]

BILLING CODE 4910-13-P