

(c) *Layout.* Both sides of the application shall contain space designated "For Official Use Only."

* * * * *

6. Amend § 9428.6 by revising paragraph (a) introductory text to read as follows:

§ 9428.6 Chief State Election Official.

(a) The following information shall be included for each state in the State-specific instructions on the form:

* * * * *

§ 9428.7 [Amended]

7. Remove paragraph (c) of § 9428.7.

Donetta L. Davidson,

Chair, U.S. Election Assistance Commission.

[FR Doc. 2010-19514 Filed 8-6-10; 8:45 am]

BILLING CODE 6820-KF-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0778; Directorate Identifier 2010-CE-034-AD]

RIN 2120-AA64

Airworthiness Directives; Piaggio Aero Industries S.p.A. Model PIAGGIO P-180 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Some cases of corrosion were detected in the interface between the elevator hinges fittings (metallic) and the horizontal stabilizer (carbon fibre); investigation identified the cause in galvanic corrosion between dissimilar materials.

If left uncorrected, this situation could lead to a structural failure of the elevator, which could result in possible loss of control of the aeroplane.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by September 23, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090; e-mail: sarjapur.nagarajan@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0778; Directorate Identifier 2010-CE-034-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2010-0124 (Correction: June 22, 2010), dated June 22, 2010, (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products The MCAI states:

Some cases of corrosion were detected in the interface between the elevator hinges fittings (metallic) and the horizontal stabilizer (carbon fibre); investigation identified the cause in galvanic corrosion between dissimilar materials.

If left uncorrected, this situation could lead to a structural failure of the elevator, which could result in possible loss of control of the aeroplane.

This AD requires:

- (1) Inspection of the hinges fittings for corrosion and of the stabilizer for delamination;
- (2) Repair of the stabilizer, if necessary;
- (3) Replacement of the fittings, if corroded;
- (4) Improvement of fittings installation;
- (5) Installation of aluminum strips in the stabilizer to improve bonding, in accordance with Piaggio Aero Industries (PAI) Service Bulletin (SB) 80-0262 Revision 2.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

PIAGGIO AERO INDUSTRIES S.p.A. has issued Service Bulletin (MANDATORY) N.: SB-80-0262, Revision 2, dated March 17, 2010. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making

these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

Costs of Compliance

We estimate that this proposed AD will affect 96 products of U.S. registry. We also estimate that it would take about 9 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$73,440, or \$765 per product.

In addition, we estimate that any necessary follow-on actions would take about 32 work-hours and require parts costing \$11,000, for a cost of \$13,720 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Piaggio Aero Industries S.p.A.: Docket No. FAA-2010-0778; Directorate Identifier 2010-CE-034-AD.

Comments Due Date

- (a) We must receive comments by September 23, 2010.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Model PIAGGIO P-180 airplanes, serial numbers 1002 and 1004 through 1191, certificated in any category.

Subject

- (d) Air Transport Association of America (ATA) Code 55: Stabilizers.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Some cases of corrosion were detected in the interface between the elevator hinges fittings (metallic) and the horizontal stabilizer (carbon fibre); investigation identified the cause in galvanic corrosion between dissimilar materials.

If left uncorrected, this situation could lead to a structural failure of the elevator, which could result in possible loss of control of the aeroplane.

This AD requires:

- (1) Inspection of the hinges fittings for corrosion and of the stabilizer for delamination;

- (2) repair of the stabilizer, if necessary;
- (3) replacement of the fittings, if corroded;
- (4) improvement of fittings installation;
- (5) installation of aluminum strips in the stabilizer to improve bonding, in accordance with Piaggio Aero Industries (PAI) Service Bulletin (SB) 80-0262 Revision 2.

Actions and Compliance

- (f) Unless already done, do the following actions:

(1) Within the next 1,500 hours time-in-service (TIS) after the effective date of this AD or within 4 years after the effective date of this AD, whichever occurs first, do the following:

(i) Remove the left-hand (LH) and the right-hand (RH) elevators and do all of the inspections and corrective actions following the Accomplishment Instructions in Parts A, B, C, D, and E of PIAGGIO AERO INDUSTRIES S.p.A. Service Bulletin (MANDATORY) N.: SB-80-0262, Revision 2, dated March 17, 2010.

(ii) Reinstall the LH and RH elevators and do the final checks following the Accomplishment Instructions, Part F, of PIAGGIO AERO INDUSTRIES S.p.A. Service Bulletin (MANDATORY) N.: SB-80-0262 Revision 2, dated March 17, 2010.

(2) We will allow "unless already done" credit for inspections and corrective actions already done, before the effective date of this AD, following PIAGGIO AERO INDUSTRIES S.p.A. Service Bulletins (MANDATORY) N.: SB-80-0262, original issue dated September 24, 2009; or Revision 1 dated December 23, 2009, for compliance with the requirements of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

- (g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090; e-mail: sarjapur.nagarajan@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act

(44 U.S.C. 3501 *et. seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA AD No.: 2010-0124 (Correction: June 22, 2010), dated June 22, 2010; and PIAGGIO AERO INDUSTRIES S.p.A. Service Bulletin (MANDATORY) N.: SB-80-0262, Revision 2, dated March 17, 2010, for related information.

Issued in Kansas City, Missouri, on August 2, 2010.

Steven W. Thompson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-19551 Filed 8-6-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2010-0428; Airspace Docket No. 10-AEA-13]

Amendment of Class D and E Airspace, Establishment of Class E Airspace; Patuxent River, MD

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the Class D and E airspace at Patuxent River Naval Air Station (NAS), Patuxent River, MD, to reflect the part-time operating status of the control tower and establish Class E airspace designated as surface areas to accommodate the additional airspace needed for the Standard Instrument Approach Procedures (SIAPs) developed for the airport. This action would enhance the safety and management of Instrument Flight Rules (IFR) operations at Patuxent River NAS, Patuxent, MD.

DATES: 0901 UTC. Comments must be received on or before September 23, 2010.

ADDRESSES: Send comments on this proposal to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2010-0428; Airspace Docket No. 10-AEA-13, at the beginning of your comments. You may also submit and review received

comments through the internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT:

Melinda Giddens, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5610.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2010-0428; Airspace Docket No. 10-AEA-13) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2010-0428; Airspace Docket No. 10-AEA-13." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the

ADDRESSES section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class D airspace and Class E airspace designated as an extension to Class D surface area at Patuxent River NAS, Patuxent River, MD, to reflect the part-time operations of the airport control tower, establishing in advance the dates and times by a Notice to Airmen, and establish Class E airspace designated as surface areas to provide controlled airspace required to support the SIAPs developed for Patuxent River NAS.

Class D airspace designations, Class E surface airspace designations and Class E airspace designations as extensions to a Class D surface area are published in Paragraph 5000, 6002, and 6004 respectively, of FAA Order 7400.9T, signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class D and Class E airspace designations listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.