

A concomitant factor that influenced the NRC's position is the NRC's awareness of a number of phenomena that are known to contribute non-conservatism to the Appendix K evaluation models. These phenomena include boiling in the downcomer annulus during reflood, downcomer entrainment and inventory reduction due to steam bypass, and fuel relocation following cladding swelling during the temperature transient. The NRC believes that if changes are made in the decay heat standard, then changes would also have to be considered in other models to ensure that an appropriate level of overall conservatism is retained in the ECCS evaluation model package.

In addition, the NRC has evaluated the advantages and disadvantages of the rulemaking requested by the petitioner with respect to the four NRC Strategic Performance Goals as follows:

1. *Maintaining Safety:* The NRC believes that the requested rulemaking would not make a significant contribution to maintaining safety because the overall conservatism provided by the Appendix K evaluation models may not be appropriately accounted for if the conservatism of using the 1971 ANS decay heat standard is individually removed.

2. *Enhancing Public Confidence:* The proposed rulemaking would not enhance public confidence without an overall assessment of ECCS evaluation model conservatism. The NRC believes that if changes are made in the decay heat standard, then changes would also have to be considered in other models to ensure that an appropriate level of overall conservatism is retained in the ECCS evaluation model package.

3. *Improving Efficiency and Effectiveness:* The NRC staff believes that it would not be efficient and effective to modify the Appendix K evaluation model using a piecemeal approach when the "best-estimate" evaluation model is already available for licensees use.

4. *Reducing Unnecessary Regulatory Burden:* The NRC agrees that the proposed rule would reduce licensees' regulatory burden. However, the NRC does not agree that the associated burden is "unnecessary" in the absence of a demonstration that overall conservatism retained in the Appendix K evaluation models would remain adequate. For reasons cited in this document, the NRC denies the petition.

Dated at Rockville, Maryland, this 26th day of November, 2003.

For the Nuclear Regulatory Commission.
J. Samuel Walker,
Acting Secretary of the Commission.
 [FR Doc. 03-30148 Filed 12-3-03; 8:45 am]
 BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-327-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, 737-700, 737-700C, 737-800, and 737-900 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Model 737-600, 737-700, 737-700C, 737-800, and 737-900 series airplanes. This proposal would require measuring the electrical resistance of the support bracket for the fire extinguisher bottle located in the left main landing gear wheel well to ensure that it does not exceed the maximum allowed resistance; and corrective actions, if necessary. This action is necessary to prevent high electrical resistance in the squib firing circuit, which could result in insufficient electrical current to fire the fire extinguisher bottle squib and discharge the fire extinguishing agent, which could lead to an uncontrolled engine fire. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 20, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-327-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-327-AD" in the subject line and need not be submitted in triplicate. Comments sent via the

Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Doug Pegors, Aerospace Engineer; Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 917-6504; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-327-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-327-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report indicating that, during a routine inspection in production at Boeing, the electrical resistance of the ground studs installed on the support bracket for the fire extinguisher bottles in the left main wheel well of certain Boeing Model 737 series airplanes was found to exceed the maximum allowed level. During manufacture, the anodize coating was not removed properly from the holes in the support bracket into which the ground studs are inserted, thereby increasing the electrical resistance between the studs and the bracket. Therefore, the electrical resistance between the bracket and the grounding studs may exceed the maximum allowed resistance. This condition, if not corrected, could result in insufficient electrical current to fire the fire extinguisher bottle squib and discharge the fire extinguishing agent, which could lead to an uncontrolled engine fire.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 737-26A1118, dated October 17, 2002, which describes procedures for:

- Measuring the electrical resistance of the dual ground studs to ensure that the electrical resistance is no greater than 0.5 milliohms;
- Measuring the bond resistance from the top terminal lug of each ground stud to the adjacent structure; and
- Corrective actions, if necessary.

The corrective actions include replacing the affected ground stud with a new ground stud; reworking the ground stud; and relocating the support bracket hole; as applicable.

Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Difference Between Proposed Rule and Service Bulletin

Because the service bulletin does not specify a corrective action to take if the bond resistance measurement found in Figure 4 of the service bulletin is greater than 1.0 milliohms, this proposed AD would require operators to rework per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA.

Cost Impact

There are approximately 133 airplanes of the affected design in the worldwide fleet. The FAA estimates that 28 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$3,640, or \$130 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by

contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2002-NM-327-AD.

Applicability: Model 737-600, 737-700, 737-700C, 737-800, and 737-900 series airplanes, as listed in Boeing Alert Service Bulletin 737-26A1118, dated October 17, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent high electrical resistance in the squib firing circuit, which could result in insufficient electrical current to fire the fire extinguisher bottle squib and discharge the fire extinguishing agent, which could lead to an uncontrolled engine fire, accomplish the following:

Inspection, Rework, Replacement, Relocation and Installation

(a) Except as provided by paragraph (b) of this AD: Within 90 days after the effective date of this AD, measure the electrical resistance of the dual ground studs of the support brackets for the fire extinguisher bottle located in the left main landing gear wheel well (including the applicable corrective actions) by accomplishing all actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-26A1118, dated October 17, 2002. Do the actions per the service bulletin. Any applicable corrective action must be accomplished prior to further flight.

Additional Rework

(b) If, when accomplishing the bond resistance measurement described in Figure 4 of the Boeing Alert Service Bulletin 737-26A1118, dated October 17, 2002, the resistance is found to be greater than 1.0 milliohms (0.001 ohms): Before further flight, rework per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office,

FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Issued in Renton, Washington, on November 28, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-30192 Filed 12-3-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-183-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319 and A320 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to all Airbus Model A320 series airplanes, that currently requires repetitive ultrasonic inspections to detect fatigue cracking in the wing/fuselage joint cruciform fittings, and corrective actions if necessary. This action would require repetitive ultrasonic inspections for fatigue cracking in the wing/fuselage joint cruciform fittings at a reduced inspection threshold and repetitive interval. This action also would add airplanes to the applicability of the existing AD. The actions specified by the proposed AD are intended to detect and correct fatigue cracks on the wing/fuselage joint cruciform fittings, which could result in reduced structural integrity of the wing/fuselage. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 5, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-183-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain

“Docket No. 2002-NM-183-AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to

Docket Number 2002-NM-183-AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-183-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On February 13, 1998, the FAA issued AD 98-04-49, amendment 39-10360 (63 FR 9934, February 27, 1998), applicable to all Airbus Model A320 series airplanes. That AD requires repetitive ultrasonic inspections to detect fatigue cracking in the wing/fuselage joint cruciform fittings, and corrective actions if necessary. That action was prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The requirements of that AD are intended to detect and correct fatigue cracks on the wing/fuselage joint cruciform fittings, which could result in reduced structural integrity of the wing/fuselage.

Actions Since Issuance of Previous Rule

The inspection threshold and repetitive intervals specified in AD 98-04-49 were based on full-scale fatigue tests. Since the issuance of that AD, the airplane manufacturer has surveyed the Model A320 series airplane fleet and found that parameters such as the weight of fuel at landing and the mean flight duration are higher than those defined for the analysis of fatigue-related tasks. Thus, the manufacturer has adjusted the reference fatigue mission. This adjustment has resulted in a reduction in the threshold and repetitive inspection intervals required by the existing AD. In addition, it has been determined that Model A319 series airplanes should also be subject to these same inspections at the reduced threshold and interval.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-57-1051, Revision 04, dated November 27, 2001. (The existing AD refers to Revision 01 of that service bulletin, dated March 21, 1996, as the acceptable source of service information for the actions required by that AD.) Revision 04 of the service bulletin describes procedures for repetitive ultrasonic inspections for cracking around fastener “a” on the rear section of the cruciform fitting at rib 1 on both wings. This inspection is similar to that described in Revision 01 of the service