

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 29, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-27304 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0985; Project Identifier AD-2022-00096-T; Amendment 39-22260; AD 2022-25-04]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-400 and 747-8 series airplanes. This AD was prompted by reports of three opened door 5 right ceiling stowage boxes that fell freely and injured a flight attendant in each event. This AD requires replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on certain other airplanes. This AD also requires an operation check of the stowage boxes or snubber, as applicable, and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 20, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 20, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-0985; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket

Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2022-0985.

FOR FURTHER INFORMATION CONTACT: Julie Linn, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3684; email: Julie.Linn@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 747-400 and 747-8 series airplanes. The NPRM published in the **Federal Register** on September 20, 2022 (87 FR 57422).

The NPRM was prompted by reports of an opened door 5 right ceiling stowage box that fell freely approximately 12 inches on a Model 747-8 airplane, and two additional door 5 ceiling stowage box free fall events on Model 747-400 airplanes. In one reported occurrence, an opened door 5 ceiling stowage box fell freely approximately 10 inches; in another, the stowage box fell freely approximately 8 inches. In each occurrence, a flight attendant was injured. Boeing and the supplier have since investigated and analyzed affected snubbers, part number (P/N) SP5378, used on the door 5 ceiling stowage boxes on Model 747-400 and 747-8 airplanes. It was determined that over time, air can get into the cylinder of the affected snubber and delay its damping functionality, which means the affected snubber will not meet the requirement of the door 5 ceiling stowage boxes to open at a rate of not more than 15 degrees per second, when open more than 2.5 inches. The supplier has designed a replacement snubber, P/N SP26172, which meets those requirements.

In the NPRM, the FAA proposed to require replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on certain other airplanes. The NPRM also proposed to require an operation check of the stowage boxes or snubber, as applicable, and applicable on-condition actions.

The FAA is issuing this AD to address an unlatched door 5 ceiling stowage box, which can open and fall freely more than 2.5 inches, possibly resulting in injury to the flightcrew or maintenance personnel.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from Air Line Pilots Association, International, who supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Boeing Special Attention Requirements Bulletin 747-25-3726 RB, dated January 6, 2022. This service information specifies procedures for replacing certain snubbers of the door 5 ceiling stowage boxes on certain airplanes, and replacing certain snubbers and changing the location of the snubber attachments on other airplanes. The service information also specifies procedures for an operation check of the stowage boxes or snubbers, as applicable, to ensure that the free-fall distance is no greater than 2.5 inches, and applicable on-condition actions including a post-snobber-replacement check until eventual replacement of any affected snubber. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Costs of Compliance

The FAA estimates that this AD affects 45 airplanes of U.S. registry. The

FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Snubber replacement and operation check	2 work-hours × \$85 per hour = \$170	\$3,712	\$3,882	\$174,690
Snubber replacement, snubber attachment relocation, and operation check.	7 work-hours × \$85 per hour = \$595	4,232	4,827	217,215

The FAA estimates the following costs to do any necessary replacement actions that would be required based on

the results of the required inspection. The agency has no way of determining

the number of aircraft that might need this replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Snubber replacement	1 work-hour × \$85 per hour = \$85	\$928	\$1,013
Post-snubber-replacement check	1 work-hour × \$85 per hour = \$85	0	85

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–25–04 The Boeing Company:
Amendment 39–22260; Docket No. FAA–2022–0985; Project Identifier AD–2022–00096–T.

(a) Effective Date

This airworthiness directive (AD) is effective January 20, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747–400 and 747–8 series airplanes, certificated in any category, as identified in Boeing Special Attention Requirements Bulletin 747–25–3726 RB, dated January 6, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by reports of three opened door 5 right ceiling stowage boxes that fell freely and injured a flight attendant in each event. The FAA is issuing this AD to address an unlatched door 5 ceiling stowage box, which can open and fall freely more than 2.5 inches, possibly resulting in injury to the flightcrew or maintenance personnel.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Special Attention Requirements Bulletin 747–25–3726 RB, dated January 6, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Requirements Bulletin 747–25–3726 RB, dated January 6, 2022.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Special Attention Service Bulletin 747–25–3726, dated January 6, 2022, which is referred to in Boeing Special Attention Requirements Bulletin 747–25–3726 RB, dated January 6, 2022.

(h) Exceptions to Service Information Specifications

Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Special Attention Requirements Bulletin 747–25–3726 RB, dated January 6, 2022, use the phrase “the original issue date of Requirements Bulletin 747–25–3726 RB,”

this AD requires using “the effective date of this AD.”

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to 9-ANMSeattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Julie Linn, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3684; email: Julie.Linn@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Requirements Bulletin 747-25-3726 RB, dated January 6, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, fr.inspection@nara.gov, or go to

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 28, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-27302 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-0571; Airspace Docket No. 22-ANM-46]

RIN 2120-AA66

Establishment of Class E Airspace; Christmas Valley Airport, OR; Correction

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting a final rule that appeared in the **Federal Register** on December 9, 2022. The Final Rule incorrectly annotated the airspace class designation in the text header of the newly designated Class E airspace beginning at 700 feet above the surface at Christmas Valley Airport, OR. This action corrects the error.

DATES: Effective 0901 UTC, February 23, 2023. The Director of the Federal Register approves this incorporation by reference under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11, *Airspace Designations and Reporting Points*, and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Nathan A. Chaffman, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S. 216th Street, Des Moines, WA 98198; telephone (206) 231-3460.

SUPPLEMENTARY INFORMATION:

History

The FAA published a final rule in the **Federal Register** (87 FR 75465; December 9, 2022) for Docket FAA-2022-0571, which established Class E airspace extending upward from 700 feet above the surface at Christmas Valley Airport, OR. Subsequent to publication, the FAA identified that the Final Rule incorrectly annotated the airspace class designator in the text header of the newly established Class E airspace beginning at 700 feet above the surface at Christmas Valley Airport, OR. The legal description's text header

currently reads “ANM OR E Christmas Valley, OR [New], but should read “ANM OR E5 Christmas Valley, OR [New].” This action corrects the error.

The Class E5 airspace designation is published in paragraph 6005 of FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in FAA Order JO 7400.11.

FAA Order JO 7400.11 is published annually and becomes effective on September 15.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to the FAA, “Establishment of Class E Airspace; Christmas Valley Airport, OR”, published in the **Federal Register** of December 9, 2022 (87 FR 75465), FR Doc. 2022-26646, is corrected as follows:

§ 71.1 [Corrected]

■ 1. On page 75466, in the third column, line 1 is corrected to read:

ANM OR E5 Christmas Valley, OR [New]

Issued in Des Moines, Washington, on December 12, 2022.

B.G. Chew,

Group Manager, Operations Support Group, Western Service Center.

[FR Doc. 2022-27268 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 744

[Docket No. 221209-0268]

RIN 0694-AJ02

Revisions to the Unverified List and the Entity List

AGENCY: Bureau of Industry and Security, Department of Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Industry and Security (BIS) is amending the Export Administration Regulations (EAR) by removing 9 persons from the Unverified List (UVL) and adding them to the Entity List, all under the destination of Russia. BIS has been unable to verify the *bona fides* of all 9 persons being removed from the UVL and added to the Entity List, due to the foreign government's prevention of timely end-use checks. BIS is also amending the