

MD-11F airplanes); as applicable. Such replacement terminates any repetitive inspections required by this AD.

Spares

(e) As of the effective date of this AD, no person shall install a rudder pedal arm assembly having part number ABH7239-1 or ABH7239-2 on any airplane.

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 27, 2002.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 02-22434 Filed 9-3-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-212-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-90-30 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model MD-90-30 airplanes. This proposal would require measuring the length of the wear indicator on the brake stack of the main landing gear (MLG) brake assembly to determine the degree of wear, and follow-on actions. This proposal also would require eventual replacement of the existing MLG brake assembly with a new, improved or modified assembly,

which would constitute terminating action for any repetitive actions being performed per this proposed AD. This action is necessary to prevent failure of the MLG brakes and consequent loss of braking capability, which could result in the airplane overrunning the runway during take-off or landing. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by October 21, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-212-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-212-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Technical Information: Ken Sujishi, Aerospace Engineer, Systems & Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5353; fax (562) 627-5210.

Other Information: Judy Golder, Airworthiness Directive Technical Editor/Writer; telephone (425) 687-4241, fax (425) 227-1232. Questions or comments may also be sent via the Internet using the following address: judy.golder@faa.gov. Questions or comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-212-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-212-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports of discrepancies of the carbon brake assembly installed on the main landing gear (MLG) of certain McDonnell Douglas Model MD-90-30 airplanes. On the discrepant MLG brake assemblies, which had wear of 50 percent or more, piston insulators had pushed below the surface of the pressure plate. In a few

cases where the brake assembly was near "full worn" condition, the piston insulators had broken through the pressure plate and pushed into the rotating carbon disk of the brake assembly. This condition, if not corrected, could result in failure of the MLG brakes and consequent loss of braking capability, which could result in the airplane overrunning the runway during take-off or landing.

Explanation of Relevant Service Information

We have reviewed and approved Boeing Alert Service Bulletin MD90-32A042, Revision 01, dated August 17, 2000, which recommends accomplishment of Aircraft Braking Systems Corporation (ABS) Service Bulletin MD90-32-13.

ABS Service Bulletin MD90-32-13, Revision 2, dated April 28, 2000, describes procedures for measuring the wear indicator on the MLG brake stack. When the wear indicator on the brake stack measures 1.30 inches or less, the ABS service bulletin specifies inspecting the contact area between the piston insulators and the pressure plate to find discrepancies of the pressure plate (*i.e.*, the surface of the piston insulator is flush with or has pushed beyond the surface of the counterbore). The follow-on actions are as follows:

- If no discrepancy of the pressure plate is found—repetitive inspections for discrepancies of the pressure plate.
- If any discrepancy is found and the length of the wear indicator on the MLG brake is within certain limits—overhaul of the MLG brake, including replacement of the carbon brake stack.
- If any discrepancy is found and the length of the wear indicator on the MLG brake is outside certain limits—repair of the brake assembly, which involves replacing the swage tube subassembly of the brake with a new subassembly, replacing the pressure plate with a new, improved pressure plate, shortening the wear indicator tube, inspecting to determine the radius of the piston insulators, and replacing the piston insulators with reworked insulators if necessary.

Overhaul or repair of the brake assembly eliminates the need for the repetitive inspections.

The FAA also has reviewed and approved Boeing Service Bulletin MD90-32-045, Revision 01, dated December 15, 2000. That service bulletin describes procedures for replacement of the MLG brake assembly with a brake assembly that has been modified according to ABS Service Bulletin MD90-32-14, dated May 9, 2000.

ABS Service Bulletin MD90-32-14 describes procedures for modifying brake assemblies in certain configurations to a new configuration. The modification involves replacing certain wear indicator tubes with new tubes, measuring the radius of the piston insulators, reworking the piston insulators if necessary, installing new or refurbished components, and reidentifying the brake assembly.

Accomplishment of the actions specified in the service bulletins described previously is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletins, described previously, except as discussed below.

Differences Between Service Bulletins and Proposed AD

ABS Service Bulletin MD90-32-13, Revision 2, specifies that, if the wear indicator on the brake stack measures more than 1.30 inches, no further action is necessary to comply with the service bulletin. However, we find that, as the brake continues in service and the wear indicator on the brake stack decreases to 1.30 inches or less, the actions in that service bulletin will apply. Therefore, this proposed AD would require repetitive measurements of the wear indicator on the brake stack every 260 landings, until the wear indicator on the brake stack measures 1.30 inches or less, at which time the proposed follow-on actions would apply.

As part of the follow-on actions that would be required by the proposed AD, Boeing Alert Service Bulletin MD90-32A042, Revision 01; and ABS Service Bulletin MD90-32-13, Revision 2; specify performing an inspection of the MLG brake assembly. However, neither service bulletin specifies what type of inspection is necessary. We have determined that a general visual inspection is necessary; therefore, paragraph (b) of this proposed AD would require a general visual inspection of the MLG brake assembly for discrepancies of the pressure plate (*i.e.*, the surface of the piston insulator is flush with or has pushed beyond the surface of the counterbore). Note 2 of this proposed AD defines such an inspection.

Also, ABS Service Bulletin MD90-32-13, Revision 2, specifies to use the

repair procedure in that service bulletin only when the wear indicator on the MLG brake is not longer than 2.10 inches. For a wear indicator on the MLG brake that is longer than 2.10 inches, the pressure plate modification cannot be accomplished per the service bulletin, and is not necessary until the MLG brake is worn further. Thus, we have clarified in this proposed AD that an MLG brake with a wear indicator longer than 2.10 inches may remain installed without repair or replacement until the MLG brake assembly is replaced with a new, improved or modified MLG brake assembly.

These issues have been discussed with the airplane manufacturer, and the manufacturer concurs with our decision to issue this proposed AD with these differences.

Cost Impact

There are approximately 115 airplanes of the affected design in the worldwide fleet. The FAA estimates that 21 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 1 work hour per airplane to accomplish the proposed measurement of the brake stack wear indicator, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this proposed action on U.S. operators is estimated to be \$1,260, or \$60 per airplane, per measurement cycle.

It would also take approximately 1 work hour per airplane to accomplish the proposed inspection for discrepancies of the pressure plate of the MLG brake, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this proposed action on U.S. operators is estimated to be \$1,260, or \$60 per airplane, per inspection cycle.

It would take approximately 6 work hours per airplane to accomplish the proposed replacement of the MLG brake assembly, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$55,000. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$1,162,560, or \$55,360 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include

incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 2001–NM–212–AD.

Applicability: Model MD–90–30 airplanes, certificated in any category; equipped with a main landing gear (MLG) brake assembly having part number (P/N) 5012193R, 5012193–1, 5012193–1–P, 5012193–2, 5012193–2–P, 5012193–3, or 5012193–3–P.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area

subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (h) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the MLG brake and consequent loss of braking capability, which could result in the airplane overrunning the runway during take-off or landing, accomplish the following:

Measurement of Brake Wear

(a) Within 120 days after the effective date of this AD, measure the length of the wear indicator on the brake stack of the MLG brake assembly to determine the degree of wear, according to Boeing Alert Service Bulletin MD90–32A042, Revision 01, dated August 17, 2000; and Aircraft Braking Systems Corporation Service Bulletin MD90–32–13, Revision 2, dated April 28, 2000.

(1) If the wear indicator measures more than 1.30 inches: Repeat the measurement of the brake stack wear indicator every 260 landings, until the wear indicator measures 1.30 inches or less. When the wear indicator measures 1.30 inches or less, do paragraph (a)(2) of this AD.

(2) If the wear indicator measures 1.30 inches or less: Before further flight, do paragraph (b) of this AD.

Repetitive Inspections for Discrepancies of Pressure Plate

(b) Perform a general visual inspection of the MLG brake assembly for discrepancies of the pressure plate (*i.e.*, the surface of the piston insulator is flush with or has pushed beyond the surface of the counterbore), according to Boeing Alert Service Bulletin MD90–32A042, Revision 01, dated August 17, 2000; and Aircraft Braking Systems Corporation Service Bulletin MD90–32–13, Revision 2, dated April 28, 2000. If no discrepancy of the pressure plate is found, repeat the inspection at intervals not to exceed 260 landings, until paragraph (c)(1), (c)(2), or (d) of this AD has been accomplished.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Corrective Actions

(c) If any discrepancy of the pressure plate is found during any inspection required by paragraph (b) of this AD: Before further flight, do paragraph (c)(1), (c)(2), (c)(3), or (d) of this AD.

(1) If the length of the wear indicator on the MLG brake is less than 0.40 inch: Overhaul the MLG brake assembly (including replacing the carbon stack) according to Boeing Alert Service Bulletin MD90–32A042, Revision 01, dated August 17, 2000; and Aircraft Braking Systems Corporation Service Bulletin MD90–32–13, Revision 2, dated April 28, 2000. Such overhaul terminates the repetitive inspections required by paragraph (b) of this AD.

(2) If the length of the wear indicator on the MLG brake is greater than or equal to 0.40 inch but less than or equal to 2.10 inches: Repair the MLG brake assembly according to Boeing Alert Service Bulletin MD90–32A042, Revision 01, dated August 17, 2000; and Aircraft Braking Systems Corporation Service Bulletin MD90–32–13, Revision 2, dated April 28, 2000. The repair procedures involve replacing the swage tube subassemblies of the brake with new subassemblies, replacing the pressure plate with a new, improved pressure plate, shortening the wear indicator tube, inspecting to determine the radius of the piston insulators, and replacing the piston insulators with reworked insulators if necessary. Such repair terminates the repetitive inspections required by paragraph (b) of this AD.

(3) If the length of the wear indicator on the brake is greater than 2.10 inches: No further action is required by this paragraph.

Replacement With Modified Brake Assembly

(d) Except as provided by paragraph (c) of this AD, at the next brake overhaul, or within 36 months after the effective date of this AD, whichever is first: Replace any MLG brake assembly having P/N 5012193R, 5012193–1, 5012193–1–P, 5012193–2, 5012193–2–P, 5012193–3, or 5012193–3–P; with a new, improved or modified MLG brake assembly having P/N 5012193–4; according to Boeing Service Bulletin MD90–32–045, Revision 01, dated December 15, 2000; and Aircraft Braking Systems Corporation Service Bulletin MD90–32–14, dated May 9, 2000. The modification involves replacement of certain wear indicator tubes with new tubes, installation of a new, improved pressure plate, measurement of the radius of the piston insulators, rework of the piston insulators if necessary, and reidentification of the brake assembly. Accomplishment of the replacement specified in this paragraph terminates the requirements of this AD.

Actions Accomplished Per Previous Revisions of Service Bulletin

(e) Inspections and corrective actions accomplished before the effective date of this AD according to Boeing Alert Service Bulletin MD90–32A042, dated April 27, 2000, is acceptable for compliance with the corresponding actions required by paragraphs (a), (b), and (c) of this AD.

(f) Replacements accomplished before the effective date of this AD according to Boeing

Service Bulletin MD90-32-045, dated July 21, 2000, are acceptable for compliance with paragraph (d) of this AD.

Spares

(g) As of the effective date of this AD, no person may install a MLG brake assembly having P/N 5012193R, 5012193-1, 5012193-2, or 5012193-3 on any airplane, unless the MLG brake assembly is inspected and any applicable corrective action has been accomplished according to this AD.

Alternative Methods of Compliance

(h) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(i) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 27, 2002.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-22436 Filed 9-3-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-108697-02]

RIN 1545-BA60

Required Distributions From Retirement Plans; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of public hearing on proposed rulemaking.

SUMMARY: This document contains a notice of public hearing on proposed regulations relating to required minimum distributions for defined benefit plans and annuity contracts providing benefits under qualified plans, individual retirement plans, and section 403(b) contracts.

DATES: The public hearing is being held on Wednesday, October 9, 2002 at 10

a.m. The IRS must receive outlines of the topics to be discussed at the hearing by Wednesday, September 25, 2002.

ADDRESSES: The public hearing is being held in room 4718, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present photo identification to enter the building.

Mail outlines to: Regulations Unit CC:ITA:RU, (REG-108697-02), room 5226, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Hand deliver outlines Monday through Friday between the hours of 8 a.m. and 5 p.m. to: Regulations Unit CC:ITA:RU, (REG-108697-02), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC. Submit electronic outlines of oral comments directly to the IRS Internet site at <http://www.irs.gov/regs>.

FOR FURTHER INFORMATION CONTACT:

Concerning submissions of comments, the hearing, and/or to be placed on the building access list to attend the hearing contact Sonya M. Cruse (202) 622-7805 (not a toll-free number).

SUPPLEMENTARY INFORMATION: The subject of the public hearing is the notice of proposed regulations (REG-108697-02) that was published in the **Federal Register** on Wednesday, April 17, 2002 (67 FR 18834).

The rules of 26 CFR 601.601(a)(3) apply to the hearing.

Persons who have submitted written comments and wish to present oral comments at the hearing, must submit an outline of the topics to be discussed and the amount of time to be devoted to each topic (signed original and eight (8) copies) by Wednesday, September 25, 2002.

A period of 10 minutes is allotted to each person for presenting oral comments.

After the deadline for receiving outlines has passed, the IRS will prepare an agenda containing the schedule of speakers. Copies of the agenda will be made available, free of charge, at the hearing.

Because of access restrictions, the IRS will not admit visitors beyond the immediate entrance area more than 30 minutes before the hearing starts.

For information about having your name placed on the building access list to attend the hearing, see the **FOR**

FURTHER INFORMATION CONTACT section of this document.

Cynthia E. Grigsby,

Chief, Regulations Unit, Associate Chief Counsel (Income Tax and Accounting).

[FR Doc. 02-22465 Filed 8-29-02; 11:51 am]

BILLING CODE 4830-01-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 4

RIN 2900-AJ60

Schedule for Rating Disabilities; The Spine

AGENCY: Department of Veterans Affairs.

ACTION: Proposed rule.

SUMMARY: This document proposes to amend the Department of Veterans Affairs (VA) Schedule for Rating Disabilities by revising that portion of the Musculoskeletal System that addresses disabilities of the spine. The intended effect of this action is to update this portion of the rating schedule to ensure that it uses current medical terminology and unambiguous criteria, and that it reflects medical advances that have occurred since the last review.

DATES: Comments must be received on or before November 4, 2002.

ADDRESSES: Mail or hand-deliver written comments to: Director, Office of Regulations Management (02D), Department of Veterans Affairs, 810 Vermont Ave., NW., Room 1154, Washington, DC 20420; or fax comments to (202) 273-9289; or e-mail comments to OGCRegulations@mail.va.gov. Comments should indicate that they are submitted in response to "RIN 2900-AJ60." All comments received will be available for public inspection in the Office of Regulations Management, Room 1158, between the hours of 8 a.m. and 4:30 p.m., Monday through Friday (except holidays).

FOR FURTHER INFORMATION CONTACT:

Carol McBrine, M.D., Consultant, Policy and Regulations Staff (211A), Compensation and Pension Service, Veterans Benefits Administration, Department of Veterans Affairs, 810 Vermont Ave., NW., Washington, DC 20420, (202) 273-7215.

SUPPLEMENTARY INFORMATION: VA proposes to amend its Schedule for Rating Disabilities by revising that portion of the Musculoskeletal System that addresses disabilities of the spine. VA published an advance notice of proposed rulemaking in the **Federal**