

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10209 (62 FR 61436, November 18, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Bombardier, Inc. (Formerly Canadair):

Docket 2001-NM-267-AD. Revises AD 97-24-02, Amendment 39-10209.

Applicability: Model CL-600-1A11 (CL-600) series airplanes, serial numbers 1004 through 1085 inclusive; Model CL-600-2A12 (CL-601) series airplanes, serial numbers 3001 through 3066 inclusive; Model CL-600-2B16 (CL-601-3A/-3R) series airplanes, serial numbers 5001 through 5194 inclusive; and Model CL-600-2B16 (CL-604) series airplanes, serial numbers 5301 through 5352 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously. To prevent cracking in the pressure bulkhead at frame station (FS) 409.00, which could result in uncontrolled depressurization of the airplane and/or reduced structural integrity of the fuselage, accomplish the following:

Restatement of Requirements of AD 97-24-02: Detailed Inspections/Repair

(a) For Model CL-600-1A11 (CL-600) airplanes: Prior to the accumulation of 1,900 total landings, or within 100 landings after December 3, 1997 (the effective date of AD 97-24-02, amendment 39-10209), whichever occurs later, perform a detailed inspection to detect cracks at FS 409.00 of the bulkhead web (part number (P/N) 600-32014-71/-95/-105), in accordance with Canadair Challenger Service Bulletin 600-0679, dated September 12, 1997.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If no crack is detected, repeat the detailed inspection thereafter at intervals not to exceed 600 landings.

(2) If any crack is detected and if all three of the conditions specified in paragraphs (a)(2)(i), (a)(2)(ii), and (a)(2)(iii) of this AD are met, within 600 landings or 12 months after the crack is detected, whichever occurs first, repair the crack in accordance with a method approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Until the repair is accomplished, repeat the detailed inspection at intervals not to exceed 100 landings.

(i) No more than one crack exists at each corner radius, as specified in the service bulletin; and

(ii) No crack extends under the angles having P/N 600-32014-13 and P/N 600-32014-15 on the aft side of the bulkhead web; and

(iii) No crack exists in angles having P/N 600-32014-13 and P/N 600-32014-15 on the aft side of the bulkhead web.

(3) If any crack other than that identified in paragraph (a)(2) of this AD is detected, prior to further flight, repair it in accordance with a method approved by the Manager, New York ACO.

(b) For Model CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A/-3R), and CL-600-2B16 (CL-604) series airplanes: Prior to the accumulation of 1,100 total landings, or within 100 landings after December 3, 1997, whichever occurs later, perform a detailed inspection to detect cracks at FS 409.00 of the bulkhead web (P/N 600-32014-105/-137), in accordance with Canadair Challenger Service Bulletin 601-0501, dated September 12, 1997 (for Model CL-600-2A12 (CL-601) and CL-600-2B16 (CL-601-3A/-3R) series airplanes); or Canadair Challenger Service Bulletin 604-53-007, dated September 30, 1997 (for Model CL-600-2B16 (CL-604) series airplanes); as applicable.

(1) If no crack is detected, repeat the detailed inspection thereafter at intervals not to exceed 600 landings.

(2) If any crack is detected and if all three of the conditions specified in paragraphs (b)(2)(i), (b)(2)(ii), and (b)(2)(iii) of this AD are met, within 600 landings or 12 months after the crack is detected, whichever occurs first, repair the crack in accordance with a method approved by the Manager, New York ACO. Until the repair is accomplished, repeat the detailed inspection at intervals not to exceed 100 landings.

(i) No more than one crack exists at each corner radius, as specified in the service bulletin; and

(ii) No crack extends under the angles having P/N 600-32014-113 and P/N 600-32014-115 on the aft side of the bulkhead web; and

(iii) No crack exists in angles having P/N 600-32014-113 and P/N 600-32014-115 on the aft side of the bulkhead web.

(3) If any crack other than that identified in paragraph (b)(2) of this AD is detected, prior to further flight, repair it in accordance with a method approved by the Manager, New York ACO.

New Requirements of This AD: Optional Terminating Modification

(c) For airplanes on which no crack has been found during accomplishment of any inspection required by AD 97-24-02; or on which the pressure bulkhead was not previously repaired: Modification of the pressure bulkhead at FS 409.00 (including inspection, installation of reinforcing material, and tests) by accomplishing all the actions specified in paragraphs 2.A. through 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0503 (for Model CL-601 and CL-601-3A/-3R series airplanes), Service Bulletin 600-0680 (for Model CL-600 series airplanes), or Service Bulletin 604-53-006 (for Model CL-604 series airplanes); all dated November 30, 1999, per the applicable service bulletin, terminates the repetitive inspections required by this AD.

Repair

(d) If any crack is found during any inspection specified in paragraph (c) of this AD: Before further flight, repair in accordance with a method approved by the Manager, New York ACO; or Transport Canada Civil Aviation or its delegated agent.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, New York ACO, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in Canadian airworthiness directive CF-1997-16R2, dated May 31, 2001.

Issued in Renton, Washington, on October 10, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-26469 Filed 10-20-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2003-16214; Airspace Docket No. 02-ANM-11]

Proposed Revision of Class E Airspace at Kalispell, MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposal would revise Class E airspace at Kalispell/Glacier Park International Airport, Kalispell, MT. Instrument Flight Rules (IFR) operations transitioning between Helena, MT, and Kalispell, MT, makes this proposal necessary. This additional airspace extending 1,200 feet or more above the surface of the earth is necessary to provide controlled airspace for the containment and safety of IFR flights transitioning between Helena, MT, and Kalispell/Glacier Park International Airport at Kalispell, MT.

DATES: Comments must be received on or before December 5, 2003.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number, FAA-2003-16214; Airspace Docket No. 03-ANM-11, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final

dispositions in person in the Docket Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone number 1 (800) 647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the Office of the Regional Air Traffic Division, Northwest Mountain Region, Federal Aviation Administration, Airspace Branch ANM-520, 1601 Lind Avenue, SW., Renton, WA 98055.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy related aspects of the proposal. Communications should identify Docket No. FAA-2003-16214; Airspace Docket 02-ANM-11, and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit, with those comments, a self-addressed stamped postcard on which the following statement is made: "Comments to Airspace Docket No. FAA-2003-16214; Airspace Docket 02-ANM-11." the postcard will be date/time stamped and returned to the commenter.

Availability of NPRM

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at <http://www.faa.gov> or the Superintendent of Document's web page at <http://www.access.gpo.gov/nara>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, 1601 Lind Avenue, SW., Renton, WA, 98055. Communications must identify both document numbers for this notice. Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution

System, which describes the application procedures.

The Proposal

This action amends Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) by adding additional Class E airspace at Kalispell, MT. This additional airspace extending 1,200 feet or more above the surface of the earth is necessary to provide additional controlled airspace for the containment and safety of IFR flights transitioning between Helena, MT, and Kalispell/Glacier Park International Airport Kalispell, MT.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9L, dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11013; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9L, Airspace Designations and Reporting Points, dated September 2, 2003, and effective September 16, 2003, is amended as follows:

Paragraph 6005 Class E airspace extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM MT E5 Kalispell, MT (Revised)

Kalispell/Glacier Park International Airport, MT

[Lat. 48°18'41" N., long. 114°15'19" W.]

Smith Lake Non Directional Beacon (NDB)

[Lat. 48°06'30" N., long. 114°27'41" W.]

That airspace extending upward from 700 feet above the surface within a 7-mile radius of Kalispell/Glacier Park International Airport, and within 4.8 miles each side of the 035° and 215° bearings from the Smith Lake NDB extending from the 7-mile radius to 10.5 miles southwest of the NDB; that airspace extending upward from 1,200 feet above the surface bounded by a line from lat. 47°30'00" N., long. 112°37'30" W.; to lat. 47°43'30" N., long. lat. 112°37'30" N., long. 48°07'30" N., long. 113°30'00" W to lat. 48°30'00" N., long. 113°30'00" W.; to lat. 48°30'00" N., long. 116°03'35" W to lat. 47°30'00" N., long. 114°54'23" W.; thence to point of origin; excluding Kalispell/Glacier Park International Airport Class D airspace, Class E2 airspace, and that airspace within Federal Airways airspace area.

* * * * *

Issued in Seattle, Washington, on October 2, 2003.

John L. Pipes,

Acting Assistant Manager, Air Traffic Division, Northwest Mountain Region.

[FR Doc. 03-26560 Filed 10-20-03; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Chapter VII

[Docket No. 031003247-3247-01]

Effects of Foreign Policy-Based Export Controls

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Request for comments on foreign policy-based export controls.

SUMMARY: The Bureau of Industry and Security (BIS) is reviewing the foreign policy-based export controls in the Export Administration Regulations to determine whether they should be modified, rescinded or extended. To