

DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–0628; Project Identifier MCAI–2024–00728–T; Amendment 39–23084; AD 2025–14–06]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.
ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A350–941 and –1041 airplanes. This AD was prompted by reports of deep spot faces on rib 9 at the lower flange bolting with the lower spar. This AD requires a special detailed inspection for discrepancies of certain pylon bolts, and applicable corrective actions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 25, 2025.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 25, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2025–0628; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Airbus material identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email *continued-airworthiness.a350@airbus.com*; website *airbus.com*.

- For European Union Aviation Safety Agency (EASA) material

identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2025–0628.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email *dan.rodina@faa.gov*.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A350–941 and –1041 airplanes. The NPRM was published in the **Federal Register** on April 29, 2025 (90 FR 17749). The NPRM was prompted by AD 2024–0234, dated December 6, 2024 (EASA AD 2024–0234) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states deep spot faces have been detected on the production line on rib 9 at the lower flange bolting with the lower spar. This condition, if not detected and corrected, could lead to reduced fatigue life, which could adversely affect the structural integrity of the airplane.

In the NPRM, the FAA proposed to require a special detailed inspection for discrepancies of certain pylon bolts, and applicable corrective actions, as specified in EASA AD 2024–0234. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2025–0628.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2024–0234 specifies procedures for a special detailed inspection for discrepancies of the 2 pylon bolts at rib 9, left-hand and right-hand sides, and applicable corrective actions (repair). Discrepancies include washers that are not correctly aligned with the nut, cracks, scratches, corrosion, damage, and missing hardware. In addition, discrepancies include a no-go condition found after measuring the spot face depth with a “GO-NoGO GAUGE.” The compliance times for the applicable corrective actions range from before next flight to 3,000 flight cycles from completion of inspection.

The FAA reviewed Airbus Service Bulletin A350–54–P011, dated July 4, 2024. This material identifies affected airplanes specified in EASA AD 2024–0234.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates this AD affects 17 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS			
Labor cost	Parts cost	Cost per product	Cost on U.S. operators
8 work-hours × \$85 per hour = \$680	\$0	\$0	\$11,560

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–14–06 Airbus SAS: Amendment 39–23084; Docket No. FAA–2025–0628; Project Identifier MCAI–2024–00728–T.

(a) Effective Date

This airworthiness directive (AD) is effective August 25, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category, having manufacturer serial numbers listed in Airbus Service Bulletin A350–54–P011, dated July 4, 2024.

(d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

(e) Unsafe Condition

This AD was prompted by reports of deep spot faces that were detected on the production line on rib 9 at lower flange bolting with the lower spar. The FAA is issuing this AD to address deep spot faces on rib 9, which if not addressed, could result in reduced fatigue life and could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0234, dated December 6, 2024 (EASA AD 2024–0234).

(h) Exception to EASA AD 2024–0234

(1) Where paragraph (2) of EASA AD 2024–0234 specifies "accomplish the corrective actions," this AD requires replacing that text with "accomplish the corrective actions, including any inspection instructions."

(2) Where paragraph (2) of EASA AD 2024–0234 specifies "Where the SB instructs to contact Airbus for approved repair instructions, this AD requires to contact Airbus for corrective action(s) instructions, and within the compliance time specified therein, to accomplish those instructions accordingly," this AD requires replacing that text with "Where the SB instructs to contact Airbus for instructions or inspections, this AD requires contacting Airbus for instructions and inspections, as applicable, and within the compliance time specified therein, accomplishing those instructions accordingly; except if any cracking is found, the cracking must be repaired before further flight using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval

(DOA). If approved by the DOA, the approval must include the DOA-authorized signature."

(3) This AD does not adopt the "Remarks" section of EASA AD 2024–0234.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0234 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any material contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Additional Information

For more information about this AD, contact Dan Rodina, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email dan.rodina@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A350–54–P011, dated July 4, 2024.

(ii) European Union Aviation Safety Agency (EASA) AD 2024–0234, dated December 6, 2024.

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) For Airbus material identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email continued-airworthiness.a350@airbus.com; website airbus.com.

(5) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(6) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations, or email fr.inspection@nara.gov.

Issued on July 9, 2025.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–13593 Filed 7–18–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–0345; Project Identifier MCAI–2024–00475–T; Amendment 39–23087; AD 2025–14–09]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2022–27–01, which applied to certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2022–27–01 required replacing affected fasteners and applying additional head nut cap protection at the front and rear spars in the center wing box (CWB). Since the FAA issued AD 2022–27–01, the FAA determined that additional Airbus SAS Model A350 manufacturer serial numbers (MSNs) are affected by the same potential unsafe condition. This AD continues to require the actions in AD 2022–27–01 and

expands the applicability to include the additional Airbus SAS Model A350 MSNs. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 25, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 25, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2025–0345; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at regulations.gov under Docket No. FAA–2025–0345.

FOR FURTHER INFORMATION CONTACT:

Kaitlyn Kosten, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 404–545–5064; email kaitlyn.e.kosten@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2022–27–01, Amendment 39–22286 (87 FR 80026, December 29, 2022) (AD 2022–27–01). AD 2022–27–01 applied to certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2022–27–01 required replacing affected fasteners and applying additional head nut cap protection at the front and rear spars in the CWB, as specified in EASA AD 2022–0080, dated May 9, 2022. The FAA issued AD 2022–27–01 to address fasteners installed in the CWB rotating

inside their fastener holes. The unsafe condition, if not addressed, could lead to loss of a fastener clamping and cracking of the nut sealant cover, possibly resulting, in case of lightning strike, in a fuel tank explosion and consequent loss of the airplane.

The NPRM was published in the **Federal Register** on March 13, 2025 (90 FR 11916). The NPRM was prompted by AD 2024–0161, dated August 19, 2024 (EASA AD 2024–0161) (also referred to as “the MCAI”), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states that additional Airbus SAS Model A350 MSNs are affected by the same potential unsafe condition, and the service information has been revised to identify the additional airplanes. EASA AD 2024–0161 retains the requirements of EASA AD 2022–0080 and expands the applicability to include additional Airbus SAS Model A350 MSNs.

In the NPRM, the FAA proposed to continue to require the actions in AD 2022–27–01 and to expand the applicability to include the additional Airbus SAS Model A350 MSNs, as specified in EASA AD 2024–0161. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA–2025–0345.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from ProTech Aero Services Limited, who supported the NPRM without change.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024–0161, which specifies procedures for replacing affected fasteners installed on the left-hand and right-hand CWB at the front and rear spar areas, and for adding head nut cap protection at the front and