

Effective Date

(a) This airworthiness directive (AD) is effective October 14, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Model 717-200 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007.

Unsafe Condition

(d) This AD results from a report of an aborted takeoff due to a control column disconnect. We are issuing this AD to prevent binding of the bolt that connects the cable 264A clevis to the bellcrank assembly against the adjacent (upper) clevis of the pull-pull cable assembly. This binding condition could result in slow airplane rotation or a control column disconnect during takeoff and a runway excursion if takeoff must be aborted.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Inspection/Corrective Actions

(f) Do the applicable actions specified in paragraphs (f)(1) and (f)(2) of this AD at the time specified, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007.

(1) For all airplanes: Do a general visual inspection of the drive assembly of the aft elevator standby loop of the elevator standby cable system for interference between the clevis and bolt of the bellcrank assembly, correct orientation of the pull-pull cable clevis bolt, and excessive freplay of the bellcrank assembly bearing. Do the inspection within 3,000 flight hours or 27 months after the effective date of this AD, whichever occurs later. Do all applicable corrective actions before further flight.

(2) For airplanes identified in the service bulletin as Group 1, Configuration 1: Modify the pull-pull cable clevis in the drive assembly of the aft elevator standby loop of the elevator standby cable system. Do the modification at the applicable time specified in paragraph 1.E., "Compliance," of the service bulletin; except, where the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, ATTN: David Rathfelder, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5229; fax (562) 627-5210; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time

for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846; Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 18, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-19721 Filed 9-5-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0562; Directorate Identifier 2008-NM-010-AD; Amendment 39-15658; AD 2008-18-01]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170 and ERJ 190 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found cases where the pressure equalization valve was not installed in the left-hand bulkhead blowout panel, on the forward and/or aft cargo compartments, thus affecting the effectiveness of fire detection, containment and suppression.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective October 14, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 14, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Kenny Kaulia, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2848; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on May 20, 2008 (73 FR 29085). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been found cases where the pressure equalization valve was not installed in the left-hand bulkhead blowout panel, on the forward and/or aft cargo compartments, thus affecting the effectiveness of fire detection, containment and suppression.

Corrective actions include inspecting for the presence of pressure equalization valves and, if necessary, installing pressure equalization valves. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 101 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$8,080, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008-18-01 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-15658. Docket No. FAA-2008-0562; Directorate Identifier 2008-NM-010-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 14, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to EMBRAER Model ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, -200 LR, -200 STD, and -200 SU airplanes, having serial numbers (S/N) 17000002, 17000004 through 17000013, and 17000015 through 17000154; and Model ERJ 190-100 STD, -100 LR, -100 IGW, -100 ECJ, -200 STD, -200 LR, and -200 IGW airplanes, having S/N 19000002, 19000004, and

19000006 through 19000060; certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 21: Air Conditioning.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

It has been found cases where the pressure equalization valve was not installed in the left-hand bulkhead blowout panel, on the forward and/or aft cargo compartments, thus affecting the effectiveness of fire detection, containment and suppression.

Corrective actions include inspecting for the presence of pressure equalization valves and, if necessary, installing pressure equalization valves.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 500 flight hours after the effective date of this AD, perform a general visual inspection on the left-hand bulkhead blowout panel of both the forward and aft cargo compartments to determine whether the pressure equalization valves, part number (P/N) 120-48865-003, are installed. If both pressure equalization valves are installed in their respective blowout panels, no additional action is required by this AD.

(2) If any valve is not installed, within 700 flight hours after the effective date of this AD, install valve P/N 120-48865-003, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 170-21-0032 or 190-21-0019, both dated August 10, 2007; as applicable.

Note 1: For the purpose of this AD, a general visual inspection (GVI) is: "A visual examination of an interior or exterior area, installation or assembly to detect obvious damage, failure or irregularity. This level of inspection is made from within touching distance, unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight or drop-light, and may require removal or opening of access panels or doors. Stands, ladders or platforms may be required to gain proximity to the area being checked."

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kenny Kaulia, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate,

FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2848; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Brazilian Airworthiness Directives 2007-11-01 and 2007-11-02, both effective December 12, 2007; and EMBRAER Service Bulletins 170-21-0032 and 190-21-0019, both dated August 10, 2007; for related information.

Material Incorporated by Reference

(i) You must use EMBRAER Service Bulletin 170-21-0032, dated August 10, 2007; or EMBRAER Service Bulletin 190-21-0019, dated August 10, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-19850 Filed 9-5-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-0036; Directorate Identifier 2007-NE-22-AD; Amendment 39-15636; AD 2008-16-18]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc RB211-524 Series Turbofan Engines; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document makes a correction to Airworthiness Directive (AD) 2008-16-18. That AD applies to Rolls-Royce (RR) RB211-524 series turbofan engines with certain high pressure (HP) turbine disks installed. That AD was published in the **Federal Register** on August 11, 2008 (73 FR 46550). Paragraph (c) in the regulatory section is incorrect. This document corrects that paragraph. In all other respects, the original document remains the same.

DATES: *Effective Date:* Effective September 8, 2008.

FOR FURTHER INFORMATION CONTACT: Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: jason.yang@faa.gov; telephone (781) 238-7747; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: On August 11, 2008 (73 FR 46550), we published a final rule AD, FR Doc. E8-18102, in the **Federal Register**. That AD applies to RR RB211-524 series turbofan engines. We need to make the following correction:

§ 39.13 [Corrected]

On page 46551, in the first column, in the Regulatory Section, in the Applicability paragraph (c), in the second line, “with certain high pressure (HP) turbine discs installed” is corrected to read “with high pressure (HP) turbine discs, part numbers (P/Ns)-serial numbers (SNs) FK24651-LAQDY6061 and -LDRCZ10453 to -LDRCZ10720, and -LQDY9903, and -LQDY9924, FK24790-CRCZ6 to -CRCZ25 and -LDRCZ10717 to -LDRCZ14022, UL23166-LQDY6516 to -LQDY8718, UL24561-LQDY6389 to -LQDY6438, UL24994-LQDY6405 to -LQDY8727, UL29472-LAQDY6013 to -LAQDY6092 and -LDRCZ10029 to -LDRCZ10821 and -LDRCZ6000 to -LDRCZ6060 and -LQDY6592 to -LQDY9993, UL29473-CRCZ24 to

-CRCZ25 and -CZ12135 to -CZ12333 and -LAQDY6010 to -LAQDY6088 and -LDRCZ10003 to -LDRCZ15372 and -LDRCZ6001 to -LDRCZ9995 and -LQDY10001 and -LQDY9606 to -LQDY9989, installed”.

Issued in Burlington, Massachusetts, on August 28, 2008.

Marc Bouthillier,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8-20498 Filed 9-5-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food And Drug Administration

21 CFR Parts 16 and 1240

[Docket No. FDA-2003-N-0427] (formerly Docket No. 2003N-0400)

Control of Communicable Diseases; Restrictions on African Rodents, Prairie Dogs, and Certain Other Animals

AGENCY: Food and Drug Administration (HHS).

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is removing its regulation that established restrictions on the capture, transport, sale, barter, exchange, distribution, and release of African rodents, prairie dogs, and certain other animals. We are removing the restrictions because we believe they are no longer needed to prevent the further introduction, transmission, or spread of monkeypox, a communicable and potentially fatal disease, in the United States.

DATES: Effective September 8, 2008.

FOR FURTHER INFORMATION CONTACT: Philip L. Chao, Office of Policy, Planning, and Preparedness (HF-23), Food and Drug Administration, 5600 Fishers Lane, Rockville, MD 20857, 301-827-0587.

SUPPLEMENTARY INFORMATION:

Table of Contents

I. What Is Monkeypox, and How Did It Spread in the United States?

II. How Did We Respond to the Monkeypox Outbreak?

III. What Other Actions Did the Department of Health and Human Services Take?

A. Why Did the Interim Final Rule Continue After January 20, 2004?

B. Were the New Data Available to the Public?

C. Is There a Risk That Monkeypox