

(3) If level 1 corrosion is found during the inspection required by paragraph (g)(1) of this AD, no further action is required by this AD.

(4) If level 2 corrosion is found during the inspection required by paragraph (g)(1) of this AD, do the action in either paragraph (g)(4)(i) or (ii) of this AD.

(i) Before further flight replace the HS assembly or repair the HS assembly in accordance with instructions from either the Manager, International Validation Branch, FAA; EASA; or Piaggio's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(ii) Within 400 hours TIS or 12 months, whichever occurs first after the inspection required by paragraph (g)(1) of this AD, and thereafter at intervals not to exceed 400 hours TIS or 12 months, whichever occurs first after the most recent inspection, repeat the inspection required by paragraph (g)(1) of this AD. In addition, inspect the internal composite structure of the HS central box for surface cracks, distortion, and damage. After each repetitive inspection, before further flight, assess the inspection findings as required by paragraph (g)(2) of this AD. If it is determined that the level 2 corrosion has worsened since the last inspection; or if any surface cracks, distortion, or damage is found during any inspection; before further flight, replace the HS assembly or repair the HS assembly in accordance with instructions from either the Manager, International Validation Branch, FAA; EASA; or Piaggio's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature. These inspections must be repeated at intervals not to exceed 400 hours TIS or 12 months, whichever occurs first after the most recent inspection, until a maximum of 660 hours TIS or 13 months, whichever occurs first after the inspection required by paragraph (g)(1) of this AD has been reached, at which time the HS assembly must be repaired or replaced.

(5) If level 3 corrosion is found during the inspection required by paragraph (g)(1) of this AD, do the actions required by paragraph (g)(5)(i) or (ii) of this AD.

(i) Before further flight after the inspection required by paragraph (g)(1) of this AD, replace the HS assembly or repair the HS assembly in accordance with instructions from either the Manager, International Validation Branch, FAA; EASA; or Piaggio's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(ii) Within 200 hours TIS or 6 months, whichever occurs first after the inspection required by paragraph (g)(1) of this AD, and thereafter at intervals not to exceed 200 hours TIS or 6 months, whichever occurs first after the most recent inspection, repeat the inspection required by paragraph (g)(1) of this AD. In addition, inspect the internal composite structure of the HS central box for surface cracks, distortion, and damage. After each repetitive inspection, before further flight, assess the inspection findings as required by paragraph (g)(2) of this AD. If it is determined that the level 3 corrosion has worsened since the last inspection; or if any surface cracks, distortion, or damage is

found; before further flight, replace the HS assembly or repair the HS assembly in accordance with instructions from either the Manager, International Validation Branch, FAA; EASA; or Piaggio's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature. These inspections must be repeated at intervals not to exceed 200 hours TIS or 6 months, whichever occurs first after the most recent inspection, until a maximum of 660 hours TIS or 13 months, whichever occurs first after the inspection required by paragraph (g)(1) of this AD, at which time the HS assembly must be repaired or replaced.

(6) Repair or replacement of the HS assembly is terminating action for the repetitive inspections required by paragraphs (g)(4)(ii) and (g)(5)(ii) of this AD.

(h) Credit for Previous Actions

You may take credit for the actions required by paragraphs (g)(1) through (5) of this AD if you performed those actions before the effective date of this AD using Piaggio Aerospace Service Bulletin 80–0489, Revision 1, dated May 13, 2022.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

(1) Refer to EASA AD 2023–0007, dated January 13, 2023, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1819.

(2) For more information about this AD, contact Sungmo Cho, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238–7241; email: sungmo.d.cho@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piaggio Aerospace Service Bulletin 80–0489, Revision 2, dated November 30, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Piaggio Aviation S.p.A., P180 Customer Support, via Pionieri e Aviatori d'Italia, snc—16154 Genoa, Italy; phone: +39 331 679 74 93; email: technicalsupport@piaggioaerospace.it.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on August 30, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–19092 Filed 9–6–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1816; Project Identifier MCAI–2021–01460–R]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH (AHD) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Deutschland GmbH (AHD) Model MBB–BK 117 D–3 helicopters. This proposed AD was prompted by recalculations of the inspection intervals for certain parts. This proposed AD would require revising the airworthiness limitations section (ALS) of the existing helicopter maintenance manual or instructions for continued airworthiness for your helicopter and the existing approved maintenance or inspection program for your helicopter, as applicable, to reduce the inspection interval of certain parts, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 23, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1816; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA material is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1816.

Other Related Service Information:

For Airbus Helicopters service information identified in this NPRM, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at airbus.com/en/products-services/helicopters/hcare-services/airbusworld. You may also view this service information at the FAA contact information under *Material Incorporated by Reference* above.

FOR FURTHER INFORMATION CONTACT: Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email william.mccully@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1816; Project Identifier MCAI-2021-01460-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email william.mccully@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0290, dated and corrected December 23, 2021 (EASA AD 2021-0290), to correct an unsafe condition for all serial-numbered Airbus Helicopters Deutschland GmbH

Model MBB-BK117 D-3 and D-3m helicopters.

This proposed AD was prompted by recalculations of the inspection intervals for certain parts. The FAA is proposing this AD to reduce the inspection intervals for certain parts. See EASA AD 2021-0290 for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0290 requires replacing components before exceeding their life limits and accomplishing maintenance tasks within thresholds and intervals specified in the applicable ALS. Depending on the results of the maintenance tasks, EASA AD 2021-0290 requires accomplishing corrective action(s) or contacting AHD [Airbus Helicopters Deutschland GmbH] for approved instructions and accomplishing those instructions. EASA AD 2021-0290 also requires revising the Aircraft Maintenance Programme (AMP) by incorporating the limitations, tasks, and associated thresholds and intervals described in the specified ALS as applicable to helicopter model and configuration. Revising the AMP constitutes terminating action for the requirements to replace components before exceeding their life limits and accomplish maintenance tasks within thresholds and intervals specified in the applicable ALS as required by EASA AD 2021-0290.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA reviewed Airbus Helicopters Alert Service Bulletin ASB MBB-BK117 D-3-04A-001, Revision 0, dated December 22, 2021. This service information specifies checking the total accumulated flight hours since new for bolt part number (P/N) D671M7501201, bolt P/N D671M7501211, and mast bolt P/N D620M0501203, and accomplishing the airworthiness inspection within the reduced airworthiness inspection interval of 400 flight hours.

The FAA also reviewed Airbus MBB-BK117 D-3 Chapter 04, ALS, Revision 1, dated December 14, 2021. This service information specifies airworthiness limitations, tasks, and associated thresholds and intervals for various parts. Revision 1 of this service information specifies various updates for certain components.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2021–0290, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD and except as discussed under “Differences Between this Proposed AD and the EASA AD.”

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2021–0290 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021–0290 through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021–0290 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021–0290. Service information referenced in EASA AD 2021–0290 for compliance will be available at *regulations.gov* under Docket No. FAA–2023–1816 after the FAA final rule is published.

Differences Between This Proposed AD and the EASA AD

EASA AD 2021–0290 applies to Model MBB–BK117 D–3m helicopters, whereas this proposed AD would not

because that model is not FAA type-certificated.

EASA AD 2021–0290 requires replacing certain components before exceeding applicable life limits, accomplishing certain maintenance tasks within thresholds and intervals as specified in the ALS, as defined within, and depending on the results, accomplishing corrective action within the compliance time specified in that ALS. EASA AD 2021–0290 also requires revising the approved AMP to incorporate the limitations, tasks, and associated thresholds and intervals described in that ALS within 12 months after its effective date. Whereas, this proposed AD would require revising existing documents and programs within 30 days to incorporate the limitations, tasks, and associated thresholds and intervals described in that ALS, and clarifies that if an incorporated limitation or threshold therein is reached before 30 days after the effective date of the final rule of this proposed AD, you still have up to 30 days after the effective date of the final rule of this proposed AD to accomplish the corresponding task.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 29 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Revising the ALS of the existing helicopter maintenance manual or instructions for continued airworthiness for your helicopter and the existing approved maintenance or inspection program for your helicopter, as applicable, would take about 2 work-hours for an estimated cost of \$170 per helicopter and \$4,930 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters Deutschland GmbH

(AHD): Docket No. FAA–2023–1816;
Project Identifier MCAI–2021–01460–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by October 23, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH (AHD) Model MBB–BK 117 D–3 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC)
Code: 6710, Main Rotor Control.

(e) Unsafe Condition

This AD was prompted by recalculations of the inspection intervals for certain parts. The FAA is issuing this AD to reduce the inspection intervals for certain parts. The unsafe condition, if not addressed, could result in failure of a part and loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0290, dated and corrected December 23, 2021 (EASA AD 2021–0290).

(h) Exceptions to EASA AD 2021–0290

(1) Where EASA AD 2021–0290 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the requirements specified in paragraphs (1), (2), (4), and (5) of EASA AD 2021–0290.

(3) Where paragraph (3) of EASA AD 2021–0290 specifies revising “the approved AMP” within 12 months after its effective date, this AD requires revising the airworthiness limitations section of your existing helicopter maintenance manual or instructions for continued airworthiness and your existing approved maintenance or inspection program, as applicable, within 30 days after the effective date of this AD.

(4) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2021–0290 is on or before the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2021–0290, or within 30 days after the effective date of this AD, whichever occurs later.

(5) This AD does not adopt the “Remarks” section of EASA AD 2021–0290.

(i) Provisions for Alternative Actions and Intervals

After the airworthiness limitations section of the existing helicopter maintenance manual or instructions for continued airworthiness; and the existing approved maintenance or inspection program, as applicable, has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) and associated thresholds and intervals, including life limits, are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2021–0290.

(j) Special Flight Permit

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342–1080; email william.mccully@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0290, dated and corrected December 23, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0290, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on August 30, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–19080 Filed 9–6–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2023–1821; Project Identifier MCAI–2022–01045–A]

RIN 2120–AA64

Airworthiness Directives; Viking Air Limited (Type Certificate Previously Held by Bombardier Inc. and de Havilland, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Viking Air Limited (type certificate previously held by Bombardier Inc. and de Havilland, Inc.) (Viking) Model DHC–3 airplanes. This proposed AD was prompted by a report of cracking in the left-hand side (LHS) and right-hand side (RHS) lower engine mount pickup fittings. This proposed AD would require a one-time inspection of the affected parts for cracking, deformation, corrosion, fretting or wear, paint or surface coating damage, and loose, missing, or broken fasteners, and applicable corrective actions. This proposed AD would also require reporting the inspection results. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by October 23, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2023–1821; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.