

Installation of Secondary Override Pump Control Relays

(l) For the airplanes identified in paragraph 1.A.1. of Boeing Alert Service Bulletin 737-28A1248, dated December 21, 2006: Within 60 months after the effective date of this AD, install two secondary override fuel pump control relays to each existing primary override fuel pump control relay for the center fuel tank fuel boost pumps, in accordance with the applicable service bulletin.

AWLs Revision for AWL No. 28-AWL-23

(m) For the airplanes identified in paragraph 1.A.1. of Boeing Alert Service Bulletin 737-28A1248, dated December 21, 2006: Concurrently with installing the secondary override pump control relays in accordance with paragraph (l) of this AD, revise the AWLs section of the Instructions for Continued Airworthiness by incorporating AWL No. 28-AWL-23 of Subsection F of Revision May 2006 of the MPD into the MPD. Accomplishing the revision in accordance with a later revision of the MPD is an acceptable method of compliance if the revision is approved by the Manager, Seattle ACO.

Terminating Action for AD 2001-08-24

(n) Accomplishing the actions required by paragraphs (g), (h), (i), (j), and (k) of this AD terminates the requirements of paragraph (a) of AD 2001-08-24 for Model 737-600, -700, -700C, -800, and -900 series airplanes that have the automatic shutoff system installed. After accomplishing the actions required by paragraphs (g), (h), (i), (j), and (k) of this AD, the AFM limitation required by paragraph (b) of AD 2001-08-24 may be removed from the AFM for those airplanes.

Terminating Action for AD 2002-24-51

(o) Accomplishing the actions required by paragraphs (g), (h), (i), (j), and (k) of this AD terminates the requirements of paragraph (b) of AD 2002-24-51 for Model 737-600, -700, -700C, -800, and -900 series airplanes that have the automatic shutoff system installed. After accomplishing the actions required by paragraphs (g), (h), (i), (j), and (k) of this AD, the AFM limitations required by paragraph (b) of AD 2002-24-51 may be removed from the AFM for those airplanes.

Alternative Methods of Compliance (AMOCs)

(p)(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on June 26, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7-13326 Filed 7-9-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28662; Directorate Identifier 2007-NM-014-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800 and -900 Series Airplanes; and Model 757-200, -200PF, -200CB, and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing airplanes, identified above. This proposed AD would require inspecting to determine if certain motor-operated shutoff valve actuators for the fuel tanks are installed, and related investigative and corrective actions if necessary. This proposed AD would also require revising the Airworthiness Limitations (AWLs) section of the Instructions for Continued Airworthiness to incorporate AWL No. 28-AWL-21, No. 28-AWL-22, and No. 28-AWL-24 (for Model 737-600, -700, -700C, -800 and -900 series airplanes), and No. 28-AWL-23, No. 28-AWL-24, and No. 28-AWL-25 (for Model 757-200, -200PF, -200CB, and -300). This proposed AD results from a design review of the fuel tank systems. We are proposing this AD to prevent electrical energy from lightning, hot shorts, or fault current from entering the fuel tank through the actuator shaft, which could result in fuel tank explosions and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by August 24, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov>

and follow the instructions for sending your comments electronically.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Judy Coyle, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6497; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28662; Directorate Identifier 2007-NM-014-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground floor of the West Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The FAA has examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (66 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21-78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design (i.e., type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with a latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

We have determined that the actions identified in this AD are necessary to reduce the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Boeing has found that, under specific conditions, it was possible for electrical current to flow through certain motor operated shutoff valve actuators in the fuel tank. Boeing has developed a new valve actuator to replace those actuators. A motor-operated shutoff valve actuator that does not have sufficient protection against electrical energy from lightning, hot shorts, and fault current, could allow electrical energy to enter the fuel tank through the actuator drive shaft, which could result in fuel tank explosions and consequent loss of the airplane.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletins 737-28A1207, dated February 15, 2007, and 757-28A0088, dated January 25, 2007. Boeing Alert Service Bulletin 757-28A0088 describes procedures for inspecting to determine the part number (P/N) of motor-operated valve (MOV) actuators for the fuel tanks; Boeing Alert Service Bulletin 737-28A1207 also specifies removing MOV actuators having a certain P/N. The service bulletins specify that no more work is necessary if the P/N is acceptable.

For Boeing Model 737-600, -700, -700C, -800 and -900 series airplanes, the affected MOVs are at 3 locations: The left engine fuel shutoff (spar) valve, the right engine fuel shutoff (spar) valve, and the fuel crossfeed valve. For Boeing Model 757-200, -200PF, -200CB, and -300 series airplanes, the affected MOVs are at 6 locations for airplanes in the single crossfeed configuration, or at 7 locations for airplanes in the dual crossfeed configuration.

If the P/N is not acceptable, the service bulletins specify related investigative and corrective actions as follows:

For all airplanes: Reworking the index plate; reworking the adapter plate if necessary; installing the adapter/shaft plate with sealant; installing the index plate with sealant; installing a new MOV actuator on the index plate with sealant; installing bonding jumpers with sealant. For Boeing Model 737-600, -700, -700C, -800 and -900 series airplanes the actions also include installing shield ground terminals using sealed faying surface bonding for the main

tank fuel quantity indicating system (FQIS). All of these actions include steps that specify measuring the electrical bonding resistance between various components and reworking the bonding if necessary.

We have also reviewed Subsection F, "AIRWORTHINESS LIMITATIONS—FUEL SYSTEM AWLs," of Boeing 737-600/700/700C/700IGW/800/900 Maintenance Planning Data (MPD) Document D626A001—CMR, Section 9, Revision May 2006; and Subsection G, "AIRWORTHINESS LIMITATIONS—FUEL SYSTEM AWLs," of Boeing 757 MPD Document D622N001, Section 9, Revision October 2006 (hereafter referred to as Revisions May 2006 and October 2006 of the MPDs). These sections of the MPDs describe the critical design configuration control limitations (CDCCL) and inspections applicable to the MOV installation. CDCCLs are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

Subsection F of Revision May 2006 of the Boeing 737-600/700/700C/700IGW/800/900 MPD adds new fuel system AWLs 28-AWL-21 (lightning and fault current protection—MOV actuator), No. 28-AWL-22 (repair of the MOV actuator), and 28-AWL-24 (lightning and fault current protection—MOV actuator).

Subsection G of Revision October 2006 of the Boeing 757 MPD adds new fuel system AWLs No. 28-AWL-23 (lightning and fault current protection—MOV actuator), No. 28-AWL-24 (repair of the MOV actuator), and No. 28-AWL-25 (lightning and fault current protection—MOV actuator).

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require the following actions:

- Inspecting to determine if certain motor-operated shutoff valve actuators for the fuel tanks are installed, and

related investigative and corrective actions if necessary.

- Revising the Airworthiness Limitations (AWLs) section of the Instructions for Continued Airworthiness to incorporate AWL No. 28-AWL-21, No. 28-AWL-22, and No. 28-AWL-24 (for 737-600, -700, -700C, -800 and -900 series airplanes).

- Revising the Airworthiness Limitations (AWLs) section of the

Instructions for Continued Airworthiness to incorporate AWL No. 28-AWL-23, No. 28-AWL-24, and No. 28-AWL-25 (for Model 757-200, -200PF, -200CB, and -300).

This proposed AD would also allow accomplishing the revision to the AWLs section of the Instructions for Continued Airworthiness in accordance with later revisions of the MPD as an acceptable

method of compliance if they are approved by the Manager, Seattle Aircraft Certification Office, FAA.

Costs of Compliance

There are about 2,916 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 1,406 airplanes of U.S. registry. The average labor rate is \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection for MOV actuators	1	\$80	1,406	\$112,480
AWL revisions	3	240	1,406	337,440

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- Is not a "significant regulatory action" under Executive Order 12866;
- Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2007-28662; Directorate Identifier 2007-NM-014-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by August 24, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737-600, -700, -700C, -800 and -900 series airplanes; and Boeing Model 757-200, -200PF, -200CB, and -300 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletins 737-28A1207, dated February 15, 2007, and 757-28A0088, dated January 25, 2007.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections and maintenance actions. Compliance with these limitations is required by 14 CFR 43.16 and 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these limitations, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 43.16 and 91.403(c), the operator must request approval for revision to the airworthiness limitations (AWLs) in the Boeing 737-600/700/700C/700IGW/800/900 Maintenance Planning Data (MPD) Document D626A001-CMR and the Boeing 757 MPD Document D622N001-9, as applicable, according to paragraph (h) of this AD.

Unsafe Condition

(d) This AD results from a design review of the fuel tank systems. We are issuing this AD to prevent electrical energy from lightning, hot shorts, or fault current from entering the fuel tank through the actuator shaft, which could result in fuel tank explosions and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Bulletin Reference

(f) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of the following service bulletins, as applicable:

(1) For Model 737-600, -700, -700C, -800 and -900 series airplanes: Boeing Alert Service Bulletin 737-28A1207, dated February 15, 2007; and

(2) For Model 757-200, -200PF, -200CB, and -300 series airplanes: Boeing Alert Service Bulletin 757-28A0088, dated January 25, 2007.

Inspection and Related Investigative/Corrective Actions

(g) Within 60 months after the effective date of this AD: Inspect the applicable motor-operated valves (MOVs) to determine whether an MOV with the affected part number (P/N) identified in the Accomplishment Instructions of the applicable service bulletin is installed. A review of airplane maintenance records is acceptable in lieu of this inspection if the P/N of the part can be conclusively determined from that review. Do all applicable related investigative and corrective actions before further flight. Do all actions in accordance with the Accomplishment Instructions of the applicable service bulletin.

Revision of AWLs Section

(h) Concurrently with the actions in paragraph (g) of this AD: Revise the AWLs section of the Instructions for Continued Airworthiness by incorporating the information in paragraphs (h)(1) and (h)(2) of this AD, as applicable. Accomplishing the revision in accordance with a later revision of the MPD is an acceptable method of compliance if the revision is approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA.

(1) Section F., "AIRWORTHINESS LIMITATIONS—FUEL SYSTEM AWLs," of Boeing 737-600/700/700C/700IGW/800/900 Maintenance Planning Data (MPD) Document D626A001—CMR, Section 9, Revision May 2006, into the MPD to incorporate AWL No. 28-AWL-21, No. 28-AWL-22, and No. 28-AWL-24.

(2) Section G., "AIRWORTHINESS LIMITATIONS—FUEL SYSTEM AWLs," of Boeing 757 MPD Document D622N001, Section 9, Revision October 2006, into the MPD to incorporate AWL No. 28-AWL-23, No. 28-AWL-24, and No. 28-AWL-25.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on June 26, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7-13366 Filed 7-9-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2007-28554; **Airspace**
Docket No. 07-ASO-13]

**Proposed Establishment of Class E
Airspace; Winfield, FL**

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish Class E5 airspace at Winfield, FL. An Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP), helicopter point in space approach, has been developed for Interstate-10 Rest Stop Heliport, Winfield, FL. As a result, controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to contain the SIAP.

DATES: Comments must be received on or before August 9, 2007.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2007-28554; Airspace Docket No. 07-ASO-13, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room C210, 1701 Columbia Avenue, College Park, Georgia 30337.

FOR FURTHER INFORMATION CONTACT: Mark D. Ward, Manager, System Support, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire.

Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2007-28554; Airspace Docket No. 07-ASO-13." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>. Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Part 71 of the Federal