

Avenue du Général Eisenhower, BP 63647, 31036 Toulouse Cedex 1, France; telephone +33 5 61 19 76 95; fax +33 5 61 19 68 20; email retrofit.ata@fr.thalesgroup.com; Internet <http://www.thalesgroup.com/aerospace>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 30, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-29713 Filed 12-7-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1224; Directorate Identifier 2012-NM-112-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. This proposed AD was prompted by a report of an uncommanded slide back of the co-pilot seat to the end stop position. This proposed AD would require a one-time inspection for a part number, a tensile test of the affected seats, and corrective actions if necessary. We are proposing this AD to detect and prevent unwanted movement of a pilot or co-pilot seat in the horizontal direction, which could lead to inadvertent input on the flight control commands and possibly result in loss of controllability of the airplane.

DATES: We must receive comments on this proposed AD by January 24, 2013.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Airbus service information identified in this proposed AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. For EADS SOGERMA service information identified in this AD, contact EADS SOGERMA, Zone Industrielle de l'Arsenal, CS. 60109, 17303 Rochefort, Cedex France; phone: 33 5 46 82 84 84; fax: 33 5 46 82 88 13; email: SCOD1@sogerma.eads.net; Internet: <http://www.sogerma.eads.net>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-1224; Directorate Identifier 2012-NM-112-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy

aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the aviation authority for Member States of the European Community, has issued EASA Airworthiness Directive 2012-0102, dated June 8, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During a steep climb manoeuvre that was flown with a high pitch (25°) for training of ground threat avoidance, an Airbus A310 aeroplane experienced an uncommanded slide back of the co-pilot seat to the end stop position.

Investigation revealed that on the affected seat, the disc key inside the clutch was broken. SOGERMA Service Bulletin (SB) No 2510112-25-813, which addresses the previous end stop switch issue and which is covered by EASA AD 2010-0070 [which corresponds to FAA AD 2011-06-09, Amendment 39-16634 (76 FR 15805, March 22, 2011)] had been accomplished on this seat, but due to seizure, the key failure was not detected at time. This broken disc key caused a jamming between the gear and the shaft of the clutch. Despite this failure, the torque transmission between the gear and the shaft was sufficient for normal operation, but not to keep the seat in locked position during climbing, due to the high longitudinal loads generated by the high aeroplane incidence.

This condition, if not detected and corrected, could cause the pilot to lose contact with the controls, leading to an inadvertent input on the flight control commands during take-off or climb, possibly resulting in loss of control of the aeroplane.

For the reasons described above, this [EASA] AD requires a one-time inspection [part number (P/N) inspection of the seats and tensile test] of the affected seats and, depending on findings, accomplishment of applicable corrective action(s) [replacing the seat or modifying the seat by replacing actuator P/N RT19H4FX with a new actuator].

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Alert Operators Transmission A25W001-12, dated June 6, 2012; and EADS SOGERMA has issued Inspection Service Bulletin

2510112–25–898, dated April 25, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 161 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$4,523 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$741,888, or \$4,608 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Airbus: Docket No. FAA–2012–1224; Directorate Identifier 2012–NM–112–AD.

(a) Comments Due Date

We must receive comments by January 24, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A300 B4–601, B4–603, B4–620, B4–622, B4–605R, B4–622R, F4–605R, F4–622R, and C4–605R Variant F airplanes; and Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes; certificated in any category; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Reason

This AD was prompted by a report of an uncommanded slide back of the co-pilot seat to the end stop position. We are issuing this AD to detect and prevent unwanted movement of a pilot or co-pilot seat in the horizontal direction, which could lead to inadvertent input on the flight control commands possibly resulting in loss of controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Part Number (P/N) Inspection

Within 6 months after the effective date of this AD, except as provided by paragraph (h) of this AD: Do an inspection to determine the part number of each SOGERMA pilot and co-pilot seat installed on the airplane. As an alternative, a review of the maintenance or delivery records may be used to determine the part number of the pilot and co-pilot seat if the part number can be positively determined.

(h) Seats That Have Been Previously Tested or Modified

SOGERMA pilot and co-pilot seats having P/N 2510112 series (all suffixes) or P/N 2510113 series (all suffixes) that, before the effective date of this AD, have already passed the tensile test specified in paragraph (i) of this AD, or have been modified in accordance with the Accomplishment Instructions of EADS SOGERMA Inspection Service Bulletin 2510112–25–898, dated April 25, 2012, are not required to be tested, and are considered to be compliant with the requirements of this AD.

(i) Tensile Test

If, during the inspection required by paragraph (g) of this AD, the part number of a seat is identified as P/N 2510112 series (all suffixes), or P/N 2510113 series (all suffixes): Within 6 months after the effective date of this AD, do a tensile test on that seat in accordance with Airbus Alert Operators Transmission (AOT) A25W001–12, dated June 6, 2012.

(j) Replacement or Modification

If the tensile test sample does not break off while performing the test required by paragraph (i) of this AD, before further flight, do one of the actions specified in paragraph (j)(1) or (j)(2) of this AD.

(1) Replace the affected seat with a new or serviceable seat that has passed the tensile test specified in paragraph (i) of this AD. Do the replacement in accordance with Airbus AOT A25W001–12, dated June 6, 2012.

(2) Modify the seat by replacing actuator P/N RT19H4FX of the affected seat, in accordance with the Accomplishment Instructions of EADS SOGERMA Inspection Service Bulletin 2510112–25–898, dated April 25, 2012; or Airbus AOT A25W001–12, dated June 6, 2012.

(k) Parts Installation Prohibition

As of the effective date of this AD, no person may install a SOGERMA pilot or co-pilot seat having P/N 2510112 series, or P/N 2510113 series, on any airplane unless it has passed the tensile test required by paragraph (i) of this AD, or has been replaced or modified as required by paragraph (j) of this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information European Aviation Safety Agency, Airworthiness Directive 2012-0102, dated June 8, 2012, and the service information specified in paragraphs (m)(1)(i) and (m)(1)(ii) of this AD, for related information.

(i) Airbus Alert Operators Transmission A300-A25W001-12, dated June 6, 2012.

(ii) EADS SOGERMA Service Bulletin 2510112-25-898, dated April 25, 2012.

(2) For Airbus service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. For EADS SOGERMA service information identified in this AD, contact EADS SOGERMA, Zone Industrielle de l'Arsenal, CS. 60109, 17303 Rochefort, Cedex France; phone: 33 5 46 82 84 84; fax: 33 5 46 82 88 13; email: SCOD1@sogerma.eads.net; Internet: <http://www.sogerma.eads.net>. You may review copies of the referenced service information

at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 30, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-29710 Filed 12-7-12; 8:45 am]

BILLING CODE 4910-13-P

CONSUMER PRODUCT SAFETY COMMISSION
16 CFR Parts 1112 and 1222

[Docket No. CPSC-2012-0067]

Safety Standard for Bedside Sleepers

AGENCY: Consumer Product Safety Commission.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Danny Keysar Child Product Safety Notification Act, Section 104 of the Consumer Product Safety Improvement Act of 2008 (CPSIA), requires the United States Consumer Product Safety Commission (Commission or CPSC) to promulgate consumer product safety standards for durable infant or toddler products. These standards are to be “substantially the same as” applicable voluntary standards or more stringent than the voluntary standard if the Commission concludes that more stringent requirements would further reduce the risk of injury associated with the product. The Commission is proposing a safety standard for bedside sleepers in response to the direction under Section 104(b) of the CPSIA.

DATES: Submit comments by February 25, 2013.

ADDRESSES: Comments related to the Paperwork Reduction Act aspects of the marking, labeling, and instructional literature of the proposed rule should be directed to the Office of Information and Regulatory Affairs, OMB, Attn: CPSC Desk Officer, FAX: 202-395-6974, or emailed to oir_submission@omb.eop.gov.

Other comments, identified by Docket No. CPSC-2012-0067, may be submitted electronically or in writing:

Electronic Submissions: Submit electronic comments to the Federal eRulemaking Portal at: <http://www.regulations.gov>. Follow the instructions for submitting comments. To ensure timely processing of comments, the Commission is no longer directly accepting comments submitted by electronic mail (email), except

through www.regulations.gov. The Commission encourages you to submit electronic comments by using the Federal eRulemaking Portal, as described above.

Written Submissions: Submit written submissions in the following way: Mail/Hand delivery/Courier (for paper, disk, or CD-ROM submissions), preferably in five copies, to: Office of the Secretary, Consumer Product Safety Commission, Room 820, 4330 East West Highway, Bethesda, MD 20814; telephone (301) 504-7923.

Instructions: All submissions received must include the agency name and docket number for this proposed rulemaking. All comments received may be posted without change, including any personal identifiers, contact information, or other personal information provided, to <http://www.regulations.gov>. Do not submit confidential business information, trade secret information, or other sensitive or protected information that you do not want to be available to the public. If furnished at all, such information should be submitted in writing.

Docket: For access to the docket to read background documents or comments received, go to <http://www.regulations.gov>, and insert the docket number, CPSC-2012-0067, into the “Search” box and follow the prompts.

FOR FURTHER INFORMATION CONTACT:

Douglas A. Lee, Project Manager, Directorate for Engineering Sciences, Consumer Product Safety Commission, 5 Research Place, Rockville, MD 20850; telephone 301-987-2073; email dlee@cpsc.gov.

SUPPLEMENTARY INFORMATION:**A. Background and Statutory Authority**

The Consumer Product Safety Improvement Act of 2008, (CPSIA, Pub. L. 110-314), was enacted on August 14, 2008. Section 104(b) of the CPSIA, part of the Danny Keysar Child Product Safety Notification Act, requires the Commission to: (1) Examine and assess the effectiveness of voluntary consumer product safety standards for durable infant or toddler products, in consultation with representatives of consumer groups, juvenile product manufacturers, and independent child product engineers and experts, and (2) promulgate consumer product safety standards for durable infant and toddler products. These standards are to be “substantially the same as” applicable voluntary standards or more stringent than the voluntary standard if the Commission concludes that more stringent requirements would further