

**PART 39—AIRWORTHINESS
DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-24-067 SAAB AIRCRAFT AB:
Amendment 39-13882. Docket 2002-
NM-182-AD.

Applicability

Model SAAB SF340A series airplanes, serial numbers (S/Ns) 004 through 159 inclusive; and Model SAAB 340B series airplanes, S/Ns 160 through 459 inclusive; certificated in any category.

Compliance

Required as indicated, unless accomplished previously.

To prevent failure of the retract actuator bracket attachment bolt (RABAB), which could result in loosening of the retract actuator bracket and consequent failure of the main landing gear (MLG) to retract, with considerable damage to other landing gear parts, including the MLG trunnion fitting, accomplish the following:

Replacement/Reidentification of RABAB

(a) For airplanes not previously modified in accordance with Saab Service Bulletin 340-32-124, Revision 01, dated May 21, 2002: Within 12 months after the effective date of this AD, perform the actions specified in paragraphs (a)(1) and (a)(2) of this AD in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-32-131, dated June 29, 2004, including Attachments 1 and 2, both dated January 2002, and Attachments 3 and 4, both dated April 2002.

Note 1: APPH Ltd. Service Bulletins AIR83022-32-28 and AIR83064-32-08, both dated January 2002, comprising Attachments 1 and 2; and Service Bulletins AIR83022-32-29 and AIR83064-32-09, both dated April 2002, comprising Attachments 3 and 4; are incorporated into Saab Service Bulletin 340-32-131 as additional sources of service information.

(1) Replace the existing RABAB with a new RABAB.

(2) Re-identify the MLG shock strut.

Inspection of RABAB

(b) For airplanes previously modified in accordance with Saab Service Bulletin 340-32-124, Revision 01, dated May 21, 2002: Within 6 months after the effective date of this AD, perform a one-time detailed inspection for corrosion, fretting, or other damage of any RABAB replaced in accordance with Saab Service Bulletin 340-32-124, Revision 01; and applicable corrective actions; in accordance with the

Accomplishment Instructions of Saab Service Bulletin 340-32-131, dated June 29, 2004, including Attachments 1 and 2, both dated January 2002, and Attachments 3 and 4, both dated April 2002.

Note 2: For the purposes of this AD, a detailed inspection is "an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirrors magnifying lenses, etc. may be necessary. Surface cleaning and elaborate procedures may be required."

Parts Installation

(c) As of the effective date of this AD, no person may install a RABAB, part number (P/N) AIR83022-5 through -18 inclusive, or P/N AIR83064 (any suffix), on any airplane.

Special Flight Permits

(d) Special flight permits are not allowed as specified in section 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199).

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(f) The actions shall be done in accordance with Saab Service Bulletin 340-32-131, dated June 29, 2004; including Attachments 1 and 2, both dated January 2002, and Attachments 3 and 4, both dated April 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Note 3: The subject of this AD is addressed in Swedish airworthiness directive 1-195, effective July 6, 2004.

Effective Date

(g) This amendment becomes effective on January 4, 2005.

Issued in Renton, Washington, on November 17, 2004.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 04-26191 Filed 11-29-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2004-18826; Airspace
Docket No. 04-ACE-52]

**Modification of Class E Airspace;
Lamar, MO**

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This document confirms the effective date of the direct final rule which revises Class E airspace at Lamar, MO.

EFFECTIVE DATE: 0901 UTC, January 20, 2005.

FOR FURTHER INFORMATION CONTACT: Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2524.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on October 4, 2004 (69 FR 59129). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on January 20, 2005. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Issued in Kansas City, MO, on November 12, 2004.

Anthony D. Roetzel,

*Acting Area Director, Western Flight Services
Operations.*

[FR Doc. 04-26343 Filed 11-29-04; 8:45 am]

BILLING CODE 4910-13-M