

Applicability: Model 737-300 series airplanes modified by Supplemental Type Certificate (STC) ST00171SE, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To ensure that the flight crew is able to remove electrical power from the in-flight entertainment (IFE) system when necessary and is advised of appropriate procedures for such action, accomplish the following:

Installation of Power Switch and Revision of Airplane Flight Manual

(a) Within 18 months after the effective date of this AD, accomplish paragraphs (a)(1) and (a)(2) of this AD, in accordance with Flight Structures Service Bulletin 94FS492-23-01, Revision 2, dated September 21, 2000.

(1) Install a master switch to apply and remove power from the IFE system.

(2) Insert the Temporary Revision included in the service bulletin into the Emergency Procedures section of the FAA-approved Airplane Flight Manual (AFM), to advise the flight crew on procedures for using the master switch installed in accordance with paragraph (a)(1) of this AD. Once the AFM has been formally revised to include the information in the Temporary Revision, the Temporary Revision may be removed from the AFM.

Spares

(b) As of the effective date of this AD, no person may install an IFE system in accordance with STC ST00171SE on any airplane, unless it is modified and the AFM is revised in accordance with this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197

and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Flight Structures Service Bulletin 94FS492-23-01, Revision 2, dated September 21, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Flight Structures, Inc., 4407 172nd Street NE., Arlington, Washington 98223. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on August 16, 2001.

Issued in Renton, Washington, on July 3, 2001.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-17158 Filed 7-11-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-229-AD; Amendment 39-12312; AD 2001-14-02]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas DC-9-51 and DC-9-83 Series Airplanes Modified by Supplemental Type Certificate SA8026NM

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all McDonnell Douglas Model DC-9-51 and DC-9-83 series airplanes modified by Supplemental Type Certificate SA8026NM, that requires deactivation of the in-flight entertainment (IFE) system and removal of the system from the airplane. This action is necessary to prevent the inability of the flight crew to remove power from the IFE system when necessary. Inability to remove power from the IFE system during a non-normal or emergency situation could result in inability to control smoke or fumes in the airplane flight deck or cabin. This action is intended to address the identified unsafe condition.

DATES: Effective August 16, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 16, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Hollingsead International, Inc., 7416 Hollister Avenue, Goleta, California 93117. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

George Mabuni, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5341; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all McDonnell Douglas Model DC-9-51 and DC-9-83 series airplanes modified by Supplemental Type Certificate SA8026NM was published in the **Federal Register** on March 2, 2001 (66 FR 13187). That action proposed to require deactivation of the in-flight entertainment (IFE) system and removal of the system from the airplane.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

After careful review of the available data, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 6 airplanes of the affected design in the worldwide fleet. The FAA estimates that 3 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these

figures, the cost impact of this AD on U.S. operators is estimated to be \$720, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-14-02 McDonnell Douglas:
Amendment 39-12312. Docket 2000-NM-229-AD.

Applicability: Model DC-9-51 and DC-9-83 series airplanes modified by Supplemental Type Certificate (STC) SA8026NM, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the inability of the flight crew to remove power from the in-flight entertainment (IFE) system when necessary; which, during a non-normal or emergency situation, could result in inability to control smoke or fumes in the airplane flight deck or cabin; accomplish the following:

Deactivation and Removal

(a) Within 18 months after the effective date of this AD, deactivate the IFE system and remove the system from the airplane, in accordance with Hollingsead International Service Bulletin 2526-2332-001, dated July 19, 2000.

Spares

(b) As of the effective date of this AD, no person shall install an IFE system in accordance with STC SA8026NM on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Hollingsead International Service Bulletin 2526-2332-001, dated July 19, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Hollingsead International, Inc., 7416 Hollister Avenue, Goleta, California 93117. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on August 16, 2001.

Issued in Renton, Washington, on June 29, 2001.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-17156 Filed 7-11-01; 8:45 am]

BILLING CODE 4910-13-U

SECURITIES AND EXCHANGE COMMISSION

17 CFR Part 211

[Release No. SAB 102]

Staff Accounting Bulletin No. 102

AGENCY: Securities and Exchange Commission.

ACTION: Publication of staff accounting bulletin.

SUMMARY: This staff accounting bulletin expresses certain of the staff's views on the development, documentation, and application of a systematic methodology as required by Financial Reporting Release No. 28 for determining allowances for loan and lease losses in accordance with generally accepted accounting principles. In particular, the guidance focuses on the documentation the staff normally would expect registrants to prepare and maintain in support of their allowances for loan losses. The guidance in this staff accounting bulletin is being issued in light of the March 10, 1999 Joint Interagency Letter to Financial Institutions in which the staff agreed to provide, in parallel with guidance provided by the federal banking agencies, guidance on loan loss allowance methodologies and supporting documentation. On July 6, 2001, the federal banking agencies issued their guidance through the Federal Financial Institutions