

Rules and Regulations

Federal Register

Vol. 67, No. 240

Friday, December 13, 2002

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NE-16-AD; Amendment 39-12952; AD 2002-23-08]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc. RB211-535 Turbofan Engines; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments; correction

SUMMARY: This document makes a correction to Airworthiness Directive (AD) 2002-23-08, applicable to Rolls-Royce plc. (RR) models RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-B-75 turbofan engines. AD 2002-23-08 was published in the **Federal Register** on November 29, 2002 (67 FR 71094). In the **DATES** section of the preamble, two dates are incorrect. This document corrects those dates. In all other respects, the original document remains the same.

EFFECTIVE DATE: December 16, 2002.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7178; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: A final rule; request for comments airworthiness directive FR Doc. 02-29001, applicable to models RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-B-75 turbofan engines, was published in the **Federal Register** on November 29, 2002 (67 FR 71094). The following correction is needed:

On page 71094, in the second column, second paragraph, in the **DATES** section,

first line, remove the phrase "Effective December 30, 2002." and add in its place "Effective December 16, 2002." Also, in the fifth line, remove the phrase "as of December 30, 2002." and add in its place "as of December 16, 2002."

Issued in Burlington, MA, on December 5, 2002.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-31395 Filed 12-12-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-287-AD; Amendment 39-12979; AD 2002-25-04]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9-10, -20, -30, -40, and -50 Series Airplanes; and C-9 (Military) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9-10, -20, -30, -40, and -50 series airplanes, and C-9 (military) airplanes, that requires a one-time visual inspection of circuit breakers to determine the manufacturer of the circuit breakers, and corrective action, if necessary. The actions specified by this AD are intended to prevent internal overheating and arcing of circuit breakers and airplane wiring due to long-term use and breakdown of internal components of the circuit breakers, which could result in smoke and fire in the flight compartment and main cabin. This action is intended to address the identified unsafe condition.

DATES: Effective January 17, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 17, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855

Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Elvin Wheeler, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5344; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-9-10, -20, -30, -40, and -50 series airplanes; and C-9 (military) airplanes was published in the **Federal Register** on June 5, 2001 (66 FR 30101). That action proposed to require a one-time visual inspection of circuit breakers to determine the manufacturer of the circuit breakers, and corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter expresses concern that, although the applicability in the proposed AD only specifies Model DC-9 and MD-80 series airplanes, the referenced circuit breakers (manufactured by Wood Electric Corporation or Wood Electric Division of Potter Brumfield Corporation), may be fitted to other FAA type-certificated products or aircraft. The commenter asks for confirmation that this is or is not the case.

We agree that the subject circuit breakers can be installed on other FAA type-certificated products. We previously issued other rulemaking actions that address the commenter's concern. AD 2001-08-16, amendment 39-12193, was issued on April 17, 2001