

**(b) Unsafe Condition**

This AD defines the unsafe condition as a crack in a bi-directional cross-bar, which could result in failure of a cross-bar and loss of control of the helicopter.

**(c) Effective Date**

This AD becomes effective January 31, 2017.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) Within the initial inspection times shown in Table 1 to paragraph (e) of this AD or the next time maintenance of the helicopter involves removing the main

gearbox, whichever comes first; and thereafter at intervals not to exceed the compliance times shown in Table 1 to paragraph (e) of this AD, inspect each cross-bar for a crack. For purposes of this AD, a torque cycle is defined as one landing with or without stopping the rotor or one external load-carrying operation; an external load-carrying operation occurs each time a helicopter picks up an external load and drops it off.

TABLE 1 TO PARAGRAPH (e)

| Helicopter model                                                 | Initial and recurrent inspection interval                                          |
|------------------------------------------------------------------|------------------------------------------------------------------------------------|
| AS350B, AS350BA, AS350B1, AS350B2, AS350C, AS350D, and AS350D1.  | 4,500 hours time-in-service (TIS) or 60,000 torque cycles, whichever occurs first. |
| AS350B3, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355 NP. | 3,300 hours TIS or 60,000 torque cycles, whichever occurs first.                   |
| EC130B4 .....                                                    |                                                                                    |
| EC130T2 .....                                                    | 3,300 hours TIS or 40,000 torque cycles, whichever occurs first.                   |

(2) If there is a crack, before further flight, replace the cross-bar.

**(f) Special Flight Permits**

Special flight permits are prohibited.

**(g) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(h) Additional Information**

(1) Airbus Helicopters Alert Service Bulletin No. EC130-05A021, No. EC130-05A022, No. AS350-05.00.84, and No. AS355-05.00.73, all Revision 0 and all dated May 21, 2015, which are not incorporated by reference, contain additional information about the subject of this final rule. For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015-0094, dated May 29, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2015-3929.

**(i) Subject**

Joint Aircraft Service Component (JASC)  
Code: 6300, Main Rotor Drive System.

Issued in Fort Worth, Texas, on December 6, 2016.

**Scott A. Horn,**

*Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.*

[FR Doc. 2016-30048 Filed 12-23-16; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2016-8850; Directorate Identifier 2016-NM-031-AD; Amendment 39-18755; AD 2016-25-29]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 767-200 and -300 series airplanes. This AD was prompted by a report of a fire in the bilge area of the cargo compartment that burned through the insulation blankets that were intended to prevent smoke from migrating behind the cargo compartment sidewall liners and upward into the main cabin. This AD requires replacing the cargo compartment insulation blankets on the left and right sides with new insulation blankets that incorporate fire stops. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective January 31, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 31, 2017.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8850.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8850; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Francis Smith, Aerospace Engineer,

Cabin Safety & Environmental Control Systems, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6596; fax: 425-917-6590; email: [francis.smith@faa.gov](mailto:francis.smith@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 767-200 and -300 series airplanes. The NPRM published in the **Federal Register** on August 30, 2016 (81 FR 59549) ("the NPRM"). The NPRM was prompted by a report of a fire in the bilge area of the cargo compartment that burned through the insulation blankets that were intended to prevent smoke from migrating behind the cargo compartment sidewall liners and upward into the main cabin. The NPRM proposed to require replacing the cargo compartment insulation blankets on the left and right sides with new insulation blankets that incorporate fire stops. We are issuing this AD to prevent a fire in the bilge area of the cargo compartment burning through the insulation blankets and consequently allowing smoke to migrate behind the cargo compartment sidewall liners and upward into the main cabin.

#### Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA's response to each comment.

#### Support for the NPRM

Boeing and United Airlines expressed support for the NPRM.

#### Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that the installation of winglets per Supplemental Type Certificate (STC) ST01920SE does not affect the accomplishment of the manufacturer's service instructions.

We agree with the commenter that STC ST01920SE does not affect the accomplishment of the manufacturer's service instructions. Therefore, the installation of STC ST01920SE does not affect the ability to accomplish the actions required by this AD. We have not changed this AD in this regard.

#### Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial

changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

#### Related Service Information Under 14 CFR part 51

We reviewed Boeing Special Attention Service Bulletin 767-25-0550, dated January 30, 2015. The service information describes procedures for replacing the cargo compartment insulation blankets on the left and right sides between stringers 29 and 33 with new insulation blankets that incorporate fire stops. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### Costs of Compliance

We estimate that this AD affects 26 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

#### ESTIMATED COSTS

| Action            | Labor cost                                          | Parts cost       | Cost per product    | Cost on U.S. operators |
|-------------------|-----------------------------------------------------|------------------|---------------------|------------------------|
| Replacement ..... | Up to 54 work-hours × \$85 per hour = \$4,590 ..... | ( <sup>1</sup> ) | Up to \$4,590 ..... | Up to \$119,340.       |

<sup>1</sup> We have received no definitive data that will enable us to provide parts cost estimates for the actions specified in this AD.

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all available costs in our cost estimate.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS  
DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2016–25–29 The Boeing Company:**

Amendment 39–18755; Docket No. FAA–2016–8850; Directorate Identifier 2016–NM–031–AD.

**(a) Effective Date**

This AD is effective January 31, 2017.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 767–200 and –300 series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 767–25–0550, dated January 30, 2015.

**(d) Subject**

Air Transport Association (ATA) of America Code 25; Equipment/furnishings.

**(e) Unsafe Condition**

This AD was prompted by a report of a fire in the bilge area of the cargo compartment that burned through the insulation blankets that were intended to prevent smoke from migrating behind the cargo compartment sidewall liners and upward into the main cabin. We are issuing this AD to prevent a fire in the bilge area of the cargo compartment burning through the insulation blankets and consequently allowing smoke to migrate behind the cargo compartment sidewall liners and upward into the main cabin.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Insulation Blanket Replacement**

Within 36 months after the effective date of this AD: Replace the cargo compartment insulation blankets on the left and right sides between stringers 29 and 33 with new insulation blankets that incorporate fire stops, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767–25–0550, dated January 30, 2015. For Groups 1 through 4, Configurations 1 and 2, airplanes identified in Boeing Special Attention Service Bulletin 767–25–0550, dated January 30, 2015, no action is required by this AD.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19,

send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (h)(4)(i) and (h)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(i) Related Information**

For more information about this AD, contact Francis Smith, Aerospace Engineer, Cabin Safety & Environmental Control Systems, ANM–150S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6596; fax: 425–917–6590; email: [francis.smith@faa.gov](mailto:francis.smith@faa.gov).

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 767–25–0550, dated January 30, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601

Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 9, 2016.

**Dionne Palermo,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016–30278 Filed 12–23–16; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 91**

[Docket No. FAA–2014–0708; Amendment No. 91–334A]

**RIN 2120–AK93**

**Extension of the Prohibition Against Certain Flights Within the Damascus (OSTT) Flight Information Region (FIR)**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** This action extends the prohibition of certain flight operations in the Damascus (OSTT) Flight Information Region (FIR) by all U.S. air carriers; U.S. commercial operators; persons exercising the privileges of a U.S. airman certificate, except when such persons are operating a U.S.-registered aircraft for a foreign air carrier; and operators of U.S.-registered civil aircraft, except when such operators are foreign air carriers. The FAA finds that this action continues to be necessary to address a potential hazard to persons and aircraft engaged in such flight operations.

**DATES:** This final rule is effective on December 30, 2016.

**FOR FURTHER INFORMATION CONTACT:** Michael Filippell, Air Transportation Division, AFS–220, Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202–267–8166; email: [Michael.e.filippell@faa.gov](mailto:Michael.e.filippell@faa.gov).

**SUPPLEMENTARY INFORMATION:****I. Executive Summary**

This action continues the prohibition against certain flight operations in the