

Proposed Rules

Federal Register

Vol. 88, No. 122

Tuesday, June 27, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

FINANCIAL STABILITY OVERSIGHT COUNCIL

12 CFR Part 1310

[Docket No. FSOC–2023–0002]

Authority To Require Supervision and Regulation of Certain Nonbank Financial Companies

AGENCY: Financial Stability Oversight Council

ACTION: Proposed interpretive guidance; extension of comment period.

SUMMARY: The Financial Stability Oversight Council (Council) is extending by 30 days the comment period on its proposed interpretive guidance, which would replace the Council's existing interpretive guidance on nonbank financial company determinations and which describes the process the Council intends to take in determining whether to subject a nonbank financial company to supervision and prudential standards by the Board of Governors of the Federal Reserve System. The comment period will now close on July 27, 2023.

DATES: *Comment due date:* July 27, 2023.

ADDRESSES: You may submit comments by either of the following methods. All submissions must refer to the document title and docket number FSOC–2023–0002.

Electronic Submission of Comments: You may submit comments electronically through the Federal eRulemaking Portal at <https://www.regulations.gov>. Electronic submission of comments allows the commenter maximum time to prepare and submit a comment, ensures timely receipt, and enables the Council to make them available to the public. Comments submitted electronically through the <https://www.regulations.gov> website can be viewed by other commenters and interested members of the public. Commenters should follow the instructions provided on that site to submit comments electronically.

Mail: Send comments to Financial Stability Oversight Council, Attn: Eric Froman, 1500 Pennsylvania Avenue NW, Room 2308, Washington, DC 20220.

All properly submitted comments will be available for inspection and downloading at <https://www.regulations.gov>.

In general, comments received, including attachments and other supporting materials, are part of the public record and are available to the public. Do not submit any information in your comment or supporting materials that you consider confidential or inappropriate for public disclosure.

FOR FURTHER INFORMATION CONTACT: Eric Froman, Office of the General Counsel, Treasury, at (202) 622–1942; Devin Mauney, Office of the General Counsel, Treasury, at (202) 622–2537; or Carol Rodrigues, Office of the General Counsel, Treasury, at (202) 622–6127.

SUPPLEMENTARY INFORMATION: On April 28, 2023, at 88 FR 26234 the Council published in the **Federal Register** proposed interpretive guidance describing the process the Council intends to take in determining whether to subject a nonbank financial company to supervision and prudential standards by the Board of Governors of the Federal Reserve System (Proposed Guidance). Comments on the Proposed Guidance were originally due on June 27, 2023.

The Council has received a request to extend the comment period to allow interested parties additional time to review and comment on the Proposed Guidance. The Council is therefore extending the comment period on the Proposed Guidance by 30 days to July 27, 2023.

Dated: June 22, 2023.

Sandra Lee,

Deputy Assistant Secretary, Financial Stability Oversight Council.

[FR Doc. 2023–13648 Filed 6–26–23; 8:45 am]

BILLING CODE 4810–AK–P–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1218; Project Identifier MCAI–2022–01025–A]

RIN 2120–AA64

Airworthiness Directives; Vulcanair S.p.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Vulcanair S.p.A. Model V1.0 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as corrosion on the lower fuselage truss. This proposed AD would require a detailed visual inspection of the right-hand (RH) and left-hand (LH) lower rear attachments of the fuselage truss for corrosion, a tactile inspection of the lower rear attachments for missing sealant, and a general visual inspection of the lower fuselage truss welded pipes for corrosion and the related rivets for missing stems and, depending on findings, additional inspections and actions (including a tap test) and applicable corrective actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by August 11, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m.

p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–1218; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Vulcanair S.p.A., via G. Pascoli, 7, 80026 Casoria (NA), Italy; phone: +39 081 5918111; email: *info@vulcanair.com*; website: *support.vulcanair.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

FOR FURTHER INFORMATION CONTACT: John DeLuca, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228–7369; email: *john.p.deluca@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–1218; Project Identifier MCAI–2022–01025–A” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your

comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to John DeLuca, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022–0155, dated August 1, 2022 (referred to after this as “the MCAI”), to correct an unsafe condition on certain serial-numbered Vulcanair S.p.A. Model V1.0 airplanes.

The MCAI was prompted by reports of corrosion on the lower fuselage truss on two Vulcanair Model V1.0 airplanes. Missing sealant or missing rivet stems were determined to be the root cause of corrosion by allowing water ingress into the lower fuselage truss. In both reported cases, corrosion was externally visible, having penetrated the thickness of the pipes. However, corrosion could be present inside the pipes and remain undetected without proper inspection. This condition, if not detected and corrected, could result in loss of control of the airplane.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–1218.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Vulcanair Aircraft V1 series Service Bulletin VA–22, rev. 0, dated June 15, 2022 (Vulcanair SB VA–22). This service information specifies procedures for inspections of the lower fuselage truss for corrosion, missing sealant, and missing rivet stems; and, in case of findings, additional inspections and actions to detect corrosion, including a tap test and raising the airplane nose. This service information specifies to contact Vulcanair for corrective actions.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in **ADDRESSES**.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the MCAI, except as discussed under “Differences Between this Proposed AD and the MCAI.”

Differences Between This Proposed AD and the MCAI

Although Vulcanair SB VA–22 specifies that “in case of doubts, raise the aircraft nose and audibly detect the presence of corrosion residues inside the fuselage truss,” this proposed AD would not require that action.

Paragraph (1) of the MCAI states to “accomplish a general visual and tactile inspection of the right-hand (RH) and left-hand (LH) lower rear attachments of the fuselage truss” in accordance with the instructions of Part A of Vulcanair SB VA–22. However, step 14, Part A, of Vulcanair SB VA–22 specifies to do a detailed visual inspection. In email communication between EASA and the FAA, EASA clarified that this should be a detailed visual inspection performed in accordance with the procedures specified in Vulcanair SB VA–22; therefore, this proposed AD would require a detailed visual inspection of the RH and LH lower rear attachments of the fuselage truss for corrosion.

The MCAI requires contacting the manufacturer for approved corrective action instructions if any corrosion is found on the lower fuselage truss. This proposed AD would require contacting either the Manager, International Validation Branch, FAA; or EASA; or Vulcanair’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 17 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed visual inspection and tactile inspection of the RH and LH lower rear attachments, and a general visual inspection of the pipes.	8 work-hours × \$85 per hour = \$680	\$0	\$680	\$11,560

The FAA estimates the following costs to do any necessary actions that

would be required based on the results of the proposed inspections.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Remove sealant and detailed inspection of inner face of longitudinal tubes connected to lower rear attachments.	4 work-hours × \$85 per hour = \$340	\$0	\$340
Detailed visual inspection and tap test of the lower fuselage truss pipes.	4 work-hours × \$85 per hour = \$340	0	340
Installation of plug P/N 5034–011 on RH and LH lower rear attachments.	0.50 work-hour × \$85 per hour = \$42.50 ...	130	172.50

The corrective action instructions that may be needed as a result of these inspections could vary significantly from airplane to airplane. The FAA has no data to determine the costs to accomplish those corrective actions or the number of airplanes that would need these corrective actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the

national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Vulcanair S.p.A.: Docket No. FAA–2023–1218; Project Identifier MCAI–2022–01025–A.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 11, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Vulcanair S.p.A. Model V1.0 airplanes, serial numbers (S/Ns) 1001 through 1034 inclusive, except S/Ns 1008 and 1019, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5311, Fuselage Main, Frame.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as corrosion on the lower fuselage truss. The FAA is issuing this AD to address the unsafe condition. The unsafe condition, if not addressed, could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 100 hours time-in-service or 12 months after the effective date of this AD, whichever occurs first, do a detailed visual inspection of the right-hand (RH) and left-hand (LH) lower rear attachments of the fuselage truss for corrosion, a tactile inspection of the RH and LH lower rear attachments of the fuselage truss for missing sealant, a general visual inspection of the

pipes on the lower fuselage truss for corrosion, and a general visual inspection of the pipes on the lower fuselage truss for rivets with missing stems, in accordance with steps 13 and 14 of Part A, in Part 2, Work Procedure, of Vulcanair Aircraft V1 series Service Bulletin VA-22, rev. 0, dated June 15, 2022 (Vulcanair SB VA-22).

(1) If, during the inspections required by the introductory text of paragraph (g) of this AD, no missing sealant and no corrosion of the LH and RH lower rear attachments are detected, and no corrosion and no missing rivet stems of the lower fuselage truss pipes are detected, before further flight, install part number (P/N) 5034-011 plugs on both the RH and LH rear attachments, in accordance with step 16 of Part A, in Part 2, Work Procedure, of Vulcanair SB VA-22. After installation of the plugs, no further action is required by this AD.

(2) If, during the inspections required by the introductory text of paragraph (g) of this AD, corrosion, missing sealant, or missing rivet stems are detected, before further flight, do the following as applicable:

(i) If corrosion or missing sealant is detected during the detailed visual inspection or tactile inspection of the RH and LH lower rear attachments, remove any sealant and do a detailed visual inspection for corrosion in accordance with step 26 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

(ii) If corrosion or missing rivet stems are detected during the general visual inspection of the lower fuselage truss pipes, do a detailed visual inspection and tap test for corrosion in accordance with steps 27 and 28 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

(3) If, during any inspection required by paragraph (g)(2) of this AD, any corrosion is detected on the lower fuselage truss, before further flight, contact the Manager, International Validation Branch, FAA; or European Union Aviation Safety Agency (EASA); or Vulcanair's EASA Design Organization Approval (DOA) for corrective action instructions and do the corrective actions. If approved by the DOA, the approval must include the DOA-authorized signature.

(4) If, during the inspections required by paragraph (g)(2) of this AD, no corrosion is detected, before further flight, apply sealant on rivets with absent stems, restore as necessary the sealant inside the RH and LH lower rear attachments, and install plugs P/N 5034-011 on both the RH and LH rear attachments, in accordance with the instructions in steps 31 and 32 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

(h) Special Flight Permits

Special flight permits are prohibited.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local

Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

(1) Refer to EASA AD 2022-0155, dated August 1, 2022, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1218.

(2) For more information about this AD, contact John DeLuca, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7369; email: john.p.deluca@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Vulcanair Aircraft V1 series Service Bulletin VA-22, rev. 0, dated June 15, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Vulcanair S.p.A., via G. Pascoli, 7, 80026 Casoria (NA), Italy; phone: +39 081 5918111; email: info@vulcanair.com; website: support.vulcanair.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on June 20, 2023.

Gaetano A. Sciortino,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-13497 Filed 6-26-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1398; Project Identifier AD-2023-00472-P]

RIN 2120-AA64

Airworthiness Directives; Hamilton Sundstrand Corporation Propellers

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Hamilton Sundstrand Corporation (Hamilton Sundstrand) Model 14SF-17 and 14SF-19 propellers. This proposed AD was prompted by a report of an auxiliary motor and pump failing to feather a propeller in flight. This proposed AD would require replacement of a certain auxiliary motor and pump. This proposed AD would also prohibit installation of a certain auxiliary motor and pump on any propeller. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by July 27, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2023-1398; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Hamilton Sundstrand, One Hamilton Road, Windsor Locks, CT 06096-1010, phone: (877) 808-7575; email: CRC@collins.com.