

“Implementation of Quality Assurance Criteria and 10 CFR 50.59 for Nuclear Power Plant Components Produced Using Advanced Manufacturing Technologies” (ADAMS Accession No. ML20317A007).

### III. Background

The NRC considers AMTs to consist of material processing and component fabrication methods that have not been traditionally used in the U.S. nuclear industry and have not yet received NRC approval through NRC-endorsed codes and standards or the approval of an industry submittal. There are several regulatory paths available to a licensee for utilizing an AMT in a nuclear application, including: (1) Development of a Code or Standard that can be incorporated by reference in section 50.55a of chapter I of title 10 of the *Code of Federal Regulations* (10 CFR); (2) selection of an unregulated in-service application; (3) submission of generic technical reports or plant-specific submittals for NRC approval; or (4) implementation of the 10 CFR 50.59, “Changes, tests and experiments,” 10 CFR 70.72, “Facility changes and change process,” or 10 CFR 72.48, “Changes, tests, and experiments” processes. Industry indicated that plans for the initial installation of AMT-fabricated components would involve the 10 CFR 50.59 process. Therefore, the NRC staff documented in the draft document a description of the processes, consistent with the QA requirements in Appendix B to 10 CFR part 50 and in accordance with 10 CFR 50.59 in order to support the staff’s performance of potential inspections of a licensee’s implementation of these requirements for AMT-fabricated components.

### IV. Specific Considerations

This report documents completion of the staff’s initial review of QA criteria and 10 CFR 50.59 requirements for AMT applications at U.S. nuclear power plants. This report does not represent a complete and final analysis of all aspects of QA criteria and 10 CFR 50.59 requirements and guidance that might be applicable to the use of AMT components at U.S. nuclear power plants. This report does not create new regulatory requirements or establish new regulatory positions with respect to the use or manufacture of AMT components for nuclear power plants. The scope of this report is limited to the review of existing requirements and guidance to address AMT components and the consideration of potential regulatory and technical challenges. This report may be subject to future

revision, as additional insights and operating experience for use of AMT components are gained.

In its effort to be open and transparent regarding potential processes for the installation of AMT-fabricated components, the NRC is requesting general comments on this document.

### V. Public Meeting

The NRC plans to hold a public meeting during the public comment period for this action. A public meeting is planned for January 2021, via online webinar. The public webinar will provide a forum for the NRC staff to discuss the document and for members of the public to provide comments on the document. The NRC does not intend to provide any responses to comments submitted during the public webinar. The public webinar will be noticed on the NRC’s public meeting website at least 10 calendar days before the meeting. Members of the public should monitor the NRC’s public meeting website for additional information about the public webinar at <https://www.nrc.gov/public-involve/public-meetings/index.cfm>. The NRC will post the notice for the public webinar and may post additional material related to this action to the Federal Rulemaking website at <https://www.regulations.gov/> under Docket ID NRC–2020–0253. The Federal Rulemaking website allows you to receive alerts when changes or additions occur in a docket folder. To subscribe: (1) Navigate to the docket folder (NRC–2020–0253); (2) click the “Sign up for Email Alerts” link; and (3) enter your email address and select how frequently you would like to receive emails (daily, weekly, or monthly).

Dated: December 2, 2020.

For the Nuclear Regulatory Commission.

**Anna H. Bradford,**

*Director, Division of New and Renewed Licenses, Office of Nuclear Reactor Regulation.*

[FR Doc. 2020–26845 Filed 12–9–20; 8:45 am]

**BILLING CODE 7590–01–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–1114; Project Identifier 2019–SW–058–AD]

**RIN 2120–AA64**

### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Helicopters Model EC120B helicopters. This proposed AD was prompted by a report of broken and bent attachment bolts of the main rotor (MR) hub scissors assembly. This proposed AD would require an inspection of the attachment bolts of the MR hub scissors assembly for discrepancies and repair if necessary; part marking of the attachment bolts of the MR hub scissors assembly; and repetitive inspections of the part marking of the attachment bolts, and repair if necessary; as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 25, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202–493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1114.

### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for

and locating Docket No. FAA–2020–1114; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Hal Jensen, Aerospace Engineer, Operational Safety Branch, FAA, 470 L'Enfant Plaza SW, Washington, DC 20024; telephone 202–267–9167; email [hal.jensen@faa.gov](mailto:hal.jensen@faa.gov).

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2020–1114; Project Identifier 2019–SW–058–AD” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposal.

##### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this

NPRM. Submissions containing CBI should be sent to Hal Jensen, Aerospace Engineer, Operational Safety Branch, FAA, 470 L'Enfant Plaza SW, Washington, DC 20024; telephone 202–267–9167; email [hal.jensen@faa.gov](mailto:hal.jensen@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

##### **Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0139, dated June 12, 2019 (EASA AD 2019–0139) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus Helicopters Model EC120B helicopters.

This proposed AD was prompted by a report of broken and bent attachment bolts of the MR hub scissors assembly. The FAA is proposing this AD to address broken and bent attachment bolts of the MR hub scissors assembly, which could lead to detachment of a MR hub scissors attachment bolt, possibly resulting in complete loss of control of the helicopter. See the MCAI for additional background information.

##### **Related Service Information Under 1 CFR Part 51**

EASA AD 2019–0139 describes procedures for an inspection of the attachment bolts of the MR hub scissors assembly for discrepancies (discrepancies include corrosion, fretting, wear, cracking, bolt play, and bolt tightening torque); and repair if necessary; part marking of the attachment bolts of the MR hub scissors assembly; and repetitive inspections, after part marking, of the attachment bolts for discrepancies, and repair if necessary. The inspections of the attachment bolts of the MR hub assembly include checking the play and torque of the scissors attachment bolts and making sure that there are no hard spots in the scissors link hinge.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

##### **FAA's Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the bilateral agreement with the State of Design Authority, the FAA has been

notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

##### **Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in EASA AD 2019–0139, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

##### **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019–0139 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2019–0139 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2019–0139 that is required for compliance with EASA AD 2019–0139 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1114 after the FAA final rule is published.

##### **Costs of Compliance**

The FAA estimates that this proposed AD affects 160 helicopters of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

## ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
5 work-hours × \$85 per hour = \$425 .....	\$0	\$425	\$68,000

The FAA estimates that it would take about 1 hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based

on these figures, the FAA estimates the cost of reporting on U.S. operators to be \$13,600, or \$85 per product.

The FAA estimates the following costs to do any necessary on-condition

actions that would be required based on the results of any required actions. The FAA has no way of determining the number of helicopters that might need these on-condition actions:

## ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
4 work-hours × \$85 per hour = \$340 .....	\$40	\$380

**Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120–0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus Helicopters:** Docket No. FAA–2020–1114; Project Identifier 2019–SW–058–AD.

**(a) Comments Due Date**

The FAA must receive comments by January 25, 2021.

**(b) Affected Airworthiness Directives (ADs)**

None.

**(c) Applicability**

This AD applies to Airbus Helicopters Model EC120B helicopters, certificated in any category, having an affected part as defined in European Union Aviation Safety Agency (EASA) AD 2019–0139, dated June 12, 2019 (EASA AD 2019–0139).

**(d) Subject**

Joint Aircraft System Component (JASC) Code 6200, Main Rotor System.

**(e) Reason**

This AD was prompted by a report of broken and bent attachment bolts of the main rotor (MR) hub scissors assembly. The FAA is issuing this AD to address broken and bent attachment bolts of the MR hub scissors assembly, which could lead to detachment of a MR hub scissors attachment bolt, possibly resulting in complete loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0139.

**(h) Exceptions to EASA AD 2019–0139**

(1) Where EASA AD 2019–0139 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2019–0139 refers to September 5, 2018 (the effective date of EASA AD 2018–0186, dated August 29, 2018), this AD requires using the effective date of this AD.

(3) The “Remarks” section of EASA AD 2019–0139 does not apply to this AD.

(4) Where EASA AD 2019–0139 refers to flight hours (FH), this AD requires using hours time-in-service.

(5) Paragraphs (3) and (4) of EASA AD 2019–0139 refer to “discrepancies.” For this AD, discrepancies include corrosion, fretting, wear, cracking, bolt play, and bolt tightening torque.

(6) Although the service information referenced in EASA AD 2019–0139 specifies to discard certain parts, this AD does not include that requirement.

(7) Where EASA AD 2019–0139 specifies to contact the manufacturer for repair instructions, repair using a method approved by the Manager, Rotorcraft Standards Branch, FAA. For a repair method to be approved by the Manager, Rotorcraft Standards Branch, as required by this paragraph, the Manager’s approval letter must specifically refer to this AD.

(8) Paragraph (5) of EASA AD 2019–0139 specifies to report inspection results to Airbus Helicopters within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(8)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Manager, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; phone: 817–222–5110; email: [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

**(j) Paperwork Reduction Act Burden Statement**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this

collection of information are mandatory as required by this AD. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

**(k) Related Information**

(1) For EASA AD 2019–0139, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1114.

(2) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, FAA, 470 L’Enfant Plaza SW, Washington, DC 20024; telephone 202–267–9167; email [hal.jensen@faa.gov](mailto:hal.jensen@faa.gov).

Issued on December 2, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–26965 Filed 12–9–20; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2020–1118; Project Identifier MCAI–2020–00516–E]**

**RIN 2120–AA64**

**Airworthiness Directives; Safran Helicopter Engines, S.A. (Type Certificate Previously Held by Turbomeca, S.A.) Turboshaft Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A. Arriel 2C, 2C1, 2S1, and 2S2 model turboshaft engines. This proposed AD was prompted by investigations by the manufacturer following level 1 failures in flight (minor anomalies) and level 2 failures on the ground (minor failures), where cracks were found on the soldered joints of torque conformation

boxes. This proposed AD would require performing initial and repetitive inspections of the resistance values of the torque conformation box and, depending on the results of the inspections, replacement of the torque conformation box. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 25, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12 140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Safran Helicopter Engines, S.A., Avenue du 1er Mai, Tarnos, France; phone: +33 (0) 5 59 74 45 11. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238–7759.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1118; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Wego Wang, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7134; fax: (781) 238–7199; email: [wego.wang@faa.gov](mailto:wego.wang@faa.gov).

**SUPPLEMENTARY INFORMATION:****Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No.