

■ 2. Section 931.231 is revised to read as follows:

§ 931.231 Assessment rate.

On and after July 1, 2003, an assessment rate of \$0.335 per 44-pound standard box or container equivalent is established for fresh Bartlett pears grown in Oregon and Washington.

Dated: October 15, 2003.

A.J. Yates,

Administrator, Agricultural Marketing Service.

[FR Doc. 03-26519 Filed 10-20-03; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-46-AD; Amendment 39-13342; AD 2003-21-07]

RIN 2120-AA64

Airworthiness Directives; The Cessna Aircraft Company Model 525 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain The Cessna Aircraft Company (Cessna) Model 525 airplanes. This AD requires you to disengage the pitch trim circuit breaker and AP servo circuit breaker and then tie strap each of them to prevent them from being engaged. This AD is the result of analysis that reveals the potential for a single-wire shorting to 28 volts or a failure of a relay in the electric pitch trim system such that the relay contacts remain closed. We are issuing this AD to correct this single-point failure in the electric pitch trim system, which will result in a runaway pitch trim condition where the pilot could not disconnect using the control wheel autopilot/trim disconnect switch. Failure of the electric trim system would result in a large pitch mistrim and would cause excessive control forces that the pilot could not overcome. **DATES:** This AD becomes effective on October 22, 2003.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation as of October 22, 2003.

We must receive any comments on this AD by December 15, 2003.

ADDRESSES: Use one of the following to submit comments on this AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel,

Attention: Rules Docket No. 2003-CE-46-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.

- *By fax:* (816) 329-3771.

- *By e-mail:* 9-ACE-7-

Docket@faa.gov. Comments sent electronically must contain "Docket No. 2003-CE-46-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may get the service information identified in this AD from The Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-6000; facsimile: (316) 517-8500.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-46-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Dan Withers, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209, telephone: (316) 946-4196; facsimile: (316) 946-4107.

SUPPLEMENTARY INFORMATION:

What events have caused this AD? The FAA has received a report of an accident involving a Cessna Model 525 airplane where the pilot ditched the airplane in the water off the coast near Coupeville, Washington. The pilot reported a problem with the pitch trim system.

Although the final investigation by the National Transportation Safety Board (NTSB) is not complete, Cessna and FAA analysis reveals the potential for a single-wire shorting to 28 volts or a failure of a relay in the electric pitch trim system such that the relay contacts remain closed and also precludes disconnect of the pitch trim using the control wheel autopilot/trim disconnect switch.

What are the consequences if the condition is not corrected? Failure of the electric trim system would result in a large pitch mistrim and would cause excessive control forces that the pilot could not overcome.

Is there service information that applies to this subject? Cessna has issued Citation Alert Service Letter ASL525-27-02, dated October 10, 2003.

What are the provisions of this service information? The service bulletin includes (as well as other information) procedures for disengaging and tie strapping the pitch trim and autopilot servo circuit breakers.

FAA's Determination and Requirements of the AD

What has FAA decided? We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design.

Since the unsafe condition described previously is likely to exist or develop on other Cessna Model 525 airplanes of the same type design, this AD is being issued to correct a single-point failure in the pitch trim system, which could result in a runaway pitch trim condition where that the pilot could not disconnect using the control wheel autopilot/trim disconnect switch. Failure of the electric trim system would result in a large pitch mistrim and would cause excessive control forces that the pilot could not overcome.

What does this AD require? This AD requires you to disengage the pitch trim circuit breaker and AP servo circuit breaker and then tie strap each of them to prevent them from being engaged.

In preparation of this rule, we contacted type clubs and aircraft operators to obtain technical information and information on operational and economic impacts. We did not receive any information through these contacts. If received, we would have included, in the rulemaking docket, a discussion of any information that may have influenced this action.

How does the revision to 14 CFR part 39 affect this AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Compliance Time of This AD

What would be the compliance time of this AD? The compliance time of this AD is within 5 days or 10 hours time-in-service after October 22, 2003 (the effective date of this AD), whichever occurs first.

Why is the compliance time of this AD presented in both hours TIS and calendar time? The unsafe condition on these airplanes is not a result of the number of times the airplane is operated. The FAA is establishing the compliance time in both hours TIS and calendar time (with the prevalent being that which occurs first).

This would assure that the unsafe condition is addressed on both high-

usage and low-usage airplanes within a reasonable time period without inadvertently grounding any of the affected airplanes.

Comments Invited

Will I have the opportunity to comment prior to the issuance of the rule? This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-46-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it. If a person contacts us through a nonwritten communication, and that contact relates to a substantive part of this AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the AD in light of those comments.

Regulatory Findings

Will this AD impact various entities? We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will

not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Will this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-46-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 1. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2003-21-07 The Cessna Aircraft Company:
Amendment 39-13342; Docket No. 2003-CE-46-AD.

When Does This AD Become Effective?

- (a) This AD becomes effective on October 22, 2003.

Are Any Other ADs Affected by This Action?

- (b) None.

What Airplanes Are Affected by This AD?

- (c) This AD affects Model 525 airplanes, serial numbers 525-0001, 525-0002, and 525-0004 through 525-0159, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

- (d) This AD is the result of analysis that reveals the potential for a single-wire shorting to 28 volts or a failure of a relay in the electric pitch trim system such that the relay contacts remain closed. We are issuing this AD to correct this single-point failure in the electric pitch trim system, which will result in a runaway pitch trim condition where the pilot could not disconnect using the control wheel autopilot/trim disconnect switch. Failure of the electric trim system would result in a large pitch mistrim and would cause excessive control forces that the pilot could not overcome.

What Must I Do To Address This Problem?

- (e) To address this problem, you must accomplish the following:

Actions	Compliance
(1) Disengage the PITCH TRIM circuit breaker located on the left circuit breaker panel. Install a tie strap (part number (P/N) MS3367-1-4 or equivalent part number) on the shaft of the PITCH TRIM circuit breaker to prevent the circuit breaker from being engaged.	Within 5 calendar days or 10 hours time-in-service after October 22, 2003 (the effective date of this AD), whichever occurs first.
(2) Disengage the AP SERVOS circuit breaker located in the right circuit breaker panel. Install a tie strap (P/N MS3367-1-4 or equivalent part number) on the shaft of the AP SERVOS circuit breaker to prevent the circuit breaker from being engaged.	Within 5 calendar days or 10 hours time-in-service after October 22, 2003 (the effective date of this AD), whichever occurs first.
(3) The Minimum Crew portion of Section II—Operating Limitations of the Airplane Flight Manual (AFM) provides information on applicable operating limitations with the autopilot inoperable.	Not Applicable.
(4) All affected airplanes were originally equipped with a P/N 6518351-3 or P/N 6518351-5 Trim PC Board Assembly. If a P/N 6518351-8 Trim PC Board Assembly is installed, contact the Wichita Aircraft Certification Office at the address in paragraph (f) of this AD to determine if the installed P/N 6518351-8 Trim PC board assembly is an alternative method of compliance to this AD.	Not Applicable.
(5) Cessna Citation Alert Service Letter ASL525-27-02, dated October 10, 2003, contains information related to this subject.	Not Applicable.

What About Alternative Methods of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.13. Send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Dan Withers, Aerospace Engineer, FAA, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209, telephone: (316) 946-4196; facsimile: (316) 946-4107.

How Do I Get Copies of the Documents Referenced in This AD?

(g) You may get copies of the document referenced in this AD from The Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-6000; facsimile: (316) 517-8500. You may view this document at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on October 10, 2003.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-26276 Filed 10-20-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30393; Amdt. No. 3080]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective October 21, 2003. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the

regulations is approved by the Director of the Federal Register as of October 21, 2003.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
2. The FAA Regional Office of the region in which affected airport is located; or
3. The Flight Inspection Area Office which originated the SIAP.
4. The Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

*For Purchase—*Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
 2. The FAA Regional Office of the region in which the affected airport is located.
- By Subscription—*Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125), telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of

the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAMs for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these chart changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPS. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) Is not a