

Issued in Renton, Washington, on July 1, 2003.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 03-17314 Filed 7-8-03; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-152-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200, -300, and -300F Series Airplanes

AGENCY: Federal Aviation
Administration, DOT.

ACTION: Notice of proposed rulemaking
(NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 767-200, -300, and -300F series airplanes. This proposal would require modification of the aft pitch load fitting of the diagonal brace of the nacelle strut of each wing. This action is necessary to prevent loss of the fuse pin of the pitch load fitting due to fatigue caused by improper clearance between the fuse pin and bushing, which could result in increased loads in the wing-to-strut joints and consequent separation of the strut and engine from the wing. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by August 25, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-152-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-152-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Suzanne Masterson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6441; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-152-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-152-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that, during production, excessive clearance between the fuse pin and the bushing of the aft pitch load fitting of the diagonal brace of the nacelle strut of the wing was found on certain Model 767 series airplanes. Such improper clearance may lead to reduced fatigue life and potential loss of the fuse pin, which could result in increased loads in the wing-to-strut joints and consequent separation of the strut and engine from the wing.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 767-54A0102, dated November 8, 2001, which describes procedures for modification of the aft pitch load fitting of the diagonal brace of the nacelle strut of each wing. The modification includes, among other things, doing dye penetrant inspections for cracking or damage of the fitting; reworking the fitting if cracking or damage is found; honing, chamfering, measuring, and machining the fitting if no cracking or damage is found; and replacing the bushing and fuse pin. Replacement of the existing bushing with a bushing having a smaller inner diameter, and replacement of the fuse pin with a new fuse pin, will ensure that the proper clearance between the fuse pin and bushing of the aft pitch load fitting of the diagonal brace is maintained. Consequently, the fuse pin will retain its designed fatigue life. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Changes to 14 CFR Part 39/Effect on the Proposed AD

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the

FAA's airworthiness directives system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. Because we have now included this material in part 39, we no longer need to include it in each individual AD; however, this AD identifies the office authorized to approve alternative methods of compliance.

Cost Impact

There are approximately 59 airplanes of the affected design in the worldwide fleet. The FAA estimates that 32 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 39 work hours per wing to accomplish the proposed actions (includes access and close-up), and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$5,256 per airplane. Based on these figures, the cost impact of the actions proposed by this AD on U.S. operators is estimated to be \$317,952, or \$9,936 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket.

A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2002–NM–152–AD.

Applicability: Model 767–200, –300, and –300F series airplanes, as listed in Boeing Alert Service Bulletin 767–54A0102, dated November 8, 2001; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of the fuse pin of the aft pitch load fitting of the diagonal brace, which could result in increased loads in the wing-to-strut joints and consequent separation of the strut and engine from the wing, accomplish the following:

Modification

(a) Within 18 months after the effective date of this AD: Modify the aft pitch load fitting of the diagonal brace of the nacelle strut of each wing (including dye penetrant inspections for cracking or damage of the fitting; reworking the fitting if cracking or damage is found; honing, chamfering, measuring, and machining the fitting if no cracking or damage is found; and replacing the bushing and fuse pin with new components) by accomplishing all of the actions specified in paragraphs 3.A. through 3.J. of the Accomplishment Instructions of Boeing Alert Service Bulletin 767–54A0102, dated November 8, 2001. Any applicable follow-on corrective actions must be done before further flight.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Issued in Renton, Washington, on July 1, 2003.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–17315 Filed 7–8–03; 8:45 am]

BILLING CODE 4910–13–P

COMMODITY FUTURES TRADING COMMISSION

17 CFR Part 1

RIN 3038–AB64

Minimum Financial and Related Reporting Requirements for Futures Commission Merchants and Introducing Brokers

AGENCY: Commodity Futures Trading Commission.

ACTION: Proposed rule.

SUMMARY: The Commodity Futures Trading Commission ("Commission") is proposing to amend certain of its minimum financial and related reporting requirements for futures commission merchants ("FCMs") and introducing brokers ("IBs"). Regulations currently require FCMs to maintain minimum adjusted net capital that is the greatest of: \$250,000; 4 percent of customer funds required to be segregated by the Commodity Exchange Act ("Act") and the Commission's regulations; the amount of adjusted net capital required by a registered futures association; or for those FCMs that also are registered as securities brokers or dealers with the Securities and Exchange Commission ("SEC"), the amount of net capital required by specified SEC regulations. This proposed rule would delete that part of the minimum adjusted net capital requirement that is based on segregated customer funds and replace it with an amount based on maintenance margin levels of futures and options positions carried by an FCM. The proposed amendment would reflect risk-based capital rules that have already been adopted by a clearing organization, two exchanges and the National Futures Association ("NFA").

The Commission also is proposing to reduce the time periods allowed before an FCM must take a capital charge for outstanding margin calls. The Commission is further proposing conforming amendments to capital computations that FCMs must perform for purposes related to equity capital, subordination agreements and the Commission's "early warning" requirements. The Commission also is proposing to reduce the time frames for