

airplanes having L/N 1 through 87 inclusive, accomplishment of the requirements of this paragraph constitutes terminating action for the inspection requirements specified in paragraph (a)(2) of this AD for the lower bulkhead/stringer interface area ONLY.

(1) *Plan "A"*: Perform detailed visual and either ultrasonic or open hole HFEC inspections, as applicable, to detect cracking of the lower bulkhead/stringer interface area, in accordance with Plan "A" and Figure 8, as defined in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000. Repeat the inspections thereafter in accordance with the flight safety program as specified under Plan "A" and Figures 3 and 8 of the service bulletin.

(2) *Plan "B"*: Except as provided by paragraph (h) of this AD, perform open hole HFEC inspections and modification of the lower bulkhead/stringer interface area, in accordance with Plan "B" and Figure 19, as defined in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000. Thereafter, repeat the detailed visual and either ultrasonic or open hole HFEC inspections, as applicable, in accordance with the after-modification inspection program as specified under Plan "B" and Figures 3 and 8 of the service bulletin. Accomplishment of the modification and inspections in accordance with this paragraph terminates the repetitive inspection requirements specified in paragraph (g)(1) of this AD.

Airplanes Modified With Original Service Bulletin: Post-Modification Work

(h) For any airplane (L/N 1 through 1254 inclusive) on which the modification specified in paragraph (g)(2) was accomplished prior to the effective date of this AD in accordance with the original issue of Boeing Alert Service Bulletin 747-53A2390, dated July 31, 1997: Prior to the accumulation of 20,000 total flight cycles, or within 2,000 flight cycles after the effective date of this AD, whichever occurs later, accomplish post-modification work in accordance with Figure 26 of Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000.

Repair

(i) Except as provided by paragraph (a)(1)(i) or (b) of this AD, if any cracking is detected during any inspection required by this AD, prior to further flight, repair in accordance with Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000. If any damage is found that is beyond the limits specified in the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Seattle ACO; or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company DER who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph,

the approval letter must specifically reference this AD.

Alternative Methods of Compliance

(j)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 98-20-25, amendment 39-10791, are approved as alternative methods of compliance with paragraph (a) of this AD.

Note 7: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(k) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(l) Except as provided by paragraphs (a)(1), (a)(1)(i), (a)(1)(ii), (b), and (i) of this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 747-53A2390, dated July 31, 1997; or Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000; as applicable.

(1) The incorporation by reference of Boeing Alert Service Bulletin 747-53A2390, Revision 1; including Appendices A, B, C, and D; dated July 6, 2000; is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Boeing Alert Service Bulletin 747-53A2390, dated July 31, 1997, was approved previously by the Director of the Federal Register as of October 7, 1998 (63 FR 50508, September 22, 1998).

(3) Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(m) This amendment becomes effective on July 16, 2001.

Issued in Renton, Washington, on May 25, 2001.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-14001 Filed 6-8-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-156-AD; Amendment 39-12254; AD 2001-11-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737, 747, and 777 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 737, 747, and 777 series airplanes, that requires replacement of the seat track fittings on all passenger seats with new, improved fittings. The actions specified by this AD are intended to prevent unrestrained movement of the passenger seats during high forward deceleration of the airplane, which could result in injury to the passengers or crew members during an emergency landing.

DATES: Effective July 16, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 16, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Jan Risheim, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-1675; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 737, 747, and 777 series airplanes was published in the **Federal Register** on December 22, 2000 (65 FR 80794). That action proposed to require replacement of the seat track fittings on all passenger seats with new, improved fittings.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received from one commenter.

Change Unsafe Condition and Paragraph (a) of Proposed Rule

A single commenter asks that the unsafe condition in the proposed rule which states, "To prevent unrestrained movement of the passenger seats during high forward deceleration of the airplane, which could result in injury to the passengers or crew members during an emergency landing," be changed to read, "To verify that during seat installation no over-torque on seat track fitting shear bolts occurred." The commenter also asks that paragraph (a) of the proposed rule be changed to read, "Within 1 month after the effective date of this AD: Inspect all the seat track fittings on all the passenger seats as specified in the applicable component maintenance manual under the section titled, 'Troubleshooting,' following the troubleshooting procedure therein."

The commenter states that if the old fitting is properly installed (i.e., the maximum allowable torque value is not exceeded, and the shear plunger is correctly engaged), no risk of unrestrained movement of the passenger seat under any circumstances, including high forward deceleration, can occur. The commenter notes that this has been demonstrated during the certification process of the seat, and found acceptable by all involved airworthiness authorities. To date there is no evidence that such an occurrence is even possible, provided that the installation specifications of the seat manufacturer are fully accomplished. The commenter also states that if the new improved fitting is used, but the maximum allowable torque value is exceeded, then an unrestrained movement of the passenger seat is possible exactly as with the old fitting in the same condition. The commenter concludes that issuance of an airworthiness directive requiring the replacement of old fittings with new, improved fittings having a higher maximum torque value only, is ineffective to prevent unrestrained seat movement. Additionally, the origin of the eventual safety problem resides in the application on the shear bolt of high torque value, exceeding the maximum allowable torque specified by the seat manufacturer.

The FAA does not concur. As stated in the proposed rule, the manufacturer

reported that the shear plunger screws of certain seat track fittings broke during installation. Analysis of the broken screws revealed that various modifications had weakened the shear plunger screws. Further analysis revealed that high torque during seat installation resulted in broken shear plunger screws and subsequent disengagement of the shear plunger from the seat track. Additionally, the manufacturer found that the threads used to attach the shear plunger screws to the seat track were filled with coating that was used on the exterior of the screws, which increases the torque required to install the screw. This information indicates that the torque required to install the shear plunger screws is very close to the strength of the screw, and as the seats are moved for maintenance or interior reconfigurations, breaking of the shear plunger screws is to be expected. The new, improved design of the seat track fitting corrects the deficiencies in the existing design, and is necessary to correct the unsafe condition specified in this final rule. Therefore, no change to the final rule is necessary.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 46 Model 737, 747, and 777 series airplanes of the affected design in the worldwide fleet.

For Model 737 series airplanes (2 U.S.-registered airplanes): It will take approximately 10 work hours per airplane to accomplish the replacement, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$15,100 per airplane. Based on these figures, the cost impact of the replacement required by this AD on U.S. operators is estimated to be \$31,400, or \$15,700 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Currently, there are no affected Model 747 series airplanes on the U.S. Register. However, should an affected airplane be imported and placed on the U.S. Register in the future, it requires approximately 29 work hours to accomplish the replacement, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$43,000. Based on these figures, the cost impact of the replacement required by this AD will be \$44,740 per airplane.

Currently, there are no affected Model 777 series airplanes on the U.S. Register. However, should an affected airplane be imported and placed on the U.S. Register in the future, it requires approximately 24 work hours to accomplish the replacement, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$36,400. Based on these figures, the cost impact of the replacement required by this AD will be \$37,840 per airplane.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS
DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-11-11 Boeing: Amendment 39-12254.
Docket 2000-NM-156-AD.

Applicability: Model 737, 747, and 777 series airplanes; certificated in any category; as specified in the Boeing service bulletins listed in Table 1. below:

TABLE 1.—APPLICABILITY

For Model 737 series airplanes.	737-25-1371, Revision 2, dated December 9, 1999;
For Model 737 series airplanes.	737-25-1407, dated December 9, 1999;
For Model 747 series airplanes.	747-25-3196, Revision 1, dated May 13, 1999; or
For Model 777 series airplanes.	777-25-0111, Revision 1, dated December 13, 1999;

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent unrestrained movement of the passenger seats during high forward deceleration of the airplane, which could result in injury to the passengers or crew members during an emergency landing, accomplish the following:

Replacement

(a) Within 18 months after the effective date of this AD: Replace all the seat track fittings on all the passenger seats with new, improved fittings, in accordance with the Accomplishment Instructions specified in Boeing Service Bulletin 737-25-1371; Revision 2 or 737-25-1407, both dated December 9, 1999 (for Model 737 series airplanes); Boeing Service Bulletin 747-25-3196, Revision 1, dated May 13, 1999 (for Model 747 series airplanes); or Boeing Service Bulletin 777-25-0111, Revision 1, dated May 13, 1999 (for Model 777 series airplanes); as applicable.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The replacement shall be done in accordance with Boeing Service Bulletin 737-25-1371, Revision 2, dated December 9, 1999; Boeing Service Bulletin 737-25-1407, dated December 9, 1999; Boeing Service Bulletin 747-25-3196, Revision 1, dated May 13, 1999; or Boeing Service Bulletin 777-25-0111, Revision 1, dated May 13, 1999; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on July 16, 2001.

Issued in Renton, Washington, on May 25, 2001.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 01-13998 Filed 6-8-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99-NM-350-AD; Amendment 39-12250; AD 2001-11-08]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400, 747-400F, 757-200, 757-200CB, 757-200PF, 767-200, 767-300, and 767-300F Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Boeing Model 747-400, 757-200, 767-200, and 767-300 series airplanes, that currently requires repetitive checks to detect certain failures in the warning electronic unit (WEU) or modular avionic warning electronic assembly (MAWEA); repetitive tests to detect any failure of tactile, visual, or aural alerts generated by the WEU or MAWEA; and corrective action, if necessary. This amendment makes these requirements applicable to other airplanes on which the defective power supplies may be installed, eliminates the repetitive tests for certain airplanes, and increases the interval for the repetitive tests for certain other airplanes. This amendment also requires replacing any subject power supply in the WEU or MAWEA with a new, modified, or serviceable power supply. The actions specified by this AD are intended to prevent failure of the WEU or MAWEA power supplies, which could result in loss of visual, aural, and tactile alerts to the flightcrew. Absence of such alerts could result in the flightcrew being unaware that an immediate or appropriate action should be taken in the event of an unsafe condition.

DATES: Effective July 16, 2001.

The incorporation by reference of certain publications, as listed in the regulations, is approved by the Director of the Federal Register as of July 16, 2001.

The incorporation by reference of certain other publications, as listed in the regulations, was approved previously by the Director of the Federal Register as of September 16, 1999 (64 FR 47653, September 1, 1999).

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Sheila I. Mariano, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2675; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal