

2021–19–17 Sikorsky Aircraft Corporation: Amendment 39–21735; Docket No. FAA–2021–0106; Project Identifier AD–2020–00708–R.

(a) Effective Date

This airworthiness directive (AD) is effective November 22, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Sikorsky Aircraft Corporation Model S–92A helicopters, certificated in any category, with the following installed:

(1) A Martin-Baker side facing utility seat supplier part number (P/N)

MBCS12410AA001 with a serial number (S/N) identified in Table 2 of Martin-Baker Special Information Leaflet (SIL) No. 831, dated July 10, 2019 (SIL 831), that is not marked with “SIL831 incorporated;” or

(2) A Martin-Baker observer seat supplier P/N MBCS12200 or MBCS7301–2 with an S/N identified in Table 2 of Martin-Baker SIL No. 833, dated July 11, 2019 (SIL 833), that is not marked with “SIL833 incorporated.”

Note 1 to paragraph (c): SIL 831 and SIL 833 are attached to Sikorsky S–92A Helicopter Alert Service Bulletin ASB 92–25–026, Basic Issue, dated March 5, 2020 (ASB 92–25–026).

Note 2 to paragraph (c): Section 3., the Accomplishment Instructions, Tables 1 and 2 of ASB 92–25–026, specify cross references of Martin-Baker supplier P/Ns with Sikorsky P/Ns and kit P/Ns.

Note 3 to paragraph (c): The marking “SIL831 incorporated” or “SIL833 incorporated,” as applicable, could be located adjacent to identification labels on the underside of the sitting platform assembly P/N MBCS4111 or MBCS12215, respectively.

(d) Subject

Joint Aircraft System Component (JASC) Code: 2500, Cabin Equipment/Furnishings; and 2520, Passenger Compartment Equipment.

(e) Unsafe Condition

This AD was prompted by an incident of a side facing utility seat detaching from wall attachment points during dynamic testing. The FAA is issuing this AD to detect and address a main back tube, a component of the main back tube assembly, which does not meet design specifications. The unsafe condition, if not addressed, could result in increased surface friction in the direction of the seat attenuation, failure of proper utility seat attenuation during a crash event, excessive lumbar loads during a crash event, and subsequent excessive occupant injury.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 125 hours time-in-service or six months after the effective date of this AD, whichever occurs first, replace each main

back tube assembly by following Section 3., Accomplishment Instructions, paragraphs C. through E., of ASB 92–25–026; except where the service information referenced in ASB 92–25–026 specifies destroying and disposing of parts or discarding parts, this AD requires removing those parts from service instead.

Note 4 to paragraph (g)(1): SIL 831 and SIL 833, referred to in ASB 92–25–026, refer to main back tube assembly as tube assembly, back main.

(2) As of the effective date of this AD, do not install a Martin-Baker side facing utility seat identified in paragraph (c)(1) of this AD or a Martin-Baker observer seat identified in paragraph (c)(2) of this AD unless the actions in paragraph (g)(1) of this AD have been accomplished.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Dorie Resnik, Aerospace Engineer, Aviation Safety Section, Boston ACO Branch, FAA, 1200 District Ave., Burlington, MA 01803; phone: (781) 238–7693; email: dorie.resnik@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Sikorsky S–92A Helicopter Alert Service Bulletin ASB 92–25–026, Basic Issue, dated March 5, 2020, with attachments:

(A) Martin-Baker Special Information Leaflet (SIL) No. 831, dated July 10, 2019; and

(B) Martin-Baker SIL No. 833, dated July 11, 2019.

(ii) [Reserved]

(3) As the design approval holder for the product identified in paragraph (c) of this AD, contact Sikorsky Aircraft Corporation for Martin-Baker service information, as well as Sikorsky S–92A helicopter service information identified in this AD, by contacting your local Sikorsky Field Representative or Sikorsky’s Service Engineering Group at Sikorsky Aircraft Corporation, Mailstop K100, 124 Quarry Road, Trumbull, CT 06611; telephone 1–800–946–4337 (1–800–Winged-S); email [\[cust_service_eng.gr-sik@lmco.com\]\(mailto:cust_service_eng.gr-sik@lmco.com\). Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>.](mailto:wcs_</p>
</div>
<div data-bbox=)

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on September 8, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–22464 Filed 10–15–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0576; Project Identifier 2019–CE–008–AD; Amendment 39–21758; AD 2021–20–20]

RIN 2120–AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Pacific Aerospace Limited Model 750XL airplanes. This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as installation of the wing leading edge tank fuel pickup assembly in a pre-stressed condition, which could cause cracks in the wing spar web or the fuel pickup assembly pipe. This AD requires inspecting the angle of the support bracket on the wing leading edge tank fuel pickup assembly and taking any necessary corrective actions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 22, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 22, 2021.

ADDRESSES: For service information identified in this final rule, contact the Civil Aviation Authority of New Zealand, Level 15, Asteron Centre, 55 Featherston Street, Wellington 6011; phone: +64 4 560 9400; fax: +64 4 569 2024; email: info@caa.govt.nz. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0576.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0576; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain serial-numbered Pacific Aerospace Limited Model 750XL airplanes. The NPRM published in the *Federal Register* on July 22, 2021 (86 FR 38615). The NPRM was prompted by MCAI originated by the Civil Aviation Authority (CAA), which is the aviation authority for New Zealand. The CAA of New Zealand has issued AD No. DCA/750XL/36, effective date February 7, 2019 (referred to after this as “the MCAI”), to correct an unsafe condition for certain Pacific Aerospace Limited Model 750XL airplanes. The MCAI states:

DCA/750XL/36 is prompted by a review of the installation of the wing leading edge fuel pickup assemblies. It was found that the fuel pickup assemblies could have been installed in a pre-stressed condition, which could result in cracks in the wing spar web, or cracks in the fuel pickup pipe. The [CAA] AD is issued to introduce the instructions in

Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/109 issue 1, dated 16 January 2019.

The MCAI requires inspecting the installation of the fuel pickup assembly and the wing spar web on both wings and, if any defects are found, taking all necessary corrective actions.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0576.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Pacific Aerospace Mandatory Service Bulletin PACSB/XL/109, Issue 1, dated January 16, 2019.

The service information contains procedures for inspecting the wing leading edge tank fuel pickup assembly to determine if the assembly is under stress and for accomplishing additional inspections and corrective actions if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in

ADDRESSES.

Costs of Compliance

The FAA estimates that this AD affects 23 airplanes of U.S. registry. The FAA also estimates it will take about 1 work-hour per airplane to comply with the inspection required by this AD. The average labor rate is \$85 per work-hour.

Based on these figures, the FAA estimates the inspection cost of this AD on U.S. operators to be \$1,955 or \$85 per airplane.

In addition, the FAA estimates that any necessary follow-on actions will

take 4 work-hours and require parts costing \$500, for a cost of \$840 per airplane. The FAA has no way of determining the number of airplanes that may need these actions.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–20–20 Pacific Aerospace Limited:
Amendment 39–21758; Docket No. FAA–2021–0576; Project Identifier 2019–CE–008–AD.

(a) Effective Date

This airworthiness directive (AD) is effective November 22, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pacific Aerospace Limited Model 750XL airplanes, serial numbers 177, 186 through 213, 220, 8001, and 8002, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 3600, Pneumatic System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of the installation of the wing leading edge tank fuel pickup assembly in a pre-stressed condition, which could cause cracks in the wing spar web or the fuel pickup assembly pipe. The FAA is issuing this AD to prevent cracks in the wing spar web and the fuel pickup pipe. This condition could result in reduced structural integrity of the wing spar or cause a fuel leak, which could result in an engine fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 165 hours time-in-service after the effective date of this AD, inspect the angle of the support bracket on the wing leading edge tank fuel pickup assembly and, before further flight, take any necessary additional actions and corrective actions by following the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin PACSB/XL/109, Issue 1, dated January 16, 2019.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your

principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Mike Kiesov, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4144; fax: (816) 329–4090; email: mike.kiesov@faa.gov.

(2) Refer to Civil Aviation Authority (CAA) of New Zealand AD No. DCA/750XL/36, dated February 7, 2019, for more information. You may examine the CAA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0576.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pacific Aerospace Mandatory Service Bulletin PACSB/XL/109, Issue 1, dated January 16, 2019.

(ii) Reserved.

(3) For service information identified in this AD, contact the Civil Aviation Authority of New Zealand, Level 15, Asteron Centre, 55 Featherston Street, Wellington 6011; phone: +64 4 560 9400; fax: +64 4 569 2024; email: info@caa.govt.nz.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on September 23, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–22460 Filed 10–15–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0575; Project Identifier MCAI–2020–00545–R; Amendment 39–21749–; AD 2021–20–11]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bell Textron Canada Limited (type certificate previously held by Bell Helicopter Textron Canada Limited) Model 429 helicopters. This AD was prompted by reports of incorrectly staked spherical bearings in the directional control bellcrank assembly. This AD requires a one-time inspection of the lower surface of the spherical bearing in the directional control bellcrank assembly to determine if it is properly staked and, depending on the findings, applicable corrective actions. For certain helicopters, this AD also requires repetitive inspections and, depending on the findings, applicable corrective actions. This AD also provides a terminating action for the repetitive inspections. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 22, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of November 22, 2021.

ADDRESSES: For service information identified in this final rule, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; telephone 1–450–437–2862 or 1–800–363–8023; fax 1–450–433–0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0575.