

Regulatory Flexibility Act

Pursuant to section 605(b) of the Regulatory Flexibility Act (RFA) (5 U.S.C. 605(b)), NCUA certifies that this rule will not have a significant economic impact on a substantial number of small entities. NCUA expects that this rule will not: (1) have significant secondary or incidental effects on a substantial number of small entities; or (2) create any additional burden on small entities. These conclusions are based on the fact that the revised regulations are minor procedural changes intended to simplify agency record access and disclosure procedures. Accordingly, a regulatory flexibility analysis is not required.

Executive Order 12612

The NCUA Board has determined that this regulation will not have a substantial direct effect on the States, on the relationship between the national government and the States, or in the distribution of power and responsibilities between the various levels of government.

Small Business Regulatory Enforcement Fairness Act

The Office of Management and Budget is reviewing this rule to determine that it is not major for purposes of the Small Business Regulatory Enforcement Fairness Act of 1996.

Agency Regulatory Goal

NCUA's goal is to promulgate clear and understandable regulations that impose minimal regulatory burden. We request your comments on whether the revisions are understandable and minimally intrusive.

List of Subjects in 12 CFR Part 792

Confidential business information, Freedom of information, Government employees.

By the National Credit Union Administration Board on October 23, 2003.

Becky Baker,

Secretary of the Board.

■ For the reasons set forth in the preamble, NCUA amends subpart A of 12 CFR part 792 as follows:

PART 792—REQUESTS FOR INFORMATION UNDER THE FREEDOM OF INFORMATION ACT AND PRIVACY ACT, AND BY SUBPOENA; SECURITY PROCEDURES FOR CLASSIFIED INFORMATION

Subpart A—The Freedom of Information Act

■ 1. The authority citation for part 792 continues to read as follows:

Authority: 5 U.S.C. 301, 552, 552a, 552b; 12 U.S.C. 1752a(d), 1766, 1789, 1795f; E.O. 12600, 52 FR 23781, 3 CFR, 1987 Comp., p. 235; E.O. 12958, 60 FR 19825, 3 CFR, 1995 Comp., p.333.

■ 2. Revise § 792.07 to read as follows:

§ 792.07 Where do I send my request?

(a) You must send your request to one of NCUA's Information Centers. The Central Office and Office of Inspector General are designated as Information Centers for the NCUA. The Freedom of Information Officer of the Office of General Counsel is responsible for the operation of the Information Center maintained at the Central Office. The Inspector General is responsible for the operation of the Inspector General Information Center.

(b) If you are seeking any NCUA record, other than those maintained by the Office of Inspector General, you should send your request to the Freedom of Information Officer at NCUA, Office of the General Counsel, 1775 Duke Street, Alexandria, Virginia 22314–3428. You may also send your request by electronic mail to FOIA@NCUA.gov.

(c) If you are seeking a record you think may be maintained by the NCUA Office of Inspector General, then you should send your request to the Inspector General, NCUA, 1775 Duke Street, Alexandria, Virginia 22314–3428.

■ 3. Amend § 792.08 by revising paragraph (a) to read as follows:

§ 792.08 What must I include in my request?

* * * * *

(a) Your name, address and telephone number where you can be reached during normal business hours. If you would like us to respond to your FOIA request by electronic mail (e-mail), you should include your e-mail address.

* * * * *

■ 4. Amend § 792.10 by adding paragraph (f) to read as follows:

§ 792.10 What will NCUA do with my request?

* * * * *

(f) The Information Center will search for records responsive to your request and will generally include all records in existence at the time the search begins. If we use a different search cut-off date, we will inform you of that date.

■ 5. Amend § 792.14 by revising the first sentence and adding a sentence after the first sentence to read as follows:

§ 792.14 Who is responsible for responding to my request?

The Freedom of Information Officer or designee is responsible for making the initial determination whether to grant or deny a request for information submitted to the Central Office Information Center. The Inspector General or designee is responsible for making the initial determination whether to grant or deny a request for information submitted to the Inspector General Information Center. * * *

■ 6. Amend § 792.28 by revising the third sentence of the introductory text to read as follows:

§ 792.28 What if I am not satisfied with the response I receive?

* * * * *

In its response to your initial request, the Freedom of Information Act Officer or the Inspector General (or designee), will notify you that you may appeal any adverse determination to the Office of General Counsel. * * *

[FR Doc. 03–27310 Filed 10–29–03; 8:45 am]

BILLING CODE 7535–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NE–42–AD; Amendment 39–13349; AD 2003–22–02]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce plc Trent 556–61 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Rolls-Royce (RR) plc RB211 Trent 556–61 turbofan engines. This AD requires a gauge inspection of the space between the high pressure (HP) fuel tubes adaptor face and seals, and a gauge inspection of the space between the fuel flow transmitter and seals, for evidence of permanent distortion of the face of the fuel tube connecting flanges, and replacement of parts if necessary. This AD is prompted by a report of fuel leaking from the engine fan cowl during an aircraft taxi. We are issuing this AD to prevent in-flight fuel leaks, which could result in an engine fire.

DATES: Effective November 14, 2003. The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the regulations as of November 14, 2003.

We must receive any comments on this AD by December 29, 2003.

ADDRESSES:

Use one of the following addresses to submit comments on this AD:

- By mail: The Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-NE-42-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

- By fax: (781) 238-7055.

- By e-mail: 9-ane-adcomment@faa.gov.

You can get the service information referenced in this AD from Rolls-Royce plc, P.O. Box 31, Derby, England, DE248BJ; telephone: 011-44-1332-242424; fax: 011-44-1332-249936.

You may examine the AD docket, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park; telephone (781) 238-7176; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The Civil Aviation Authority, (CAA), which is the airworthiness authority for the United Kingdom (U.K.), recently notified the FAA that an unsafe condition may exist on all RR plc RB211 Trent 556-61 engines with serial numbers (SNs) before 71125, except for those SNs that are listed in Table 1 of this AD. The CAA advises that fuel was observed running from the engine fan cowl doors during an aircraft taxi. Further investigation revealed the source of the fuel leak to be permanent distortion of the face of the fuel tube connecting flanges at the fuel flow meter resulting in a significant fuel leak, which could result in an engine fire. The CAA also advises that the distortion of the flange is not aggravated by service use, but by exposure to fuel pressures that extrudes the seal through the gap between the flanges.

Relevant Service Information

We have reviewed and approved the technical contents of RR plc Alert Service Bulletin (ASB) RB.211-73-AE200, dated July 11, 2003, that describes procedures for the following:

- Gauge inspection of the space between the HP fuel tubes adaptor face and the seals, and replacement of the seal gasket and tube, if necessary; and
- Gauge inspection of the space between the fuel flow transmitter and the seals, and replacement of the seal gasket and tube, if necessary.

The CAA classified this service bulletin as alert and issued AD G-2003-0001, dated July 15, 2003, in order to ensure the airworthiness of these RR plc engines in the U.K.

Bilateral Airworthiness Agreement

This engine model is manufactured in the U.K. and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Under this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. We have examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination and Requirements of This AD

Although no airplanes that are registered in the United States use these engines, the possibility exists that the engines could be used on airplanes that are registered in the United States in the future. The unsafe condition described previously is likely to exist or develop on other RR plc Trent 556-61 engines of the same type design. We are issuing this AD to prevent in-flight fuel leaks, which could result in an engine fire. You must use the service information described previously to perform the actions required by this AD.

FAA's Determination of the Effective Date

Since there are currently no domestic operators of this engine model, notice and opportunity for public comment before issuing this AD are unnecessary. Therefore, a situation exists that allows the immediate adoption of this regulation.

Changes to 14 CFR Part 39—Effect on the AD

On July 10, 2002, we issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs our AD system. This regulation now includes material that relates to special flight permits, alternative methods of compliance, and altered products. This material previously was included in

each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-42-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it. If a person contacts us verbally, and that contact relates to a substantive part of this AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications with you. You may get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and

Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-42-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2003-22-02 Rolls-Royce plc: Amendment 39-13349. Docket No. 2003-NE-42-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective November 14, 2003.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Rolls-Royce plc (RR) RB211 Trent 556-61 engines with serial numbers (SNs) before 71125, except for those SNs that are listed in the following Table 1 of this AD.

TABLE 1.—ENGINE SNS NOT AFFECTED BY THIS AD

71001	71003	71006	71012	71013
71015	71016	71017	71020	71021
71022	71023	71032	71037	71053
71060	71064	71068	71069	71070
71072	71073	71074	71076	71077
71078	71079	71080	71083	71084
71085	71086	71087	71088	71089
71090	71091	71092	71093	71094
71095	70196	71097	71098	71099
71100	71101	71102	71104	71105
71106	71107	71108	71109	71110
71111	71112	71113	71114	71115
71116	71117	71118	71120	71121
71122	71123			

These engines are installed on, but not limited to, Airbus A340 airplanes.

Unsafe Condition

(d) This AD is prompted by a report of fuel leaking from the engine fan cowl during an aircraft taxi. We are issuing this AD to prevent in-flight fuel leaks, which could result in an engine fire.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Credit for Previous Compliance

(f) For engines that have incorporated RR Alert Service Bulletin (ASB) No. RB.211-73-AE200, dated July 11, 2003, no further action is required.

One-Time Gauge Inspections

(g) Before further flight, gauge inspect the space between the high pressure (HP) fuel tubes adaptor face and seals and the space between the fuel flow transmitter and the seals for evidence of permanent distortion of the face of the fuel tube connecting flanges, and replace parts if necessary. Use paragraphs 3.A. through 3.B. of the Accomplishment Instructions of RR ASB No. RB.211-73-AE200, dated July 11, 2003, to do the inspections and parts replacements.

Alternative Methods of Compliance

(h) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(i) You must use Rolls-Royce plc ASB No. RB.211-73-AE200, dated July 11, 2003, to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Rolls-Royce plc, P.O. Box 31, Derby, England, DE24 8BJ; telephone: 011-44-1332-242424; fax: 011-44-1332-249936. You may review copies at the Federal Aviation Administration, New England Executive Park, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Related Information

(j) CAA airworthiness directive G-2003-0001, dated July 15, 2003, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on October 20, 2003.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03-27152 Filed 10-29-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-37-AD; Amendment 39-13350; AD 2003-22-03]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc Trent 768-60 and Trent 772-60 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Rolls-Royce plc (RR) RB211 Trent 768-60 and Trent 772-60 turbofan engines. This AD requires reworking the low