

Actions Accomplished According to Previous Issue of Service Bulletin

(o) Actions accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 727-53A0198, Revision 2, dated October 30, 2003, are considered acceptable for compliance with the corresponding action specified in this AD.

Alternative Methods of Compliance (AMOCs)

(p)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) The inspections specified in paragraph (i) of this AD are approved as a method of compliance (MOC) to paragraph (g) of AD 98-11-03 R1, amendment 39-10983, for the inspections of Structurally Significant Items (SSI) F-13A and F-14A of Supplemental Structural Inspection Document (SSID), D6-48040-1, affected by the repair or modification. The MOC applies only to the areas inspected in accordance with the service bulletin. All provisions of AD 98-11-03 R1 that are not specifically referenced in paragraphs (p)(4) and (p)(5) of this AD remain fully applicable and must be complied with.

(5) For airplanes on which no repair or preventive modification has been done in accordance with Boeing Service Bulletin 727-53-0198, dated January 11, 1990; Boeing Service Bulletin 727-53-0198, Revision 1, dated July 25, 1991; Boeing Alert Service Bulletin 727-53A0198, Revision 2, dated October 30, 2003; or Boeing Service Bulletin 727-53A0198, Revision 3, dated October 2, 2006: The inspections and actions specified in paragraph (g) of this AD are approved as a MOC to paragraph (c) of AD 98-11-03 R1 for the inspections of SSI F-13A and F-14A of SSID, D6-48040-1. This MOC applies only to the areas inspected in accordance with the service bulletin. All other provisions of AD 98-11-03 R1 that are not specifically referenced in paragraphs (p)(4) and (p)(5) of this AD remain fully applicable and must be complied with.

Material Incorporated by Reference

(q) You must use Boeing Service Bulletin 727-53A0198, Revision 3, dated October 2,

2006, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 25, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-10983 Filed 6-8-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27806; Directorate Identifier 2006-NM-287-AD; Amendment 39-15090; AD 2007-12-12]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

* * * discovery of interferences between the power wire supplying the galley's coffee-maker and the surrounding structure. These interferences might, by chafing and degrading the wire insulation, generate short circuits between the wire and the aircraft ground through the composite cabinet structure, without activation of the Circuit Breaker (C/B). Several hot spots may then be created and generate a large amount of thick smokes just behind the cockpit.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective July 16, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 16, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on April 9, 2007 (72 FR 17443). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

This Airworthiness Directive (AD) is issued following discovery of interferences between the power wire supplying the galley's coffee-maker and the surrounding structure. These interferences might, by chafing and degrading the wire insulation, generate short circuits between the wire and the aircraft ground through the composite cabinet structure, without activation of the Circuit Breaker (C/B). Several hot spots may then be created and generate a large amount of thick smokes just behind the cockpit.

This AD aims to prevent this kind of incident, mandating a wire inspection [for damaged wire sleeves], a check for a proper clearance and if necessary a wire re-routing.

The MCAI also requires disabling the galley's coffee-maker, and, in addition to wire re-routing, any required corrective actions. (Corrective actions include replacing worn or defective wire sleeves and shortening wires.) You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a Note within the AD.

Costs of Compliance

Based on the service information, we estimate that this AD will affect about 44 products of U.S. registry. We also estimate that it will take about 46 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the AD on U.S. operators to be \$161,920, or \$3,680 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations

for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-12-12 Dassault Aviation:

Amendment 39-15090. Docket No. FAA-2007-27806; Directorate Identifier 2006-NM-287-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective July 16, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Dassault Model Mystere-Falcon 50 airplanes; certificated in any category; with serial number 275 through 293 and 295 through 303 and 305 through 330 inclusive, with the exception of airplanes which have already embodied the Dassault Service Bulletin F50-456.

Subject

(d) Electrical Power; Equipment/Furnishings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: This Airworthiness Directive (AD) is issued following discovery of interferences between the power wire supplying the galley's coffee-maker and the surrounding structure. These interferences might, by chafing and degrading the wire insulation, generate short circuits between the wire and the aircraft ground through the composite cabinet structure, without activation of the Circuit Breaker (C/B). Several hot spots may then be created and generate a large amount of thick smokes just behind the cockpit.

This AD aims to prevent this kind of incident, mandating a wire inspection [for damaged wire sleeves], a check for a proper clearance and if necessary a wire re-routing. The MCAI also requires disabling the galley's coffee-maker, and, in addition to wire re-routing, any required corrective actions. (Corrective actions include replacing worn or defective wire sleeves and shortening wires.)

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 50 flight hours or 1 month after the effective date of this AD, whichever occurs first, disable the galley's coffee-maker by pulling and locking out the circuit breaker 710HG, as instructed in Dassault Service Bulletin F50-471, dated October 25, 2006.

(2) Within 1,530 flight hours or 24 months after the effective date of this AD, whichever occurs first, inspect for damaged wire sleeves, check their proper clearance, and if a discrepancy is found, prior to next flight, proceed to do all applicable corrective actions as indicated in the Accomplishment Instructions of Dassault Service Bulletin F50-456, dated October 25, 2006. Doing the actions specified in this paragraph terminates the requirements of paragraph (f)(1) of this AD, and after the actions have been done, the circuit breaker collar required by paragraph (f)(1) of this AD may be removed.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: The MCAI does not indicate that doing the actions specified in Dassault Service Bulletin F50-456, dated October 25, 2006, terminates the requirement to disable the coffee-maker. This AD indicates that doing the actions specified in Dassault Service Bulletin F50-456 terminates the requirements to disable the coffee-maker, and after the actions have been done, the circuit breaker collar may be removed.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, 1601 Lind Avenue, SW., Renton, Washington 98057-3356, telephone

(425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Emergency Airworthiness Directive 2006-0329-E, dated October 25,

2006; Dassault Service Bulletin F50-471, dated October 25, 2006; and Dassault Service Bulletin F50-456, dated October 25, 2006; for related information.

Material Incorporated by Reference

(i) You must use the service information specified in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 1.—MATERIAL INCORPORATED BY REFERENCE

Dassault Service Bulletin	Revision level	Date
F50-456	Original	October 25, 2006.
F50-471	Original	October 25, 2006.

Issued in Renton, Washington, on May 30, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-10991 Filed 6-8-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-27525; Directorate Identifier 2006-NM-159-AD; Amendment 39-15089; AD 2007-12-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, 747SR, and 747SP Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain Boeing Model 747 airplanes. That AD currently requires repetitive inspections to detect cracks and/or corrosion of the girt bar

support fitting at certain main entry doors (MED), and repair or replacement of the support fitting. The existing AD also provides for various terminating actions for the repetitive inspections. This new AD requires the following additional actions: An inspection, for certain airplanes, for correct installation of square and conical washers in the girt bar support fitting; an inspection, for certain other airplanes, to determine if the washers are installed; and related investigative and corrective action if necessary. This AD results from a report that the square and conical washers may be installed incorrectly in the girt bar support fitting on airplanes on which the support fitting was repaired or replaced in accordance with the requirements of the existing AD. We are issuing this AD to detect and correct corrosion of the girt bar support fitting, which could result in separation of the escape slide from the lower door sill during deployment, and subsequently prevent proper operation of the escape slides at the main entry doors during an emergency. We are also issuing this AD to detect and correct incorrect installation of the square and conical washers in the girt bar support fitting, which could result in failure of the escape slide when deployed.

DATES: This AD becomes effective July 16, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of July 16, 2007.

On December 16, 1996 (61 FR 58318, November 14, 1996), the Director of the Federal Register approved the incorporation by reference of Boeing Service Bulletin 747-53A2378, Revision 1, dated March 10, 1994.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Patrick Gillespie, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6429; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the