

meetings. In addition, developing seed related issues are also addressed from the perspective of the FSA and FSA Regulations in the "Items of Interest in Seed Control," published quarterly. This publication is available to both State seed control programs and seed companies.

The Extent to Which the Regulations Overlap, Duplicate, or Conflict With Other Federal Rules and to the Extent Feasible With State and Local Government Rules

We are unaware of any FSA Regulations that duplicate or are in conflict with other Federal rules. Sections of the FSA Regulations serve to complement those of several other Federal agencies such as the Food and Drug Administration (FDA), the Environmental Protection Agency (EPA), and APHIS.

For instance, the FDA regards any interstate shipment of seed that could be used for food as adulterated if it has been treated with a chemical considered a poison, unless the seed has been colored to prevent its subsequent inadvertent use as human food or feed for animals (21 CFR 2.25). The EPA requires in 40 CFR 153.55, that pesticides used in treating seed must contain an EPA-approved dye to impart an unnatural color to the seed. Section 201.31a of the FSA Regulations prescribes how treated seed must be labeled when shipped in interstate commerce. The regulations of all three agencies work together to ensure that treated seed is stained and correctly labeled when shipped in interstate commerce.

APHIS enforces the Plant Protection Act (PPA) by prohibiting the importation and interstate movement of seeds containing noxious weeds listed at 7 CFR part 360. Potential imports and interstate movements of seed of these species are regulated by APHIS by permit. Section 201.16 of the FSA Regulations designates seeds of species listed in 7 CFR part 360, except for *Cuscuta* species, as noxious and prohibits the interstate shipment of agricultural and vegetable seeds containing them. This section of the FSA Regulations provides a mechanism to control any of these destructive noxious weeds should they become established.

The FSA and its regulations serve to complement State seed laws and regulations. State seed control programs take action against mislabeled seed sold in their States by issuing stop sale orders against the seed. The seed can not be sold until it is correctly relabeled. States are usually unable to take

regulatory action against the interstate supplier of seed for a number of reasons. The FSA Regulations allow AMS to assist States by taking regulatory action against the interstate shippers of the seed. This cooperative regulatory effort with the States is reflected in Federal/State cooperative agreements between AMS and the Departments of Agriculture in each State.

The Length of Time Since the Regulations Have Been Evaluated or the Degree to Which Technology, Economic Conditions, or Other Factors Have Changed in the Area Affected by the Regulations

The FSA Regulations were recently amended. The final rule was published in the **Federal Register** on January 11, 2000. The amendments to the FSA became effective, February 10, 2000, except for the section making seeds of species listed in the FNWA noxious which becomes effective January 11, 2001.

Some of the amendments updated the seed testing regulations to incorporate the latest in seed testing knowledge so they are the same as the Association of Official Seed Analysts Rules for Testing Seeds, followed by most States for seed law enforcement. This action prevents potential conflicts with State regulations.

Other amendments updated the certified seed regulations in the FSA to make them consistent with State seed certification regulations. These amendments reflect current seed certification practices, and provide minimum certification standards for new crops, such as chemically assisted hybrid cotton.

[FR Doc. 01-7084 Filed 3-21-01; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NE-49-AD]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney PW4000 Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The Federal Aviation Administration (FAA) proposes to adopt a new airworthiness directive (AD) that

is applicable to certain models of Pratt & Whitney (PW) PW4000 series turbofan engines. This proposal would require operators to perform initial and repetitive inspections for cracking of high pressure compressor (HPC) front drum rotors based on cycle usage. This proposal would also require the removal from service of any cracked HPC front drum rotors. This proposal is prompted by reports that seven HPC drum rotors have been found cracked on the spacer surface between the 6th and 7th stage disks. The actions specified by the proposed AD are intended to detect premature cracking of the HPC drum rotor that could result in an uncontained engine failure and damage to the airplane.

DATES: Comments must be received by May 21, 2001.

ADDRESSES: Submit comments to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-NE-49-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Pratt & Whitney, 400 Main Street, East Hartford, CT 06108. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Tara Goodman, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington MA 01803-5299; telephone: 781-238-7130, fax: 781-238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NE-49-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-NE-49-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

This proposal is prompted by reports that seven HPC front drum rotors have been found cracked in the axial direction on the spacer surface between the 6th and 7th stage disks. These axial cracks may propagate into the disk and lead to compressor disk fracture, which could result in an uncontained engine failure. The manufacturer is investigating the cause of the cracking. There is currently no terminating action to the repetitive inspection requirements of the proposed AD. This proposed rule may be revised based on the results of the manufacturer's investigation.

Manufacturer's Service Information

The FAA has reviewed and approved the technical contents of PW Alert Service Bulletin (ASB) No. PW4ENG A72-722, dated September 29, 2000. That ASB provides procedures for operators to perform on-wing and off-wing initial and repetitive HPC drum rotor borescope inspections.

Differences Between Manufacturer's Service Information and this AD

Although ASB No. PW4ENG A72-722, dated September 29, 2000, exempts PW4158 engine serial numbers P728534 through P728546, from the inspection requirements, this AD includes those engines in the initial and repetitive inspections and requires replacing any drum rotor that is cracked. The FAA has

determined that there is insufficient data to permit the exception of these particular engines from the proposed inspection requirements.

Also, although ASB No. PW4ENG A72-722, dated September 29, 2000, provides procedures for operators to perform off-wing initial and repetitive HPC drum rotor inspections, the off-wing requirements are not mandated by the proposed rule. The FAA has evaluated a 20-year cumulative risk assessment and has determined that an acceptable level of safety will be met by requiring the on-wing inspections at the cyclic intervals detailed in the ASB.

ASB No. PW4ENG A72-722, dated September 29, 2000, states in item 12 of the Accomplishment Instructions for the on-wing inspection that an eddy current nondestructive inspection must be done within five engine cycles of finding a crack indication. The FAA has determined that if confirmation of cracking is necessary, an eddy current inspection must be conducted prior to further flight.

Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other PW4000 series turbofan engines of this same type design, the proposed AD would require operators to perform initial borescope inspections on HPC drum rotors before accumulating 1,500 cycles-since-new (CSN) on the effective date of this AD. This proposed AD would also require thereafter, inspections within 2,200 cycles-since-last-inspection, and the removal from service of any cracked HPC front drum rotor. The compliance intervals were established by analysis of service data and evaluation of a risk analysis. The actions would be required to be accomplished in accordance with the ASB described previously.

Economic Analysis

The FAA estimates that there are 1,970 engines of the affected design in the worldwide fleet, and that 538 engines installed on aircraft of U.S. registry would be affected by this proposed AD. The FAA also estimates that it would take approximately 2.5 work hours per engine to accomplish the proposed on-wing inspection, and that the average labor rate is \$60 per work hour. It is estimated that three engines would be found with cracked HPC front drum rotors in the time frame of one year. Approximately 269 engines will be inspected on average per year. The cost of removal and reinstallation of an engine is approximately \$10,000, and the cost of replacing the HPC front drum rotor is approximately \$750,000.

Required replacement parts would cost \$356,130 per engine. Based on these figures, the total cost impact per year of the proposed AD for accomplishing initial inspections and replacing HPC front drum rotors, on U.S. operators is estimated to be \$3,388,730.

Regulatory Impact

This proposal does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposal.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Pratt & Whitney: Docket No. 2000-NE-49-AD.

Applicability: This airworthiness directive (AD) applies to Pratt & Whitney (PW) models

PW4052, PW4056, PW4060, PW4062, PW4152, PW4156A, PW4158, PW4460, and PW4462 turbofan engines. These engines are installed on but not limited to Boeing 747, 767, McDonnell Douglas MD-11, Airbus Industrie A300, and A310 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Required as indicated, unless accomplished previously.

To detect premature cracking of the high pressure compressor (HPC) front drum rotor, that could result in an uncontained engine failure and damage to the airplane, accomplish the following:

Initial Inspection

(a) Perform an initial inspection in accordance with the Accomplishment Instructions, On-Wing paragraphs 1 through 13, of PW Alert Service Bulletin (ASB) No. PW4ENG A72-722, dated September 29, 2000, as follows:

(1) Perform an initial inspection of HPC front drum rotors before accumulating 1,500 cycles-since-new.

(2) If the presence of a crack needs to be confirmed, perform an eddy current inspection (ECI) before further flight.

(3) If the presence of a crack is confirmed, remove and replace with a serviceable HPC front drum rotor before further flight.

Repetitive Inspections

(b) Thereafter, perform inspections within 2,200 cycles-since-last-inspection, in accordance with the Accomplishment Instructions, On-Wing paragraphs 1 through 13, of PW ASB No. PW4ENG A72-722, dated September 29, 2000.

(1) If the presence of a crack needs to be confirmed, perform an ECI before further flight.

(2) If the presence of a crack is confirmed, remove and replace with a serviceable HPC front drum rotor before further flight.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their request through an appropriate Federal Aviation Administration (FAA) Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on March 14, 2001.

Mark Liptak,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 01-7081 Filed 3-21-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-126100-00]

RIN 1545-AY62

Guidance on Reporting of Deposit Interest Paid to Nonresident Aliens; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Change of date of public hearing; reopening period to submit outlines of oral comments; reopening public comment period.

SUMMARY: This document changes the date of the public hearing on the proposed regulations under section 6049 that provide guidance on the reporting requirements for interest on deposits maintained at the U.S. office of certain financial institutions and paid to nonresident alien individuals. It also reopens the period to submit public comments and outlines of oral comments.

DATES: The public hearing will be held June 21, 2001, beginning at 10 a.m.

Additional public comments and outlines of oral comments must be received by May 31, 2001.

ADDRESSES: The public hearing will be held in the Auditorium, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC. Send submissions to: Regulations Unit CC (REG-126100-00), room 5226, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand delivered between the hours of 8 a.m. and 5 p.m. to: Regulations Unit CC (REG-126100-00), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC. Alternatively, taxpayers may submit outlines of oral comments electronically directly to the IRS Internet site at http://www.irs.gov/tax_regs/reglist.html.

FOR FURTHER INFORMATION CONTACT:

Concerning the regulations, Kate Hwa, (202) 622-3840; concerning submission, LaNita Van Dyke, (202) 622-7190 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

A notice of proposed rulemaking and notice of public hearing, appearing in the **Federal Register** on Wednesday, January 17, 2001 (66 FR 3925), announced that a public hearing on the proposed regulations under section 6049, providing guidance on the reporting requirements for interest on deposits maintained at the U.S. office of certain financial institutions and paid to nonresident alien individuals would be held on March 21, 2001, in Room 4718, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC. Subsequently, the date of the public hearing has changed to June 21, 2001, at 10 a.m. in the Auditorium. Public comments and outlines of oral comments must be received by May 31, 2001.

Cynthia Grigsby,

Chief, Regulations Unit, Office of Special Counsel, (Modernization & Strategic Planning).

[FR Doc. 01-7162 Filed 3-19-01; 2:49 pm]

BILLING CODE 4830-01-p