

per line item entry during calendar year 2006.

* * * * *

■ 4. Section 1205.27 is revised to read as follows:

§ 1205.27 Participation in the sign-up period.

The sign-up period will be from September 4, 2007, through November 30, 2007. Those persons who favor the conduct of a continuance referendum and who wish to request that USDA conduct such a referendum may do so by submitting such request in accordance with this section. All requests must be received by the appropriate USDA office by November 30, 2007.

(a) Before the sign-up period begins, FSA shall establish a list of known, eligible, Upland cotton producers in the country that it serves during the representative period, and AMS shall also establish a list of known, eligible Upland cotton importers.

(b) Before the start of the sign-up period, AMS shall mail a request form to each known, eligible, cotton importer. Importers who wish to request a referendum and who do not receive a request form in the mail by September 4, 2007, may participate in the sign-up period by submitting a signed, written request for a continuance referendum, along with a copy of a U.S. Customs and Border Protection form 7501 showing payment of a cotton assessment for calendar year 2006. Importers must submit their requests and supporting documents to USDA, FSA, DAFO, Attention: Rick Pinkston, P.O. Box 23103, Washington, DC 20026-3103. All requests and supporting documents must be received by November 30, 2007.

(c) Each person on the county FSA office lists may participate in the sign-up period. Eligible producers must date and sign their name on the "County FSA Office Sign-up Sheet." A person whose name does not appear on the county FSA office list may participate in the sign-up period.

Such person must be identified on FSA-578 during the representative period or provide documentation that demonstrates that the person was a cotton producer during the representative period. Cotton producers not listed on the FSA-578 shall submit at least one sales receipt for cotton they planted during the representative period. Cotton producers must make requests to the county FSA office where the producer's farm is located. If the producer's land is in more than one county, the producer shall make request at the county officer where FSA administratively maintains and

processes the producer's farm records. It is the responsibility of the person to provide the information need by the county FSA office to determine eligibility. It is not the responsibility of the county FSA office to obtain this information. If any person whose name does not appear on the county FSA office list fails to provide at least one sales receipt for the cotton they produced during the representative period, the county FSA office shall determine that such person is ineligible to participate in the sign-up period, and shall note "ineligible" in the remarks section next to the person's name on the county FSA office sign-up sheet. In lieu of personally appearing at a county FSA office, eligible producers may request a sign-up form from the county FSA office where the producer's farm is located. If the producer's land is in more than one county, the producer shall make the request for the sign-up form at the county office where the FSA administratively maintains and processes the producer's farm records. Such request must be accompanied by a copy of at least one sales receipt for cotton they produced during the representative period. The appropriate FSA office must receive all completed forms and supporting documentation by November 30, 2007.

■ 7. In § 1205.28, the first sentence is revised to read as follows:

§ 1205.28 Counting.

County FSA offices and FSA, Deputy Administrator for Field Operations (DAFO), shall begin counting requests no later than November 30, 2007. * * *

■ 8. Section 1205.29 is revised to read as follows:

§ 1205.29 Reporting results.

(a) Each county FSA office shall prepare and transmit to the state FSA office by December 7, 2007, a written report of the number of eligible producers who requested the conduct of a referendum, and the number of ineligible persons who made requests.

(b) DAFO shall prepare, by December 7, 2007, a written report of the number of eligible importers who requested the conduct of a referendum, and the number of ineligible persons who made requests.

(c) Each state FSA office shall, by December 7, 2007, forward all county reports to DAFO. By December 14, 2007, DAFO shall forward its report of the total number of eligible producers and importers that requested a continuance referendum, through the sign-up period, to the Deputy Administrator, Cotton Program, AMS, Stop 0224, 1400

Independence Ave., SW., Washington, DC 20250-0224.

Dated: August 28, 2007.

Lloyd C. Day,

Administrator, Agricultural Marketing Service.

[FR Doc. 07-4312 Filed 9-5-07; 8:45 am]

BILLING CODE 3410-02-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27983; Directorate Identifier 2006-NM-192-AD; Amendment 39-15188; AD 2007-18-08]

RIN 2120-AA64

Airworthiness Directives; Avions Marcel Dassault-Breguet Model Falcon 10 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all Avions Marcel Dassault-Breguet Model Falcon 10 airplanes. That AD currently requires either revising the airplane flight manual (AFM) and installing a placard in the flight deck to prohibit flight into known or forecasted icing conditions, or repetitively inspecting for delamination of the flexible hoses in the wing (slat) anti-icing system and performing corrective actions if necessary. That AD also provides optional terminating action for the repetitive inspections. This new AD mandates the previously optional terminating action. This AD results from a report of in-service delamination of a flexible hose in the slat anti-icing system at a time earlier than previously reported. We are issuing this AD to prevent collapse of the flexible hoses in the slat anti-icing system, which could lead to insufficient anti-icing capability and, if icing is encountered in this situation, could result in reduced controllability of the airplane.

DATES: This AD becomes effective October 11, 2007.

The Director of the Federal Register approved the incorporation by reference of Dassault Service Bulletin F10-313, Revision 1, dated May 10, 2006, as of October 11, 2007.

On September 26, 2005 (70 FR 53540, September 9, 2005), the Director of the Federal Register approved the

incorporation by reference of Dassault Alert Service Bulletin F10–A312, Revision 1, dated June 27, 2005, including the Service Bulletins Compliance Card.

On April 26, 2005 (70 FR 18282, April 11, 2005), the Director of the Federal Register approved the incorporation by reference of Dassault Alert Service Bulletin F10–A312, dated February 25, 2005.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1137; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647–5527) is located on the ground floor of

the West Building at the DOT street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2005–18–14, amendment 39–14254 (70 FR 53540, September 9, 2005). The existing AD applies to all Avions Marcel Dassault-Breguet Model Falcon 10 airplanes. That NPRM was published in the **Federal Register** on April 24, 2007 (72 FR 20293). That NPRM proposed to retain the existing requirements: Either revising the airplane flight manual (AFM) and installing a placard in the flight deck to prohibit flight into known or forecasted icing conditions, or repetitively inspecting for delamination of certain flexible hoses in the wing (slat) anti-icing system and doing corrective actions if necessary. That NPRM also proposed to mandate the previously optional terminating action for the repetitive inspection requirements.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comment that has been received on the NPRM.

Request To Revise Paragraph (l) of the NPRM

The commenter, Dassault, notes an error in paragraph (l) of the NPRM. As proposed, paragraph (l) referred to credit allowed for a hose replaced before the effective date “of this service bulletin,” but should have referred to

the effective date “of this AD.” We agree and have corrected this inadvertent error in this final rule.

Additional Changes to Final Rule

We have revised this action to clarify the appropriate procedure for notifying the principal inspector before using any approved alternative method of compliance (AMOC) on any airplane to which the AMOC applies.

In retaining the language from the existing AD, we inadvertently also restated an error in Note 3, which referred to “paragraph (j)(1).” There is no subparagraph in paragraph (j). We have revised Note 3 in this final rule to refer to “paragraph (j).”

The NPRM restated paragraphs (h) and (j) from AD 2005–18–14. References to the effective date of this AD should be the effective date of AD 2005–18–14. These references have been clarified in the final rule.

Conclusion

We have carefully reviewed the available data, including the comment that has been received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD, at an average hourly labor rate of \$80.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
AFM revision and placard installation (an option in AD 2005–18–14).	1	\$0	\$80	Up to 146	Up to \$11,680.
Detailed inspection (an option in AD 2005–18–14).	1	0	\$80, per inspection cycle.	Up to 146	Up to \$11,680, per inspection cycle.
Borecope inspection (an option in AD 2005–18–14).	3	0	\$240, per inspection cycle.	Up to 146	Up to \$35,040, per inspection cycle.
Hose replacement (new action)	8	880	\$1,520	Up to 146	Up to \$221,920.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701,

“General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866;

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-14254 (70 FR 53540, September 9, 2005) and by adding the following new airworthiness directive (AD):

2007-18-08 Avions Marcel Dassault-Breguet Aviation (AMD/BA):
Amendment 39-15188. Docket No. FAA-2007-27983; Directorate Identifier 2006-NM-192-AD.

Effective Date

(a) This AD becomes effective October 11, 2007.

Affected ADs

(b) This AD supersedes AD 2005-18-14.

Applicability

(c) This AD applies to all Avions Marcel Dassault-Breguet Model Falcon 10 airplanes.

Unsafe Condition

(d) This AD results from a report of in-service delamination of a flexible hose in the slat anti-icing system at a time earlier than previously reported. We are issuing this AD to prevent collapse of the flexible hoses in the slat anti-icing system, which could lead to insufficient anti-icing capability and, if icing is encountered in this situation, could result in reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within

the compliance times specified, unless the actions have already been done.

Restatement of the Requirements of AD 2005-18-14

Repetitive Detailed Inspections, or Airplane Flight Manual (AFM) Revision and Placard Installation

(f) Within 14 days after April 26, 2005 (the effective date of AD 2005-07-23, which was superseded by AD 2005-18-14), perform the actions specified in either paragraph (f)(1) or (f)(2) of this AD:

(1) Revise the Limitations section of the Dassault Aviation Falcon 10 AFM, and install a placard in the flight deck, to include the following information.

"Flights into known or forecasted icing conditions are prohibited."

The AFM revision may be done by inserting a copy of this AD into the AFM. Install the placard on the pedestal in clear view of the pilot.

(2) Determine the part number of each flexible hose installed in the slat anti-icing system, perform a detailed inspection of the internal walls of the hoses for delamination, and perform any applicable corrective action, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Dassault Alert Service Bulletin F10-A312, dated February 25, 2005. If the part number for any hose cannot be determined, before further flight, replace that hose with a hose having part number (P/N) FAL1005D. Any corrective action must be done before further flight. Repeat the detailed inspection thereafter at intervals not to exceed 60 flight cycles or 3 months, whichever is first, until the actions required by paragraph (i) of this AD are accomplished.

Note 1: When a statement identical to that in paragraph (f)(1) of this AD has been included in the general revision of the AFM, the general revision may be inserted into the AFM, and the copy of this AD may be removed from the AFM.

Note 2: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(g) For airplanes on which the actions described in paragraph (f)(1) of this AD are performed, doing the actions described in paragraph (f)(2) of this AD is terminating action for the requirements of paragraph (f)(1) of this AD. Once the initial detailed inspection specified in paragraph (f)(2) of this AD is performed, the AFM limitation and placard required by paragraph (f)(1) of this AD may be removed.

Borescope Inspections

(h) For airplanes not operated under the limitation in paragraph (f)(1) of this AD: Before the next 10 flight cycles in which the slat anti-icing system is activated after September 26, 2005 (the effective date of AD

2005-18-14), do a borescope inspection of each flexible hose installed in the slat anti-icing system. Do all the inspections and any applicable corrective action (including replacing the hose with a new hose having P/N FAL1005D), by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Dassault Alert Service Bulletin F10-A312, Revision 1, dated June 27, 2005. Any corrective action must be done before further flight. Repeat the inspection thereafter at intervals not to exceed 10 flight cycles in which the slat anti-icing system is activated. Doing this inspection terminates the repetitive inspection requirements of paragraph (f)(2) of this AD.

(i) For airplanes on which the actions described in paragraph (f)(1) of this AD are performed, doing the actions described in paragraph (h) of this AD is terminating action for the requirements of paragraph (f)(1) of this AD. Once the initial borescope inspection specified in paragraph (h) of this AD is performed, the AFM limitation and placard required by paragraph (f)(1) of this AD may be removed.

AFM Revision

(j) For airplanes not operated under the limitation in paragraph (f)(1) of this AD: Before further flight after September 26, 2005, revise the Limitations section of the Dassault Aviation Falcon 10 AFM, to include the following information.

"After each flight in which the slat anti-ice system is activated, inform maintenance." The AFM revision may be done by inserting a copy of this AD into the AFM.

Note 3: When a statement identical to that in paragraph (j) of this AD has been included in the general revision of the AFM, the general revision may be inserted into the AFM, and the copy of this AD may be removed from the AFM.

New Requirements of This AD

Hose Replacement

(k) Within 330 flight hours or 7 months after the effective date of this AD, whichever occurs first: Replace the flexible hoses installed in the slat anti-icing system with new hoses having P/N FAL1007, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F10-313, Revision 1, dated May 10, 2006. This replacement terminates the requirements of paragraphs (f) through (j) of this AD. For airplanes previously operated under the limitation in paragraph (f)(1) of this AD: When the hoses have been replaced, the AFM limitation and placard required by paragraph (f)(1) of this AD may be removed. Repeat the hose replacement at intervals not to exceed 700 flight cycles.

(l) Replacement of a hose before the effective date of this AD in accordance with Dassault Service Bulletin F10-313, dated August 10, 2005, is acceptable for compliance with the requirements of paragraph (k) of this AD.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, International Branch, ANM-116, FAA, has the authority to approve

AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC approved previously in accordance with AD 2005–18–14 is approved as an AMOC for the corresponding provisions of this AD.

Related Information

(n) European Aviation Safety Agency airworthiness directive 2006–0114, dated

May 10, 2006, also addresses the subject of this AD.

Material Incorporated by Reference

(o) You must use the service bulletins identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Dassault Service Bulletin F10–313, Revision 1, dated May 10, 2006, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On September 26, 2005 (70 FR 53540, September 9, 2005), the Director of the Federal Register approved the incorporation by reference of Dassault Alert Service Bulletin F10–A312, Revision 1, dated June 27, 2005, including the Service Bulletins Compliance Card.

(3) On April 26, 2005 (70 FR 18282, April 11, 2005), the Director of the Federal Register approved the incorporation by reference of Dassault Alert Service Bulletin F10–A312, dated February 25, 2005, including the Service Bulletins Compliance Card.

(4) Contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 1.—SERVICE INFORMATION INCORPORATED BY REFERENCE

Service Bulletin	Revision level	Date
Dassault Alert Service Bulletin F10–A312, including the Service Bulletins Compliance Card	Original	February 25, 2005.
Dassault Alert Service Bulletin F10–A312, including the Service Bulletins Compliance Card	Revision 1	June 27, 2005.
Dassault Service Bulletin F10–313	Revision 1	May 10, 2006.

Issued in Renton, Washington, on August 17, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7–17288 Filed 9–5–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27776; Directorate Identifier 2006–NM–170–AD; Amendment 39–15189; AD 2007–18–09]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all Airbus Model A318–100, A319–100, A320–200, A321–100, and A321–200 series airplanes, and Model A320–111 airplanes. That AD currently requires an inspection to determine whether certain braking and steering control units (BSCUs) are installed or have ever been installed. For airplanes on which certain BSCUs are installed or have ever been installed, the existing AD requires an inspection of the nose landing gear (NLG) upper

support, and corrective action if necessary; and a check of the NLG strut inflation pressure, and an adjustment if necessary. For some of these airplanes, the existing AD also requires a revision to the aircraft flight manual to incorporate an operating procedure to recover normal steering in the event of a steering failure. This new AD instead requires repetitive inspections of the NLG upper support, and related investigative/corrective actions in accordance with new service information; and removes the one-time inspection that was required by the existing AD. This new AD also provides an optional terminating action for the repetitive inspections. This AD results from a report of an incident where an airplane landed with the NLG turned 90 degrees from centerline, and from additional reports of NLG upper support anti-rotation lugs rupturing in service. We are issuing this AD to prevent landings with the NLG turned 90 degrees from centerline, which could result in reduced controllability of the airplane.

DATES: This AD becomes effective October 11, 2007.

The Director of the **Federal Register** approved the incorporation by reference of a certain publication listed in the AD as of October 11, 2007.

On November 30, 2005 (70 FR 70715, November 23, 2005), the Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD.

ADDRESSES: You may examine the AD docket on the Internet at [http://](http://dms.dot.gov)

dms.dot.gov or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2141; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647–5527) is located on the ground floor of the West Building at the DOT street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2005–24–06, amendment 39–14386 (70 FR 70715, November 23, 2005). The existing AD applies to all Airbus Model A318–100, A319–100, A320–200, A321–100, and A321–200 series airplanes, and Model A320–111