

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747-400 and 747-400D series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD results from reports of cracks found in the Section 41 upper deck floor beam upper chords. We are issuing this AD to detect and correct cracks in these chords, which could become large and cause the floor beams to become severed and result in rapid decompression or reduced controllability of the airplane.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Inspections and Corrective Actions

(g) Except as required by paragraphs (h) and (i) of this AD: At the applicable times in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, do an inspection (open-hole or surface high frequency eddy current), to detect cracks in the floor panel attachment fastener holes of the Section 41 upper deck floor beam upper chords, and do applicable related investigative and corrective actions, by accomplishing all the applicable actions specified in the Accomplishment Instructions of the service bulletin. Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., "Compliance," of the service bulletin.

(h) If any crack is found during any inspection required by paragraph (g) of this AD, and Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Where Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on

any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on February 5, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3386 Filed 2-17-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY**Internal Revenue Service****26 CFR Part 1**

[REG-148326-05]

RIN 1545-BF50

Further Guidance on the Application of Section 409A to Nonqualified Deferred Compensation Plans; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking.

SUMMARY: This document contains a correction to a notice of proposed rulemaking (REG-148326-05) that was published in the **Federal Register** on Monday, December 8, 2008 (73 FR 74380) providing guidance on the calculation of amounts includible in income under section 409A(a) and the additional taxes imposed by such section with respect to service providers participating in certain nonqualified deferred compensation plans. The regulations would affect such service providers and the service recipients for whom the service providers provide services.

FOR FURTHER INFORMATION CONTACT: Stephen Tackney, (202) 927-9639 (not a toll-free number).

SUPPLEMENTARY INFORMATION:**Background**

The correction notice that is the subject of this document is under section 409A of the Internal Revenue Code.

Need for Correction

As published, the notice of proposed rulemaking (REG-148326-05) contains an error that may prove to be misleading and is in need of clarification.

Correction of Publication

Accordingly, the publication of the notice of proposed rulemaking (REG-148326-05), which was the subject of FR Doc. E8-28894, is corrected as follows:

On page 74380, column 3, in the preamble, under the caption **FOR FURTHER INFORMATION CONTACT:**, lines 1 and 2 from the bottom of the paragraph, the language "hearing, Funmi Taylor at (202) 622-7190 (not toll-free numbers)." is corrected to read "hearing, Funmi Taylor at (202) 622-3628 (not toll-free numbers)".

LaNita Van Dyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedure and Administration).

[FR Doc. E9-3323 Filed 2-17-09; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 110**

[Docket No. USCG-2008-0027]

RIN 1625-AA01

Anchorage Regulations; Port of New York

AGENCY: Coast Guard, DHS.

ACTION: Proposed rule; withdrawal.

SUMMARY: The Coast Guard is withdrawing its proposed rule concerning the revision of boundaries of three anchorage grounds adjacent to Ellis and Liberty Islands in Upper New York Bay. The proposed rule is being withdrawn due to the decision not to expand two security zones around Ellis and Liberty Islands. The decision not to expand the security zones removes the need to revise the anchorage ground boundaries.

DATES: The proposed rule published at 73 FR 27775, May 14, 2008, is withdrawn, effective February 18, 2009.

ADDRESSES: The docket for this withdrawn rulemaking is available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m.