

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-12523 (66 FR 60144), and by adding a new airworthiness directive (AD), to read as follows:

Agusta S.p.A.: Docket No. 2001-SW-15-AD. Revises AD 2001-24-07, Amendment 39-12523.

Applicability: Model A109C, A109E, and A109K2 helicopters, with main rotor blade (blade), part number (P/N) 709-0103-01—all dash numbers, having a serial number (S/N) up to and including S/N 1428 with a prefix of either “EM-” or “A5-” installed, certificated in any category.

Compliance: Required within 10 hours time-in-service (TIS), unless accomplished previously, and thereafter at intervals not to exceed 25 hours TIS.

To prevent failure of a blade tip cap, excessive vibration, and subsequent loss of control of the helicopter, accomplish the following:

(a) Tap inspect the upper and lower sides of each tip cap for bonding separation between the metal shells and the honeycomb core using a steel hammer, P/N 109-3101-58-1, or a coin (quarter) in the area indicated as honeycomb core on Figure 1 of Alert Bollettino Tecnico Nos. 109-106, 109K-22, or 109EP-1, all Revision B, and dated December 19, 2000 (ABT), as applicable. Also, tap inspect for bonding separation in the tip cap to blade bond area (no bonding voids are permitted in this area).

(b) Visually inspect the upper and lower sides of each blade tip cap for swelling or deformation.

(c) Dye-penetrant inspect the tip cap leading edge along the welded joint line of the upper and lower tip cap skin shells for a crack in accordance with the Compliance Instructions, paragraph 3, of the applicable ABT.

(d) If any swelling, deformation, crack, or bonding separation that exceeds the prescribed limits in the applicable maintenance manual is found, replace the blade with an airworthy blade.

(e) Replacement blades affected by this AD must comply with the repetitive inspection requirements of this AD. Replacing an affected blade with a blade having an

airworthy blade tip cap, P/N 709-0103-29-109, is terminating action for the requirements of this AD for that blade.

(f) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Office, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

Note: The subject of this AD is addressed in Ente Nazionale per l'Aviazione Civile (Italy) AD Nos. 2000-571, 2000-572, and 2000-573, all dated December 22, 2000.

Issued in Fort Worth, Texas, on January 16, 2004.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-1687 Filed 1-26-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2002-NM-300-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dornier Model 328-100 series airplanes. This proposal would require repetitive inspections of certain support arms of the ground spoiler assemblies for cracking, and replacement of any ground spoiler assembly having cracking with a new ground spoiler assembly. This proposal would also require certain inspections for discrepancies of the ground spoiler assemblies and the flap of each wing; and corrective actions if necessary. This action is necessary to prevent failure of the support arms due to cracking, which could result in loss of function and/or separation of the affected ground spoiler assemblies from the airplane, and consequent reduced controllability of the airplane during landing or rejected take-off operations. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by February 26, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport

Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-30AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain “Docket No. 2002-NM-300-AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from AvCraft Aerospace GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before

and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-300-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-300-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on certain Dornier Model 328-100 series airplanes. The LBA advises that cracking has been found in support arms No. 3 and No. 8 on ground spoiler assemblies No. 1 and No. 2, part numbers 001B577A1000 and 001B577A1100. The cracking is caused by higher loads placed on the support arms as a result of insufficient clearance between the bottom of the trailing edges of the ground spoilers and the upper surfaces of the wing flaps. This condition, if not corrected, could result in loss of function and/or separation of the affected ground spoiler assemblies from the airplane, and consequent reduced controllability of the airplane during landing or rejected take-off operations.

Explanation of Relevant Service Information

Dornier has issued Service Bulletin SB-328-57-435, Revision 1, dated August 7, 2002, which describes procedures for repetitive eddy current inspections to detect cracking in the bottom edge of the flange for ground spoiler support arms No. 3 and No. 8 of ground spoiler assemblies No. 1 and No. 2, part numbers 001B577A1000 and 001B577A1100, left and right sides of the airplane; and replacement of any ground spoiler assembly having cracking with a new ground spoiler assembly.

Dornier has also issued Service Bulletin SB-328-57-439, Revision 1, dated March 10, 2003, which describes procedures for a visual inspection,

contour inspection, and clearance inspection of the ground spoilers and the flap of each wing for discrepancies, and corrective action if necessary. The service bulletin includes the following:

- Procedures for a visual inspection of the flap protection strip for chafing marks, reporting inspection results to the manufacturer, and inspecting the bottom surface of the ground spoiler and the mating upper surface of the flap of each wing for surface damage (chafing marks or paint damage), and repair if necessary. If abnormal chafing marks are found, the service bulletin recommends doing the inspection of the spoiler arms per Dornier Service Bulletin SB-328-57-435, Revision 1, dated August 7, 2002.

- Procedures for a contour inspection of the ground spoiler and the flap of each wing to determine if they are within the specified tolerances, adjusting the ground spoiler actuator if out of tolerance, and reporting the inspection results to the manufacturer.

- Procedures for a clearance inspection between the bottom of the trailing edge of the ground spoiler and the upper surface of the flap of each wing. If there is a notable deflection (spring back effect) between the ground spoiler and the surface, the service bulletin recommends reporting the inspection results to the manufacturer. If there is no notable deflection (spring back effect) between the ground spoiler and the surface, the service bulletin recommends adjusting the ground spoiler actuator and repeating the clearance inspection.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition. The LBA classified these service bulletins as mandatory and issued German airworthiness directives 2002-258, dated September 5, 2002, and 2003-357, dated November 11, 2003, to ensure the continued airworthiness of these airplanes in Germany.

FAA's Conclusions

This airplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept us informed of the situation described above. We have examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are

certificated for operation in the United States.

Explanation of Requirements of Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously, except as discussed below.

Differences Between the Proposed AD, German Airworthiness Directive, and Service Information

Operators should note that Service Bulletin SB-328-57-439, Revision 1, dated March 10, 2003, recommends doing the actions in the service bulletin "as soon as possible or at the latest at the next A-check or equivalent." German airworthiness directive 2003-357, dated November 11, 2003, recommends doing the actions "at latest at the next A-Check or equivalent." Because "A-check" schedules vary among operators, this proposed AD would require accomplishment of the actions within 400 flight cycles after the effective date of this proposed AD, and accomplishment of any required corrective action before further flight. We find that compliance of within 400 flight cycles after the effective date of this proposed AD is appropriate for affected airplanes to continue to operate without compromising safety.

Service Bulletin SB-328-57-435, Revision 1, states to contact Dornier if any crack is found in a support arm for a ground spoiler, and to send the affected ground spoiler to Dornier, but those actions are not required by this proposed AD. Service Bulletin SB-328-57-439, Revision 1, also recommends that inspection results for cracking of support arms be sent to Dornier, but that action is not required by this proposed AD.

Clarification of Procedures for Installing New Ground Spoiler

Service Bulletin SB-328-57-435, Revision 1, specifies that if a crack is found in a support arm of a ground spoiler during any inspection, the ground spoiler should be replaced with a new ground spoiler. However, the service bulletin does not include procedures for replacing the ground spoiler. This proposed AD specifies that any ground spoiler replacement should be done per the applicable section(s) of chapters 27 or 57 of the maintenance manual.

Cost Impact

We estimate that 53 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 2 work hours per airplane to accomplish the proposed general visual, contour, and clearance inspections of the ground spoilers, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of these proposed inspections on U.S. operators is estimated to be \$6,890, or \$130 per airplane.

It would take approximately 4 work hours per airplane to accomplish the proposed inspection of the support arms for the ground spoilers, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of this proposed inspection on U.S. operators is estimated to be \$13,780, or \$260 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fairchild Dornier GMBH (Formerly Dornier Luftfahrt GmbH): Docket 2002–NM–300–AD.

Applicability: Model 328–100 series airplanes, as listed in Dornier Service Bulletin SB–328–57–435, Revision 1, dated August 7, 2002; and Dornier Service Bulletin SB–328–57–439, Revision 1, dated March 10, 2003; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the support arms of the ground spoiler assemblies due to cracking, which could result in loss of function and/or separation of the affected ground spoiler assemblies from the airplane, and consequent reduced controllability of the airplane during landing or rejected take-off operations, accomplish the following:

Visual, Contour, and Clearance Inspections of Ground Spoilers, and Corrective Actions

(a) Within 400 flight cycles after the effective date of this AD: Do the inspections for discrepancies of the ground spoiler assemblies and the wing flaps by doing all the actions per the Accomplishment Instructions of Dornier Service Bulletin SB–328–57–439, Revision 1, dated March 10, 2003. Any applicable corrective action must be done before further flight per the service bulletin.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Inspection of Ground Spoiler Support Arms

(b) Within 4 weeks after the effective date of this AD, or prior to the accumulation of 4,000 total flight cycles, whichever is later: Do an eddy current inspection for cracking in the bottom edge of the flange for ground spoiler support arms No. 3 and No. 8, left and right sides of the airplane. Do the inspection by accomplishing all of the actions per the Accomplishment Instructions of Dornier Service Bulletin SB–328–57–435, Revision 1, dated August 7, 2002. Repeat the inspection thereafter at intervals not to exceed 1,000 flight cycles.

Corrective Action

(c) If any cracking is found during any inspection required by paragraph (b) of this AD, before further flight, replace the affected ground spoiler assembly with a new ground spoiler assembly per the applicable section(s) of chapters 27 or 57 of the Dornier Model 328–100 Maintenance Manual.

Certain Recommendations in Service Bulletins Not Required

(d) Dornier Service Bulletin SB–328–57–435, Revision 1, dated August 7, 2002, states to contact Dornier if any crack is found in a support arm for a ground spoiler, and to send the affected ground spoiler to Dornier, but those actions are not required by this AD. Dornier Service Bulletin SB–328–57–439, Revision 1, dated March 10, 2003, recommends that inspection results for cracking of support arms be sent to Dornier, but that action is not required by this AD.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in German airworthiness directives 2002–258, dated September 5, 2002, and 2003–357, dated November 11, 2003.

Issued in Renton, Washington, on January 20, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–1660 Filed 1–26–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NM–66–AD]

RIN 2120–AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB–145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.