

TABLE 2 TO PARAGRAPHS (g) AND (i) OF THIS AD—Parts To Be Inspected/Installed
[Airbus Service Bulletin A320–53–1293]

Affected P/N	Acceptable replacement P/N	Area
D2707033520000	D2707033520000	Cargo.
D2827027120000	D2827027120000	Cargo.
D2827093500400	D2827093500400	Cargo.
D2907013701200	D2907013701251	Cargo.
D2907013800400	D2907013800451	Cargo.
D3247012900000	D3247012900051	Cargo.
D3817003820000	D3817003820000	Cargo.
D3817012320200	D3817012320251	Cargo.
D3837021201600	D3837021201600	Cargo.
D3837033300400	D3837033300400	Cargo.
D4918518320200	D4918518320200	Cargo.
D5347043420400	D5347043420451	Cargo.
D9248511000000	D9248511000051	Cargo.
D9249254100200	D9249254100251	Cargo.
D9249282300000	D9249282300000	Cargo.

TABLE 3 TO PARAGRAPHS (g) AND (i) OF THIS AD—Parts To Be Inspected/Installed
[Airbus Service Bulletin A320–53–1294]

Affected P/N	Acceptable replacement P/N	Area
D2827098326800	D2827098326851	Frame.
D5347051620600	D5347051620651	Frame.
D5347051720600	D5347051720651	Frame.
D5347057120000	D5347057120051	Frame.
D5347067520600	D5347067520651	Frame.
D5347067521400	D5347067521451	Frame.
D5347067520800	D5347067520851	Frame.
D5347067521000	D5347067521051	Frame.
D5347067521600	D5347067521651	Frame.
D5347067620600	D5347067620651	Frame.
D5347067720200	D5347067720251	Frame.
D5347067720400	D5347067720451	Frame.
D5347986520200	D5347986520251	Frame.

(h) Exception to Paragraph (g) of This AD

Where Subtask 531293–832–207–001 of Airbus Service Bulletin A320–53–1293, dated July 23, 2015; including Appendixes 01 and 02, dated July 23, 2015, specifies inspecting Item 19 of Figure A–GVAAA for material heat treatment conformity, and that figure (incorrectly) identifies the inspection area for Item 19 as the four hinge brackets adjacent to the A-profile, this AD requires inspecting part number D491–85183–202–00, which is the A-profile, and not just the brackets.

Note 1 to paragraph (h) of this AD: Airbus Technical Adaptation 80095365/011/2016, Issue 1, dated December 1, 2016 (“TA”) specifies that for Figure A–GVAAA, Sheet 01, of Airbus Service Bulletin A320–53–1293, dated July 30, 2015, Item 19 should point to part number D491–85183–202–00 (and not just to the brackets). The TA also specifies that for Figure A–GRAAA, Sheet 01, of Airbus Service Bulletin A320–53–1293, dated July 30, 2015, the correct Item 19 identification is part number D491–85183–202–00.

(i) Replacement

If during the measurement required by paragraph (g) of this AD, any affected part number specified in table 1, 2, or 3 to

paragraphs (g) and (i) of this AD is found to have a measured value greater than that specified in Figure A–GFAAA, Sheet 01, “Inspection Flowchart,” of the applicable service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD: Before further flight, replace the affected part with the corresponding acceptable replacement part specified in table 1, 2, or 3 to paragraphs (g) and (i) of this AD, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD.

(j) No Reporting Requirement

Although the service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone: 425–227–1405; fax: 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015–0219, dated November 3, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–6431.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320–53–1292, dated July 23, 2015; including Appendixes 01 and 02, dated July 23, 2015.

(ii) Airbus Service Bulletin A320–53–1293, dated July 30, 2015; including Appendixes 01 and 02, dated July 30, 2015.

(iii) Airbus Service Bulletin A320–53–1294, dated July 23, 2015; including Appendixes 01 and 02, dated July 23, 2015.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—ELIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 2, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–04657 Filed 3–10–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–8183; Directorate Identifier 2015–NM–083–AD; Amendment 39–18822; AD 2017–05–11]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2012-08-11 for certain Bombardier, Inc. Model DHC-8-400 series airplanes. AD 2012-08-11 required repetitive inspections for defects and damage of the retract port flexible hoses on the main landing gear (MLG) retraction actuators, and replacement if necessary. This AD continues to require the actions in AD 2012-08-11, requires reorientation of the retraction actuator of the MLG, and removes airplanes from the applicability. This AD was prompted by test results that showed that failure of a retract port flexible hose of a MLG retraction actuator could cause excessive hydraulic fluid leakage. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 17, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 17, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of May 29, 2012 (77 FR 24351, April 24, 2012).

ADDRESSES: For Bombardier service information identified in this final rule, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. For Goodrich service information identified in this final rule, contact Goodrich Aerospace Canada Ltd., Landing Systems, 1400 South Service Road, West Oakville, ON, Canada L6L 5Y7; telephone +1-877-808-7575; fax: +1-905-825-6320; email: crc@utas.utc.com; Internet: <https://techpubs.goodrich.com/ContactUs>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8183.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8183; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket

contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Mechanical Systems Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2012-08-11, Amendment 39-17028 (77 FR 24351, April 24, 2012) ("AD 2012-08-11"). AD 2012-08-11 applied to certain Bombardier, Inc. Model DHC-8-400 series airplanes. The NPRM published in the **Federal Register** on August 5, 2016 (81 FR 51821). The NPRM was prompted by our determination that the left and right MLG retraction actuator ports must be reoriented and the retract port flexible hoses replaced with hydraulic tube assemblies to address the identified unsafe condition. The NPRM proposed to continue to require the actions required by AD 2012-08-11. The NPRM also proposed to require reorientation of the retraction actuator of the MLG, which would terminate the repetitive inspections, and to remove certain airplanes from the applicability. We are issuing this AD to prevent hydraulic fluid leakage in the event of a retract port flexible hose failure; this condition could lead to an undamped extension of the MLG and could result in MLG structural failure, leading to an unsafe, asymmetric landing configuration.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2011-14R1, effective May 21, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model DHC-8-400, -401, and -402 airplanes. This AD also removes airplanes from the applicability of AD 2012-08-11. The MCAI states:

Testing has shown that in the event of a main landing gear (MLG) retraction actuator retract port flexible hose failure, in-flight vibrations may cause excessive hydraulic

fluid leakage. This could potentially lead to an undamped extension of the MLG, which may result in MLG structural failure, leading to an unsafe asymmetric landing configuration.

The original issue of this [Canadian] AD mandated the [detailed] inspection [for defects and damage] of the retract port flexible hose and its replacement [installing a new retract port flexible hose], when required, to prevent damage to the MLG caused by undamped gear extensions.

Revision 1 of this [Canadian] AD mandates the reorientation of the MLG Retraction Actuator to prevent hydraulic fluid leakage in the event of a damaged retract port flexible hose.

Airplanes having serial number 4425 and on were modified in production and, therefore, the identified unsafe condition does not apply to these airplanes. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8183.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Refer to Updated Service Information

Horizon Air requested that the NPRM be revised to refer to Bombardier Service Bulletin 84-32-106, Revision B, dated June 18, 2015. As a result, Horizon Air stated that Bombardier Service Bulletin 84-32-106, Revision A, dated April 24, 2015, should be included in paragraph (i), "Credit for Previous Actions," of the proposed AD along with Bombardier Service Bulletin 84-32-106, dated September 28, 2012.

We agree to refer to the latest service information. We have confirmed that the revised service information does not require any work beyond what was published in the NPRM. We have revised this AD to refer to Bombardier Service Bulletin 84-32-106, Revision B, dated June 18, 2015, as the appropriate source of service information for completing certain actions (Modification Summary (ModSum) 4-902418) required by this AD. We have also revised this AD to provide credit for actions done before the effective date of this AD using Bombardier Service Bulletin 84-32-106, Revision A, dated April 24, 2015.

Request To Correct MCAI Number

Contact Air Technik GmbH commented that Canadian AD CF-2011-14R1, effective May 21, 2015, is incorrectly referenced in paragraph (k),

“Related Information,” of the proposed AD as Canadian AD CF–2011–24R1, effective May 21, 2015.

We agree that paragraph (k)(1) of this AD should refer to Canadian AD CF–2011–14R1, effective May 21, 2015. We have revised paragraph (k)(1) of this AD accordingly.

Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Bombardier, Inc. has issued the following service information.

- Bombardier Service Bulletin 84–32–105, Revision A, dated April 24, 2015. This service information describes procedures for reworking and reorienting the retraction actuators (ModSum 4–902327).

- Bombardier Service Bulletin 84–32–106, Revision B, dated June 18, 2015. This service information describes procedures for reworking and installing reconfigured hydraulic tube assemblies for the retraction actuators (ModSum 4–902418).

Goodrich Aerospace Canada Ltd. has issued the following service information.

- Goodrich Service Bulletin 46550–32–99 R2, dated February 19, 2015. This service information describes

procedures for reworking and reorienting the retraction actuators.

- Goodrich Service Bulletin 46455–32–100 R1, dated March 20, 2013. This service information describes procedures for reworking and installing reconfigured hydraulic tube assemblies for the retraction actuators.

These service bulletins contain different requirements and must be accomplished at the same time. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 82 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection (retained action from AD 2012–08–11).	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0	\$85 per inspection cycle.	\$6,970 per inspection cycle.
Reorient MLG retraction actuators (new action).	4 work-hours × \$85 per hour = \$340	0	\$340	\$27,880.

We estimate the following costs to do any necessary replacements that will be

required based on the results of the required inspection. We have no way of

determining the number of aircraft that might need this replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace the retract port flexible hose (retained action from AD 2012-08-11).	4 work-hours × \$85 per hour = \$340	\$713	\$1,053

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures for the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2012–08–11, Amendment 39–17028 (77 FR 24351, April 24, 2012), and adding the following new AD:

2017–05–11 Bombardier, Inc.: Amendment 39–18822; Docket No. FAA–2016–8183; Directorate Identifier 2015–NM–083–AD.

(a) Effective Date

This AD is effective April 17, 2017.

(b) Affected ADs

This AD replaces AD 2012–08–11, Amendment 39–17028 (77 FR 24351, April 24, 2012) (“AD 2012–08–11”).

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC–8–400, –401, and –402 airplanes, certificated in any category, serial numbers 4001 through 4424 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by test reports that showed that failure of a retract port flexible hose of a main landing gear (MLG) retraction actuator could cause excessive hydraulic fluid leakage. We are issuing this AD to prevent hydraulic fluid leakage in the event of a retract port flexible hose failure; this condition could lead to an undamped extension of the MLG and could result in MLG structural failure, leading to an unsafe asymmetric landing configuration.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Repetitive Inspections and Follow-on Action, With New Reference

This paragraph restates the requirements of paragraph (g) of AD 2012–08–11, with new reference to terminating action. Within 600 flight hours after May 29, 2012 (the effective date of AD 2012–08–11), do a detailed inspection for defects and damage of the retract port flexible hose of the left and right MLG retraction actuators, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84–32–89, dated March 22, 2011. Repeat the inspection thereafter at intervals not to exceed 600 flight hours. If any defect or damage is found, before further flight, replace the retract port flexible hose with a new or serviceable retract port flexible hose, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84–32–89, dated March 22, 2011. Doing the actions required

by paragraph (h) of this AD terminates the inspections required by this paragraph.

(h) New Requirement of This AD: Reorient MLG Retraction Actuators

Within 6,000 flight hours or 36 months, whichever occurs first after the effective date of this AD: Reorient the MLG retraction actuator by incorporating Bombardier Modification Summaries 4–902418 and 4–902327, in accordance with the Accomplishment Instructions of the applicable service information specified in paragraphs (h)(1) and (h)(2) of this AD. Accomplishment of the actions required by this paragraph terminates the actions required by paragraph (g) of this AD.

(1) Bombardier Service Bulletin 84–32–105, Revision A, dated April 24, 2015; and Goodrich Service Bulletin 46550–32–99 R2, dated February 19, 2015.

(2) Bombardier Service Bulletin 84–32–106, Revision B, dated June 18, 2015; and Goodrich Service Bulletin 46455–32–100 R1, dated March 20, 2013.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (i)(1), (i)(2), or (i)(3) of this AD, as applicable.

(1) Bombardier Service Bulletin 84–32–105, dated September 28, 2012.

(2) Bombardier Service Bulletin 84–32–106, dated September 10, 2012.

(3) Bombardier Service Bulletin 84–32–106, Revision A, dated April 24, 2015.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2012–08–11 are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2011–14R1, dated May 21, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–8183.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(4), (l)(5), and (l)(6) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 84–32–105, Revision A, dated April 24, 2015.

(ii) Bombardier Service Bulletin 84–32–106, Revision B, dated June 18, 2015.

(iii) Goodrich Service Bulletin 46550–32–99 R2, dated February 19, 2015.

(iv) Goodrich Service Bulletin 46455–32–100 R1, dated March 20, 2013.

(3) The following service information was approved for IBR on May 29, 2012 (77 FR 24351, April 24, 2012).

(i) Bombardier Service Bulletin 84–32–89, dated March 22, 2011.

(ii) Reserved.

(4) For Bombardier service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(5) For Goodrich service information identified in this AD, contact Goodrich Aerospace Canada Ltd., Landing Systems, 1400 South Service Road, West Oakville, ON, Canada L6L 5Y7; telephone +1–877–808–7575; fax: +1–905–825–6320; email: crc@utas.utc.com; Internet: <https://techpubs.goodrich.com/ContactUs>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 28, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–04514 Filed 3–10–17; 8:45 am]

BILLING CODE 4910–13–P